

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8d5"
    },
    "firstName": "Kiran Sir",
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418f3",
    "email": "kiran@cosmosbank.in",
    "mobileNo": "9594609519",
    "workMobileNo": "9594609519",
    "lastName": "sir"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Kiran Sir",
    "expectedFees": null,
    "quotedAmount": "4000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8d5",
  "branchCode": "000007",
  "type": "BRANCH",
  "name": "Mulund (West) Branch",
  "email": "cosmos@mulundwestgmail.com",
  "mobileNo": "022-21640621",
  "alternateMobileNo": "022-21646370",
  "address": "Apurva Co-Op. Housing Society, Govardhan Nagar, L.B.S. Road, Mulund
(West), Mumbai - 400 080, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "663da98cfcea71232186f142",
  "role": "ACCOUNTANT",
  "firstName": "SONAL ",
  "email": "sonal.ambekar19@gmail.com",
  "lastName": " SHIVGAN",
  "mobileNo": "9773395869",
```

```
"designation": "",
"shortName": "SO",
"workWithDocumentMaker": "",
"profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.17490747698102",
  "longitude": "72.94177920006315"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.94177920006315,
    19.17490747698102
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "10/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-11T07:45:54.574Z",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-10",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-10",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-12",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-12",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-12",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "25000",
```

```
"lumpsumValue": "1",
"rateMax": "26000",
"areaType": {
  "Name": "Carpet",
  "Value": "Carpet",
  "name": "Carpet",
  "value": "Carpet"
}
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nahur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "11",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```



```
"key": "buildingName",
"value": "Mulund Shangri-La ",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "P. K. Road Extention",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```

```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "551/77/B",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1104",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "T",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 080",
  "label": false
},
"suburb": {
```

```
"status": true,
"name": "Suburb",
"key": "suburb",
"value": "Mulund (West)",
"label": false
}
},
"flatSpecifications": {
"roof": {
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
"label": "Teak Wood Door frame with Solid door with safety door"
},
"windows": {
"value": "PowderCoatedAluminiumSliding",
"label": "Powder Coated Aluminium Sliding"
},
"fittings": {
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
"value": "Cement_Plastering+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
}
},
}
```

```
"townplanApprovedByList": {
  "label": "Municipal Corporation of Greater Mumbai (MCGM)",
  "value": "MCGM"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "K. Kamarajar Raod",
  "west": "Arihant Car Showroom",
  "south": "Commercial Building",
  "east": "Purshottam Khairaj Road Extention"
},
"asPerDocumentAgreement": {
  "north": "44 Wide Proposed Road",
  "west": "Plot CTS No. 551/77/A",
  "south": "Government land forming of Nala",
  "east": "60 Ft. wide Road known as Purshottam Khairaj Road Extention"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Flat No. 1101 & 1102",
    "east": "Marginal Space",
    "south": "Flat No. 1103",
    "west": "Lift"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
```

```
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As amended plan cum Occupation Certificate is
available it is assumed that the construction is as per Sanctioned Plan",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "ordinary",
  "label": "Ordinary"
},
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "22.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "27670",
  "depreciatedBuildingRate": "2170"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "133050",
  "landRate": "63960",
  "igrImage": "cases/6780faaff25068da52482d2f/igr_1736835949172_Image.png",
  "squareMeterGuideLineRate": "146355.00",
  "squareFeetGuideLineRate": "13597.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "85",
  "rate": "12449.00",
  "squareFeetGuideLineRate": "12449.00",
```

```
"squareMeterGuideLineRate": "133996.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "Information not available",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonry",
    "value": "6\"_Thk._Brick_Masonry"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  }
}
```

```
},
"pavementLaid": {
  "label": "Yes",
  "value": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2010",
  "fullDate": "1/1/2010"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
```



```
"label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
}
```

```
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "45",
"ageOfBuilding": "15",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "12",
"flatFloorNo": "11",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6780faaff25068da52482d2f/
routeMap_1736844580586_Image.png",
    "routeLat": "19.166904",
    "routeLng": "72.944199",
    "stationName": "Nahur",
    "routeDistance": "1.9 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "hdwg0f",
      "name": "hdwg0f",
      "image": "cases/6780faaff25068da52482d2f/
routeMap_1736844542330_Image.png"
    }
  ]
}
```

```
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "2584400.00",
    "depreciationPercentage": "22.5",
    "depreciatedCostOfConstruction": "581490.00",
    "totalFairMarketValue": "21181210.00"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "21762700.00",
  "finalValue": "21762700.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
  "status": true,
```

```
"remark": "SYSTEMGENERATED",
"date": "Tue Jan 14 2025 09:42:50 GMT+0000 (Coordinated Universal Time)",
"number": "2310042",
"dayCount": "6",
"monthCount": "161",
"generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "11487937.00",
  "selectedBuildUpValue": "922.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "678221a2290edae64f159c7c",
  "name": "externallmg_1736581521692_image.jpeg",
  "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581521692_image.jpeg",
  "orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "678221a2290edae64f159c86",
    "name": "externallmg_1736581525723_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525723_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678221a2290edae64f159c85",
    "name": "externallmg_1736581525672_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525672_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678221a2290edae64f159c84",
    "name": "externallmg_1736581525167_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525167_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678221a3290edae64f159c89",
    "name": "externallmg_1736581526412_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581526412_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678221a3290edae64f159c87",
```

```
    "name": "externallmg_1736581525887_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525887_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678221a3290edae64f159c8c",
    "name": "externallmg_1736581527112_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581527112_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678221a2290edae64f159c82",
    "name": "externallmg_1736581524392_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581524392_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678221a2290edae64f159c7c",
    "name": "externallmg_1736581521692_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581521692_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678221a2290edae64f159c81",
    "name": "externallmg_1736581524157_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581524157_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678221a3290edae64f159c8f",
    "name": "externallmg_1736581528183_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581528183_image.jpeg",
    "orientation": "portrait"
  }
],
```



```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "27245.00",
    "max": "30599.00"
  },
  "builtUpRateRange": {
    "min": "22704.00",
    "max": "25500.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "769.00",
"empanelmentNo": [
  "HO/Credit/87/2022-23"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
```

```
"invoiceIds": [],
"paymentIds": [],
"_id": "6780faaff25068da52482d2f",
"ownerName": "Mr. Rajesh Shambhulal Bhanushali & Mrs. Sangeeta Rajesh
Bhanushali",
"ownerPhoneNo": "9324088004",
"appAddress": "Flat no. 1104, 11th Floor, Mulund Shangri-La, Mulund",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "20/01/2025",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Middleton Developers Ltd.",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Shri. Rajesh Shambhulal Bhanushali & Mrs. Sangeeta Rajesh
Bhanushali",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "4648/1/2009"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName":
"document_1736838698765_Agreement_for_sale_2_Rajesh_Bhanushali.pdf",
    "path": "cases/6780faaff25068da52482d2f/
document_1736838698765_Agreement_for_sale_2_Rajesh_Bhanushali.pdf",
    "id": "404348",
    "uploadedBy": "663da98cfcea71232186f142",
    "createdAt": "Tue Jan 14 2025 07:11:40 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
```

```
"label": "Commencement Certificate"
},
"inputs": {
  "documentDate": "26/05/2008",
  "nameOfApprovingAuthority": {
    "value": "Mumbai_Metropolitan_Region_Development_Authority",
    "label": "Mumbai Metropolitan Region Development Authority"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "MMRDA / SE / SRA CELL / 24 / IOA-86 / PL / T Ward"
},
"isHardCopy": false,
"displayStatus": true,
"fileName":
"document_1736838868173_Commencement_Certificate_Rajesh_Bhanushali.pdf",
"path": "cases/6780faaff25068da52482d2f/
document_1736838868173_Commencement_Certificate_Rajesh_Bhanushali.pdf",
"id": "948835",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Tue Jan 14 2025 07:14:28 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/03/2010",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MMRDA / SRA CELL / OSD / 24 / IOA-86 / PL / T"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "698756",
  "path": "cases/6780faaff25068da52482d2f/document_1736839006083_141488.pdf",
  "fileName": "document_1736839006083_141488.pdf"
```

```
}
],
"caseNumber": "013614",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "747098",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jan 10 2025 10:47:11 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rajesh Shambhulal Bhanushali & Mrs. Sangeeta Rajesh Bhanushali",
    "phone": "9324088004",
    "ownershipShare": "",
    "email": "",
    "id": "401471"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "67821f37290edae64f159bea",
    "area": "965",
    "providedByName": "Rajesh Shambhulal Bhanushali And Sangeeta Rajesh Bhanushali",
    "providedByContactNo": "9324088004"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "8",
```

```
"name": "Living Room",
"length": "17.50",
"length1": "17",
"length2": "6",
"width": "18.50",
"width1": "18",
"width2": "6",
"totalArea": "323.75",
"images": [],
"finalArea": "327.84",
"extraAreas": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "678638bc601c90e696201b1b",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "0.58",
    "length1": "0",
    "length2": "7",
    "width": "3.58",
    "width1": "3",
    "width2": "7",
    "totalArea": "2.09"
  }
]
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Kitchen",
  "length": "10.33",
  "length1": "10",
  "length2": "4",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "97.31",
  "images": [],
  "finalArea": "126.07000000000001",
  "extraAreas": [
```

```
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "_id": "6786396a290edae64f16d6f5",
  "name": "Extra",
  "extraAreaType": "Add",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "28.76"
}
],
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "30.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "11.92",
  "length1": "11",
  "length2": "11",
```



```
"width": "11.92",
"width1": "11",
"width2": "11",
"totalArea": "142.01",
"images": [],
"finalArea": "142.01",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "38.00",
  "images": [],
  "finalArea": "38.00",
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "11.92",
  "width1": "11",
  "width2": "11",
  "totalArea": "147.96",
  "images": [],
  "extraAreas": [],
  "finalArea": "147.96"
},
{
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "40.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "40.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "40.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "40.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    }
  },
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "0",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "78.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "78.12",
  "percentageBeforeTotal": "78.12",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "71.44",
    "totalAreaDocument": "769",
    "docBuiltpupPercentage": "20",
    "docFinalBUILTUp": "922.80",
    "docFinalBUILTUpSquareMeter": "85.73",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "700675"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "768.00",
```

```
"squareMeterArea": "71.35",
"expectedRate": "30598.96",
"percentage": ""
},
"builtUpArea": {
  "area": "921.60",
  "squareMeterArea": "85.62",
  "expectedRate": "25499.13",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "678603ae601c90e6961fe571",
"property": "Flat",
"area": "768",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "23500000",
"expectedRate": "30598.96",
"builtUpExpectedRate": "25499.13",
"image": "cases/6780faaff25068da52482d2f/indicator_1736835716781_Image.png",
"squareMeter": "71.35",
"id": "110608"
},
{
  "carpetArea": {
    "area": "1200.00",
    "squareMeterArea": "111.48",
    "expectedRate": "27916.67",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1440.00",
    "squareMeterArea": "133.78",
    "expectedRate": "23263.89",
    "percentage": "20"
  },
}
```

```
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "678603ae601c90e6961fe572",
"property": "Flat",
"area": "1200",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "_",
"expectedPrice": "33500000",
"expectedRate": "27916.67",
"builtUpExpectedRate": "23263.89",
"image": "cases/6780faaff25068da52482d2f/indicator_1736835745716_Image.png",
"squareMeter": "111.48",
"id": "898471"
},
{
  "carpetArea": {
    "area": "958.00",
    "squareMeterArea": "89.00",
    "expectedRate": "27244.26",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1149.60",
    "squareMeterArea": "106.80",
    "expectedRate": "22703.55",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "678603ae601c90e6961fe573",
  "property": "Flat",
  "area": "958",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "26100000",
"expectedRate": "27244.26",
"builtUpExpectedRate": "22703.55",
"image": "cases/6780faaff25068da52482d2f/indicator_1736835791414_Image.png",
"squareMeter": "89.00",
"id": "258602"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "678221a2290edae64f159c7c",
"name": "externalImg_1736581521692_image.jpeg",
"path": "cases/6780faaff25068da52482d2f/
externalImg_1736581521692_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "678221a2290edae64f159c7d",
"name": "externalImg_1736581523017_image.jpeg",
"path": "cases/6780faaff25068da52482d2f/
externalImg_1736581523017_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "678221a2290edae64f159c7e",
"name": "externalImg_1736581523157_image.jpeg",
"path": "cases/6780faaff25068da52482d2f/
externalImg_1736581523157_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "678221a2290edae64f159c7f",
```

```
    "name": "externallmg_1736581523272_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581523272_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a2290edae64f159c80",
    "name": "externallmg_1736581524108_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581524108_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a2290edae64f159c81",
    "name": "externallmg_1736581524157_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581524157_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a2290edae64f159c82",
    "name": "externallmg_1736581524392_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581524392_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a2290edae64f159c83",
    "name": "externallmg_1736581524406_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581524406_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a2290edae64f159c84",
    "name": "externallmg_1736581525167_image.jpeg",
```

```
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525167_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a2290edae64f159c85",
    "name": "externallmg_1736581525672_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525672_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a2290edae64f159c86",
    "name": "externallmg_1736581525723_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525723_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a3290edae64f159c87",
    "name": "externallmg_1736581525887_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581525887_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a3290edae64f159c88",
    "name": "externallmg_1736581526242_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581526242_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678221a3290edae64f159c89",
    "name": "externallmg_1736581526412_image.jpeg",
    "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581526412_image.jpeg",
```



```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678221a3290edae64f159c8a",
  "name": "externallmg_1736581526647_image.jpeg",
  "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581526647_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678221a3290edae64f159c8b",
  "name": "externallmg_1736581526903_image.jpeg",
  "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581526903_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678221a3290edae64f159c8c",
  "name": "externallmg_1736581527112_image.jpeg",
  "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581527112_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678221a3290edae64f159c8d",
  "name": "externallmg_1736581527488_image.jpeg",
  "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581527488_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678221a3290edae64f159c8e",
  "name": "externallmg_1736581527977_image.jpeg",
  "path": "cases/6780faaff25068da52482d2f/
externallmg_1736581527977_image.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678221a3290edae64f159c8f",
      "name": "externalImg_1736581528183_image.jpeg",
      "path": "cases/6780faaff25068da52482d2f/
externalImg_1736581528183_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "Agreement (2).pdf",
      "filename": "1736835981283_Agreement_2.pdf",
      "path": "cases/6780faaff25068da52482d2f/
processingDocuments/1736835981283_Agreement_2.pdf",
      "size": "18386942",
      "createdAt": "Tue Jan 14 2025 06:26:22 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "OC.jpeg",
      "filename": "1736835981661_OC.jpeg",
      "path": "cases/6780faaff25068da52482d2f/
processingDocuments/1736835981661_OC.jpeg",
      "size": "141488",
      "createdAt": "Tue Jan 14 2025 06:26:22 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "OC1.jpeg",
      "filename": "1736835982870_OC1.jpeg",
      "path": "cases/6780faaff25068da52482d2f/
processingDocuments/1736835982870_OC1.jpeg",
      "size": "131147",
      "createdAt": "Tue Jan 14 2025 06:26:22 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "cosmos - calculation - rajesh.xlsx",
      "filename": "1736836001431_cosmos__calculation__rajesh.xlsx",
      "path": "cases/6780faaff25068da52482d2f/
processingDocuments/1736836001431_cosmos__calculation__rajesh.xlsx",
      "size": "16874",
```

```
"createdAt": "Tue Jan 14 2025 06:26:41 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - rajesh.xlsx",
  "filename": "1736836001432_Summary__rajesh.xlsx",
  "path": "cases/6780faaff25068da52482d2f/
processingDocuments/1736836001432_Summary__rajesh.xlsx",
  "size": "1681400",
  "createdAt": "Tue Jan 14 2025 06:26:41 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6784a1d4601c90e6961f474c",
    "note": "Working done. required OC\n",
    "taskId": "678109365a336ce64e523120",
    "createdAt": "2025-01-13T05:17:08.074Z"
  }
],
"createdAt": "2025-01-10T10:47:11.116Z",
"updatedAt": "2025-01-14T10:22:15.197Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1104, 11th Floor, Mulund Shangri-La , P. K. Road
Extention, Village - Nahur, Municipality Ward No. T, Mulund (West), Taluka - Kurla,
District - Mumbai Suburban , 400 080, State - Maharashtra, India",
"updatedBy": "663da98cfcea71232186f142",
"addressForMap": ""
```

```
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Rajesh Bhanushali",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Self ",
"rerald": "",
"siteVisitContactNo": "9324088004",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet",
"carpetTotal": "891.88",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2025-01-12",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 769.00",
"flatRate": "28300",
"landOtherRate": "25500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"finalBuiltupArea": "1067.00",
"finalCarpetArea": "970.00",
"finalSalableArea": "1173.70",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
```

```

    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Jan 14 2025 07:02:36 GMT+0000 (Coordinated
Universal Time)",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "78.12",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'6"	18'6"	323.75
Kitchen	10'4"	9'5"	97.31
Passage	10'00"	3'00"	30.00
Bedroom	11'11"	11'11"	142.01
Toilet	9'6"	4'0"	38.00
Bedroom	12'5"	11'11"	147.96
Passage	10'00"	4'00"	40.00
Toilet	10'00"	4'00"	40.00
Other Composition :			
Balcony Area	10'5"	7'6"	78.12