

```
{
  "typeOfReport": {
    "value": "Shop",
    "label": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "660cfbdfc8c252224ff06ac1"
    },
    "firstName": "Sandeep ",
    "type": "CREDITOFFICER",
    "_id": "660cfbdfc8c252224ff06ac6",
    "lastName": "Deshettiwar",
    "mobileNo": "",
    "workMobileNo": "7775875419",
    "email": "vjdome@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "660cfbdfc8c252224ff06ac1",
  "name": "E Vijaya Dombivali East Branch",
  "branchCode": "",
  "mobileNo": "02512456336",
  "alternateMobileNo": "",
  "email": "vjdome@bankofbaroda.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Vaishampayan Building Babasahev Joshi Road, Off Phadke Road
Dombivali East - 421201"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82",
  "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.202424140907905",
  "longitude": "73.0864242792018"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-13",
      "remark": "MANUAL_IN_TASK"
    }
  ]
}
],
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"compositionFlatType": {
  "value": "Single_Unit",
  "label": "Single Unit"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nandivali Tarfe Panchanad",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  }
}
```

```
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivali (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Nanu Park",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```

```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nandivali Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Swami Samarth Math, Samarth Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
}
```



```
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "12/2/1 & 12/3/A",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```

```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 201",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Glass_door_with_MS_Rolling_Shutter",
    "label": "Glass door with MS Rolling Shutter"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_with_POP_false_Celling",
    "label": "Cement Plastering with POP false Celling"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
```

```
"label": "No"
},
"asPerActualAgreement": {
  "north": "Nala",
  "west": "Open Plot",
  "south": "Road",
  "east": "Open Plot"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "Height of Shop is 9.56 ft.",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No.KDMC / TPD /
```

BP /27 Village / 2016 - 2017 / 48 / 527 Dated 16.03.2022 issued by Municipal Corporation",

"approvePlanVerified": "Yes",  
"empanelledOfApprovePlan": "No",  
"unauthorizedConstruction": "",  
"extraDetailOfBuilding": "",  
"compoundWall": ""

},

"apfDetails": {  
"buildings": [],  
"compositions": []

},

"compositeRate": {  
"remark": "",  
"depreciationPercentage": "",  
"depreciationRatioOfBuilding": "",  
"salvageValue": "",  
"depreciatedCostOfConstruction": "",  
"depreciatedBuildingRate": ""

},

"igrFinalRate": {  
"floorRatePercentage": "0.00"

},

"outgoingDetail": {  
"areaStatusList": {  
"value": "Medium",  
"label": "Medium"

},

"propertyTypeOfUseList": {  
"value": "Shop",  
"label": "Shop"

},

"propertyOccupiedByList": {  
"value": "-",  
"label": "Others"

},

"monthlyRent": "N.A.",  
"assessmentNo": "Details not available",  
"taxPaidHolderName": "Details not available",  
"taxAmount": "Details not available",  
"electricityServiceConnectionNo": "Details not available",  
"meterCardHolderName": "Details not available",  
"undividedAreaOfLandAsPerSaleDeed": "Details not available",  
"floorSpaceIndex": "As per KDMC norms",  
"tenantName": "",  
"maintenanceOfFlat": "Good"

```
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt / Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2024",
    "fullDate": "1/1/2024"
  },
  "planningArea": {
    "value": "Residential_cum_Commercial",
    "label": "Residential cum Commercial"
  },
  "typeOfStructure": {
```

```
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
},
"walls": {
"value": "1",
"label": "Yes"
},
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
},
"maintenancelssues": {
"value": "Information_not_available",
"label": "Information not available"
}
```

```
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "16",
"flatFloorNo": "Ground",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "231.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6784bc60290edae64f15f0ef/
routeMap_1736919771819_Image.png",
    "routeLat": "19.202459",
    "routeLng": "73.086553",
    "stationName": "Dombivli",
```



```
"routeDistance": "2.1 Km",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "8ou855",
    "name": "8ou855",
    "image": "cases/6784bc60290edae64f15f0ef/
routeMap_1737006522734_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
```

```
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "0.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "0.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "231.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6785f1b0290edae64f167ab7",
      "name":
"externallmg_1736831407852_WhatsApp_Image_20250114_at_103550_AM_2.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407852_WhatsApp_Image_20250114_at_103550_AM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6785f1bc5a336ce64e5303a1",
      "name":
"externallmg_1736831419915_WhatsApp_Image_20250114_at_103552_AM.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419915_WhatsApp_Image_20250114_at_103552_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6785f1bc5a336ce64e53039e",
      "name":
"externallmg_1736831419859_WhatsApp_Image_20250114_at_103551_AM.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419859_WhatsApp_Image_20250114_at_103551_AM.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "6785f1bc5a336ce64e5303a4",
      "name":
"externallmg_1736831419977_WhatsApp_Image_20250114_at_103553_AM.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419977_WhatsApp_Image_20250114_at_103553_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6785f1bc5a336ce64e5303a0",
      "name":
"externallmg_1736831419892_WhatsApp_Image_20250114_at_103552_AM_2.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419892_WhatsApp_Image_20250114_at_103552_AM_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6785f1bc5a336ce64e53039d",
      "name":
"externallmg_1736831419837_WhatsApp_Image_20250114_at_103551_AM_2.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419837_WhatsApp_Image_20250114_at_103551_AM_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6785f1bc5a336ce64e5303a2",
      "name":
"externallmg_1736831419944_WhatsApp_Image_20250114_at_103553_AM_1.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419944_WhatsApp_Image_20250114_at_103553_AM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6785f1b0290edae64f167ab9",
      "name":
"externallmg_1736831407896_WhatsApp_Image_20250114_at_103551_AM_1.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407896_WhatsApp_Image_20250114_at_103551_AM_1.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "status": false,
  "_id": "6785f1b0290edae64f167ab3",
  "name":
"externallmg_1736831407757_WhatsApp_Image_20250114_at_103548_AM.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407757_WhatsApp_Image_20250114_at_103548_AM.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6785f1b0290edae64f167ab6",
  "name":
"externallmg_1736831407831_WhatsApp_Image_20250114_at_103550_AM_1.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407831_WhatsApp_Image_20250114_at_103550_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6785f1b0290edae64f167ab7",
  "name":
"externallmg_1736831407852_WhatsApp_Image_20250114_at_103550_AM_2.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407852_WhatsApp_Image_20250114_at_103550_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6785f1b0290edae64f167ab1",
  "name":
"externallmg_1736831407716_WhatsApp_Image_20250114_at_103548_AM_1.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407716_WhatsApp_Image_20250114_at_103548_AM_1.jpeg",
  "orientation": "landscape"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
}
```

```
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```

```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "210.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6784bc60290edae64f15f0ef",
"ownerName": "Mr. Bhim G. Patil",
"ownerPhoneNo": "9137376177",
"fullAddress": "Commercial Shop No. 001, Ground Floor, Nanu Park, Near Swami
Samarth Math, Samarth Nagar, New/Current Survey No. 12/2/1 & 12/3/A, Nandivali
Road, Village - Nandivali Tarfe Panchanad, Taluka - Kalyan, District - Thane, Dombivali
(East), PIN Code - 421 201, State - Maharashtra, India",
"remark": "Lead not create shop no. 2",
"documents": [
```

```
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "04/12/2018",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "M/s. B. G. Patil & Son",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Shri. Bhim Gatlu Patil",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "13282 / 2018"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1737347971539_Agreement__Shop_001.pdf",
  "path": "cases/6784bc60290edae64f15f0ef/
document_1737347971539_Agreement__Shop_001.pdf",
  "id": "512605",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Mon Jan 20 2025 04:39:32 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "documentDate": "04/12/2018"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1737348272973_Agreement__Shop_002.pdf",
  "path": "cases/6784bc60290edae64f15f0ef/
document_1737348272973_Agreement__Shop_002.pdf",
  "id": "818852",
```

```
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Jan 20 2025 04:44:34 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700014199"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1737348342854_RERA_Certificate.pdf",
"path": "cases/6784bc60290edae64f15f0ef/
document_1737348342854_RERA_Certificate.pdf",
"id": "810846",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Jan 20 2025 04:45:43 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "26/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / TPD / BP / 27 Village / 2016 - 2017 / 48 / 20"
},
```

```
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1737348432805_CC.pdf",
"path": "cases/6784bc60290edae64f15f0ef/document_1737348432805_CC.pdf",
"id": "743015",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Jan 20 2025 04:47:13 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "04/08/2020",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / CC / 27 Village / 11"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1737348628772_OC__2_to_7.pdf",
"path": "cases/6784bc60290edae64f15f0ef/
document_1737348628772_OC__2_to_7.pdf",
"id": "307472",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Jan 20 2025 04:50:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "16/03/2022",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "KDMC / TPD / BP /27 Village / 2016 - 2017 / 48 / 527"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1737348771608_Approved_Plan__Ground_Floor.pdf",
"path": "cases/6784bc60290edae64f15f0ef/
document_1737348771608_Approved_Plan__Ground_Floor.pdf",
"id": "636026",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Jan 20 2025 04:52:52 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "013630",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "721327",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jan 13 2025 07:10:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Bhim G. Patil",
    "phone": "9137376177",
    "ownershipShare": "",
    "email": "",
    "id": "654565"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
],
```

```
"id": "314296",
"name": "Shop",
"length": "197.00",
"length1": "197",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "197.00",
"images": [],
"extraAreas": [],
"finalArea": "197.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Ota",
  "length": "119.00",
  "length1": "119",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "119.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  {
    "id": "300111",
    "selectAreaTypeDocument": "Carpet",
```

```
"totalAreaDocument": "210",
"squareMeterArea": "19.51",
"docFinalBuiltUp": "231",
"docFinalBuiltUpSquareMeter": "21.461000000000002",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6785f1b0290edae64f167aac",
  "name":
"externalImg_1736831407564_WhatsApp_Image_20250114_at_103546_AM_1.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externalImg_1736831407564_WhatsApp_Image_20250114_at_103546_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6785f1b0290edae64f167aad",
  "name":
"externalImg_1736831407605_WhatsApp_Image_20250114_at_103546_AM.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externalImg_1736831407605_WhatsApp_Image_20250114_at_103546_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6785f1b0290edae64f167aae",
  "name":
"externalImg_1736831407621_WhatsApp_Image_20250114_at_103547_AM_1.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externalImg_1736831407621_WhatsApp_Image_20250114_at_103547_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "6785f1b0290edae64f167aaf",
    "name":
"externallmg_1736831407678_WhatsApp_Image_20250114_at_103547_AM_2.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407678_WhatsApp_Image_20250114_at_103547_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1b0290edae64f167ab0",
    "name":
"externallmg_1736831407711_WhatsApp_Image_20250114_at_103547_AM.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407711_WhatsApp_Image_20250114_at_103547_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1b0290edae64f167ab1",
    "name":
"externallmg_1736831407716_WhatsApp_Image_20250114_at_103548_AM_1.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407716_WhatsApp_Image_20250114_at_103548_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1b0290edae64f167ab2",
    "name":
"externallmg_1736831407745_WhatsApp_Image_20250114_at_103548_AM_2.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407745_WhatsApp_Image_20250114_at_103548_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1b0290edae64f167ab3",
    "name":
"externallmg_1736831407757_WhatsApp_Image_20250114_at_103548_AM.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407757_WhatsApp_Image_20250114_at_103548_AM.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6785f1b0290edae64f167ab4",
      "name":
"externallmg_1736831407774_WhatsApp_Image_20250114_at_103549_AM_1.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407774_WhatsApp_Image_20250114_at_103549_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6785f1b0290edae64f167ab5",
      "name":
"externallmg_1736831407803_WhatsApp_Image_20250114_at_103549_AM.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407803_WhatsApp_Image_20250114_at_103549_AM.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6785f1b0290edae64f167ab6",
      "name":
"externallmg_1736831407831_WhatsApp_Image_20250114_at_103550_AM_1.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407831_WhatsApp_Image_20250114_at_103550_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6785f1b0290edae64f167ab7",
      "name":
"externallmg_1736831407852_WhatsApp_Image_20250114_at_103550_AM_2.jpeg",
      "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407852_WhatsApp_Image_20250114_at_103550_AM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6785f1b0290edae64f167ab8",
      "name":
"externallmg_1736831407875_WhatsApp_Image_20250114_at_103550_AM.jpeg",
```

```
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407875_WhatsApp_Image_20250114_at_103550_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1b0290edae64f167ab9",
    "name":
"externallmg_1736831407896_WhatsApp_Image_20250114_at_103551_AM_1.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831407896_WhatsApp_Image_20250114_at_103551_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1bc5a336ce64e53039d",
    "name":
"externallmg_1736831419837_WhatsApp_Image_20250114_at_103551_AM_2.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419837_WhatsApp_Image_20250114_at_103551_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1bc5a336ce64e53039e",
    "name":
"externallmg_1736831419859_WhatsApp_Image_20250114_at_103551_AM.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419859_WhatsApp_Image_20250114_at_103551_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1bc5a336ce64e53039f",
    "name":
"externallmg_1736831419868_WhatsApp_Image_20250114_at_103552_AM_1.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419868_WhatsApp_Image_20250114_at_103552_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6785f1bc5a336ce64e5303a0",
  "name":
"externallmg_1736831419892_WhatsApp_Image_20250114_at_103552_AM_2.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419892_WhatsApp_Image_20250114_at_103552_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6785f1bc5a336ce64e5303a1",
  "name":
"externallmg_1736831419915_WhatsApp_Image_20250114_at_103552_AM.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419915_WhatsApp_Image_20250114_at_103552_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6785f1bc5a336ce64e5303a2",
  "name":
"externallmg_1736831419944_WhatsApp_Image_20250114_at_103553_AM_1.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419944_WhatsApp_Image_20250114_at_103553_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6785f1bc5a336ce64e5303a3",
  "name":
"externallmg_1736831419967_WhatsApp_Image_20250114_at_103553_AM_2.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419967_WhatsApp_Image_20250114_at_103553_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6785f1bc5a336ce64e5303a4",
  "name":
"externallmg_1736831419977_WhatsApp_Image_20250114_at_103553_AM.jpeg",
  "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831419977_WhatsApp_Image_20250114_at_103553_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1bc5a336ce64e5303a5",
    "name":
"externallmg_1736831420012_WhatsApp_Image_20250114_at_103554_AM_1.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831420012_WhatsApp_Image_20250114_at_103554_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6785f1bc5a336ce64e5303a6",
    "name":
"externallmg_1736831420041_WhatsApp_Image_20250114_at_103554_AM.jpeg",
    "path": "cases/6784bc60290edae64f15f0ef/
externallmg_1736831420041_WhatsApp_Image_20250114_at_103554_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67908fc5a2c3df47c926062a",
    "note": "Pending for value confirmation",
    "taskId": "6784bc6c290edae64f15f175",
    "createdAt": "2025-01-22T06:27:17.011Z"
  }
],
```

```
"createdAt": "2025-01-13T07:10:24.822Z",
"updatedAt": "2025-01-22T06:52:13.892Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mrs. Pallavi Sakpal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9820327691",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"briefDescOfProperty": "Shop + Otl",
"carpetTotal": "197.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "347.60",
"finalCarpetArea": "316.00",
"finalSalableArea": "382.36",
"salablePercentage": "10",
"toBeAdded": "",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
```

```

    "value": "Independent_Building"
  },
  "roadFacing": true,
  "mall": false
},
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 197.00\nOvla Area in Sq. Ft. = 119.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 210.00",
"reportGeneratedDate": "Mon Jan 20 2025 04:10:19 GMT+0000 (Coordinated Universal Time)",
"siteVisitDate": "2025-01-13"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Shop	197'00"	1'00"	197.00
Ovla	119'00"	1'00"	119.00
Other Composition :			