

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Abhishek",
    "type": "CREDITOFFICER",
    "_id": "6704f8096d5ad2b2230a3f87",
    "email": "abhishek.jagtap@ssl.co.in",
    "lastName": "Jagtap",
    "mobileNo": "",
    "workMobileNo": "8454824296"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Abhishek",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "663da98cfcea71232186f142",
  "role": "ACCOUNTANT",
  "firstName": "SONAL ",
  "email": "sonal.ambekar19@gmail.com",
  "lastName": " SHIVGAN",
```

```
"mobileNo": "9773395869",
"designation": "",
"shortName": "SO",
"workWithDocumentMaker": "",
"profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.988277",
  "longitude": "73.909495"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.909495,
    18.988277
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-15",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vadghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "4",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raidgad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "89",
  "label": true
},
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Balaji",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "R-3",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pushpak Node",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```



```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "Sector No. R-3",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "401",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410 206",
```

```
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Powder_Coated_Aluminum_Sliding_Windows",
    "label": "Proposed Powder Coated Aluminum Sliding Windows"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
```

```
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
  "value": "Panvel_Municipal_Corporation",
  "label": "Panvel Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Dream Park Building ",
  "west": "Krishna Residency",
  "south": "Road",
  "east": "Residential Building & Open Plot"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 102 and 103",
  "west": "Plot No. 88",
  "south": "9.00 Mtrs. Wide Road",
  "east": "Plot No. 90"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building under construction",
    "east": "Building under construction",
    "south": "Building under construction",
    "west": "Building under construction"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  }
},
```

```
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved building plan no. CIDCO/BP-18760/TPO(NM
& K)/2023/11803 Dated 12.01.2024 issued by CIDCO",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "49400",
  "landRate": "4390",
  "igrImage": "cases/67865522290edae64f170d3f/igr_1736930264118_Image.png",
  "squareMeterGuideLineRate": "49400.00",
  "squareFeetGuideLineRate": "4589.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "49400.00",
  "squareMeterGuideLineRate": "49400.00",
  "squareFeetGuideLineRate": "4589.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
```

```
"label": "Medium"
},
"propertyTypeOfUseList": {
  "value": "Proposed_Residential_Purpose",
  "label": "Proposed Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"monthlyRent": "N.A",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "Information not available",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  }
},
```

```
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Proposed_Plain_Looking",
  "label": "Proposed Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_RCC_Slab",
  "label": "Proposed RCC Slab"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
}
```

```
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
```



```
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "458.70",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67865522290edae64f170d3f/
routeMap_1737027504152_Image.png",
    "routeLat": "18.986659",
    "routeLng": "73.092615",
    "stationName": "Panvel",
    "routeDistance": "4.2 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "2dodd",
      "name": "2dodd",
      "image": "cases/67865522290edae64f170d3f/
routeMap_1737027392647_Image.png"
    }
  ]
},
```

```
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4170000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "4170000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "6",
    "percentage": "34.285714285714285",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "4",
    "percentage": "4.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "4",
    "percentage": "4.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "52.29",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2104974.00",
  "selectedBuildUpValue": "458.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67887dc75a336ce64e54385c",
      "name": "externalimg_1736998343338_IMG20250116WA0008.jpg",
      "path": "cases/67865522290edae64f170d3f/
externalimg_1736998343338_IMG20250116WA0008.jpg",
      "orientation": "portrait"
    }
  ]
},
],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8e5",
    "name": "externallmg_1736998358788_IMG20250116WA0015.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358788_IMG20250116WA0015.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8e8",
    "name": "externallmg_1736998358837_IMG20250116WA0018.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358837_IMG20250116WA0018.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8e9",
    "name": "externallmg_1736998358838_IMG20250116WA0019.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358838_IMG20250116WA0019.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8ea",
    "name": "externallmg_1736998358842_IMG20250116WA0020.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358842_IMG20250116WA0020.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8f1",
    "name": "externallmg_1736998358919_IMG20250116WA0027.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358919_IMG20250116WA0027.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8e4",
    "name": "externallmg_1736998358778_IMG20250116WA0014.jpg",
```

```
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358778_IMG20250116WA0014.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8ee",
    "name": "externallmg_1736998358886_IMG20250116WA0024.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358886_IMG20250116WA0024.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67887dd7290edae64f17f8e2",
    "name": "externallmg_1736998358771_IMG20250116WA0012.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358771_IMG20250116WA0012.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9980.00",
    "max": "11451.00"
  },
  "builtUpRateRange": {
    "min": "9073.00",
    "max": "10410.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "417.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67865522290edae64f170d3f",
"ownerName": "Mr. Aniruddha Deepak Pawar, Ms. Archana Deepak Pawar & Mrs.
Anita Deepak Pawar",
"ownerPhoneNo": "8879693942",
"appAddress": "Flat no. 401, 4th Floor, Sai Balaji, Plot no. 89, Sector no. R3, Pushpak
Node, Vadghar, Navi Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "07/01/2025",
      "amount": "Rs. 33,18,120.00",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Shree Ganesh Enterprises (Promoter)",
      "to": {
        "value": "Purchaser",
```

```
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Aniruddha Deepak Pawar, Ms. Archana Deepak Pawar & Mrs. Anita Deepak Pawar",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "411/2025"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1737024794172_Agreement_for_sale.pdf",
"path": "cases/67865522290edae64f170d3f/document_1737024794172_Agreement_for_sale.pdf",
"id": "647944",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Thu Jan 16 2025 10:53:15 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "12/01/2024",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO/BP-18760/TPO(NM & K)/2023/11803"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1737024888713_Commencement_Certificate.pdf",
  "path": "cases/67865522290edae64f170d3f/document_1737024888713_Commencement_Certificate.pdf",
  "id": "357690",
  "uploadedBy": "663da98cfcea71232186f142",
  "createdAt": "Thu Jan 16 2025 10:54:49 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
}
```

```
"inputs": {
  "documentDate": "22/01/2025",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P52000055807"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1737024998668_RERA_Certificate.pdf",
"path": "cases/67865522290edae64f170d3f/
document_1737024998668_RERA_Certificate.pdf",
"id": "314202",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Thu Jan 16 2025 10:56:38 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "12/01/2024",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO/BP-18760/TPO(NM & K)/2023/11803 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1737026646428_Building_Plan.pdf",
  "path": "cases/67865522290edae64f170d3f/
document_1737026646428_Building_Plan.pdf",
  "id": "180543",
  "uploadedBy": "663da98cfcea71232186f142",
  "createdAt": "Thu Jan 16 2025 11:24:06 GMT+0000 (Coordinated Universal Time)"
}
```

```
}
],
"caseNumber": "013659",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "437780",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jan 14 2025 12:14:26 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Aniruddha Deepak Pawar, Ms. Archana Deepak Pawar & Mrs. Anita Deepak Pawar",
    "phone": "8879693942",
    "ownershipShare": "",
    "email": "",
    "id": "502086"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "120019",
    "name": "Kitchen",
    "length": "7.58",
    "length1": "7",
    "length2": "7",
    "width": "6.42",
    "width1": "6",
    "width2": "5",
    "totalArea": "48.66",
    "images": [],
    "extraAreas": [],
    "finalArea": "48.66"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "7.50",
  "length1": "7",
  "length2": "6",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "28.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.12"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
```

```
"totalArea": "20.00",
"images": [],
"extraAreas": [],
"finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Living Room",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "13.17",
  "width1": "13",
  "width2": "2",
  "totalArea": "118.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "118.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "81.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
```

```
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "6.17",
  "width1": "6",
  "width2": "2",
  "totalArea": "18.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.5",
  "percentageBeforeTotal": "18.50",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "29.25",
  "images": [],
```



```
"extraAreas": [],
"finalArea": "29.25",
"percentageBeforeTotal": "29.25",
"percentage": "100"
},
],
"externalReport": [],
"documentPerArea": [
{
"typeofDocument": {
"label": " Agreement",
"value": "652d16a0316e1359cebd3c15"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"selectAreaTypeDocument": "Carpet",
"squareMeterArea": "38.74",
"totalAreaDocument": "417",
"docBuiltpPercentage": "10",
"docFinalBUILTUp": "458.70",
"docFinalBUILTUpSquareMeter": "42.61",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "776591"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "500.00",
"squareMeterArea": "46.45",
"expectedRate": "9980.00",
"percentage": ""
},
"builtUpArea": {
"area": "550.00",
"squareMeterArea": "51.10",
"expectedRate": "9072.73",
"percentage": "10"
},
"saleableArea": {
"area": "",
```

```
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6787746b601c90e69620a589",
"property": "Flat",
"area": "500",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "4990000",
"expectedRate": "9980.00",
"builtUpExpectedRate": "9072.73",
"image": "cases/67865522290edae64f170d3f/
indicator_1736929519031_Image.png",
"squareMeter": "46.45",
"id": "312578"
},
{
"carpetArea": {
"area": "405.00",
"squareMeterArea": "37.63",
"expectedRate": "10370.37",
"percentage": ""
},
"builtUpArea": {
"area": "445.50",
"squareMeterArea": "41.39",
"expectedRate": "9427.61",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6787746b601c90e69620a58a",
"property": "Flat",
"area": "405",
"builtUpPercentage": "10",
```

```
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "4200000",
"expectedRate": "10370.37",
"builtUpExpectedRate": "9427.61",
"image": "cases/67865522290edae64f170d3f/
indicator_1736929877884_Image.png",
"squareMeter": "37.63",
"id": "451597"
},
{
  "carpetArea": {
    "area": "430.00",
    "squareMeterArea": "39.95",
    "expectedRate": "10697.67",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "473.00",
    "squareMeterArea": "43.94",
    "expectedRate": "9725.16",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6787746b601c90e69620a58b",
  "property": "Flat",
  "area": "430",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "4600000",
  "expectedRate": "10697.67",
  "builtUpExpectedRate": "9725.16",
  "image": "cases/67865522290edae64f170d3f/
indicator_1736929754075_Image.png",
```

```
"squareMeter": "39.95",
"id": "210430"
},
{
  "carpetArea": {
    "area": "262.00",
    "squareMeterArea": "24.34",
    "expectedRate": "11450.38",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "288.20",
    "squareMeterArea": "26.77",
    "expectedRate": "10409.44",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6787746b601c90e69620a58c",
  "property": "Flat",
  "area": "262",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3000000",
  "expectedRate": "11450.38",
  "builtUpExpectedRate": "10409.44",
  "image": "cases/67865522290edae64f170d3f/
indicator_1736930002150_Image.png",
  "squareMeter": "24.34",
  "id": "109899"
},
{
  "carpetArea": {
    "area": "333.00",
    "squareMeterArea": "30.94",
    "expectedRate": "10000.00",
    "percentage": ""
  },
```

```
},
"builtUpArea": {
  "area": "366.30",
  "squareMeterArea": "34.03",
  "expectedRate": "9090.91",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "6787746b601c90e69620a58d",
"property": "Flat",
"area": "333",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "3330000",
"expectedRate": "10000.00",
"builtUpExpectedRate": "9090.91",
"image": "cases/67865522290edae64f170d3f/
indicator_1736930191183_Image.png",
"squareMeter": "30.94",
"id": "992005"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e543857",
    "name": "externalImg_1736998343246_IMG20250116WA0002.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998343246_IMG20250116WA0002.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e543858",
```

```
    "name": "externalImg_1736998343252_IMG20250116WA0004.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998343252_IMG20250116WA0004.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e543859",
    "name": "externalImg_1736998343257_IMG20250116WA0005.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998343257_IMG20250116WA0005.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e54385a",
    "name": "externalImg_1736998343298_IMG20250116WA0006.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998343298_IMG20250116WA0006.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e54385b",
    "name": "externalImg_1736998343334_IMG20250116WA0007.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998343334_IMG20250116WA0007.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e54385c",
    "name": "externalImg_1736998343338_IMG20250116WA0008.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998343338_IMG20250116WA0008.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e54385d",
    "name": "externalImg_1736998343366_IMG20250116WA0009.jpg",
```

```
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998343366_IMG20250116WA0009.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e54385e",
    "name": "externallmg_1736998343368_IMG20250116WA0010.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998343368_IMG20250116WA0010.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dc75a336ce64e54385f",
    "name": "externallmg_1736998343385_IMG20250116WA0011.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998343385_IMG20250116WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8e2",
    "name": "externallmg_1736998358771_IMG20250116WA0012.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358771_IMG20250116WA0012.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8e3",
    "name": "externallmg_1736998358775_IMG20250116WA0013.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358775_IMG20250116WA0013.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8e4",
    "name": "externallmg_1736998358778_IMG20250116WA0014.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358778_IMG20250116WA0014.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8e5",
  "name": "externallmg_1736998358788_IMG20250116WA0015.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358788_IMG20250116WA0015.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8e6",
  "name": "externallmg_1736998358823_IMG20250116WA0016.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358823_IMG20250116WA0016.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8e7",
  "name": "externallmg_1736998358825_IMG20250116WA0017.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358825_IMG20250116WA0017.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8e8",
  "name": "externallmg_1736998358837_IMG20250116WA0018.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358837_IMG20250116WA0018.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8e9",
  "name": "externallmg_1736998358838_IMG20250116WA0019.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358838_IMG20250116WA0019.jpg",
  "orientation": "portrait"
}
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8ea",
    "name": "externallmg_1736998358842_IMG20250116WA0020.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358842_IMG20250116WA0020.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8eb",
    "name": "externallmg_1736998358868_IMG20250116WA0021.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358868_IMG20250116WA0021.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8ec",
    "name": "externallmg_1736998358870_IMG20250116WA0022.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358870_IMG20250116WA0022.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8ed",
    "name": "externallmg_1736998358884_IMG20250116WA0023.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358884_IMG20250116WA0023.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8ee",
    "name": "externallmg_1736998358886_IMG20250116WA0024.jpg",
    "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358886_IMG20250116WA0024.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8ef",
  "name": "externallmg_1736998358900_IMG20250116WA0025.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358900_IMG20250116WA0025.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8f0",
  "name": "externallmg_1736998358903_IMG20250116WA0026.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358903_IMG20250116WA0026.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8f1",
  "name": "externallmg_1736998358919_IMG20250116WA0027.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358919_IMG20250116WA0027.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8f2",
  "name": "externallmg_1736998358924_IMG20250116WA0028.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358924_IMG20250116WA0028.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67887dd7290edae64f17f8f3",
  "name": "externallmg_1736998358951_IMG20250116WA0029.jpg",
  "path": "cases/67865522290edae64f170d3f/
externallmg_1736998358951_IMG20250116WA0029.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8f4",
    "name": "externalImg_1736998358954_IMG20250116WA0030.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998358954_IMG20250116WA0030.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67887dd7290edae64f17f8f5",
    "name": "externalImg_1736998358968_IMG20250116WA0031.jpg",
    "path": "cases/67865522290edae64f170d3f/
externalImg_1736998358968_IMG20250116WA0031.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "CC.pdf",
    "filename": "1736930296948_CC.pdf",
    "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930296948_CC.pdf",
    "size": "138050",
    "createdAt": "Wed Jan 15 2025 08:38:17 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  },
  {
    "originalname": "Plan.pdf",
    "filename": "1736930296956_Plan.pdf",
    "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930296956_Plan.pdf",
    "size": "1947662",
    "createdAt": "Wed Jan 15 2025 08:38:17 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  },
  {
    "originalname": "RERA.pdf",
    "filename": "1736930297001_RERA.pdf",
    "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930297001_RERA.pdf",
    "size": "704491",
    "createdAt": "Wed Jan 15 2025 08:38:17 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  }
]
```

```
},
{
  "originalname": "203(1).pdf",
  "filename": "1736930306662_2031.pdf",
  "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930306662_2031.pdf",
  "size": "147263",
  "createdAt": "Wed Jan 15 2025 08:38:26 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
  "originalname": "203.pdf",
  "filename": "1736930306666_203.pdf",
  "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930306666_203.pdf",
  "size": "144093",
  "createdAt": "Wed Jan 15 2025 08:38:26 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
  "originalname": "407.pdf",
  "filename": "1736930306670_407.pdf",
  "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930306670_407.pdf",
  "size": "145225",
  "createdAt": "Wed Jan 15 2025 08:38:26 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
  "originalname": "502.pdf",
  "filename": "1736930306698_502.pdf",
  "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930306698_502.pdf",
  "size": "148039",
  "createdAt": "Wed Jan 15 2025 08:38:26 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9147bf3dd69653a591e8c"
},
{
  "originalname": "Ref_Report_Archana_Krishna_Mane.pdf",
  "filename": "1736930373544_Ref_Report_Archana_Krishna_Mane.pdf",
  "path": "cases/67865522290edae64f170d3f/
processingDocuments/1736930373544_Ref_Report_Archana_Krishna_Mane.pdf",
  "size": "2193332",
  "createdAt": "Wed Jan 15 2025 08:39:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9147bf3dd69653a591e8c"
}
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-14T12:14:26.151Z",
"updatedAt": "2025-01-17T05:00:43.534Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 401, 4th Floor, Sai Balaji, Plot No. 89, Sector R-3,
Pushpak Node, Village - Vadghar, Navi Mumbai, Taluka - Panvel, District - Raidgad,
410 206, State - Maharashtra, India",
"updatedBy": "60f9147bf3dd69653a591e8c",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Santosh Mhatre",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Builder's Person",
"rerald": "",
"siteVisitContactNo": "7738723357",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 417.00",
"flatRate": "10000",
"landOtherRate": "7500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Toilet +
Bathroom",
```

```

"carpetTotal": "296.28",
"otherCarpetTotal": "47.75",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "18.50",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "359.46",
"finalCarpetArea": "326.78",
"finalSalableArea": "395.40",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Jan 16 2025 10:11:23 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-01-15"
}

```

Name	Length	Width	Total
Composition :			
Kitchen	7'7"	6'5"	48.66
Passage	7'6"	3'9"	28.12
Toilet	3'00"	4'00"	12.00
Bathroom	5'00"	4'00"	20.00

Living Room	9'00"	13'2"	118.50
Bedroom	9'00"	9'00"	81.00
Other Composition :			
Flowerbed	3'00"	6'2"	18.50
Flowerbed	3'3"	9'00"	29.25