

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Atul",
    "type": "CREDITOFFICER",
    "_id": "67342e940b8f93c1cf1c3a20",
    "email": "atul.landge123@gmail.com",
    "lastName": "Landge",
    "mobileNo": "",
    "workMobileNo": "9768604755"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Atul",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.149287974393733",
  "longitude": "72.92807819804804"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.92807819804804,
19.149287974393733
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-17",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kanjur, Bhandup (West)",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "28",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shraddha Classic",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "T.P. Road ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "49, 49/1 to 8, 73, 73/1 to 4, 74, 74/1 to 7 & 80 (Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2804",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "PIN - 400 078",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
```

```
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Slum_Rehabilitation_Authority",
"label": "Slum Rehabilitation Authority"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Slum Area",
"west": "Panchmukhi SRA Building",
"south": "Wing - A ",
"east": "Internal Road & Solitaire Apartment 5"
},
"asPerDocumentAgreement": {
"north": "Details not available ",
"west": "Details not available ",
"south": "Details not available ",
"east": "Details not available "
},
"unitBoundaries": {
"asPerActual": {
"north": "Building is Under Construction ",
"east": "Building is Under Construction ",
"south": "Building is Under Construction ",
"west": "Building is Under Construction "
},
"asPerDocument": {
"north": "Flat No. 2805",
"east": "Staircase ",
"south": "Flat No. 2803",
"west": "Marginal Space "
},
"setDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
"buses": {
"title": "Buses"
}
```

```
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "As per Approved Plan, the composition of Residential Flat will be 1 Bedroom + Living Room + Kitchen + 2 Toilets. (i.e. 1BHK)",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan Document No.S / PVT & STGOVT / 0005 / 20131021 / AP Dated 10.01.2024 issued by Slum Rehabilitation Authority (SRA).\n",
  "approvePlanVerified": "N.A., as the building is under construction",
  "empanelledOfApprovePlan": "No",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "19500.00",
  "depreciatedBuildingRate": "3000"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "125950",
  "landRate": "60030",
  "igrImage": "cases/67877a16290edae64f17870b/igr_1737095166929_Image.png",
  "squareMeterGuideLineRate": "144843.00",
  "squareFeetGuideLineRate": "13456.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "0",
```

```
"rate": "125950.00",
"squareMeterGuideLineRate": "144843.00",
"squareFeetGuideLineRate": "13456.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "17,000/- (Expected rental income per month after completion\nof
construction works)",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per SRA norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is Under Construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
}
```

```
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Open / Covered Car Parking Space ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
}
```

```
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
```



```
    "value": "As_per_RERA_Certificate",
    "label": "As per RERA Certificate"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "0",
  "ageOfBuilding": "0",
  "noOfBasement": "1",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "39",
  "flatFloorNo": "28",
  "noOfLifts": "3",
  "noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
  "area": "396.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67877a16290edae64f17870b/
routeMap_1737116672581_Image.png",
    "routeLat": "19.149278",
    "routeLng": "72.928500",
    "stationName": "Bhandup",
    "routeDistance": "1.8 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
```

```
{
  "id": "jqhnei",
  "name": "jqhnei",
  "image": "cases/67877a16290edae64f17870b/
routeMap_1737173347103_Image.png"
}
],
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "7020000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
```

```
"finalValue": "7020000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "42",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "30",
    "percentage": "5.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "30",
    "percentage": "5.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "30",
"percentage": "2.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "30",
"percentage": "2.50",
"isHideFloor": false,
"status": true
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "65.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5328576.00",
  "selectedBuildUpValue": "396.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "678a27f7290edae64f1947b4",
    "name": "externallmg_1737107444532_1737107435833_image_2.jpeg",
    "path": "cases/67877a16290edae64f17870b/
externallmg_1737107444532_1737107435833_image_2.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "678a27f7290edae64f1947b2",
    "name": "externallmg_1737107437516_1737107435833_image_0.jpeg",
    "path": "cases/67877a16290edae64f17870b/
externallmg_1737107437516_1737107435833_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a27f7290edae64f1947b4",
    "name": "externallmg_1737107444532_1737107435833_image_2.jpeg",
    "path": "cases/67877a16290edae64f17870b/
externallmg_1737107444532_1737107435833_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a27af5a336ce64e553b5a",
    "name": "externallmg_1737107371919_1737107364978_image_1.jpeg",
    "path": "cases/67877a16290edae64f17870b/
externallmg_1737107371919_1737107364978_image_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16311.00",
    "max": "19720.00"
  },
  "builtUpRateRange": {
    "min": "14828.00",
```

```
"max": "17927.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "360.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67877a16290edae64f17870b",
"ownerName": "Akash Sanjay Shinde & Tejal Sanjay Shinde ",
"ownerPhoneNo": "7738291700",
"appAddress": "Flat no. 2804, 28th Floor, Wing - B, Shraddha Classic, Village - Kanjur",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",

```

```
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "14/12/2023",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Shraddha Landmark Pvt. Ltd. ",
  "to": {
    "value": "Allottee",
    "label": "Allottee"
  },
  "Allottee": "Akash Sanjay Shinde & Tejal Sanjay Shinde ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "24832 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "520303",
"path": "cases/67877a16290edae64f17870b/
document_1736932130716_1736932110009_Racpc_Ghatkopar_Akash_Shinde.pdf",
"fileName":
"document_1736932130716_1736932110009_Racpc_Ghatkopar_Akash_Shinde.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "10/01/2024",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "S / PVT & STGOVT / 0005 / 20131021 / AP"
  },
  "isHardCopy": false,
```

```
"displayStatus": false,
"fileName": "document_1737115826489_Plan.pdf",
"path": "cases/67877a16290edae64f17870b/document_1737115826489_Plan.pdf",
"id": "894739",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Jan 17 2025 12:10:28 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "01/03/2024",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "S / PVT & STGOVT / 0005 / 20131021 / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1737115882802_135502.pdf",
  "path": "cases/67877a16290edae64f17870b/
document_1737115882802_135502.pdf",
  "id": "841979",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Fri Jan 17 2025 12:11:22 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",

```

```
    "label": "No"
  },
  "No": "P51800028400"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1737115922148_RERA.pdf",
"path": "cases/67877a16290edae64f17870b/
document_1737115922148_RERA.pdf",
"id": "821784",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Jan 17 2025 12:12:02 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "013676",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "733586",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jan 15 2025 09:04:22 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Akash Sanjay Shinde & Tejal Sanjay Shinde ",
    "phone": "7738291700",
    "ownershipShare": "",
    "email": "",
    "id": "707879"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "347257",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "360",
  "squareMeterArea": "33.45",
  "docFinalBuiltUp": "396",
  "docFinalBuiltUpSquareMeter": "36.795",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "371.00",
      "squareMeterArea": "34.47",
      "expectedRate": "19557.95",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "408.10",
      "squareMeterArea": "37.91",
      "expectedRate": "17779.96",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "6789f812290edae64f19112d",
    "property": "Shraddha Classic, Bhandup West",
    "area": "371",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "Housing.Com",
    "expectedPrice": "7256000",
```

```
"expectedRate": "19557.95",
"builtUpExpectedRate": "17779.96",
"image": "cases/67877a16290edae64f17870b/
indicator_1737094683063_Image.png",
"squareMeter": "34.47",
"id": "297187"
},
{
"carpetArea": {
"area": "371.00",
"squareMeterArea": "34.47",
"expectedRate": "19719.68",
"percentage": ""
},
"builtUpArea": {
"area": "408.10",
"squareMeterArea": "37.91",
"expectedRate": "17926.98",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6789f812290edae64f19112e",
"property": "Shraddha Classic, Bhandup West",
"area": "371",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "square_yards",
"expectedPrice": "7316000",
"expectedRate": "19719.68",
"builtUpExpectedRate": "17926.98",
"image": "cases/67877a16290edae64f17870b/
indicator_1737094811507_Image.png",
"squareMeter": "34.47",
"id": "939392"
},
{
"carpetArea": {
```

```
"area": "360.00",
"squareMeterArea": "33.45",
"expectedRate": "19305.56",
"percentage": ""
},
"builtUpArea": {
"area": "396.00",
"squareMeterArea": "36.79",
"expectedRate": "17550.51",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6789f812290edae64f19112f",
"property": "Shraddha Classic, Bhandup West",
"area": "360",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Housing.Com",
"expectedPrice": "6950000",
"expectedRate": "19305.56",
"builtUpExpectedRate": "17550.51",
"image": "cases/67877a16290edae64f17870b/
indicator_1737094936617_Image.png",
"squareMeter": "33.45",
"id": "796803"
},
{
"carpetArea": {
"area": "360.00",
"squareMeterArea": "33.45",
"expectedRate": "16500.00",
"percentage": ""
},
"builtUpArea": {
"area": "396.00",
"squareMeterArea": "36.79",
"expectedRate": "15000.00",
```

```
"percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "6789f812290edae64f191130",
"property": "Shraddha Classic, Bhandup West",
"area": "360",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "21",
"source": "Index_no.2",
"expectedPrice": "5940000",
"expectedRate": "16500.00",
"builtUpExpectedRate": "15000.00",
"image": "cases/67877a16290edae64f17870b/
indicator_1737095015120_Image.png",
"squareMeter": "33.45",
"id": "846488"
},
{
  "carpetArea": {
    "area": "361.00",
    "squareMeterArea": "33.54",
    "expectedRate": "16310.25",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "397.10",
    "squareMeterArea": "36.89",
    "expectedRate": "14827.50",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
```



```
  "_id": "6789f812290edae64f191131",
  "property": "Shraddha Classic, Bhandup West",
  "area": "361",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "33",
  "source": "Index_no.2",
  "expectedPrice": "5888000",
  "expectedRate": "16310.25",
  "builtUpExpectedRate": "14827.50",
  "image": "cases/67877a16290edae64f17870b/
indicator_1737095062790_Image.png",
  "squareMeter": "33.54",
  "id": "938230"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a27f7290edae64f1947b2",
  "name": "externallmg_1737107437516_1737107435833_image_0.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107437516_1737107435833_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a27f7290edae64f1947b3",
  "name": "externallmg_1737107442123_1737107435833_image_1.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107442123_1737107435833_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a27f7290edae64f1947b4",
  "name": "externallmg_1737107444532_1737107435833_image_2.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107444532_1737107435833_image_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a27f7290edae64f1947b5",
  "name": "externallmg_1737107445298_1737107435833_image_3.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107445298_1737107435833_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a27f7290edae64f1947b6",
  "name": "externallmg_1737107446257_1737107435833_image_4.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107446257_1737107435833_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a27af5a336ce64e553b59",
  "name": "externallmg_1737107371746_1737107364978_image_0.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107371746_1737107364978_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a27af5a336ce64e553b5a",
  "name": "externallmg_1737107371919_1737107364978_image_1.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107371919_1737107364978_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a27af5a336ce64e553b5b",
  "name": "externallmg_1737107372244_1737107364978_image_2.jpeg",
  "path": "cases/67877a16290edae64f17870b/
externallmg_1737107372244_1737107364978_image_2.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a27af5a336ce64e553b5c",
    "name": "externallmg_1737107372689_1737107364978_image_3.jpeg",
    "path": "cases/67877a16290edae64f17870b/
externallmg_1737107372689_1737107364978_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a27af5a336ce64e553b5d",
    "name": "externallmg_1737107374619_1737107364978_image_4.jpeg",
    "path": "cases/67877a16290edae64f17870b/
externallmg_1737107374619_1737107364978_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a27af5a336ce64e553b5e",
    "name": "externallmg_1737107374786_1737107364978_image_5.jpeg",
    "path": "cases/67877a16290edae64f17870b/
externallmg_1737107374786_1737107364978_image_5.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1714717498514_16500.pdf",
    "filename": "1737113706406_1714717498514_16500.pdf",
    "path": "cases/67877a16290edae64f17870b/
processingDocuments/1737113706406_1714717498514_16500.pdf",
    "size": "156911",
    "createdAt": "Fri Jan 17 2025 11:35:06 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1714717498534_1710418983890_Calculation.xlsx",
    "filename": "1737113706422_1714717498534_1710418983890_Calculation.xlsx",
    "path": "cases/67877a16290edae64f17870b/processingDocuments/1737113706422_1714717498534_1710418983890_Calculation.xlsx",
    "size": "1866102",
    "createdAt": "Fri Jan 17 2025 11:35:06 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
]
```

```
    },
    {
      "originalname": "1714717498499_16300.pdf",
      "filename": "1737113706580_1714717498499_16300.pdf",
      "path": "cases/67877a16290edae64f17870b/
processingDocuments/1737113706580_1714717498499_16300.pdf",
      "size": "155337",
      "createdAt": "Fri Jan 17 2025 11:35:06 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    },
    {
      "originalname": "SBI - Jayesh Jaykumar Walawalkar.pdf",
      "filename": "1737113803973_SBI__Jayesh_Jaykumar_Walawalkar.pdf",
      "path": "cases/67877a16290edae64f17870b/
processingDocuments/1737113803973_SBI__Jayesh_Jaykumar_Walawalkar.pdf",
      "size": "8562550",
      "createdAt": "Fri Jan 17 2025 11:36:46 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    },
    {
      "originalname": "Amended CC.jpeg",
      "filename": "1737116717402_Amended_CC.jpeg",
      "path": "cases/67877a16290edae64f17870b/
processingDocuments/1737116717402_Amended_CC.jpeg",
      "size": "135502",
      "createdAt": "Fri Jan 17 2025 12:25:18 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "62fe044a48a26047e6552796"
    },
    {
      "originalname": "PLan.pdf",
      "filename": "1737116717408_PLan.pdf",
      "path": "cases/67877a16290edae64f17870b/
processingDocuments/1737116717408_PLan.pdf",
      "size": "13116995",
      "createdAt": "Fri Jan 17 2025 12:25:18 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "62fe044a48a26047e6552796"
    },
    {
      "originalname": "RERA.pdf",
      "filename": "1737116717647_RERA.pdf",
      "path": "cases/67877a16290edae64f17870b/
processingDocuments/1737116717647_RERA.pdf",
      "size": "151176",
      "createdAt": "Fri Jan 17 2025 12:25:18 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "62fe044a48a26047e6552796"
    }
  }
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6789f821601c90e69621df9a",
    "note": "Rate verification done, pending for visit",
    "taskId": "678794f05a336ce64e540874",
    "createdAt": "2025-01-17T06:26:41.994Z"
  }
],
"createdAt": "2025-01-15T09:04:22.830Z",
"updatedAt": "2025-01-18T04:09:08.776Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f915d3f3dd69653a592199",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2804, 28th Floor, Wing - B, Shraddha Classic, T.P.
Road , Village - Kanjur, Bhandup (West), Municipality Ward No. S, Taluka - Kurla,
District - Mumbai Suburban , PIN - 400 078, State - Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Miss. Maya Mule",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person ",
"rerald": "",
"siteVisitContactNo": "7045794445",
```

```
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 360.00",
"flatRate": "19500",
"landOtherRate": "16500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			