

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "650045afa8e9b70221e079ee"
    },
    "firstName": "Gaurishankar",
    "type": "CREDITOFFICER",
    "_id": "650045afa8e9b70221e079f0",
    "lastName": "Sir",
    "mobileNo": "7709049947",
    "workMobileNo": "7709049947",
    "email": "sbi.10376@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "650045afa8e9b70221e079ee",
  "name": "MERI Branch",
  "branchCode": "10376",
  "mobileNo": "2530294",
  "alternateMobileNo": "",
  "email": "sbi.10376@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Maharashtra Eng. Research Institute Branch\nDindori Road, MERI,
Nashik, Maharashtra,\nNashik - 422004, State - Maharashtra, Country - India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
```

```
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordination",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.042556",
  "longitude": "73.807386"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "15/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-15",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Mhasrul",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
```

```
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "42",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Neelam Srushti",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "off Vani - Dindori Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Nayara Petrol Pump, Near Hotel City Spice, Vaiduwadi",
  "label": false
},
"wing": {
  "status": false,
```



```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "229/ 234/ 1A/ 302/ 2/ 4/ 5 ",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "404",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 422 004",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "By Plot No. 41 & 43",
    "west": "By Colony Road",
    "south": "By 15.00 Mtr. Wide Road",
    "east": "By Colony Road"
  },
  "asPerDocumentAgreement": {
    "north": "By Plot No. 41 & 43",
    "west": "By Colony Road",
    "south": "By 15.00 Mtr. Wide Road",
    "east": "By Colony Road"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "By Duct & Flat No. 405",
      "east": "By Passage & Flat No. 403",
      "south": "By Front Margin",
      "west": "By Side Margin"
    },
    "asPerDocument": {
      "north": "By Duct & Flat No. 405",
      "east": "By Passage & Flat No. 403",
      "south": "By Front Margin",
      "west": "By Side Margin"
    }
  }
}
```

```
    },
    "isDisplay": true,
    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan Digitally Signed by Prashant Dagaji Pagar Accompanying Commencement Certificate Permit No. NMCB/RB/2024/APL/00691 date 10.06.2024 Executive Engineer Town Planning Nashik Municipal Corporation, Nashik",
  "approvePlanVerified": "Yes",
  "empanelledOfApprovePlan": "No",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "35000",
  "landRate": "13500",
  "igrImage": "cases/67877b9a290edae64f178a35/igr_1736932664734_Image.png",
```

```
"squareMeterGuideLineRate": "35000.00",
"squareFeetGuideLineRate": "3252.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "35000.00",
  "squareMeterGuideLineRate": "35000.00",
  "squareFeetGuideLineRate": "3252.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Buidling is under construction",
  "taxPaidHolderName": "Buidling is under construction",
  "taxAmount": "Buidling is under construction",
  "electricityServiceConnectionNo": "Buidling is under construction",
  "meterCardHolderName": "Buidling is under construction",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As Per NMC NOrms",
  "tenantName": "",
  "maintenanceOfFlat": "Buidling is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Aeveloped Area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  }
}
```

```
},
"partitions": {
  "value": "Proposed_6"_Thk._Brick_Masonry",
  "label": "Proposed 6" Thk. Brick Masonery"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
}
```



```
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "762.30",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67877b9a290edae64f178a35/
routeMap_1736934506303_Image.png",
    "routeLat": "20.042707",
    "routeLng": "73.807400",
    "stationName": "Nashik Road",
    "routeDistance": "14.2",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
```

```
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "d6df1",
    "name": "d6df1",
    "image": "cases/67877b9a290edae64f178a35/
routeMap_1736934438009_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "800000",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
```

```
"totalOthersRate": "200000",
"finalTotal": "5435200.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValue": "0",
"finalValue": "4435200.00",
"purchaseValueDocument": {
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1736931940643_Agreement_for_sale_Mansing_1.pdf",
  "path": "cases/67877b9a290edae64f178a35/
document_1736931940643_Agreement_for_sale_Mansing_1.pdf",
  "id": "210843",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Jan 15 2025 09:10:50 GMT+0000 (Coordinated Universal Time)",
  "documentDate": "01/01/2025",
  "amount": "3200000",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "M/s. Neelam Builders & Developers",
  "to": {
    "value": "buyer",
    "label": "buyer"
  },
  "buyer": "Mr. Mansing Jagannath Sankpal & Mrs. Ashwini Mansing Sankpal",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "03/2025"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Jan 15 2025 10:40:43 GMT+0000 (Coordinated Universal Time)",
  "number": "2310061",
  "dayCount": "11",
  "monthCount": "180",
  "generatedBy": "64cde526dc9f3034f3fefa49"
```

```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "2",
    "percentage": "8.888888888888889",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "18.89",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2479000.00",
  "selectedBuildUpValue": "762.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67877bf5290edae64f178bb4",
      "name":
"externalImg_1736932341055_WhatsApp_Image_20250115_at_142123.jpeg",
      "path": "cases/67877b9a290edae64f178a35/
externalImg_1736932341055_WhatsApp_Image_20250115_at_142123.jpeg",
```

```
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "67877bf5290edae64f178bac",
    "name":
"externallmg_1736932339435_WhatsApp_Image_20250115_at_142116.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932339435_WhatsApp_Image_20250115_at_142116.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67877bf5290edae64f178bad",
    "name":
"externallmg_1736932339634_WhatsApp_Image_20250115_at_142117.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932339634_WhatsApp_Image_20250115_at_142117.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67877bf5290edae64f178baf",
    "name":
"externallmg_1736932340033_WhatsApp_Image_20250115_at_142119.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932340033_WhatsApp_Image_20250115_at_142119.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67877bf5290edae64f178bb4",
    "name":
"externallmg_1736932341055_WhatsApp_Image_20250115_at_142123.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932341055_WhatsApp_Image_20250115_at_142123.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67877bf5290edae64f178bb2",
    "name":
"externallmg_1736932340604_WhatsApp_Image_20250115_at_142121.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932340604_WhatsApp_Image_20250115_at_142121.jpeg",
```

```
    "orientation": "landscape"
  }
],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5301.00",
    "max": "6640.00"
  },
  "builtUpRateRange": {
    "min": "4417.00",
    "max": "5534.00"
  },
  "saleableRateRange": {
    "min": "3681.00",
    "max": "4612.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```



```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
finalValuationArea": "693.00",
empanelmentNo": [
"NZO /CR/22-23/39"
],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67877b9a290edae64f178a35",
"ownerName": "Mr. Mansing Jagannath Sankpal & Mrs. Ashwini Mansing Sankpal",
"ownerPhoneNo": "9421606857",
"fullAddress": "Residential Flat No. 404, 4th Floor, Neelam Srushti, Behind Nayara
Petrol Pump, Near Hotel City Spice, Vaiduwadi, Plot No. 42, off Vani - Dindori Road,
Village - Mhasrul, Taluka - Nashik, District - Nashik, Nashik, PIN Code - 422 004, State
- Maharashtra, Country - India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "01/01/2025",
      "amount": "3200000",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Neelam Builders & Developers",
      "to": {
        "value": "buyer",
        "label": "buyer"
      },
      "buyer": "Mr. Mansing Jagannath Sankpal & Mrs. Ashwini Mansing Sankpal",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "03/2025"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1736931940643_Agreement_for_sale_Mansing_1.pdf",
    "path": "cases/67877b9a290edae64f178a35/
document_1736931940643_Agreement_for_sale_Mansing_1.pdf",
    "id": "210843",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
```

```
"createdAt": "Wed Jan 15 2025 09:10:50 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "10/06/2024",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "Permit No. NMCB/ RB/ 2024/ APL/ 00691"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1736932063620_document_1726474377290_CC.pdf",
"path": "cases/67877b9a290edae64f178a35/
document_1736932063620_document_1726474377290_CC.pdf",
"id": "263598",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Jan 15 2025 09:10:50 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "10/06/2024",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "Permit No. NMCB/ RB/ 2024/ APL/ 00691"
},
"isHardCopy": false,
```

```
"displayStatus": false,
"id": "341294",
"path": "cases/67877b9a290edae64f178a35/
document_1736932198078_document_1726474408029_plan.pdf",
"fileName": "document_1736932198078_document_1726474408029_plan.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "16/07/2024",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51600077022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1736932245681_document_1726474414604_rera_cert.pdf",
"path": "cases/67877b9a290edae64f178a35/
document_1736932245681_document_1726474414604_rera_cert.pdf",
"id": "934579",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Jan 15 2025 09:10:50 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013677",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "263942",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jan 15 2025 09:10:50 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. Mansing Jagannath Sankpal & Mrs. Ashwini Mansing Sankpal",
    "phone": "9421606857",
    "ownershipShare": "",
    "email": "",
    "id": "411110"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "64.38",
    "totalAreaDocument": "693",
    "docBultupPercentage": "10",
    "docFinalBultUp": "762.30",
    "docFinalBultUpSquareMeter": "70.82",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "845901"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "566.00",
      "squareMeterArea": "52.58",
      "expectedRate": "5300.35",
      "percentage": ""
    }
  },
]
```

```
"builtUpArea": {
  "area": "679.20",
  "squareMeterArea": "63.10",
  "expectedRate": "4416.96",
  "percentage": "20"
},
"saleableArea": {
  "area": "815.04",
  "squareMeterArea": "75.72",
  "expectedRate": "3680.80",
  "percentage": "20"
},
"printInReport": true,
"_id": "67877dc0290edae64f178e96",
"property": "Flat",
"area": "566",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "3000000",
"expectedRate": "5300.35",
"builtUpExpectedRate": "4416.96",
"image": "cases/67877b9a290edae64f178a35/
indicator_1736932555904_Image.png",
"squareMeter": "52.58",
"id": "115958"
},
{
  "carpetArea": {
    "area": "625.00",
    "squareMeterArea": "58.06",
    "expectedRate": "6640.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "750.00",
    "squareMeterArea": "69.68",
    "expectedRate": "5533.33",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "900.00",
    "squareMeterArea": "83.61",
```

```
    "expectedRate": "4611.11",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67877dc0290edae64f178e97",
  "property": "Flat",
  "area": "900",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Saleable",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "4150000",
  "expectedRate": "4611.111111111111",
  "builtUpExpectedRate": "5533.33",
  "image": "cases/67877b9a290edae64f178a35/
indicator_1736932618298_Image.png",
  "squareMeter": "83.61",
  "id": "740559"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67877bf5290edae64f178ba9",
    "name":
"externalImg_1736932338874_WhatsApp_Image_20250115_at_142114.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externalImg_1736932338874_WhatsApp_Image_20250115_at_142114.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67877bf5290edae64f178baa",
    "name":
"externalImg_1736932339035_WhatsApp_Image_20250115_at_142115.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externalImg_1736932339035_WhatsApp_Image_20250115_at_142115.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "67877bf5290edae64f178bab",
    "name":
"externallmg_1736932339232_WhatsApp_Image_20250115_at_142116_1.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932339232_WhatsApp_Image_20250115_at_142116_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67877bf5290edae64f178bac",
    "name":
"externallmg_1736932339435_WhatsApp_Image_20250115_at_142116.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932339435_WhatsApp_Image_20250115_at_142116.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67877bf5290edae64f178bad",
    "name":
"externallmg_1736932339634_WhatsApp_Image_20250115_at_142117.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932339634_WhatsApp_Image_20250115_at_142117.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67877bf5290edae64f178bae",
    "name":
"externallmg_1736932339872_WhatsApp_Image_20250115_at_142118.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932339872_WhatsApp_Image_20250115_at_142118.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67877bf5290edae64f178baf",
    "name":
"externallmg_1736932340033_WhatsApp_Image_20250115_at_142119.jpeg",
    "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932340033_WhatsApp_Image_20250115_at_142119.jpeg",
    "orientation": "landscape"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67877bf5290edae64f178bb0",
  "name":
  "externallmg_1736932340192_WhatsApp_Image_20250115_at_142120.jpeg",
  "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932340192_WhatsApp_Image_20250115_at_142120.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67877bf5290edae64f178bb1",
  "name":
  "externallmg_1736932340348_WhatsApp_Image_20250115_at_142121_1.jpeg",
  "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932340348_WhatsApp_Image_20250115_at_142121_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67877bf5290edae64f178bb2",
  "name":
  "externallmg_1736932340604_WhatsApp_Image_20250115_at_142121.jpeg",
  "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932340604_WhatsApp_Image_20250115_at_142121.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67877bf5290edae64f178bb3",
  "name":
  "externallmg_1736932340821_WhatsApp_Image_20250115_at_142122.jpeg",
  "path": "cases/67877b9a290edae64f178a35/
externallmg_1736932340821_WhatsApp_Image_20250115_at_142122.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67877bf5290edae64f178bb4",
  "name":
  "externallmg_1736932341055_WhatsApp_Image_20250115_at_142123.jpeg",
```

```
    "path": "cases/67877b9a290edae64f178a35/
externalImg_1736932341055_WhatsApp_Image_20250115_at_142123.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Mansing Cal.xlsx",
    "filename": "1736932826164_Mansing_Cal.xlsx",
    "path": "cases/67877b9a290edae64f178a35/
processingDocuments/1736932826164_Mansing_Cal.xlsx",
    "size": "659895",
    "createdAt": "Wed Jan 15 2025 09:20:27 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "SBI - Mr. Mansing Jagannath Sankpal & Mrs. Ashwini Mansing
Sankpal.pdf",
    "filename": "1736934735934_SBI__Mr_Mansing_Jagannath_Sankpal__Mrs_Ashwin
i_Mansing_Sankpal.pdf",
    "path": "cases/67877b9a290edae64f178a35/processingDocuments/1736934735934
_SBI__Mr_Mansing_Jagannath_Sankpal__Mrs_Ashwini_Mansing_Sankpal.pdf",
    "size": "4560550",
    "createdAt": "Wed Jan 15 2025 09:52:22 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-15T09:10:50.634Z",
"updatedAt": "2025-01-15T10:49:25.576Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "647ed1960ab64c23c9fcf71d",
"contactPersonName": "Mr. Shailesh Velani ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Builder",
"rerald": ""
```

```
"siteVisitContactNo": "9421606857",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 693.00",
"flatRate": "6400",
"landOtherRate": "4400",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
}
```

"reportGeneratedDate": "Wed Jan 15 2025 09:32:58 GMT+0000 (Coordinated Universal Time)",

"siteVisitDate": "2025-01-15"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			