

```
{
  "typeOfReport": {
    "value": "Bungalow",
    "label": "Bungalow"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb67"
    },
    "firstName": "Dilip",
    "type": "CREDITOFFICER",
    "_id": "67767413b40b8ce125dc19ee",
    "email": "sbi.31482@sbi.co.in",
    "lastName": "Soni",
    "mobileNo": "",
    "workMobileNo": "8005608419"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb67",
  "branchCode": "000357",
  "type": "BRANCH",
  "name": "Balotra Industrial Area Branch ",
  "email": "sbi.31482@sbi.co.in",
  "mobileNo": "1800-425-3800",
  "alternateMobileNo": "",
  "address": "State bank of India\r\nIndustrial area branch\r\nBalotra - 344022, State - \r\nRajasthan, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
  "lastName": "Patil",
  "mobileNo": "8830049996",
  "designation": "Valuation Engineer",
  "shortName": "SSP",
  "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
```

```
"latitude": "18.776865623322255",
"longitude": "73.39856337573195"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "15/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Tungarli",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Maval",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Maval",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "21",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gold Valley CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "C-3",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Vadgaon Maval",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```

```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "44/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```



```
"status": false,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```



```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6787a2ac290edae64f17dc00",
"ownerName": "Mr. Anand P. Golecha And Mr. Pravin P. Golecha",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9821839739",
"contactPersonName": "Ishwar Shukla",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Anand P. Golecha And Mr. Pravin P. Golecha",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "672959"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact",
"fullAddress": "Residential Bungalow No. Ground Floor, Gold Valley CHSL, Plot No.
```

21, Sector C-3, New/Current Survey No. 44/3, Vadgaon Maval, Village - Tungarli, Taluka - Maval, District - Maval, State - Maharashtra, India",

"remark": "",

"documents": [

{

"documentType": {

"value": "60ae1248aa6d152c1801b2ee",

"label": "Previous Valuation Report"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document_1736942245157_Valuation_Report__Anand_Golecha.pdf",

"path": "cases/6787a2ac290edae64f17dc00/

document_1736942245157_Valuation_Report__Anand_Golecha.pdf",

"id": "307804",

"uploadedBy": "6006d4ce5080a310ac1fdfc2",

"createdAt": "Wed Jan 15 2025 11:57:31 GMT+0000 (Coordinated Universal Time)"

}

],

"isUrgent": "false",

"isExternal": "false",

"proposePurchaserName": "",

"assignmentType": {

"value": "Commercial",

"label": "Commercial"

},

"rerald": "",

"scheduleSiteVisitDate": "Invalid date",

"caseNumber": "013684",

"createdBy": "6006d4ce5080a310ac1fdfc2",

"caseHistory": [

{

"id": "363008",

"title": "Create Case",

"description": "Create Case",

"datetime": "Wed Jan 15 2025 11:57:32 GMT+0000 (Coordinated Universal Time)"

}

],

"proposePurchasers": [],

"siteInspection": [],

"composition": [],

"otherComposition": [],

"externalReport": [],

"documentPerArea": [],

"images": [],

"indicatorArr": [],

```
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190da3",
    "name": "externalImg_1737094445870_1737094415359_image_0.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externalImg_1737094445870_1737094415359_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190da4",
    "name": "externalImg_1737094453513_1737094415359_image_1.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externalImg_1737094453513_1737094415359_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190da5",
    "name": "externalImg_1737094455423_1737094415359_image_2.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externalImg_1737094455423_1737094415359_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190da6",
    "name": "externalImg_1737094456820_1737094415359_image_3.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externalImg_1737094456820_1737094415359_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190da7",
    "name": "externalImg_1737094459468_1737094415359_image_4.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externalImg_1737094459468_1737094415359_image_4.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6789f564290edae64f190da8",
  "name": "externallmg_1737094461186_1737094415359_image_5.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094461186_1737094415359_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6789f564290edae64f190da9",
  "name": "externallmg_1737094463702_1737094415359_image_6.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094463702_1737094415359_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6789f564290edae64f190daa",
  "name": "externallmg_1737094467411_1737094415359_image_7.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094467411_1737094415359_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6789f564290edae64f190dab",
  "name": "externallmg_1737094470201_1737094415359_image_8.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094470201_1737094415359_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6789f564290edae64f190dac",
  "name": "externallmg_1737094472331_1737094415359_image_9.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094472331_1737094415359_image_9.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190dad",
    "name": "externallmg_1737094475345_1737094415359_image_10.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094475345_1737094415359_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190dae",
    "name": "externallmg_1737094480240_1737094415359_image_11.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094480240_1737094415359_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190daf",
    "name": "externallmg_1737094483956_1737094415359_image_12.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094483956_1737094415359_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190db0",
    "name": "externallmg_1737094486156_1737094415359_image_13.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094486156_1737094415359_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190db1",
    "name": "externallmg_1737094487451_1737094415359_image_14.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094487451_1737094415359_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "6789f564290edae64f190db2",
    "name": "externallmg_1737094490776_1737094415359_image_15.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094490776_1737094415359_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190db3",
    "name": "externallmg_1737094492736_1737094415359_image_16.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094492736_1737094415359_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190db4",
    "name": "externallmg_1737094495002_1737094415359_image_17.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094495002_1737094415359_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190db5",
    "name": "externallmg_1737094496301_1737094415359_image_18.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094496301_1737094415359_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6789f564290edae64f190db6",
    "name": "externallmg_1737094498512_1737094415359_image_19.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094498512_1737094415359_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6789f569290edae64f190df9",
    "name": "externallmg_1737094454369_1737094447208_image_0.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094454369_1737094447208_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190dfa",
    "name": "externallmg_1737094456984_1737094447208_image_1.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094456984_1737094447208_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190dfb",
    "name": "externallmg_1737094458949_1737094447208_image_2.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094458949_1737094447208_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190dfc",
    "name": "externallmg_1737094460973_1737094447208_image_3.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094460973_1737094447208_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190dfd",
    "name": "externallmg_1737094462303_1737094447208_image_4.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094462303_1737094447208_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190dfe",
```

```
    "name": "externallmg_1737094463631_1737094447208_image_5.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094463631_1737094447208_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190dff",
    "name": "externallmg_1737094468301_1737094447208_image_6.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094468301_1737094447208_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e00",
    "name": "externallmg_1737094474001_1737094447208_image_7.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094474001_1737094447208_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e01",
    "name": "externallmg_1737094478346_1737094447208_image_8.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094478346_1737094447208_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e02",
    "name": "externallmg_1737094481136_1737094447208_image_9.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094481136_1737094447208_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e03",
    "name": "externallmg_1737094484263_1737094447208_image_10.jpeg",
```



```
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094484263_1737094447208_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e04",
    "name": "externallmg_1737094486867_1737094447208_image_11.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094486867_1737094447208_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e05",
    "name": "externallmg_1737094492307_1737094447208_image_12.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094492307_1737094447208_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e06",
    "name": "externallmg_1737094494527_1737094447208_image_13.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094494527_1737094447208_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e07",
    "name": "externallmg_1737094495946_1737094447208_image_14.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094495946_1737094447208_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f569290edae64f190e08",
    "name": "externallmg_1737094497873_1737094447208_image_15.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094497873_1737094447208_image_15.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f569290edae64f190e09",
  "name": "externallmg_1737094499286_1737094447208_image_16.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094499286_1737094447208_image_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f569290edae64f190e0a",
  "name": "externallmg_1737094500906_1737094447208_image_17.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094500906_1737094447208_image_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f569290edae64f190e0b",
  "name": "externallmg_1737094501672_1737094447208_image_18.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094501672_1737094447208_image_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f569290edae64f190e0c",
  "name": "externallmg_1737094503253_1737094447208_image_19.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094503253_1737094447208_image_19.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f593601c90e69621dcf6",
  "name": "externallmg_1737094537369_1737094534118_image_0.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094537369_1737094534118_image_0.jpeg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6789f593601c90e69621dcf7",
      "name": "externallmg_1737094538286_1737094534118_image_1.jpeg",
      "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094538286_1737094534118_image_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6789f593601c90e69621dcf8",
      "name": "externallmg_1737094538987_1737094534118_image_2.jpeg",
      "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094538987_1737094534118_image_2.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6789f593601c90e69621dcf9",
      "name": "externallmg_1737094540989_1737094534118_image_3.jpeg",
      "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094540989_1737094534118_image_3.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6789f593601c90e69621dcfa",
      "name": "externallmg_1737094541070_1737094534118_image_4.jpeg",
      "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094541070_1737094534118_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6789f593601c90e69621dcfb",
      "name": "externallmg_1737094541541_1737094534118_image_5.jpeg",
      "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094541541_1737094534118_image_5.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f593601c90e69621dcfc",
  "name": "externallmg_1737094543365_1737094534118_image_6.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094543365_1737094534118_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f593601c90e69621dcfd",
  "name": "externallmg_1737094543383_1737094534118_image_7.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094543383_1737094534118_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f593601c90e69621dcfe",
  "name": "externallmg_1737094544161_1737094534118_image_8.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094544161_1737094534118_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f593601c90e69621dcff",
  "name": "externallmg_1737094545327_1737094534118_image_9.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094545327_1737094534118_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6789f593601c90e69621dd00",
  "name": "externallmg_1737094545742_1737094534118_image_10.jpeg",
  "path": "cases/6787a2ac290edae64f17dc00/
externallmg_1737094545742_1737094534118_image_10.jpeg",
  "orientation": "landscape"
},
{
```

```

    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6789f593601c90e69621dd01",
    "name": "externalimg_1737094546546_1737094534118_image_11.jpeg",
    "path": "cases/6787a2ac290edae64f17dc00/
externalimg_1737094546546_1737094534118_image_11.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-15T11:57:32.248Z",
"updatedAt": "2025-01-17T06:15:47.956Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "65dee3f79a876858ab30487f"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			