

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "645ddc537f94762ec789bd1a"
    },
    "firstName": "Om Prakash ",
    "type": "CREDITOFFICER",
    "_id": "645ddc537f94762ec789bd1c",
    "lastName": "Chandrawal",
    "mobileNo": "",
    "workMobileNo": "8058448791",
    "email": "sbipoolhouse.00656@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "645ddc537f94762ec789bd1a",
  "name": "Jaipur Main Branch\t",
  "branchCode": "00656",
  "mobileNo": "1414096290",
  "alternateMobileNo": "",
  "email": "sbipoolhouse.00656@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SANGANERI GATE, JAIPUR.M\nRAJASTHAN"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
```

```
  "_id": "67776d60a5477d50e7dbc213",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "AJAY",
  "email": "ajayrewale503@gmail.com",
  "lastName": "REWALE",
  "mobileNo": "9766640171",
  "designation": "",
  "shortName": "AJAY",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "663da98cfcea71232186f142",
  "role": "ACCOUNTANT",
  "firstName": "SONAL ",
  "email": "sonal.ambekar19@gmail.com",
  "lastName": " SHIVGAN",
  "mobileNo": "9773395869",
  "designation": "",
  "shortName": "SO",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
```

```
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
}
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.272712734141834",
  "longitude": "72.87186708625282"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-17",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-16",
      "remark": "MANUAL_IN_TASK"
    }
  ],
},
}
```

```
{
  "status": "COMPLETED",
  "dateTime": "2025-01-17",
  "remark": "MANUAL_IN_TASK"
}
],
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mira",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "1",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "9",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Shanti Garden",
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "4",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Police Commissioner Office",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "146 to 151, 152/1",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "17 to 22, 23/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "104",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401 107",
  "label": false
}
```

```

},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {

```

```
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Mars Building",
  "west": "Shanti Garden, Sector 4",
  "south": "Shanti Garden Road",
  "east": "Shanti Garden, Sector 5"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Stairase",
    "south": "Marginal Space",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  }
},
```

```

"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "Flat No. 103 & 104 are internally merged with single
entrances. The said valuation is for Flat No. 104.",
"dateOfIssusApprovePlan": "As Occupancy Certificate No. MNP / NR / 4266 / 0647
Dated 28.03.2007 issued by Mira Bhayander Municipal Corporation is available it is
assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "1. As per site inspection, Flat No. 103 & 104 are internally merged with
single entrances. For the purpose of valuation, we have considered Area of Flat No. 103
as per Agreement. The said valuation is only for Flat No. 104. <br />\n2. At the time of
visit, the External building renovation work was in progress.",
  "depreciationPercentage": "27",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "13525",
  "depreciatedBuildingRate": "1825"
},
"igrRate": {
  "propertyName": "Flat ",
  "rate": "97700",
  "landRate": "28700",
  "igrImage": "cases/678a263c601c90e696220828/igr_1737201074870_Image.png",
  "squareMeterGuideLineRate": "97700.00",
  "squareFeetGuideLineRate": "9077.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "82",
  "rate": "7923.00",
  "squareMeterGuideLineRate": "85280.00",

```

```
"squareFeetGuideLineRate": "7923.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "Information not available",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\_Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2007",
  "fullDate": "1/1/2007"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
```

```
"label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
}
```



```
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "42",
"ageOfBuilding": "18",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "462.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/678a263c601c90e696220828/
routeMap_1737198772072_Image.png",
    "routeLat": "19.272750",
    "routeLng": "72.872611",
    "stationName": "Mira Road",
    "routeDistance": "2.4",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "xwn8pk",
    "name": "xwn8pk",
```

```
    "image": "cases/678a263c601c90e696220828/
routeMap_1737198544735_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "6248550.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "6248550.00"
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "3660426.00",
"selectedBuildUpValue": "462.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "678a98c35a336ce64e557828",
"name": "externalImg_1737136251270_1737136161438_image_9.jpeg",
```

```
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136251270_1737136161438_image_9.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "678a9932290edae64f1994c7",
    "name": "externallmg_1737136355896_1737136238089_image_1.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136355896_1737136238089_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a9932290edae64f1994c9",
    "name": "externallmg_1737136363785_1737136238089_image_3.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136363785_1737136238089_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a9932290edae64f1994cf",
    "name": "externallmg_1737136391789_1737136238089_image_9.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136391789_1737136238089_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678b8ad0290edae64f1a323a",
    "name": "externallmg_1737198287475_externallmg_1737136883087_1737136596
736_image_8.jpeg",
    "path": "cases/678a263c601c90e696220828/externallmg_1737198287475_extern
allmg_1737136883087_1737136596736_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a98c35a336ce64e557828",
    "name": "externallmg_1737136251270_1737136161438_image_9.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136251270_1737136161438_image_9.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a98c35a336ce64e557823",
    "name": "externallmg_1737136211380_1737136161438_image_4.jpeg",
    "path": "cases/678a263c601c90e696220828/externallmg_1737136211380_1737136161438_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "678b8b24601c90e69622c654",
    "name": "externallmg_1737198371345_externallmg_1737136762829_1737136646878_image_7.jpeg",
    "path": "cases/678a263c601c90e696220828/externallmg_1737198371345_externallmg_1737136762829_1737136646878_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a9932290edae64f1994ce",
    "name": "externallmg_1737136388304_1737136238089_image_8.jpeg",
    "path": "cases/678a263c601c90e696220828/externallmg_1737136388304_1737136238089_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a9932290edae64f1994c6",
    "name": "externallmg_1737136345076_1737136238089_image_0.jpeg",
    "path": "cases/678a263c601c90e696220828/externallmg_1737136345076_1737136238089_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a9932290edae64f1994cc",
    "name": "externallmg_1737136379670_1737136238089_image_6.jpeg",
    "path": "cases/678a263c601c90e696220828/externallmg_1737136379670_1737136238089_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a98c35a336ce64e55782c",
```

```
    "name": "externallmg_1737136294417_1737136161438_image_13.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136294417_1737136161438_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678a98c35a336ce64e55782b",
    "name": "externallmg_1737136281405_1737136161438_image_12.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136281405_1737136161438_image_12.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16689.00",
    "max": "21112.00"
  },
  "builtUpRateRange": {
    "min": "13908.00",
    "max": "17593.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "462.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"paymentStatus": "RECEIVED",
"invoiceIds": [],
"paymentIds": [
  "678a3ba75a336ce64e5552d2"
],
"_id": "678a263c601c90e696220828",
"ownerName": "Mrs. Monika Boradia (Jain)",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9867520432",
"contactPersonName": "Mrs. Monika Boradia",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mrs. Monika Boradia (Jain)",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "555806"
  }
],
"caseReferredBy": "5ff3ead28cda966090eacbbe",
"relationWithOwner": "Owner",
"fullAddress": "Residential Flat No. 104, 1st Floor, Building No 9, Shanti Garden,
Sector 4, Near Police Commissioner Office, Village - Mira, Mira Road (East), Taluka -
Thane, District - Thane, 401 107, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    }
  }
]
```

```

    },
    "inputs": {
      "documentDate": "23/12/2021",
      "remark": " issued by Vastukala Consultants (I) Pvt. Ltd.."
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "412907",
    "path": "cases/678a263c601c90e696220828/
document_1737106970567_Valuation_Report_Monika_Bordia_Jain__104.pdf",
    "fileName":
"document_1737106970567_Valuation_Report_Monika_Bordia_Jain__104.pdf"
  },
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "03/12/2005",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "M/s. Ram Nagar Development Corporation",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mrs. Monika Boradia (Jain)",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "7997/2005"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1737196519286_Agreement.pdf",
    "path": "cases/678a263c601c90e696220828/
document_1737196519286_Agreement.pdf",
    "id": "364591",
    "uploadedBy": "663da98cfcea71232186f142",
    "createdAt": "Sat Jan 18 2025 10:35:21 GMT+0000 (Coordinated Universal Time)"
  },
  {

```

```
"documentType": {
  "value": "60ae1250aa6d152c1801b316",
  "label": "Part Occupancy Certificate"
},
"inputs": {
  "documentDate": "28/03/2007",
  "nameOfApprovingAuthority": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "No. MNP / NR / 4266 / 0647"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1737196830626_Part_Occupancy_Certificate.pdf",
"path": "cases/678a263c601c90e696220828/
document_1737196830626_Part_Occupancy_Certificate.pdf",
"id": "752052",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Sat Jan 18 2025 10:40:30 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "31/01/2005",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MB / MNP / NR / 2094 / 2004 – 2005"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "501682",
  "path": "cases/678a263c601c90e696220828/
document_1737201959251_Commencemet_Certificate.pdf",
```

```
"fileName": "document_1737201959251_Commencemet_Certificate.pdf"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"rerald": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "013733",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "267948",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Fri Jan 17 2025 09:43:23 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "323489",
    "name": "Living Room",
    "length": "14.25",
    "length1": "14",
    "length2": "3",
    "width": "9.67",
    "width1": "9",
    "width2": "8",
    "totalArea": "137.75",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
          "value": "Square_Feet",
          "label": "Square Feet"
        }
      }
    ]
  }
]
```

```
    "_id": "678b97255a336ce64e560ed3",
    "name": "Extra area",
    "extraAreaType": "Add",
    "length": "14.25",
    "length1": "14",
    "length2": "3",
    "width": "9.67",
    "width1": "9",
    "width2": "8",
    "totalArea": "137.75"
  }
],
"finalArea": "275.5"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "85.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "2.67",
  "length1": "2",
  "length2": "8",
  "width": "10.17",
  "width1": "10",
  "width2": "2",
  "totalArea": "27.11",
```

```
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "678b9777290edae64f1a4c56",
    "name": "Extra area",
    "extraAreaType": "Add",
    "length": "2.67",
    "length1": "2",
    "length2": "8",
    "width": "9.75",
    "width1": "9",
    "width2": "9",
    "totalArea": "26.00"
  }
],
"finalArea": "53.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "9.25",
  "width1": "9",
  "width2": "3",
  "totalArea": "114.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "114.85"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
```



```
"length": "10.50",
"length1": "10",
"length2": "6",
"width": "8.25",
"width1": "8",
"width2": "3",
"totalArea": "86.62",
"images": [],
"extraAreas": [],
"finalArea": "86.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "12.33",
  "length1": "12",
  "length2": "4",
  "width": "9.25",
  "width1": "9",
  "width2": "3",
  "totalArea": "114.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "114.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "8.33",
  "width1": "8",
  "width2": "4",
  "totalArea": "33.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.33"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
  },
  {
    "name": {
      "label": "Niche",
    }
  }
]
```

```
    "value": "Niche"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "2.42",
  "length1": "2",
  "length2": "5",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "23.36",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.36",
  "percentageBeforeTotal": "23.36",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "25.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.31",
  "percentageBeforeTotal": "25.31",
  "percentage": "100"
}
```

```
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Terrace Area",
    "value": "Terrace_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "42.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "42.25",
  "percentageBeforeTotal": "42.25",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Terrace Area",
    "value": "Terrace_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "9.67",
```

```
"width1": "9",
"width2": "8",
"totalArea": "42.69",
"images": [],
"extraAreas": [],
"finalArea": "42.69",
"percentageBeforeTotal": "42.69",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "826069",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "462",
  "squareMeterArea": "42.92",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBUILTUPPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
},
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "721281",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "384.5",
  "squareMeterArea": "35.72",
  "docFinalBuiltUp": "461.4",
```

```
"docFinalBuiltUpSquareMeter": "42.864",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "385",
"squareMeterArea": "35.77",
"expectedRate": "16623.38",
"percentage": ""
},
"builtUpArea": {
"area": "462.00",
"squareMeterArea": "42.92",
"expectedRate": "13852.81",
"percentage": ""
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": false,
"_id": "678b94ba290edae64f1a470d",
"property": "Flat",
"area": "462",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "6400000",
"expectedRate": "16623.38",
"builtUpExpectedRate": "6400000",
"image": "cases/678a263c601c90e696220828/
indicator_1737200478169_Image.png",
"squareMeter": "42.92",
"id": "334384"
},
```

```
{
  "carpetArea": {
    "area": "251.67",
    "squareMeterArea": "23.38",
    "expectedRate": "16688.52",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "302.00",
    "squareMeterArea": "28.06",
    "expectedRate": "13907.28",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "678b94ba290edae64f1a470e",
  "property": "Flat",
  "area": "302",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "1",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4200000",
  "expectedRate": "16688.52",
  "builtUpExpectedRate": "4200000",
  "image": "cases/678a263c601c90e696220828/
indicator_1737200597981_Image.png",
  "squareMeter": "28.06",
  "id": "419869"
},
{
  "carpetArea": {
    "area": "400",
    "squareMeterArea": "37.16",
    "expectedRate": "17500.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "480.00",
```

```
"squareMeterArea": "44.59",
"expectedRate": "14583.33",
"percentage": ""
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "678b94ba290edae64f1a470f",
"property": "Flat",
"area": "480",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "4",
"source": "square_yards",
"expectedPrice": "7000000",
"expectedRate": "17500.00",
"builtUpExpectedRate": "7000000",
"image": "cases/678a263c601c90e696220828/
indicator_1737200719701_Image.png",
"squareMeter": "44.59",
"id": "224525"
},
{
  "carpetArea": {
    "area": "360",
    "squareMeterArea": "33.45",
    "expectedRate": "21111.11",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "432.00",
    "squareMeterArea": "40.13",
    "expectedRate": "17592.59",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```



```
    },
    "printlnReport": true,
    "_id": "678b94ba290edae64f1a4710",
    "property": "Flat",
    "area": "432",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "7",
    "source": "Nobroker.com",
    "expectedPrice": "7600000",
    "expectedRate": "21111.11",
    "builtUpExpectedRate": "7600000",
    "image": "cases/678a263c601c90e696220828/
indicator_1737200826197_Image.png",
    "squareMeter": "40.13",
    "id": "174205"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a9932290edae64f1994c6",
    "name": "externallmg_1737136345076_1737136238089_image_0.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136345076_1737136238089_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a9932290edae64f1994c7",
    "name": "externallmg_1737136355896_1737136238089_image_1.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136355896_1737136238089_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a9932290edae64f1994c8",
    "name": "externallmg_1737136359004_1737136238089_image_2.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136359004_1737136238089_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a9932290edae64f1994c9",
  "name": "externallmg_1737136363785_1737136238089_image_3.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136363785_1737136238089_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a9932290edae64f1994ca",
  "name": "externallmg_1737136369624_1737136238089_image_4.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136369624_1737136238089_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a9932290edae64f1994cb",
  "name": "externallmg_1737136374705_1737136238089_image_5.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136374705_1737136238089_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a9932290edae64f1994cc",
  "name": "externallmg_1737136379670_1737136238089_image_6.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136379670_1737136238089_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a9932290edae64f1994cd",
  "name": "externallmg_1737136384714_1737136238089_image_7.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136384714_1737136238089_image_7.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a9932290edae64f1994ce",
      "name": "externallmg_1737136388304_1737136238089_image_8.jpeg",
      "path": "cases/678a263c601c90e696220828/
externallmg_1737136388304_1737136238089_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a9932290edae64f1994cf",
      "name": "externallmg_1737136391789_1737136238089_image_9.jpeg",
      "path": "cases/678a263c601c90e696220828/
externallmg_1737136391789_1737136238089_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a9932290edae64f1994d0",
      "name": "externallmg_1737136397430_1737136238089_image_10.jpeg",
      "path": "cases/678a263c601c90e696220828/
externallmg_1737136397430_1737136238089_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a9932290edae64f1994d1",
      "name": "externallmg_1737136402420_1737136238089_image_11.jpeg",
      "path": "cases/678a263c601c90e696220828/
externallmg_1737136402420_1737136238089_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a9932290edae64f1994d2",
      "name": "externallmg_1737136409020_1737136238089_image_12.jpeg",
      "path": "cases/678a263c601c90e696220828/
externallmg_1737136409020_1737136238089_image_12.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a98c35a336ce64e55781f",
  "name": "externallmg_1737136167136_1737136161437_image_0.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136167136_1737136161437_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a98c35a336ce64e557820",
  "name": "externallmg_1737136180125_1737136161437_image_1.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136180125_1737136161437_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a98c35a336ce64e557821",
  "name": "externallmg_1737136191970_1737136161437_image_2.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136191970_1737136161437_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a98c35a336ce64e557822",
  "name": "externallmg_1737136207954_1737136161437_image_3.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136207954_1737136161437_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678a98c35a336ce64e557823",
  "name": "externallmg_1737136211380_1737136161438_image_4.jpeg",
  "path": "cases/678a263c601c90e696220828/
externallmg_1737136211380_1737136161438_image_4.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e557824",
    "name": "externallmg_1737136224586_1737136161438_image_5.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136224586_1737136161438_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e557825",
    "name": "externallmg_1737136231591_1737136161438_image_6.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136231591_1737136161438_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e557826",
    "name": "externallmg_1737136240840_1737136161438_image_7.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136240840_1737136161438_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e557827",
    "name": "externallmg_1737136249684_1737136161438_image_8.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136249684_1737136161438_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e557828",
    "name": "externallmg_1737136251270_1737136161438_image_9.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136251270_1737136161438_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "678a98c35a336ce64e557829",
    "name": "externallmg_1737136261350_1737136161438_image_10.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136261350_1737136161438_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e55782a",
    "name": "externallmg_1737136269500_1737136161438_image_11.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136269500_1737136161438_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e55782b",
    "name": "externallmg_1737136281405_1737136161438_image_12.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136281405_1737136161438_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e55782c",
    "name": "externallmg_1737136294417_1737136161438_image_13.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136294417_1737136161438_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678a98c35a336ce64e55782d",
    "name": "externallmg_1737136310950_1737136161438_image_14.jpeg",
    "path": "cases/678a263c601c90e696220828/
externallmg_1737136310950_1737136161438_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "678b8ad0290edae64f1a323a",
    "name": "externalimg_1737198287475_externalimg_1737136883087_17371365967
36_image_8.jpeg",
    "path": "cases/678a263c601c90e696220828/externalimg_1737198287475_external
mg_1737136883087_1737136596736_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678b8b24601c90e69622c654",
    "name": "externalimg_1737198371345_externalimg_1737136762829_17371366468
78_image_7.jpeg",
    "path": "cases/678a263c601c90e696220828/externalimg_1737198371345_external
mg_1737136762829_1737136646878_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678b9c69290edae64f1a5533",
    "name": "externalimg_1737202792965_externalimg_1737136860806_17371365967
36_image_6.jpeg",
    "path": "cases/678a263c601c90e696220828/externalimg_1737202792965_external
mg_1737136860806_1737136596736_image_6.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2).xlsx",
    "filename": "1737442553596_Calculation_2.xlsx",
    "path": "cases/678a263c601c90e696220828/
processingDocuments/1737442553596_Calculation_2.xlsx",
    "size": "16391",
    "createdAt": "Tue Jan 21 2025 06:55:53 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - monika - 104.xlsx",
    "filename": "1737442564980_Summary__monika__104.xlsx",
    "path": "cases/678a263c601c90e696220828/
processingDocuments/1737442564980_Summary__monika__104.xlsx",
    "size": "2755977",
    "createdAt": "Tue Jan 21 2025 06:56:05 GMT+0000 (Coordinated Universal Time)",
```

```
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "678a29dc5a336ce64e553e64",
    "note": "working done. visit pending.",
    "taskId": "678a263c290edae64f1943b6",
    "createdAt": "2025-01-17T09:58:52.740Z"
  },
  {
    "createdBy": {
      "_id": "64102465140f140ffc59dc49",
      "role": "ACCOUNTANT",
      "firstName": "Pooja",
      "lastName": "Dagare"
    },
    "workType": "DELETE_INVOICE",
    "display": true,
    "status": true,
    "_id": "678a39f0601c90e696221e2c",
    "createdAt": "2025-01-17T11:07:28.478Z"
  },
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
```



```
"display": true,
"status": true,
"_id": "678b33185a336ce64e5585f7",
"note": "Required OC",
"taskId": "678a263c290edae64f1943b6",
"createdAt": "2025-01-18T04:50:32.899Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "678f45b85a336ce64e570b0c",
  "note": "by mistake task completed (Task Reopen)",
  "taskId": "678de5e4290edae64f1a9e62",
  "createdAt": "2025-01-21T06:59:04.271Z"
},
{
  "createdBy": {
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "678f4600290edae64f1b7cc6",
  "note": "draft shared",
  "taskId": "678de5e4290edae64f1a9e62",
  "createdAt": "2025-01-21T07:00:16.388Z"
}
],
"createdAt": "2025-01-17T09:43:24.065Z",
"updatedAt": "2025-01-23T05:33:02.244Z",
"__v": 0,
"addressForMap": "",
```

```
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"builtupPercentage": "10",
"carpetTotal": "794.49",
"extendOfSiteRemark": "",
"finalBuiltupArea": "973.95",
"finalCarpetArea": "885.41",
"finalSalableArea": "1071.35",
"otherCarpetTotal": "133.61",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 842.00\nDuct Area in Sq. Ft. =
26.00\nBalcony Area in Sq. Ft. = 88.00\nChajja Aera in Sq. Ft. = 37.00\n(Area as per
actual site measurement of Flat No. 103 &\n104)\n\n\n",
"toBeAdded": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Jan 18 2025 10:13:15 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-01-17",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 462.00",
"buildingServicesRate": "2500",
"flatRate": "14200",
"landOtherRate": "11700",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Passage + 3 Toilet",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "90.92",
```

"otherCompositionSaleableTotal": "0.00"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	14'3"	9'8"	137.75
Kitchen	10'00"	8'6"	85.00
Passage	2'8"	10'2"	27.11
Bedroom	12'5"	9'3"	114.85
Bedroom	10'6"	8'3"	86.62
Bedroom	12'4"	9'3"	114.08
Toilet	4'00"	5'00"	20.00
Toilet	4'00"	3'00"	12.00
Toilet	4'00"	8'4"	33.33
Other Composition :			
Niche	2'5"	9'8"	23.36
Dry Balcony	3'9"	6'9"	25.31
Terrace Area	4'4"	9'9"	42.25
Terrace Area	4'5"	9'8"	42.69