

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66c2ed670f117327db71fcd3"
    },
    "firstName": "Rajdeep",
    "type": "CREDITOFFICER",
    "_id": "6756e3b2821be57904f1b9e1",
    "email": "bom16@mahabank.co.in",
    "lastName": "kumar Jha",
    "mobileNo": "",
    "workMobileNo": "9555714809"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9484645",
    "discussWithPerson": "Rajdeep",
    "expectedFees": 4742.3225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "66c2ed670f117327db71fcd3",
  "name": "Gadkari chowk branch (16)",
  "branchCode": "",
  "mobileNo": "0224443960",
  "alternateMobileNo": "",
  "email": "bom16@mahabank.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Opp Sena Bhawan Dadar West Mumbai 400028"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
```

```
"firstName": "Ramkrishna ",
"email": "rampatakar1991@gmail.com",
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "67776d60a5477d50e7dbc213",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "AJAY",
  "email": "ajayrewale503@gmail.com",
  "lastName": "REWALE",
  "mobileNo": "9766640171",
  "designation": "",
  "shortName": "AJAY",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ],
    "_id": "60af80072ffdf65bcd658651",
```

```
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.170704269342302",
  "longitude": "72.84661981057803"
},
"geo": {
  "type": "Point",
```

```
"coordinates": [
  72.84661981057803,
  19.170704269342302
],
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "23/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pahadi",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "12",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "AGARWAL FLORENCE",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "905,905/1 to 5",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1102",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "400062",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
}
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```



```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67920e52936736429e694ba0",
"ownerName": "Vikram Singh Jeetmal jain",
"ownerPhoneNo": "9892417057",
"appAddress": "flat no - A - 1102, Wing - A, 11th floor, Goregaon West, Agarwal
florance, Village - pahadi ",
"remark": "contact person - Nilesh Agarwal ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67920e52936736429e694ba0/
document_1737625162058_1737625152566_1101_A.pdf",
    "fileName": "document_1737625162058_1737625152566_1101_A.pdf",
    "id": "158086",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Thu Jan 23 2025 09:39:30 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
```

```
},
"inputs": {
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P51800032916"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1737625858714_Rere_certificate.pdf",
"path": "cases/67920e52936736429e694ba0/
document_1737625858714_Rere_certificate.pdf",
"id": "866064",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Thu Jan 23 2025 09:51:01 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "013860",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "242887",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 23 2025 09:39:30 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Vikram Singh Jeetmal jain",
    "phone": "9892417057",
    "ownershipShare": "",
    "email": "",
    "id": "261344"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6793032a936736429e699fa5",
  "name": "externallmg_1737687830473_1737687827350_image_0.jpeg",
  "path": "cases/67920e52936736429e694ba0/
externallmg_1737687830473_1737687827350_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6793032a936736429e699fa6",
  "name": "externallmg_1737687832263_1737687827350_image_1.jpeg",
  "path": "cases/67920e52936736429e694ba0/
externallmg_1737687832263_1737687827350_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6793032a936736429e699fa7",
  "name": "externallmg_1737687833983_1737687827350_image_2.jpeg",
  "path": "cases/67920e52936736429e694ba0/
externallmg_1737687833983_1737687827350_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6793032a936736429e699fa8",
  "name": "externallmg_1737687836188_1737687827350_image_3.jpeg",
  "path": "cases/67920e52936736429e694ba0/
externallmg_1737687836188_1737687827350_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6793032a936736429e699fa9",
  "name": "externallmg_1737687836603_1737687827350_image_4.jpeg",
  "path": "cases/67920e52936736429e694ba0/
externallmg_1737687836603_1737687827350_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699faa",
    "name": "externallmg_1737687837778_1737687827350_image_5.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687837778_1737687827350_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699fab",
    "name": "externallmg_1737687840244_1737687827350_image_6.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687840244_1737687827350_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699fac",
    "name": "externallmg_1737687841988_1737687827350_image_7.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687841988_1737687827350_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699fad",
    "name": "externallmg_1737687843613_1737687827350_image_8.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687843613_1737687827350_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699fae",
    "name": "externallmg_1737687844079_1737687827350_image_9.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687844079_1737687827350_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "6793032a936736429e699faf",
    "name": "externallmg_1737687846043_1737687827350_image_10.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687846043_1737687827350_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699fb0",
    "name": "externallmg_1737687847593_1737687827350_image_11.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687847593_1737687827350_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699fb1",
    "name": "externallmg_1737687848838_1737687827350_image_12.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687848838_1737687827350_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6793032a936736429e699fb2",
    "name": "externallmg_1737687849021_1737687827350_image_13.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687849021_1737687827350_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679310b7936736429e69a74e",
    "name": "externallmg_1737691307761_1737691306069_image_0.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737691307761_1737691306069_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "679310b7936736429e69a74f",
    "name": "externallmg_1737691314637_1737691306069_image_1.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737691314637_1737691306069_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fe3",
    "name": "externallmg_1737687888844_1737687886176_image_0.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687888844_1737687886176_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fe4",
    "name": "externallmg_1737687889494_1737687886176_image_1.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687889494_1737687886176_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fe5",
    "name": "externallmg_1737687890433_1737687886176_image_2.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687890433_1737687886176_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fe6",
    "name": "externallmg_1737687891549_1737687886176_image_3.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687891549_1737687886176_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fe7",
```

```
    "name": "externallmg_1737687892488_1737687886176_image_4.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687892488_1737687886176_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fe8",
    "name": "externallmg_1737687893252_1737687886176_image_5.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687893252_1737687886176_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fe9",
    "name": "externallmg_1737687894102_1737687886176_image_6.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687894102_1737687886176_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fea",
    "name": "externallmg_1737687895953_1737687886176_image_7.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687895953_1737687886176_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699feb",
    "name": "externallmg_1737687897393_1737687886176_image_8.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687897393_1737687886176_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fec",
    "name": "externallmg_1737687898308_1737687886176_image_9.jpeg",
```

```
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687898308_1737687886176_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fed",
    "name": "externallmg_1737687899393_1737687886176_image_10.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687899393_1737687886176_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6793035d936736429e699fee",
    "name": "externallmg_1737687900408_1737687886176_image_11.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737687900408_1737687886176_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679310e022c790429f69e449",
    "name": "externallmg_1737691330927_1737691323551_image_0.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737691330927_1737691323551_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679310e022c790429f69e44a",
    "name": "externallmg_1737691338517_1737691323551_image_1.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737691338517_1737691323551_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679310e022c790429f69e44b",
    "name": "externallmg_1737691345223_1737691323551_image_2.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737691345223_1737691323551_image_2.jpeg",
```



```

    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679310e022c790429f69e44c",
    "name": "externallmg_1737691353512_1737691323551_image_3.jpeg",
    "path": "cases/67920e52936736429e694ba0/
externallmg_1737691353512_1737691323551_image_3.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-23T09:39:30.532Z",
"updatedAt": "2025-01-24T04:02:40.920Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1102, 12th Floor, Wing - A, AGARWAL
FLORENCE, Village - Pahadi, Goregaon West, Mumbai, 400062, State - Maharashtra,
India",
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Nilesh Agarwal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"reralId": "P51800032916",
"siteVisitContactNo": "9892417057"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---