

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63fc957bce84bf289baa55ec"
    },
    "firstName": "Rambhau",
    "type": "CREDITOFFICER",
    "_id": "67776c1382ea0d50e1005de8",
    "email": "sbi.051168@sbi.co.in",
    "lastName": "Taktewale",
    "mobileNo": "",
    "workMobileNo": "9561064635"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
  }
}
```

```
"discussWithPerson": "Rambhau",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63fc957bce84bf289baa55ec",
  "name": "SARB Churchgate",
  "branchCode": "",
  "mobileNo": "02222053163",
  "alternateMobileNo": "",
  "email": "sarc.mumbai@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "6th Floor, International 16, Maharshi Karve Road, Churchgate, Mumbai -
400020, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
```

```
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
    }
  ]
}
```

```
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.096619477560704",
  "longitude": "72.84911402625919"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84911402625919,
    19.096619477560704
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "23/01/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "10",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
```

```
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pragati Gulati Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nariman Road ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Nariman Tower",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```

```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```



```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400057",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vile Parle East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
```

```
"fairMarketValue": {
  "costOfConstruction": "",
  "depreciationPercentage": "",
  "depreciatedCostOfConstruction": "",
  "totalFairMarketValue": ""
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
```

```
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
  "label": "Lead",
  "value": "LEAD"
},
siteVisitType": "FULL",
isExternalReport": false,
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
```



```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67921351936736429e695455",
"ownerName": "Mr. Aniruddha Balkrishna Joshi And Mrs. Pallavi Aniruddha Joshi",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 1001,10 Floor, Pragati Gulati Heights,Nariman Road,Near
Nariman Tower,Vile Parel East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Old Valuation Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67921351936736429e695455/
document_1737626441831_4076066.pdf",
    "fileName": "document_1737626441831_4076066.pdf",
    "id": "122160",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Thu Jan 23 2025 10:00:49 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1737630106519_Valuation_Report_Aniruddha_Joshi.pdf",
    "path": "cases/67921351936736429e695455/
document_1737630106519_Valuation_Report_Aniruddha_Joshi.pdf",
    "id": "913897",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Jan 23 2025 11:01:48 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013863",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
```

```
"id": "518690",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Thu Jan 23 2025 10:00:49 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Aniruddha Balkrishna Joshi And Mrs. Pallavi Aniruddha Joshi",
"phone": "0000000000",
"ownershipShare": "",
"email": "",
"id": "112972"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "679223b97d5dfa42c9caccc7",
"name": "externalImg_1737630646107_1737630643250_image_0.jpeg",
"path": "cases/67921351936736429e695455/externalImg_1737630646107_1737630643250_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "679223b97d5dfa42c9caccc8",
"name": "externalImg_1737630646460_1737630643250_image_1.jpeg",
"path": "cases/67921351936736429e695455/externalImg_1737630646460_1737630643250_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "679223b97d5dfa42c9caccc9",
```

```
    "name": "externallmg_1737630646620_1737630643250_image_2.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630646620_1737630643250_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9caccca",
    "name": "externallmg_1737630646738_1737630643250_image_3.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630646738_1737630643250_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9cacccb",
    "name": "externallmg_1737630646897_1737630643250_image_4.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630646897_1737630643250_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9cacccc",
    "name": "externallmg_1737630647011_1737630643250_image_5.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630647011_1737630643250_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9cacccd",
    "name": "externallmg_1737630647130_1737630643250_image_6.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630647130_1737630643250_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9caccce",
    "name": "externallmg_1737630647442_1737630643250_image_7.jpeg",
```

```
    "path": "cases/67921351936736429e695455/
externallmg_1737630647442_1737630643250_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9cacccf",
    "name": "externallmg_1737630647601_1737630643250_image_8.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630647601_1737630643250_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9caccd0",
    "name": "externallmg_1737630647697_1737630643250_image_9.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630647697_1737630643250_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9caccd1",
    "name": "externallmg_1737630647927_1737630643250_image_10.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630647927_1737630643250_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9caccd2",
    "name": "externallmg_1737630648109_1737630643250_image_11.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630648109_1737630643250_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "679223b97d5dfa42c9caccd3",
    "name": "externallmg_1737630648217_1737630643250_image_12.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630648217_1737630643250_image_12.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679223b97d5dfa42c9caccd4",
  "name": "externallmg_1737630648354_1737630643250_image_13.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630648354_1737630643250_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679223b97d5dfa42c9caccd5",
  "name": "externallmg_1737630648501_1737630643250_image_14.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630648501_1737630643250_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679223b97d5dfa42c9caccd6",
  "name": "externallmg_1737630648634_1737630643251_image_15.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630648634_1737630643251_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679223b97d5dfa42c9caccd7",
  "name": "externallmg_1737630648840_1737630643251_image_16.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630648840_1737630643251_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679223b97d5dfa42c9caccd8",
  "name": "externallmg_1737630649052_1737630643251_image_17.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630649052_1737630643251_image_17.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "679223b97d5dfa42c9caccd9",
      "name": "externallmg_1737630649146_1737630643251_image_18.jpeg",
      "path": "cases/67921351936736429e695455/
externallmg_1737630649146_1737630643251_image_18.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "679223b97d5dfa42c9cacdda",
      "name": "externallmg_1737630649362_1737630643251_image_19.jpeg",
      "path": "cases/67921351936736429e695455/
externallmg_1737630649362_1737630643251_image_19.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "679224247d5dfa42c9cacda9",
      "name": "externallmg_1737630743293_1737630740699_image_0.jpeg",
      "path": "cases/67921351936736429e695455/
externallmg_1737630743293_1737630740699_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "679224247d5dfa42c9cacdaa",
      "name": "externallmg_1737630744906_1737630740699_image_1.jpeg",
      "path": "cases/67921351936736429e695455/
externallmg_1737630744906_1737630740699_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "679224247d5dfa42c9cacdab",
      "name": "externallmg_1737630745959_1737630740699_image_2.jpeg",
      "path": "cases/67921351936736429e695455/
externallmg_1737630745959_1737630740699_image_2.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacadac",
  "name": "externallmg_1737630747012_1737630740699_image_3.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630747012_1737630740699_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacadad",
  "name": "externallmg_1737630748114_1737630740699_image_4.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630748114_1737630740699_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacdae",
  "name": "externallmg_1737630748449_1737630740699_image_5.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630748449_1737630740699_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacdaf",
  "name": "externallmg_1737630749020_1737630740699_image_6.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630749020_1737630740699_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacdb0",
  "name": "externallmg_1737630749414_1737630740699_image_7.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630749414_1737630740699_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679224247d5dfa42c9cacdb1",
    "name": "externallmg_1737630749901_1737630740699_image_8.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630749901_1737630740699_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679224247d5dfa42c9cacdb2",
    "name": "externallmg_1737630750542_1737630740699_image_9.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630750542_1737630740699_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679224247d5dfa42c9cacdb3",
    "name": "externallmg_1737630751069_1737630740699_image_10.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630751069_1737630740699_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679224247d5dfa42c9cacdb4",
    "name": "externallmg_1737630751592_1737630740699_image_11.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630751592_1737630740699_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679224247d5dfa42c9cacdb5",
    "name": "externallmg_1737630752138_1737630740700_image_12.jpeg",
    "path": "cases/67921351936736429e695455/
externallmg_1737630752138_1737630740700_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "679224247d5dfa42c9cacdb6",
  "name": "externallmg_1737630752663_1737630740700_image_13.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630752663_1737630740700_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacdb7",
  "name": "externallmg_1737630753068_1737630740700_image_14.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630753068_1737630740700_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacdb8",
  "name": "externallmg_1737630753706_1737630740700_image_15.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630753706_1737630740700_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacdb9",
  "name": "externallmg_1737630754187_1737630740700_image_16.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630754187_1737630740700_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679224247d5dfa42c9cacdba",
  "name": "externallmg_1737630754593_1737630740700_image_17.jpeg",
  "path": "cases/67921351936736429e695455/
externallmg_1737630754593_1737630740700_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "679224247d5dfa42c9cacdbb",
    "name": "externalimg_1737630754758_1737630740700_image_18.jpeg",
    "path": "cases/67921351936736429e695455/
externalimg_1737630754758_1737630740700_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679224247d5dfa42c9cacdbc",
    "name": "externalimg_1737630755276_1737630740700_image_19.jpeg",
    "path": "cases/67921351936736429e695455/
externalimg_1737630755276_1737630740700_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-23T10:00:49.304Z",
"updatedAt": "2025-01-23T11:12:36.172Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1001, 10th Floor, Pragati Gulati Heights, Nariman
Road , Near Nariman Tower, Vile Parle East, Mumbai, 400057",
"updatedBy": "62550ed0aba01e0af98f2f75",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Aniruddha Balkrishna Joshi And Mrs. Pallavi Aniruddha
Joshi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "0000000000"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			