

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Uttam",
    "type": "CREDITOFFICER",
    "_id": "64cb5e480faf29427aca80c8",
    "lastName": "Sanap",
    "mobileNo": "02225009143",
    "workMobileNo": "7028022330",
    "email": "racpc.ghatkopar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
```

```
"discussWithPerson": "Uttam",
"expectedFees": null,
"quotedAmount": "2500"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
```

```
"_id": "60e03dac6576061dae462469",
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63fc4680ce84bf289ba9c7fc",
    "role": "SITEENGINEER",
    "firstName": "Nikhil ",
    "email": "valtechnical2022@gmail.com",
    "lastName": "Sonawane",
    "mobileNo": "9819470709",
    "designation": "",
    "shortName": "NS",
    "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
    "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
```

```
"type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
```

```
{
  "title": {
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.187849830585492",
  "longitude": "73.04429707901738"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.04429707901738,
    19.187849830585492
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-11",
      "remark": "NPA Account "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-10",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"schedule": []
}
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dawale",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "12",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "A",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Radhe Krishna Residency",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nirmal Nagari Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "4, Hissa No. 14",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 612",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Diva (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "External_site_visit_only",
"label": "External site visit only"
},
"doors": {
"value": "Teak_wood_door_frame_with_solid_flush_door",
"label": "Teak wood door frame with solid flush door"
},
"windows": {
"value": "External_site_visit_only",
"label": "External site visit only"
},
"fittings": {
"value": "External_site_visit_only",
"label": "External site visit only"
},
"finishing": {
"value": "External_site_visit_only",
"label": "External site visit only"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Thane_Municipal_Corporation",
"label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
```

```

"north": "Open Plot",
"west": "Internal Road & Ramchandra Residency",
"south": "Road",
"east": "Wing - B"
},
"asPerDocumentAgreement": {
  "north": "Natural Pond",
  "west": "Hissa No. 10",
  "south": "12 Meter DP Road",
  "east": "Survey No. 3"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "External Site Visit Only",
    "east": "External Site Visit Only",
    "south": "External Site Visit Only",
    "west": "External Site Visit Only"
  },
  "asPerDocument": {
    "north": "Flat No. 1201",
    "east": "Marginal Space",
    "south": "Marginal Space",
    "west": "Passage & Flat No. 1203"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "At the time of visit, the property was locked hence internal
site inspection and photographs could not be taken. Hence, our report is based on
external visit & documents provided by bank only. As per Approved Plan, the
composition of Residential Flat is 1 Bedroom + Living Room + Kitchen + 2 Toilets.",
"dateOfIssusApprovePlan": "Copy of Approved Plan Document No. V.P. No. S11 /

```

0194 / 18 - TMC / TDD / 4257 / 22 dated 25.11.2022 issued by Thane Municipal Corporation",

```
"approvePlanVerified": "N.A.",  
"empanelledOfApprovePlan": "No",  
"unauthorizedConstruction": "",  
"extraDetailOfBuilding": "",  
"compoundWall": ""
```

```
},
```

```
"apfDetails": {  
  "buildings": [],  
  "compositions": []
```

```
},
```

```
"compositeRate": {
```

"remark": "At the time of visit, the property was locked hence internal site inspection and photographs could not be taken. Hence, our report is based on external visit & documents provided by bank only.",

```
"depreciationPercentage": "",  
"depreciationRatioOfBuilding": "",  
"salvageValue": "",  
"depreciatedCostOfConstruction": "",  
"depreciatedBuildingRate": ""
```

```
},
```

```
"igrRate": {
```

```
"propertyName": "Residential",  
"rate": "52300",  
"landRate": "10400",  
"igrImage": "cases/6794bfe55e0680e107366379/igr_1739344222170_Image.png",  
"squareMeterGuideLineRate": "57530.00",  
"squareFeetGuideLineRate": "5345.00"
```

```
},
```

```
"igrFinalRate": {
```

```
"floorRatePercentage": "10",  
"depreciationPercentage": "0",  
"rate": "52300.00",  
"squareMeterGuideLineRate": "57530.00",  
"squareFeetGuideLineRate": "5345.00"
```

```
},
```

```
"outgoingDetail": {
```

```
"areaStatusList": {  
  "value": "Medium",  
  "label": "Medium"
```

```
},
```

```
"propertyTypeOfUseList": {
```

```
"value": "Residential_Purpose",  
"label": "Residential Purpose"
```

```
},
```

```
"propertyOccupiedByList": {
  "value": "External_Site_Visit_Only",
  "label": "External Site Visit Only"
},
"monthlyRent": "9,000/- (Expected rental income per month)",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "External Site Visit Only"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
```

```
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
```

```
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "13",
"flatFloorNo": "12",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "9"
```



```
},
"finalPlinthArea": {
  "area": "437.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6794bfe55e0680e107366379/
routeMap_1739347354966_Image.png",
    "routeLat": "19.162701",
    "routeLng": "73.048241",
    "stationName": "Diva Junction",
    "routeDistance": "3.2 Km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "rm5hls",
      "name": "rm5hls",
      "image": "cases/6794bfe55e0680e107366379/
routeMap_1739347281432_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
}
```

```
},
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3582000.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "3582000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2340041.00",
  "selectedBuildUpValue": "437.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67ab33b819ca979ae9474fa8",
      "name": "externallmg_r_1739273132252_1739273127065_image_4.jpg",
      "path": "cases/6794bfe55e0680e107366379/externallmg_r_1739273132252_1739273127065_image_4.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "67ab33b819ca979ae9474fb2",
      "name": "externallmg_r_1739273139353_1739273127065_image_12.jpg",
      "path": "cases/6794bfe55e0680e107366379/externallmg_r_1739273139353_1739273127065_image_12.jpg",
```

```
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "67ab33b819ca979ae9474faf",
    "name": "externallmg_r_1739273137638_1739273127065_image_10.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273137638_1739273127065_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ab33b819ca979ae9474fa9",
    "name": "externallmg_r_1739273131358_1739273127065_image_3.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273131358_1739273127065_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ab33b819ca979ae9474fa8",
    "name": "externallmg_r_1739273132252_1739273127065_image_4.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273132252_1739273127065_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ab33b819ca979ae9474fad",
    "name": "externallmg_r_1739273133132_1739273127065_image_5.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273133132_1739273127065_image_5.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "67ab33b819ca979ae9474fb1",
    "name": "externallmg_r_1739273136888_1739273127065_image_9.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273136888_1739273127065_image_9.jpg",
    "orientation": "portrait"
  }
]
```

```
    }
  ],
  "compositionImages": [],
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8649.00",
    "max": "9670.00"
  },
  "builtUpRateRange": {
    "min": "7863.00",
    "max": "8791.00"
  },
  "saleableRateRange": {
    "min": "5649.00",
    "max": "5649.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```



```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "398.00",
"empanelmentNo": [
  "SME/TCC/2021-22/85/13"
],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6794bfe55e0680e107366379",
"ownerName": "Mrs. Poonam Umesh Nishad & Mr. Umesh Ramkewal Nishad",
"ownerPhoneNo": "9833818663",
"appAddress": "Flat no. 1202, 12th Floor, Building - A, Radha Krishna Residency, Near
Nirmal Nagari, Diva East ",
"remark": "NPA Account ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "20/01/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Mangalam Infra",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mrs. Poonam Umesh Nishad & Mr. Umesh Ramkewal Nishad",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "1538/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "908293",
    "path": "cases/6794bfe55e0680e107366379/
document_1738992221280_POONAM_NISHAD_1202_2.pdf",
    "fileName": "document_1738992221280_POONAM_NISHAD_1202_2.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
```

```
"label": "RERA Certificate"
},
"inputs": {
  "documentDate": "08/09/2021",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P51700022023"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1739348624728_rera.pdf",
"path": "cases/6794bfe55e0680e107366379/document_1739348624728_rera.pdf",
"id": "242551",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Feb 12 2025 08:23:45 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "V.P. No. S11 / 0194 / 18 - TMC / TDD / 4257 / 22 dated
25.11.2022"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1739348670881_CC.pdf",
  "path": "cases/6794bfe55e0680e107366379/document_1739348670881_CC.pdf",
  "id": "819891",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Feb 12 2025 08:24:31 GMT+0000 (Coordinated Universal Time)"
}
```

```
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "V.P. No. S11 / 0194 / 18 - TMC / TDD / 4257 / 22 dated
25.11.2022"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1739348686339_pLAN.pdf",
    "path": "cases/6794bfe55e0680e107366379/document_1739348686339_pLAN.pdf",
    "id": "370600",
    "uploadedBy": "627221f4afd7d55eddeddcb4",
    "createdAt": "Wed Feb 12 2025 08:24:48 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "31/03/2024",
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "TMCB / FO / 2024 / APL / 00081"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1739348740251_OC.pdf",
```

```
"path": "cases/6794bfe55e0680e107366379/document_1739348740251_OC.pdf",
"id": "906042",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Feb 12 2025 08:25:41 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "013935",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
"id": "995170",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Sat Jan 25 2025 10:41:41 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mrs. Poonam Umesh Nishad & Mr. Umesh Ramkewal Nishad",
"phone": "9833818663",
"ownershipShare": "",
"email": "",
"id": "623632"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "462755",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "398",
"squareMeterArea": "36.98",
"docFinalBuiltUp": "437.8",
"docFinalBuiltUpSquareMeter": "40.678",
```

```
"docBuiltpPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "398.00",
"squareMeterArea": "36.98",
"expectedRate": "9296.48",
"percentage": ""
},
"builtUpArea": {
"area": "437.80",
"squareMeterArea": "40.67",
"expectedRate": "8451.35",
"percentage": "10"
},
"saleableArea": {
"area": "655",
"squareMeterArea": "60.85",
"expectedRate": "5648.85",
"percentage": ""
},
"printlnReport": true,
"_id": "67ac4a0ad716769af0d55ae5",
"property": "Radhe Krishna Residency, Diva",
"area": "398",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "square_yards",
"expectedPrice": "3700000",
"expectedRate": "9296.48",
"builtUpExpectedRate": "8451.35",
"image": "cases/6794bfe55e0680e107366379/
indicator_1739343869114_Image.png",
"squareMeter": "36.98",
"id": "442492"
},
{
```

```
"carpetArea": {
  "area": "430.00",
  "squareMeterArea": "39.95",
  "expectedRate": "9302.33",
  "percentage": ""
},
"builtUpArea": {
  "area": "473.00",
  "squareMeterArea": "43.94",
  "expectedRate": "8456.66",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67ac4a0ad716769af0d55ae6",
"property": "Radhe Krishna Residency, Diva",
"area": "430",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Housing.Com",
"expectedPrice": "4000000",
"expectedRate": "9302.33",
"builtUpExpectedRate": "8456.66",
"image": "cases/6794bfe55e0680e107366379/
indicator_1739343955068_Image.png",
"squareMeter": "39.95",
"id": "830575"
},
{
  "carpetArea": {
    "area": "393.00",
    "squareMeterArea": "36.51",
    "expectedRate": "9669.21",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "432.30",
    "squareMeterArea": "40.16",
```

```
    "expectedRate": "8790.19",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "67ac4a0ad716769af0d55ae7",
  "property": "Radhe Krishna Residency, Diva",
  "area": "393",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "1",
  "source": "Index_no.2",
  "expectedPrice": "3800000",
  "expectedRate": "9669.21",
  "builtUpExpectedRate": "8790.19",
  "image": "cases/6794bfe55e0680e107366379/
indicator_1739344027629_Image.png",
  "squareMeter": "36.51",
  "id": "112817"
},
{
  "carpetArea": {
    "area": "344.00",
    "squareMeterArea": "31.96",
    "expectedRate": "8648.26",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "378.40",
    "squareMeterArea": "35.15",
    "expectedRate": "7862.05",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
}
```



```
"printlnReport": true,
  "_id": "67ac4a0ad716769af0d55ae8",
  "property": "Radhe Krishna Residency, Diva",
  "area": "344",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "12",
  "source": "Index_no.2",
  "expectedPrice": "2975000",
  "expectedRate": "8648.26",
  "builtUpExpectedRate": "7862.05",
  "image": "cases/6794bfe55e0680e107366379/
indicator_1739344082526_Image.png",
  "squareMeter": "31.96",
  "id": "964198"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474fa6",
    "name": "externalImg_1739273129379_1739273127065_image_0.png",
    "path": "cases/6794bfe55e0680e107366379/
externalImg_1739273129379_1739273127065_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474fa7",
    "name": "externalImg_r_1739273130513_1739273127065_image_2.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externalImg_r_1739273130513_1739273127065_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474fa8",
    "name": "externalImg_r_1739273132252_1739273127065_image_4.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externalImg_r_1739273132252_1739273127065_image_4.jpg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474fa9",
    "name": "externallmg_r_1739273131358_1739273127065_image_3.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273131358_1739273127065_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474faa",
    "name": "externallmg_r_1739273129908_1739273127065_image_1.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273129908_1739273127065_image_1.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474fab",
    "name": "externallmg_r_1739273134184_1739273127065_image_6.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273134184_1739273127065_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474fac",
    "name": "externallmg_r_1739273135252_1739273127065_image_7.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273135252_1739273127065_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ab33b819ca979ae9474fad",
    "name": "externallmg_r_1739273133132_1739273127065_image_5.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273133132_1739273127065_image_5.jpg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ab33b819ca979ae9474fae",
  "name": "externallmg_r_1739273136153_1739273127065_image_8.jpg",
  "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273136153_1739273127065_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ab33b819ca979ae9474faf",
  "name": "externallmg_r_1739273137638_1739273127065_image_10.jpg",
  "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273137638_1739273127065_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ab33b819ca979ae9474fb0",
  "name": "externallmg_r_1739273138602_1739273127065_image_11.jpg",
  "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273138602_1739273127065_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ab33b819ca979ae9474fb1",
  "name": "externallmg_r_1739273136888_1739273127065_image_9.jpg",
  "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273136888_1739273127065_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ab33b819ca979ae9474fb2",
  "name": "externallmg_r_1739273139353_1739273127065_image_12.jpg",
  "path": "cases/6794bfe55e0680e107366379/
externallmg_r_1739273139353_1739273127065_image_12.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ab339b19ca979ae9474f66",
    "name": "externalimg_r_1739273113007_1739273102104_image_0.jpg",
    "path": "cases/6794bfe55e0680e107366379/
externalimg_r_1739273113007_1739273102104_image_0.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr_27508.pdf",
    "filename": "1739344272138_igr_27508.pdf",
    "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739344272138_igr_27508.pdf",
    "size": "156016",
    "createdAt": "Wed Feb 12 2025 07:11:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "84e9c4d5-f425-40f6-9372-8f93475d6d4b.pdf",
    "filename": "1739344272152_84e9c4d5f42540f693728f93475d6d4b.pdf",
    "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739344272152_84e9c4d5f42540f693728f93475d6d4b.pdf",
    "size": "604127",
    "createdAt": "Wed Feb 12 2025 07:11:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1719386343043_1717159298325_Calculation_1.xlsx",
    "filename":
"1739344272204_1719386343043_1717159298325_Calculation_1.xlsx",
    "path": "cases/6794bfe55e0680e107366379/processingDocuments/1739344272204
_1719386343043_1717159298325_Calculation_1.xlsx",
    "size": "1185319",
    "createdAt": "Wed Feb 12 2025 07:11:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_1589.pdf",
    "filename": "1739344272305_igr_1589.pdf",
    "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739344272305_igr_1589.pdf",
    "size": "189215",
    "createdAt": "Wed Feb 12 2025 07:11:12 GMT+0000 (Coordinated Universal Time)",
```

```
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "igr_26291.pdf",
  "filename": "1739344272411_igr_26291.pdf",
  "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739344272411_igr_26291.pdf",
  "size": "153398",
  "createdAt": "Wed Feb 12 2025 07:11:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "CC.pdf",
  "filename": "1739351202376_CC.pdf",
  "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739351202376_CC.pdf",
  "size": "1001668",
  "createdAt": "Wed Feb 12 2025 09:06:45 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "OC.pdf",
  "filename": "1739351203260_OC.pdf",
  "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739351203260_OC.pdf",
  "size": "1001663",
  "createdAt": "Wed Feb 12 2025 09:06:45 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "pLAN.pdf",
  "filename": "1739351204120_pLAN.pdf",
  "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739351204120_pLAN.pdf",
  "size": "2084857",
  "createdAt": "Wed Feb 12 2025 09:06:45 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "rera.pdf",
  "filename": "1739351205064_rera.pdf",
  "path": "cases/6794bfe55e0680e107366379/
processingDocuments/1739351205064_rera.pdf",
  "size": "151845",
  "createdAt": "Wed Feb 12 2025 09:06:45 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
```

```
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-25T10:41:41.224Z",
"updatedAt": "2025-02-12T11:30:38.241Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1202, 12th Floor, Building No A, Radhe Krishna
Residency, Nirmal Nagari Road, Village - Dawale, Diva (East), Taluka - Thane, District -
Thane, PIN Code - 400 612, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "No Person",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "-",
"rerald": "",
"siteVisitContactNo": "0000000000",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 398.00",
"flatRate": "9000",
"landOtherRate": "6500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
```

```

    },
    "leaseDetails": {
      "lessorName": "",
      "lesseeName": "",
      "leasePremium": "",
      "leaseRent": "",
      "leasePeriod": 0,
      "leaseFrom": "",
      "leaseTo": "",
      "remainingLeasePeriod": 0,
      "leaseDate": ""
    }
  },
  "finalSaleablePercentage": "0",
  "builtupPercentage": "10",
  "carpetTotal": "0",
  "extendOfSiteRemark": "",
  "finalBuiltupArea": "0.00",
  "finalCarpetArea": "0.00",
  "finalSalableArea": "0.00",
  "otherCarpetTotal": "0",
  "salablePercentage": "10",
  "siteMeasurementRemark": "",
  "toBeAdded": "",
  "reportGeneratedDate": "Wed Feb 12 2025 08:49:01 GMT+0000 (Coordinated
Universal Time)",
  "siteVisitDate": "2025-02-10"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			