

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cb"
    },
    "firstName": "Mukesh",
    "type": "CREDITOFFICER",
    "_id": "668bb759e61b5802e8d945d3",
    "email": "amt5so.09276@sbi.co.in",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7208509979"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "61546482",
    "discussWithPerson": "Mukesh",
    "expectedFees": 30773.241,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cb",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Diamond Branch (BKC)",
  "email": "sbi.09276@sbi.co.in",
  "mobileNo": "022-2675 2300",
  "alternateMobileNo": "",
  "address": "D/3, West Core, Bharat Dimond Bourse, Bandra-Kurla Complex, Bandra
(East), Mumbai - 400 051, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - BHARAT DIAMOND BRANCH",
  "fax": "022-2675 2381",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
```

```
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
      },
    ]
  }
]
```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.005348670234966",
  "longitude": "72.82861795440971"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82861795440971,
    19.005348670234966
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-29",
      "remark": ""
    }
  ],
  {
```

```
    "status": "COMPLETED",
    "dateTime": "2025-01-28",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-01-29",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-01-30",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-01-29",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Lower Parel Division",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "45",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Main",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Lower Parel, Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
```

```
"name": "Taluka",
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Trump Tower Mumbai Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp. Hard Rock Cafe",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Senapati Bapat Marg / Pandurang Budkar Marg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "464",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "4502",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "G/S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 013",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "ItalianMarbleFlooring",
    "label": "Italian Marble Flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
```

```
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "HigherClass",
    "label": "Higher Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Lodha Compound",
    "west": "IKEA Shop",
    "south": "Lodha Marquise",
    "east": "Lodha Park Compound"
  },
  "asPerDocumentAgreement": {
    "north": "Pandurang Budhkar Marg",
    "west": "Boundaries of Victoria Mills",
    "south": "Boundary Walls of Kamala Mills Limited",
    "east": "Senapati Bapat Marg and Parel Central Railway Station"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Marginal Space",
      "south": "Lift Lobby / Staircase",
      "west": "Marginal Space"
    },
    "asPerDocument": {
      "north": "Marginal Space",
      "east": "Marginal Space",
```

```

    "south": "Lift Lobby / Staircase",
    "west": "Marginal Space"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "+ Wardrobes Area<br/>\n\n1.\tAs per Agreement Sale Plan,
the composition of flat No. 4502 is Living/Dining + Kitchen + 3 Bedrooms + Kid's
Bedroom + 5 Toilets + Utility + Sotre + Puja + Shoe Rack. <br/>\n2.\tAs per Agreement
Sale Plan, the composition of Flat No. 4502 is Living/Dining + Kitchen + 2 Bedrooms +
Kid's Bedroom + Store + Puja + 3 Toiles + 1 WC. <br/>\n",
"dateOfIssusApprovePlan": "As Part Occupancy Certificate is received it may be
assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "Internal changes done",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "1.\tAs per Agreement Sale Plan, the composition of flat No. 4502 is Living/
Dining + Kitchen + 3 Bedrooms + Kid's Bedroom + 5 Toilets + Utility + Sotre + Puja +
Shoe Rack. <br/>\n2.\tAs per Agreement Sale Plan, the composition of Flat No. 4502 is
Living/Dining + Kitchen + 2 Bedrooms + Kid's Bedroom + Store + Puja + 3 Toiles + 1
WC. <br/>\n3.\tAs per site inspection, Flat No. 4502 & 4503 are internally amalgamated
with single entrance to form single flat. The composition of amalgamated flat is Living/
Dining + Kitchen + 3 Bedrooms + Servant Room + 3 Toilets + 1 WC + + Store Room +
Theater Area + Wardrobes. <br/> \n4.\tFor the purpose of valuation, we have

```

considered the agreement area of Flat No. 1502 only.
\n5. As per Further Commencement Certificate, Wing 4 is 3 Basements + Ground + 1st to 6th Podium + 7th (pt) Podium / refuge area / habitable + 8th to 78th (pt) upper floors for residential user.",

```
"depreciationPercentage": "9",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "59730",
"depreciatedBuildingRate": "2730"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "323420",
"landRate": "126110",
"igrImage": "cases/6763ad3231b0132fc581a353/igr_1738227618805_Image.png",
"squareMeterGuideLineRate": "388104.00",
"squareFeetGuideLineRate": "36056.00"
},
"igrFinalRate": {
"floorRatePercentage": "20",
"depreciationPercentage": "94",
"rate": "34596.00",
"squareFeetGuideLineRate": "34596.00",
"squareMeterGuideLineRate": "372384.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "I_Class",
"label": "I Class"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Tax Invoice Number : BCAM/24-25/1265",
"taxPaidHolderName": "Arun C. Shah / Meena A Shah / Amit A Shah",
"taxAmount": "Rs. 305/-",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per MCGM norms",
```

```
"tenantName": "",
"maintenanceOfFlat": "Excellent"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "3 Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2019",
    "fullDate": "1/1/2019"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  }
}
```

```
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
```



```
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "As_Per_Part_Occupancy_Certificate",
"label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "6",
"totalLifeBuilding": "60",
"estimatedAge": "54",
"noOfBasement": "4",
"noOfPodium": "7",
"noOfAmenityFloors": "",
"noOfFloors": "78",
"flatFloorNo": "45",
"noOfLifts": "6",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
"area": "1813.20",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/6763ad3231b0132fc581a353/
routeMap_1738321681546_Image.png",
"routeLat": "19.004805",
```

```
"routeLng": "72.828222",
"stationName": "Prabhadevi",
"routeDistance": "1.00 km ",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "cf0yxq",
    "name": "cf0yxq",
    "image": "cases/6763ad3231b0132fc581a353/
routeMap_1738321668898_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "3",
"othersRate": "1500000",
"totalothersRate": "4500000",
"finaltotal": "94752030.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "90252030.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "62729467.00",
"selectedBuildUpValue": "1813.20",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "679b434f49234c16a221445a",
"name": "externallmg_1738228558473_externallmg_1738149176597_1738149146439_image_0.jpeg",
"path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558473_externallmg_1738149176597_1738149146439_image_0.jpeg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "679b434f49234c16a2214455",
"name": "externallmg_1738228558413_externallmg_1738149068910_1738149061227_image_4.jpeg",
"path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558413_externallmg_1738149068910_1738149061227_image_4.jpeg",
"orientation": "portrait"
}
],
"externalPhotos": [
{
"status": false,
"_id": "679b434f49234c16a221445a",
"name": "externallmg_1738228558473_externallmg_1738149176597_1738149146439_image_0.jpeg",
```

```
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558473_externa
llmg_1738149176597_1738149146439_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "679b434f49234c16a2214456",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558443_externa
llmg_1738149069052_1738149061227_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b434f49234c16a2214458",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558447_externa
llmg_1738149069867_1738149061227_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b434f49234c16a221445c",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558504_externa
llmg_1738149177919_1738149146439_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b434f49234c16a2214460",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558532_externa
llmg_1738149180049_1738149146439_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b434f49234c16a2214463",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558549_externa
llmg_1738149180603_1738149146439_image_10.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144bc",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574021_externa
llmg_1738149180699_1738149146439_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144bd",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574054_externa
llmg_1738149181150_1738149146439_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144be",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574065_externa
llmg_1738149181243_1738149146439_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144bf",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574066_externa
llmg_1738149182258_1738149146439_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144c0",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574069_externa
llmg_1738149182873_1738149146439_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144c1",
    "name": "Living Room",
```



```
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574088_externa
llmg_1738149182910_1738149146439_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144c2",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574090_externa
llmg_1738149182969_1738149146439_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "679b435f49234c16a22144bb",
    "name": "Living Room",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574017_externa
llmg_1738149180687_1738149146439_image_11.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "56533.00",
    "max": "60589.00"
  },
  "builtUpRateRange": {
    "min": "51394.00",
    "max": "55081.00"
  },
  "saleableRateRange": {
    "min": "42829.00",
    "max": "45901.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1511.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6763ad3231b0132fc581a353",
"ownerName": "Mr. Arun C. Shah",
"ownerPhoneNo": "8433758339",
"appAddress": "flat no - B 4502 & 4503, 45th floor, Trump Tower, lower Parel ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/11/2014",
      "from": {
        "value": "Company",
        "label": "Company"
      },
      "Company": "Jawala Real Estate Private Limited",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Arun C. Shah, Mr. Amit A. Shah & Ms. Meena Shah",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      }
    }
  }
]
```

```
    },
    "Registration_No": " 5115/2014"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "512026",
  "path": "cases/6763ad3231b0132fc581a353/document_1734591888171_AGREEM
ENT_COPY_OF_FLAT_B_4502_ARUNBHAIAMIT_MEENA_SHAH.pdf",
  "fileName": "document_1734591888171_AGREEMENT_COPY_OF_FLAT_B_4502_
ARUNBHAIAMIT_MEENA_SHAH.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fb",
    "label": "Title Investigation Report"
  },
  "inputs": {
    "documentDate": "17/08/2023",
    "remark": " Ref. No. PC/IndusInd Bank Ltd. Prabhadevi (W) Br./LSR-133/23 issued
by Padiyar & Co."
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "114641",
  "path": "cases/6763ad3231b0132fc581a353/
document_1734591901814_TRUMP_TOWER_B4502_DT17082023.pdf",
  "fileName":
"document_1734591901814_TRUMP_TOWER_B4502_DT17082023.pdf"
},
{
  "documentType": {
    "value": "60ae125eaa6d152c1801b353",
    "label": "Maintenance Bill"
  },
  "inputs": {
    "remark": " No. BCAM/24-25/1265 dated 07/10/2024 in the name of Arun C. shah /
Meena A. Shah / Amit A. Shah issued by Trump Tower Mumbai Co-op. Hsg. Soc. Ltd."
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "879892",
  "path": "cases/6763ad3231b0132fc581a353/
document_1738303001555_B4502_ARUN_SHAH__Maintenance_Bill.pdf",
  "fileName":
"document_1738303001555_B4502_ARUN_SHAH__Maintenance_Bill.pdf"
},
}
```

```

{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "27/12/2019",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " EB/1342/GS/A/OCC/3/NEW"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "476478",
  "path": "cases/6763ad3231b0132fc581a353/document_1738303121959_OC.pdf",
  "fileName": "document_1738303121959_OC.pdf"
},
{
  "documentType": {
    "value": "60ae12b3aa6d152c1801b4dc",
    "label": "Further Commencement Certificate"
  },
  "inputs": {
    "remark": " No. EEBPC/1342/GS/A dated11/12/2018 issued by Municipal Corporation of Greater Mumbai.."
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "641140",
  "path": "cases/6763ad3231b0132fc581a353/document_1738323684097_FCC_REPORT.pdf",
  "fileName": "document_1738323684097_FCC_REPORT.pdf"
}
],
"caseNumber": "013173",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "192364",
    "title": "Create Lead",
  }
]

```

```
"description": "Create Lead",
"datetime": "Thu Dec 19 2024 05:20:50 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Arun C. Shah",
"phone": "8433758339",
"ownershipShare": "",
"email": "",
"id": "367817"
},
{
"name": "Mr. Amit A. Shah",
"phone": "",
"email": "",
"ownershipShare": "",
"panNo": "",
"aadharNo": "",
"id": "335999"
},
{
"name": "Ms. Meena Shah",
"phone": "",
"email": "",
"ownershipShare": "",
"panNo": "",
"aadharNo": "",
"id": "706028"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "564648",
"name": "Passage",
"length": "12.25",
"length1": "12",
"length2": "3",
"width": "9.17",
"width1": "9",
```

```
"width2": "2",
"totalArea": "112.29",
"images": [],
"extraAreas": [],
"finalArea": "112.29"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "17",
  "name": "Living Room",
  "length": "",
  "length1": "35",
  "length2": "4",
  "width": "",
  "width1": "25",
  "width2": "1",
  "totalArea": "886.28",
  "images": [],
  "finalArea": "887.4499999999999",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "28.72",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.72"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
```



```
},
  "id": "4",
  "name": "Servent Room",
  "length": "6.00",
  "length1": "6",
  "length2": "6",
  "width": "2.33",
  "width1": "6",
  "width2": "0",
  "totalArea": "39.00",
  "images": [],
  "finalArea": "39.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "2.33",
  "width1": "2",
  "width2": "4",
  "totalArea": "14.97",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.97"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "12.83",
  "length1": "12",
  "length2": "10",
  "width": "11.08",
  "width1": "11",
  "width2": "1",
  "totalArea": "142.24",
```

```
"images": [],
"extraAreas": [],
"finalArea": "142.24"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "15.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "16.67",
  "length1": "16",
  "length2": "8",
  "width": "16.00",
  "width1": "16",
  "width2": "00",
  "totalArea": "266.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "266.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
```

```
"name": "Passage",
"length": "23.42",
"length1": "23",
"length2": "5",
"width": "3.50",
"width1": "3",
"width2": "6",
"totalArea": "81.96",
"images": [],
"extraAreas": [],
"finalArea": "81.96"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Sitting Room",
  "length": "15.25",
  "length1": "15",
  "length2": "3",
  "width": "12.00",
  "width1": "12",
  "width2": "00",
  "totalArea": "183.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "183.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "17.50",
  "length1": "17",
  "length2": "6",
  "width": "12.08",
  "width1": "12",
  "width2": "1",
  "totalArea": "211.46",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "211.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "51.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "51.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "18.42",
  "length1": "18",
  "length2": "5",
  "width": "14.08",
  "width1": "14",
  "width2": "1",
  "totalArea": "259.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "259.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Toilet",
  "length": "14.33",
```

```
"length1": "14",
"length2": "4",
"width": "6.08",
"width1": "6",
"width2": "1",
"totalArea": "87.19",
"images": [],
"extraAreas": [],
"finalArea": "87.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "14",
  "name": "WC",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "15.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "15",
  "name": "Toilet",
  "length": "14.33",
  "length1": "14",
  "length2": "4",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "87.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "87.19"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "16",
  "name": "Store Room",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "15.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.46"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Wardrobes",
      "value": "Wardrobes"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "",
    "length1": "14",
    "length2": "4",
    "width": "",
    "width1": "8",
    "width2": "4",
    "totalArea": "119.44",
    "images": [],
    "extraAreas": [],
    "finalArea": "119.44",
    "percentageBeforeTotal": "119.44",
    "percentage": "100"
  }
]
```

```
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "234830",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1511",
    "squareMeterArea": "140.38",
    "docFinalBuiltUp": "1813.2",
    "docFinalBuiltUpSquareMeter": "168.456",
    "docBuiltpPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "1300.00",
      "squareMeterArea": "120.77",
      "expectedRate": "59230.77",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1430.00",
      "squareMeterArea": "132.85",
      "expectedRate": "53846.15",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "1716.00",
      "squareMeterArea": "159.42",
      "expectedRate": "44871.79",
      "percentage": "20"
    }
  },
]
```

```
"printlnReport": true,
"_id": "679b3ff149234c16a2213cf3",
"property": "Residential Flat",
"area": "1300",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "77000000",
"expectedRate": "59230.77",
"builtUpExpectedRate": "53846.15",
"image": "cases/6763ad3231b0132fc581a353/
indicator_1738227368256_Image.png",
"squareMeter": "120.77",
"id": "901520"
},
{
  "carpetArea": {
    "area": "1546.00",
    "squareMeterArea": "143.63",
    "expectedRate": "56532.99",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1700.60",
    "squareMeterArea": "157.99",
    "expectedRate": "51393.63",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "2040.72",
    "squareMeterArea": "189.59",
    "expectedRate": "42828.02",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "679b3ff149234c16a2213cf4",
  "property": "Residential Flat",
  "area": "1546",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
```



```
"source": "https://www.99acres.com/",
"expectedPrice": "87400000",
"expectedRate": "56532.99",
"builtUpExpectedRate": "51393.63",
"image": "cases/6763ad3231b0132fc581a353/
indicator_1738227430706_Image.png",
"squareMeter": "143.63",
"id": "926681"
},
{
"carpetArea": {
"area": "1511.00",
"squareMeterArea": "140.38",
"expectedRate": "57544.67",
"percentage": ""
},
"builtUpArea": {
"area": "1662.10",
"squareMeterArea": "154.41",
"expectedRate": "52313.34",
"percentage": "10"
},
"saleableArea": {
"area": "1994.52",
"squareMeterArea": "185.30",
"expectedRate": "43594.45",
"percentage": "20"
},
"printInReport": true,
"_id": "679b3ff149234c16a2213cf5",
"property": "Residential Flat",
"area": "1511",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "86950000",
"expectedRate": "57544.67",
"builtUpExpectedRate": "52313.34",
"image": "cases/6763ad3231b0132fc581a353/
indicator_1738227508671_Image.png",
"squareMeter": "140.38",
"id": "868139"
},
```

```
{
  "carpetArea": {
    "area": "1373.86",
    "squareMeterArea": "127.64",
    "expectedRate": "60588.42",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1511.25",
    "squareMeterArea": "140.40",
    "expectedRate": "55080.23",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "1813.50",
    "squareMeterArea": "168.48",
    "expectedRate": "45900.19",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "679b3ff149234c16a2213cf6",
  "property": "Residential Flat",
  "area": "1511.25",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "83240000",
  "expectedRate": "60588.42",
  "builtUpExpectedRate": "83240000",
  "image": "cases/6763ad3231b0132fc581a353/
indicator_1738227571249_Image.png",
  "squareMeter": "140.40",
  "id": "852284"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679a0d3f115bdf16690a03b9",
    "name": "externalImg_1738149177501_1738149146439_image_1.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/
externalImg_1738149177501_1738149146439_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679a0ccf7dd57116683cd380",
  "name": "externallmg_1738149067705_1738149061227_image_0.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/
externallmg_1738149067705_1738149061227_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679a0ccf7dd57116683cd381",
  "name": "externallmg_1738149067780_1738149061227_image_1.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/
externallmg_1738149067780_1738149061227_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679a0ccf7dd57116683cd382",
  "name": "externallmg_1738149068699_1738149061227_image_2.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/
externallmg_1738149068699_1738149061227_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "679a0ccf7dd57116683cd383",
  "name": "externallmg_1738149068786_1738149061227_image_3.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/
externallmg_1738149068786_1738149061227_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679b434f49234c16a2214455",
  "name": "externallmg_1738228558413_externallmg_1738149068910_17381490612
27_image_4.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558413_externall
mg_1738149068910_1738149061227_image_4.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a2214456",
    "name": "externallmg_1738228558443_externallmg_1738149069052_17381490612
27_image_5.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558443_externall
mg_1738149069052_1738149061227_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a2214457",
    "name": "externallmg_1738228558446_externallmg_1738149069363_17381490612
27_image_6.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558446_externall
mg_1738149069363_1738149061227_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a2214458",
    "name": "externallmg_1738228558447_externallmg_1738149069867_17381490612
27_image_7.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558447_externall
mg_1738149069867_1738149061227_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a2214459",
    "name": "externallmg_1738228558461_externallmg_1738149070294_17381490612
27_image_8.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558461_externall
mg_1738149070294_1738149061227_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a221445a",
```

```
    "name": "externallmg_1738228558473_externallmg_1738149176597_17381491464
39_image_0.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558473_externall
mg_1738149176597_1738149146439_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a221445b",
    "name": "externallmg_1738228558481_externallmg_1738149177683_17381491464
39_image_2.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558481_externall
mg_1738149177683_1738149146439_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a221445c",
    "name": "externallmg_1738228558504_externallmg_1738149177919_17381491464
39_image_3.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558504_externall
mg_1738149177919_1738149146439_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a221445d",
    "name": "externallmg_1738228558507_externallmg_1738149179131_17381491464
39_image_4.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558507_externall
mg_1738149179131_1738149146439_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b434f49234c16a221445e",
    "name": "externallmg_1738228558509_externallmg_1738149179156_17381491464
39_image_5.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558509_externall
mg_1738149179156_1738149146439_image_5.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679b434f49234c16a221445f",
  "name": "externallmg_1738228558521_externallmg_1738149180037_17381491464
39_image_6.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558521_externall
mg_1738149180037_1738149146439_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679b434f49234c16a2214460",
  "name": "externallmg_1738228558532_externallmg_1738149180049_17381491464
39_image_7.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558532_externall
mg_1738149180049_1738149146439_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679b434f49234c16a2214461",
  "name": "externallmg_1738228558534_externallmg_1738149180122_17381491464
39_image_8.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558534_externall
mg_1738149180122_1738149146439_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679b434f49234c16a2214462",
  "name": "externallmg_1738228558547_externallmg_1738149180583_17381491464
39_image_9.jpeg",
  "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558547_externall
mg_1738149180583_1738149146439_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679b434f49234c16a2214463",
  "name": "externallmg_1738228558549_externallmg_1738149180603_17381491464
39_image_10.jpeg",
```

```
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228558549_externallmg_1738149180603_1738149146439_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144bb",
    "name": "externallmg_1738228574017_externallmg_1738149180687_1738149146439_image_11.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574017_externallmg_1738149180687_1738149146439_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144bc",
    "name": "externallmg_1738228574021_externallmg_1738149180699_1738149146439_image_12.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574021_externallmg_1738149180699_1738149146439_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144bd",
    "name": "externallmg_1738228574054_externallmg_1738149181150_1738149146439_image_13.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574054_externallmg_1738149181150_1738149146439_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144be",
    "name": "externallmg_1738228574065_externallmg_1738149181243_1738149146439_image_14.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574065_externallmg_1738149181243_1738149146439_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "679b435f49234c16a22144bf",
    "name": "externallmg_1738228574066_externallmg_1738149182258_17381491464
39_image_15.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574066_externall
mg_1738149182258_1738149146439_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144c0",
    "name": "externallmg_1738228574069_externallmg_1738149182873_17381491464
39_image_16.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574069_externall
mg_1738149182873_1738149146439_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144c1",
    "name": "externallmg_1738228574088_externallmg_1738149182910_17381491464
39_image_17.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574088_externall
mg_1738149182910_1738149146439_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144c2",
    "name": "externallmg_1738228574090_externallmg_1738149182969_17381491464
39_image_18.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574090_externall
mg_1738149182969_1738149146439_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b435f49234c16a22144c3",
    "name": "externallmg_1738228574104_externallmg_1738149182985_17381491464
39_image_19.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/externallmg_1738228574104_externall
mg_1738149182985_1738149146439_image_19.jpeg",
```



```
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Ankit A. Shah And Mrs. Miki A. Shah -Flat No. 3601, 3701, 4502 &
4503 -State Bank of India ( Diamond Branch (BKC).xlsx",
    "filename": "1738227676519_Ankit_A_Shah_And_Mrs_Miki_A_Shah__Flat_No_360
1_3701_4502__4503_State_Bank_of_India__Diamond_Branch_BKC.xlsx",
    "path": "cases/6763ad3231b0132fc581a353/processingDocuments/1738227676519
_Ankit_A_Shah_And_Mrs_Miki_A_Shah__Flat_No_3601_3701_4502__4503_State_Ba
nk_of_India__Diamond_Branch_BKC.xlsx",
    "size": "1795559",
    "createdAt": "Thu Jan 30 2025 09:01:16 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1738326172132_OC.pdf",
    "path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326172132_OC.pdf",
    "size": "549698",
    "createdAt": "Fri Jan 31 2025 12:22:53 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Old Valuation Report.pdf",
    "filename": "1738326172144_Old_Valuation_Report.pdf",
    "path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326172144_Old_Valuation_Report.pdf",
    "size": "749962",
    "createdAt": "Fri Jan 31 2025 12:22:53 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2014 - 4502.pdf",
    "filename": "1738326172161_Sale_Deed__2014__4502.pdf",
    "path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326172161_Sale_Deed__2014__4502.pdf",
    "size": "4026457",
    "createdAt": "Fri Jan 31 2025 12:22:53 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
```

```
    "filename": "1738326172322_Site_Details.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326172322_Site_Details.jpeg",
    "size": "178005",
    "createdAt": "Fri Jan 31 2025 12:22:53 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sketch.jpeg",
    "filename": "1738326172671_Sketch.jpeg",
    "path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326172671_Sketch.jpeg",
    "size": "698971",
    "createdAt": "Fri Jan 31 2025 12:22:53 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Title 1.pdf",
    "filename": "1738326172684_Title_1.pdf",
    "path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326172684_Title_1.pdf",
    "size": "6884965",
    "createdAt": "Fri Jan 31 2025 12:22:53 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "AGREEMENT COPY OF FLAT B 4502 ARUNBHAI.AAMIT.
MEENA SHAH.pdf",
    "filename": "1738326187766_AGREEMENT_COPY_OF_FLAT_B_4502_ARUNBHA
IAAMIT_MEENA_SHAH.pdf",
    "path": "cases/6763ad3231b0132fc581a353/processingDocuments/1738326187766
_AGREEMENT_COPY_OF_FLAT_B_4502_ARUNBHAI.AAMIT_MEENA_SHAH.pdf",
    "size": "4013014",
    "createdAt": "Fri Jan 31 2025 12:23:08 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "APPROVED FLOOR PALN B 4502.jpg",
    "filename": "1738326187843_APPROVED_FLOOR_PALN_B_4502.jpg",
    "path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326187843_APPROVED_FLOOR_PALN_B_4502.jpg",
    "size": "2861318",
    "createdAt": "Fri Jan 31 2025 12:23:08 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
```

```
"originalname": "B-4502_ARUN SHAH - Maintenance Bill.pdf",
"filename": "1738326188045_B4502_ARUN_SHAH__Maintenance_Bill.pdf",
"path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326188045_B4502_ARUN_SHAH__Maintenance_Bill.pdf",
"size": "25197",
"createdAt": "Fri Jan 31 2025 12:23:08 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Boundaries.jpeg",
"filename": "1738326188046_Boundaries.jpeg",
"path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326188046_Boundaries.jpeg",
"size": "92681",
"createdAt": "Fri Jan 31 2025 12:23:08 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Dimention.jpeg",
"filename": "1738326188433_Dimention.jpeg",
"path": "cases/6763ad3231b0132fc581a353/
processingDocuments/1738326188433_Dimention.jpeg",
"size": "607158",
"createdAt": "Fri Jan 31 2025 12:23:08 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "679868ce2f3738a577c87acd",
"note": "Value Checked - pending for site visit",
"taskId": "6763c50a31b0132fc581d432",
"createdAt": "2025-01-28T05:19:10.655Z"
}
```

```
    },
    {
      "createdBy": {
        "_id": "64dc7184ccaf1e7b7f637f47",
        "role": "FRONTDESK",
        "firstName": "Binumon",
        "lastName": "Moozhickal",
        "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "679b7d9d115bdf16690b220c",
      "note": "value confirmed (Task Reopen)",
      "taskId": "6763c50a31b0132fc581d432",
      "createdAt": "2025-01-30T13:24:45.085Z"
    }
  ],
  "createdAt": "2024-12-19T05:20:50.084Z",
  "updatedAt": "2025-01-31T12:32:26.976Z",
  "__v": 0,
  "uniqueNo": "",
  "updatedBy": "60f91b6f344e052188ffd1fc",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 4502, 45th Floor, Wing - B, Trump Tower Mumbai
Co-op. Hsg. Soc. Ltd., Opp. Hard Rock Cafe, Senapati Bapat Marg / Pandurang Budkar
Marg, Village - Lower Parel Division, Municipality Ward No. G/S, District - Mumbai Main,
Lower Parel, Mumbai, PIN - 400 013, State - Maharashtra, India",
  "addressForMap": "",
  "caseReferredBy": "62723addafd7d55eddeddfe4",
  "contactPersonName": "Mr. Vikas Amberkar",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Office Staff",
  "reald": "",
  "siteVisitContactNo": "9619495973",
  "siteVisitDate": "2025-01-29",
  "buildingServicesRate": "3000",
```

```
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1511.00",
"flatRate": "60000",
"landOtherRate": "57000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Fri Jan 31 2025 00:00:00 GMT+0000 (Coordinated Universal Time)",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 4 Passage + Servent Room + 4 Toilet + Sitting Room + WC + Store Room",
"carpetTotal": "2499.4100000000003",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "3142.62",
"finalCarpetArea": "2618.85",
"finalSalableArea": "3142.62",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 2498.24\nWardrobes Area in Sq. Ft. = 119.44\n<br />\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
```

"otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "119.44",
 "otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Passage	12'3"	9'2"	112.29
Living Room	35'4"	25'1"	886.28
Passage	7'10"	3'8"	28.72
Servent Room	6'6"	6'0"	39.00
Toilet	6'5"	2'4"	14.97
Kitchen	12'10"	11'1"	142.24
Passage	4'10"	3'2"	15.31
Bedroom	16'8"	16'00"	266.67
Passage	23'5"	3'6"	81.96
Sitting Room	15'3"	12'00"	183.00
Bedroom	17'6"	12'1"	211.46
Toilet	7'9"	6'8"	51.67
Bedroom	18'5"	14'1"	259.37
Toilet	14'4"	6'1"	87.19
WC	4'5"	3'6"	15.46
Toilet	14'4"	6'1"	87.19
Store Room	4'5"	3'6"	15.46
Other Composition :			
Wardrobes	14'4"	8'4"	119.44