

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65f004d9857bdc098a9acc0e"
    },
    "firstName": "Vivek",
    "type": "CREDITOFFICER",
    "_id": "65f004d9857bdc098a9acc10",
    "lastName": "Rane",
    "mobileNo": "",
    "workMobileNo": "8758661331",
    "email": "bmthan4567@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65f004d9857bdc098a9acc0e",
  "name": "Virar West",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "bmthan4567@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "A-1/A-2, Ground Floor, Regancey CHSL, Agashi Road, Near Vijaya
Bank, Virar West"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "67776d60a5477d50e7dbc213",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "AJAY",
"email": "ajayrewale503@gmail.com",
"lastName": "REWALE",
"mobileNo": "9766640171",
"designation": "",
"shortName": "AJAY",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
```

```
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    }
  },

```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.424369101279307",
  "longitude": "72.82102956897592"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82102956897592,
    19.424369101279307
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-05",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
}
```

```
],
"schedule": [],
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"compositionFlatType": {
"value": "1BHK",
"label": "1 BHK"
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
"status": true,
"name": "Country",
"key": "country",
"value": "Country - India",
"label": false
},
"village": {
"status": true,
"name": "Village",
"key": "village",
"value": "Tulinj",
"label": true
},
"floorNo": {
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
"status": false,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Salasar Apartment Co-Op. Hsg. Soc. Ltd.",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "90, 92, 95, Hissa No. 3, 1, 3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B/G-2",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 209",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
```

```
    "value": "Nallasopara (East)",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "412.5",
  "depreciatedCostOfConstruction": "7087.50",
  "depreciatedBuildingRate": "2087.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "47800",
  "landRate": "13100",
  "igrImage": "cases/67a0593da2b18adef0cb44a6/igr_1738668941180_Image.png",
  "squareMeterGuideLineRate": "47800.00",
  "squareFeetGuideLineRate": "4441.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
```

```
"depreciationPercentage": "89",
"rate": "4086.00",
"squareFeetGuideLineRate": "4086.00",
"squareMeterGuideLineRate": "43983.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2014",
    "fullDate": "1/1/2014"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
```

```
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
},
```

```
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "49",
"ageOfBuilding": "11",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  }
},
"finalLatLng": {
  "coordinates": []
},
```

```
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "27",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "10.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "1675260.00",
  "selectedBuildUpValue": "410.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67a31ea4a92c39df2abdaed8",
      "name": "externallmg_1738743450692_1738743407908_image_14.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743450692_1738743407908_image_14.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67a31ea4a92c39df2abdaecb",
      "name": "externallmg_1738743427892_1738743407908_image_1.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743427892_1738743407908_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67a31ea4a92c39df2abdaeca",
      "name": "externallmg_1738743427562_1738743407907_image_0.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743427562_1738743407907_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67a31ea4a92c39df2abdaecc",
      "name": "externallmg_1738743430287_1738743407908_image_2.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743430287_1738743407908_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67a31ea4a92c39df2abdaed0",
      "name": "externallmg_1738743434178_1738743407908_image_6.jpeg",
```

```
    "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743434178_1738743407908_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67a31ea4a92c39df2abdaed1",
    "name": "externallmg_1738743435213_1738743407908_image_7.jpeg",
    "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743435213_1738743407908_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67a31ea4a92c39df2abdaed2",
    "name": "externallmg_1738743435942_1738743407908_image_8.jpeg",
    "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743435942_1738743407908_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67a31ea4a92c39df2abdaed9",
    "name": "externallmg_1738743452617_1738743407908_image_15.jpeg",
    "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743452617_1738743407908_image_15.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8229.00",
    "max": "10121.00"
  },
  "builtUpRateRange": {
    "min": "6858.00",
    "max": "8434.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```

```
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "410.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67a0593da2b18adef0cb44a6",
"ownerName": "Smt. Pushpa & Mr. Kapil Purohit",
"ownerPhoneNo": "9284490097",
"appAddress": "FLAT NO B/G-2 GROUND FLOOR B WING SALASAR APARTMENT
CHS LTD VILLAGE TULINJ NALLASOPARA EAST PALGHAR 401209",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "28/01/2025",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      }
    }
  }
]
```

```
},
"Transferor": "Mr. Vinod Hari Pandey & Mrs. Suman V. Pandey ",
"to": {
  "value": "Transferee",
  "label": "Transferee"
},
"Transferee": "Smt. Pushpa & Mr. Kapil Purohit ",
"number": {
  "value": "No",
  "label": "No"
},
"No": "1903 / 2025"
},
"isHardCopy": false,
"displayStatus": true,
"id": "213373",
"path": "cases/67a0593da2b18adef0cb44a6/
document_1738561611151_1738561609500_Kapil_purohit_agreement.pdf",
"fileName":
"document_1738561611151_1738561609500_Kapil_purohit_agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "26/06/2014",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "VVCMC / TP / POC / VP - 0583 / 58 / 2014 - 15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738755763242_OC.pdf",
  "path": "cases/67a0593da2b18adef0cb44a6/document_1738755763242_OC.pdf",
  "id": "699388",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Wed Feb 05 2025 11:42:43 GMT+0000 (Coordinated Universal Time)"
},
```

```
{
  "documentType": {
    "value": "60ae1259aa6d152c1801b33d",
    "label": "Revised Development Permission Certificate"
  },
  "inputs": {
    "documentDate": "17/01/2013",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "VVCMC/ TP / RDP / VP - 0583 / 0172 / 2012 - 13"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738755798331_OC.pdf",
  "path": "cases/67a0593da2b18adef0cb44a6/document_1738755798331_OC.pdf",
  "id": "226791",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Wed Feb 05 2025 11:43:18 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014071",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "990191",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Feb 03 2025 05:50:53 GMT+0000 (Coordinated Universal Time)"
  }
]
],
"owners": [
  {
    "name": "Smt. Pushpa & Mr. Kapil Purohit ",
    "phone": "9284490097",
    "ownershipShare": "",
    "email": "",
    "id": "434575"
  }
]
],
"proposePurchasers": [],
```



```
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "303391",
    "name": "Living Room",
    "length": "12.50",
    "length1": "12",
    "length2": "6",
    "width": "8.92",
    "width1": "8",
    "width2": "11",
    "totalArea": "111.46",
    "images": [],
    "extraAreas": [],
    "finalArea": "111.46"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "8.75",
    "length1": "8",
    "length2": "9",
    "width": "6.75",
    "width1": "6",
    "width2": "9",
    "totalArea": "59.06",
    "images": [],
    "extraAreas": [],
    "finalArea": "59.06"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Bedroom",
    "length": "7.08",
```

```
"length1": "7",
"length2": "1",
"width": "9.42",
"width1": "9",
"width2": "5",
"totalArea": "66.70",
"images": [],
"extraAreas": [],
"finalArea": "66.70"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "38.09",
    "totalAreaDocument": "410",
    "docBuiltpupPercentage": "",
    "docFinalBUILTUp": "0.00",
```

```
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "352393"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "472.50",
"squareMeterArea": "43.90",
"expectedRate": "8888.89",
"percentage": ""
},
"builtUpArea": {
"area": "567.00",
"squareMeterArea": "52.68",
"expectedRate": "7407.41",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67a1fb99a2b18adef0ccb1be",
"property": "Residential Flat",
"area": "567",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4200000.00",
"expectedRate": "8888.89",
"builtUpExpectedRate": "4200000.00",
"image": "cases/67a0593da2b18adef0cb44a6/
indicator_1738668721047_Image.png",
"squareMeter": "52.68",
"id": "217528"
},
```

```
{
  "carpetArea": {
    "area": "291.67",
    "squareMeterArea": "27.10",
    "expectedRate": "8228.48",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "350.00",
    "squareMeterArea": "32.52",
    "expectedRate": "6857.14",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67a1fb99a2b18adef0ccb1bf",
  "property": "Residential Flat",
  "area": "350",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "2400000",
  "expectedRate": "8228.48",
  "builtUpExpectedRate": "2400000",
  "image": "cases/67a0593da2b18adef0cb44a6/
indicator_1738668738792_Image.png",
  "squareMeter": "32.52",
  "id": "649935"
},
{
  "carpetArea": {
    "area": "345.83",
    "squareMeterArea": "32.13",
    "expectedRate": "10120.58",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "415.00",
```

```
"squareMeterArea": "38.55",
"expectedRate": "8433.73",
"percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67a1fb99a2b18adef0ccb1c0",
"property": "Residential Flat",
"area": "415",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "3500000",
"expectedRate": "10120.58",
"builtUpExpectedRate": "3500000",
"image": "cases/67a0593da2b18adef0cb44a6/
indicator_1738668869011_Image.png",
"squareMeter": "38.55",
"id": "216003"
},
{
  "carpetArea": {
    "area": "400",
    "squareMeterArea": "37.16",
    "expectedRate": "8750.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "463.00",
    "squareMeterArea": "43.01",
    "expectedRate": "7559.40",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```

```
    },
    "printlnReport": true,
    "_id": "67a1fb99a2b18adef0ccb1c1",
    "property": "Residential Flat",
    "area": "463",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Nobroker.com",
    "expectedPrice": "3500000",
    "expectedRate": "8750.00",
    "builtUpExpectedRate": "3500000",
    "image": "cases/67a0593da2b18adef0cb44a6/
indicator_1738668885539_Image.png",
    "squareMeter": "43.01",
    "id": "645672"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a31ea4a92c39df2abdaeca",
    "name": "externalImg_1738743427562_1738743407907_image_0.jpeg",
    "path": "cases/67a0593da2b18adef0cb44a6/
externalImg_1738743427562_1738743407907_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a31ea4a92c39df2abdaecb",
    "name": "externalImg_1738743427892_1738743407908_image_1.jpeg",
    "path": "cases/67a0593da2b18adef0cb44a6/
externalImg_1738743427892_1738743407908_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a31ea4a92c39df2abdaecc",
    "name": "externalImg_1738743430287_1738743407908_image_2.jpeg",
    "path": "cases/67a0593da2b18adef0cb44a6/
externalImg_1738743430287_1738743407908_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaecd",
  "name": "externallmg_1738743430637_1738743407908_image_3.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743430637_1738743407908_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaece",
  "name": "externallmg_1738743431212_1738743407908_image_4.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743431212_1738743407908_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaecf",
  "name": "externallmg_1738743431587_1738743407908_image_5.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743431587_1738743407908_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaed0",
  "name": "externallmg_1738743434178_1738743407908_image_6.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743434178_1738743407908_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaed1",
  "name": "externallmg_1738743435213_1738743407908_image_7.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743435213_1738743407908_image_7.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a31ea4a92c39df2abdaed2",
      "name": "externallmg_1738743435942_1738743407908_image_8.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743435942_1738743407908_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a31ea4a92c39df2abdaed3",
      "name": "externallmg_1738743437002_1738743407908_image_9.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743437002_1738743407908_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a31ea4a92c39df2abdaed4",
      "name": "externallmg_1738743439442_1738743407908_image_10.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743439442_1738743407908_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a31ea4a92c39df2abdaed5",
      "name": "externallmg_1738743442507_1738743407908_image_11.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743442507_1738743407908_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a31ea4a92c39df2abdaed6",
      "name": "externallmg_1738743445542_1738743407908_image_12.jpeg",
      "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743445542_1738743407908_image_12.jpeg",
      "orientation": "portrait"
    },
  },
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaed7",
  "name": "externallmg_1738743450032_1738743407908_image_13.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743450032_1738743407908_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaed8",
  "name": "externallmg_1738743450692_1738743407908_image_14.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743450692_1738743407908_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaed9",
  "name": "externallmg_1738743452617_1738743407908_image_15.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743452617_1738743407908_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaeda",
  "name": "externallmg_1738743454757_1738743407908_image_16.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743454757_1738743407908_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a31ea4a92c39df2abdaedb",
  "name": "externallmg_1738743457902_1738743407908_image_17.jpeg",
  "path": "cases/67a0593da2b18adef0cb44a6/
externallmg_1738743457902_1738743407908_image_17.jpeg",
  "orientation": "portrait"
},
{
```

```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67a3232cc6108fdeef48ed92",
"name": "externalImg_1738744614061_1738744603001_image_0.jpeg",
"path": "cases/67a0593da2b18adef0cb44a6/
externalImg_1738744614061_1738744603001_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67a3232cc6108fdeef48ed93",
"name": "externalImg_1738744616616_1738744603001_image_1.jpeg",
"path": "cases/67a0593da2b18adef0cb44a6/
externalImg_1738744616616_1738744603001_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67a3232cc6108fdeef48ed94",
"name": "externalImg_1738744619661_1738744603001_image_2.jpeg",
"path": "cases/67a0593da2b18adef0cb44a6/
externalImg_1738744619661_1738744603001_image_2.jpeg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "AGR.pdf",
"filename": "1738653400006_AGR.pdf",
"path": "cases/67a0593da2b18adef0cb44a6/
processingDocuments/1738653400006_AGR.pdf",
"size": "8705363",
"createdAt": "Tue Feb 04 2025 07:16:41 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "OC.pdf",
"filename": "1738653400186_OC.pdf",
"path": "cases/67a0593da2b18adef0cb44a6/
processingDocuments/1738653400186_OC.pdf",
"size": "615506",
"createdAt": "Tue Feb 04 2025 07:16:41 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
```

```
    },
    {
      "originalName": "Summary New=PUSHPA.xlsx",
      "filename": "1738669006071_Summary_NewPUSHPA.xlsx",
      "path": "cases/67a0593da2b18adef0cb44a6/
processingDocuments/1738669006071_Summary_NewPUSHPA.xlsx",
      "size": "2629042",
      "createdAt": "Tue Feb 04 2025 11:36:46 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "60eeaeddf3dd69653a581316",
        "role": "MAKER + RATE VERIFIER + CHEAKER",
        "firstName": "Shyam",
        "lastName": "Kajvilkar",
        "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "67a085a5c6108fdeef47810c",
      "note": "Total Composite \t 5,887.50 \n\t\nABU\t410\nFMV\t 24,13,875.00 \nRV\t
21,72,487.50 \nDV\t 19,31,100.00 \n",
      "taskId": "67a0593da2b18adef0cb44be",
      "createdAt": "2025-02-03T09:00:21.074Z"
    },
    {
      "createdBy": {
        "_id": "60eeaeddf3dd69653a581316",
        "role": "MAKER + RATE VERIFIER + CHEAKER",
        "firstName": "Shyam",
        "lastName": "Kajvilkar",
        "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "67a1bee8a92c39df2ab cdf90",
      "note": "Total Composite \t 6,187.50 \n\t\nABU\t410\nFMV\t 25,36,875.00 \nRV\t
```

```
22,83,187.50 \nDV\t 20,29,500.00 \n",
  "taskId": "67a0593da2b18adef0cb44be",
  "createdAt": "2025-02-04T07:16:56.663Z"
}
],
"createdAt": "2025-02-03T05:50:53.325Z",
"updatedAt": "2025-02-05T11:54:52.378Z",
"__v": 0,
"updatedBy": "62fe044a48a26047e6552796",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. B/G-2, Ground Floor, Wing - B, Salasar Apartment
Co-Op. Hsg. Soc. Ltd., Village - Tulinj, Nallasopara (East), Taluka - Vasai, District -
Palghar, PIN - 401 209, State - Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Smt. Pushpa & Mr. Kapil Purohit",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9284490097",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 410.00",
"flatRate": "7500",
"landOtherRate": "5000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
```

```

"carpetTotal": "178.16",
"extendOfSiteRemark": "",
"finalBuiltupArea": "290.64",
"finalCarpetArea": "264.22",
"finalSalableArea": "319.71",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet",
"reportGeneratedDate": "Wed Feb 05 2025 11:19:45 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-02-04",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	12'6"	8'11"	111.46
Kitchen	8'9"	6'9"	59.06
Bedroom	7'1"	9'5"	66.70
Toilet	4'00"	6'9"	27.00

Other
Composition :
