

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b949"
    },
    "firstName": "Vimal Soni",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f2a",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-7977761831"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "21838600",
    "discussWithPerson": "Vimal Soni",
    "expectedFees": 10919.300000000001,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank (Borivali) LTD",
  "displayName": "Janaseva Sahakari Bank (Borivali) LTD",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b949",
  "branchCode": "000002",
  "type": "BRANCH",
  "name": "Borivli (West) Branch",
  "email": "jssbl@mtnl.net.in",
  "mobileNo": "28332893",
  "alternateMobileNo": "",
  "address": "Aravali Business Centre(Phhol Mahal) Ramdas Surtale Marg Off
SOdawala Lane Boriwali (West) Mumbai 4000092",
  "ledgerName": "Janseva Sahakari Bank Borivali (W)",
  "fax": "28998842",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.17241215215466",
  "longitude": "72.94137713618682"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    72.94137713618682,
    19.17241215215466
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "3/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "30000",
  "lumpsumValue": "1",
  "rateMax": "31000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Lower Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Avior Corporate Park CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nirmal Galaxy ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "L B S MArg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "LG 28",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400080",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund West",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "Vitrified_Tile_Flooring"
  },
  "doors": {
    "label": "MS Rolling Shutter",
    "value": "MS_Rolling_Shutter"
  },
  "windows": {
    "label": "N.A.",
    "value": "N.A."
  },
  "fittings": {
    "label": "Concealed Plumbing with Conduit & Concealed Electrical wiring",
    "value": "Concealed_Plumbing_with_Conduit_&_Concealed_Electrical_wiring"
  },
  "finishing": {
```

```
    "label": "Cement plastering",
    "value": "Cement_plastering"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "polaris a, b tower",
    "west": "lbs marg",
    "south": "madan mohan malviya road",
    "east": "parking bldg mlcp"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
```

```
"buses": {
  "title": "Buses"
},
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
```

```
"label": "Yes",
"value": "Yes"
},
"carParking": {
  "label": "Open Car Parking",
  "value": "Open_Car_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"propertyTypeList": {
  "label": "Commercial",
  "value": "Commercial"
},
"planningArea": {
  "label": "Commercial",
  "value": "Commercial"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
```

```
"label": "No",
"value": "0"
},
"groundStilt": {
"label": "Lower Ground + Upper Ground Floor",
"value": "Lower_Ground+_Upper_Ground_Floor"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "8",
"flatFloorNo": "",
"noOfLifts": "08",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "032"
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
"coordinates": []
},
"locationMapImg": []
},
"valuation": {
"fairMarketValue": {
"costOfConstruction": "",
"depreciationPercentage": "",
"depreciatedCostOfConstruction": "",
"totalFairMarketValue": ""
}
},
"outward": {
"status": false,
```

```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
}
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67a07534c6108fdeef4771a4",
"ownerName": "Mr .Tejpal Singh Buttar ",
"ownerPhoneNo": "9224441517",
```

```
"appAddress": "Commercial Shop N LG -28 Lower Ground floor B-wing Avior
Corporate Park Co-Op Soc Ltd Nirmal Galaxy LBS Marg Mulund West Mumbai
400080",
"remark": "8691010101",
"documents": [
  {
    "documentType": {
      "label": "Old Valution Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67a07534c6108fdeef4771a4/
document_1738568998457_230551.pdf",
    "fileName": "document_1738568998457_230551.pdf",
    "id": "891399",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Feb 03 2025 07:50:11 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1738587431732_Shop_No_28__Tejpal_Singh_Buttar.pdf",
    "path": "cases/67a07534c6108fdeef4771a4/
document_1738587431732_Shop_No_28__Tejpal_Singh_Buttar.pdf",
    "id": "243206",
    "uploadedBy": "5ffe92d27737ca4d986b6453",
    "createdAt": "Mon Feb 03 2025 12:57:16 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014079",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "640134",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Feb 03 2025 07:50:12 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
```

```
"name": "Mr .Tejpal Singh Buttar ",
"phone": "9224441517",
"ownershipShare": "",
"email": "",
"id": "681701"
}
],
"proposePurchasers": [],
"siteInspection": [
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
}_id": "67a21baec6108fdeef488aec",
"area": "2047",
"providedByName": "Mr .Tejpal Singh Buttar ",
"providedByContactNo": "9224441517"
}
],
"composition": [
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "349618",
"name": "Living Room",
"length": "1.00",
"length1": "1",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "1.00",
"images": [],
"extraAreas": [],
"finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a21cb9a92c39df2abd52b0",
    "name": "externalImg_1738677370478_image.jpeg",
    "path": "cases/67a07534c6108fdeef4771a4/
externalImg_1738677370478_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a21cb9a92c39df2abd52b1",
    "name": "externalImg_1738677381817_image.jpeg",
    "path": "cases/67a07534c6108fdeef4771a4/
externalImg_1738677381817_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a21cb9a92c39df2abd52b2",
    "name": "externalImg_r_1738677368111_image.jpeg",
    "path": "cases/67a07534c6108fdeef4771a4/
externalImg_r_1738677368111_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a21cb9a92c39df2abd52b3",
    "name": "externalImg_r_1738677370824_image.jpeg",
    "path": "cases/67a07534c6108fdeef4771a4/
externalImg_r_1738677370824_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a21cb9a92c39df2abd52b4",
    "name": "externalImg_r_1738677358202_image.jpeg",
    "path": "cases/67a07534c6108fdeef4771a4/
externalImg_r_1738677358202_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52b5",
  "name": "externallmg_r_1738677365738_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677365738_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52b6",
  "name": "externallmg_r_1738677376456_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677376456_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52b7",
  "name": "externallmg_r_1738677379151_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677379151_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52b8",
  "name": "externallmg_r_1738677381986_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677381986_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52b9",
  "name": "externallmg_r_1738677373463_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677373463_image.jpeg",
  "orientation": "portrait"
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52ba",
  "name": "externalimg_r_1738677384379_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externalimg_r_1738677384379_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52bb",
  "name": "externalimg_r_1738677387038_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externalimg_r_1738677387038_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52bc",
  "name": "externalimg_r_1738677390909_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externalimg_r_1738677390909_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52bd",
  "name": "externalimg_r_1738677393407_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externalimg_r_1738677393407_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52be",
  "name": "externalimg_r_1738677396266_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externalimg_r_1738677396266_image.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52bf",
  "name": "externallmg_r_1738677401685_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677401685_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52c0",
  "name": "externallmg_r_1738677398883_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677398883_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52c1",
  "name": "externallmg_r_1738677404188_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677404188_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52c2",
  "name": "externallmg_r_1738677406771_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677406771_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a21cb9a92c39df2abd52c3",
  "name": "externallmg_r_1738677409678_image.jpeg",
  "path": "cases/67a07534c6108fdeef4771a4/
externallmg_r_1738677409678_image.jpeg",
  "orientation": "landscape"
}
],
```

```

"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-03T07:50:12.221Z",
"updatedAt": "2025-02-04T13:57:32.685Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Commercial Shop No. LG 28, Lower Ground Floor, Wing - B, Avior
Corporate Park CHSL, Nirmal Galaxy , L B S MArg, Mulund West, Mumbai, 400080,
State - Maharashtra, India",
"updatedBy": "65829f7c65d49d78457ec7be",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr .Tejpal Singh Buttar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9224441517",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			