

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7e7"
    },
    "firstName": "Saurabh",
    "type": "CREDITOFFICER",
    "_id": "654c6e32637db60f88b77c5b",
    "lastName": "Nege",
    "mobileNo": "",
    "workMobileNo": "8928822578",
    "email": "saurabh.nege@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "55000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7e7",
  "branchCode": "000048",
  "type": "BRANCH",
  "name": "MIDC Andheri (East) Branch",
  "email": "sbi.17879@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Plot No. B-1, MIDC Industrial Area, Central Road, Andheri (East),
Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "STATE BANK OF INDIA- MIDC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
},
{
"value": "AM161706-3",
"label": "Chartered Engineer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "17.70353395135637 ",
  "longitude": "75.90764640625056"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Solapur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Solapur",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Solapur",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "68/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "413002",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67a2e924c6108fdeef489a82",
"ownerName": "M/s. Solapur Bioenergy Systems Pvt. Ltd.",
"ownerPhoneNo": "7304902059",
"fullAddress": "Residential Land and Building No. Ground Floor, New/Current Survey
No. 68/1, Village - Solapur, Taluka - Solapur, District - Solapur, 413002",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1297aa6d152c1801b459",
      "label": "Lease Agreement"
    },
    "inputs": {
      "documentDate": "01/07/2004",
      "from": {
        "value": "Licensor",
        "label": "Licensor"
      },
      "Licensor": "Solapur Municipal Corporation",
      "to": {
        "value": "Lessee",
        "label": "Lessee"
      },
      "Lessee": "M/s. Solapur Bioenergy Systems Pvt. Ltd."
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1738729623811_SBESPLLand_Lease_Agreement_with_SMC.pdf",
```

```
"path": "cases/67a2e924c6108fdeef489a82/
document_1738729623811_SBESPLLand_Lease_Agreement_with_SMC.pdf",
"id": "454669",
"uploadedBy": "60f91822f3dd69653a5922e3",
"createdAt": "Wed Feb 05 2025 04:29:24 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e5",
    "label": "Allotment Letter"
  },
  "inputs": {
    "documentDate": "20/11/2009",
    "from": {
      "value": "Licensor",
      "label": "Licensor"
    },
    "Licensor": "Solapur Municipal Corporation",
    "to": {
      "value": "Lessee",
      "label": "Lessee"
    },
    "Lessee": "M/s. Solapur Bioenergy Systems Pvt. Ltd."
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738729723915_SPV_letterSMC.pdf",
  "path": "cases/67a2e924c6108fdeef489a82/
document_1738729723915_SPV_letterSMC.pdf",
"id": "392687",
"uploadedBy": "60f91822f3dd69653a5922e3",
"createdAt": "Wed Feb 05 2025 04:29:24 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "06/01/2025",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "330289054150"
  },
}
```

```
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1738729752029_SBESPLUtility_Bill.pdf",
    "path": "cases/67a2e924c6108fdeef489a82/
document_1738729752029_SBESPLUtility_Bill.pdf",
    "id": "494015",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Wed Feb 05 2025 04:29:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "014127",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "962708",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Feb 05 2025 04:29:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "M/s. Solapur Bioenergy Systems Pvt. Ltd.",
    "phone": "7304902059",
    "ownershipShare": "",
    "email": "",
    "id": "430715"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a5ce90a92c39df2abf24af",
```

```
    "name":
"externallmg_1738919557321_20250203_10647PMBByGPSMapCamera.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externallmg_1738919557321_20250203_10647PMBByGPSMapCamera.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24b0",
  "name":
"externallmg_1738919557372_20250203_10703PMBByGPSMapCamera.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externallmg_1738919557372_20250203_10703PMBByGPSMapCamera.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24b1",
  "name":
"externallmg_1738919557467_20250203_125400PMBByGPSMapCamera.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externallmg_1738919557467_20250203_125400PMBByGPSMapCamera.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24b2",
  "name":
"externallmg_1738919557685_20250203_125427PMBByGPSMapCamera.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externallmg_1738919557685_20250203_125427PMBByGPSMapCamera.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24b3",
  "name": "externallmg_r_1738919559407_IMG_20250203_123106.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externallmg_r_1738919559407_IMG_20250203_123106.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a5ce90a92c39df2abf24b4",
    "name": "externallmg_r_1738919557911_IMG_20250203_122852.jpg",
    "path": "cases/67a2e924c6108fdeef489a82/
externallmg_r_1738919557911_IMG_20250203_122852.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a5ce90a92c39df2abf24b5",
    "name": "externallmg_r_1738919558306_IMG_20250203_122920.jpg",
    "path": "cases/67a2e924c6108fdeef489a82/
externallmg_r_1738919558306_IMG_20250203_122920.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a5ce90a92c39df2abf24b6",
    "name": "externallmg_r_1738919558828_IMG_20250203_122936.jpg",
    "path": "cases/67a2e924c6108fdeef489a82/
externallmg_r_1738919558828_IMG_20250203_122936.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a5ce90a92c39df2abf24b7",
    "name": "externallmg_r_1738919559704_IMG_20250203_123148.jpg",
    "path": "cases/67a2e924c6108fdeef489a82/
externallmg_r_1738919559704_IMG_20250203_123148.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a5ce90a92c39df2abf24b8",
    "name": "externallmg_r_1738919560426_IMG_20250203_123213.jpg",
    "path": "cases/67a2e924c6108fdeef489a82/
externallmg_r_1738919560426_IMG_20250203_123213.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67a5ce90a92c39df2abf24b9",
  "name": "externalimg_r_1738919561151_IMG_20250203_124550.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externalimg_r_1738919561151_IMG_20250203_124550.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24ba",
  "name": "externalimg_r_1738919561038_IMG_20250203_123335.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externalimg_r_1738919561038_IMG_20250203_123335.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24bb",
  "name": "externalimg_r_1738919562241_IMG_20250203_125131.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externalimg_r_1738919562241_IMG_20250203_125131.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24bc",
  "name": "externalimg_r_1738919561891_IMG_20250203_124819.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externalimg_r_1738919561891_IMG_20250203_124819.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a5ce90a92c39df2abf24bd",
  "name": "externalimg_r_1738919562866_IMG_20250203_125154.jpg",
  "path": "cases/67a2e924c6108fdeef489a82/
externalimg_r_1738919562866_IMG_20250203_125154.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67a5ce90a92c39df2abf24be",
    "name": "externalimg_r_1738919563210_IMG_20250203_125312.jpg",
    "path": "cases/67a2e924c6108fdeef489a82/
externalimg_r_1738919563210_IMG_20250203_125312.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a5ce90a92c39df2abf24bf",
    "name": "externalimg_r_1738919563843_IMG_20250203_125805.jpg",
    "path": "cases/67a2e924c6108fdeef489a82/
externalimg_r_1738919563843_IMG_20250203_125805.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "62fb6919bc41567298b48f4d",
      "role": "ACCOUNTANT",
      "firstName": "Asmita",
      "lastName": "Rathod",
      "profilePhoto": "users/62fb6919bc41567298b48f4d/
profilePhoto_1688800525153_image.jpeg"
    },
    "workType": "DELETE_INVOICE",
    "display": true,
    "status": true,
    "_id": "67a2f378a2b18adef0ccf65f",
    "createdAt": "2025-02-05T05:13:28.003Z"
  }
],
"createdAt": "2025-02-05T04:29:24.594Z",
"updatedAt": "2025-02-07T09:12:48.336Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "M/s. Solapur Bioenergy Systems Pvt. Ltd.",
"email": "",
"isExternal": "false",
```


"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "7304902059"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
