

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65f004d9857bdc098a9acc0e"
    },
    "firstName": "Vivek",
    "type": "CREDITOFFICER",
    "_id": "65f004d9857bdc098a9acc10",
    "lastName": "Rane",
    "mobileNo": "",
    "workMobileNo": "8758661331",
    "email": "bmthan4567@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2500000",
  }
}
```

```
"discussWithPerson": "Vivek",
"expectedFees": 1250,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65f004d9857bdc098a9acc0e",
  "name": "Virar West",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "bmthan4567@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "A-1/A-2, Ground Floor, Regancey CHSL, Agashi Road, Near Vijaya
Bank, Virar West"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
```

```
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "659ccce98f39506e83489828",
    "role": "DELIVERYPERSON",
    "firstName": "Amit",
    "email": "amitsalvi2909@gmail.com",
    "lastName": "Salvi",
    "mobileNo": "7499830659",
    "shortName": "Amit",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "67776d60a5477d50e7dbc213",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "AJAY",
    "email": "ajayrewale503@gmail.com",
    "lastName": "REWALE",
    "mobileNo": "9766640171",
    "designation": "",
    "shortName": "AJAY",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordination",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
```

```
{
  "value": "[N]C.C.I.T/I -14/52/2008-09",
  "label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.22597229651152",
  "longitude": "73.07773367789737"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07773367789737,
    19.22597229651152
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "5/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gaskopari",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Darya Apartment",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "105",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
}
```

```
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67a2f0f4a92c39df2abd6dad",
"ownerName": "Mr. Pradeep Yashwant Rahatwal",
"ownerPhoneNo": "8758661331",
"appAddress": "FLAT NO 105 1ST FLOOR DARYA APARTMENT GASKOPARI
VILLAGE VIRAR EAST PALGHAR 401305",
"remark": "vivek rane manager cbi 8758661331\n\nVisit Done Ajay rewale",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67a2f0f4a92c39df2abd6dad/
document_1738731697452_1738731693770_Pradeep_rahatal_agreement.pdf",
    "fileName":
"document_1738731697452_1738731693770_Pradeep_rahatal_agreement.pdf",
    "id": "916805",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Wed Feb 05 2025 05:02:44 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014128",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "815084",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Wed Feb 05 2025 05:02:44 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Pradeep Yashwant Rahatwal",
"phone": "8758661331",
"ownershipShare": "",
"email": "",
"id": "233542"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67a32a07a92c39df2abdbabd",
"name": "externalImg_1738746355181_1738746353303_image_0.jpeg",
"path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746355181_1738746353303_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67a32a07a92c39df2abdbabe",
"name": "externalImg_1738746362440_1738746353303_image_1.jpeg",
"path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746362440_1738746353303_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67a32a7fc6108fdeef48f6bb",
"name": "externalImg_1738746463572_1738746458739_image_0.jpeg",
"path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746463572_1738746458739_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6bc",
  "name": "externallmg_1738746464610_1738746458739_image_1.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746464610_1738746458739_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6bd",
  "name": "externallmg_1738746469779_1738746458739_image_2.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746469779_1738746458739_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6be",
  "name": "externallmg_1738746473364_1738746458739_image_3.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746473364_1738746458739_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6bf",
  "name": "externallmg_1738746474269_1738746458739_image_4.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746474269_1738746458739_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6c0",
  "name": "externallmg_1738746478338_1738746458739_image_5.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746478338_1738746458739_image_5.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6c1",
    "name": "externallmg_1738746481433_1738746458739_image_6.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746481433_1738746458739_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6c2",
    "name": "externallmg_1738746483446_1738746458739_image_7.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746483446_1738746458739_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6c3",
    "name": "externallmg_1738746485455_1738746458739_image_8.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746485455_1738746458739_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6c4",
    "name": "externallmg_1738746487111_1738746458739_image_9.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746487111_1738746458739_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6c5",
    "name": "externallmg_1738746487709_1738746458739_image_10.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746487709_1738746458739_image_10.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6c6",
  "name": "externallmg_1738746488507_1738746458739_image_11.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746488507_1738746458739_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6c7",
  "name": "externallmg_1738746489333_1738746458739_image_12.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746489333_1738746458739_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6c8",
  "name": "externallmg_1738746489950_1738746458739_image_13.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746489950_1738746458739_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6c9",
  "name": "externallmg_1738746491016_1738746458739_image_14.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746491016_1738746458739_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32a7fc6108fdeef48f6ca",
  "name": "externallmg_1738746492092_1738746458739_image_15.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746492092_1738746458739_image_15.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6cb",
    "name": "externallmg_1738746492949_1738746458739_image_16.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746492949_1738746458739_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6cc",
    "name": "externallmg_1738746493367_1738746458739_image_17.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746493367_1738746458739_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6cd",
    "name": "externallmg_1738746494211_1738746458739_image_18.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746494211_1738746458739_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32a7fc6108fdeef48f6ce",
    "name": "externallmg_1738746494400_1738746458739_image_19.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746494400_1738746458739_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd5611",
    "name": "externallmg_1738746544059_1738746538114_image_0.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746544059_1738746538114_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67a32abaa2b18adef0cd5612",
  "name": "externallmg_1738746544241_1738746538114_image_1.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746544241_1738746538114_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32abaa2b18adef0cd5613",
  "name": "externallmg_1738746544972_1738746538114_image_2.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746544972_1738746538114_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32abaa2b18adef0cd5614",
  "name": "externallmg_1738746545570_1738746538114_image_3.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746545570_1738746538114_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32abaa2b18adef0cd5615",
  "name": "externallmg_1738746546294_1738746538114_image_4.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746546294_1738746538114_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a32abaa2b18adef0cd5616",
  "name": "externallmg_1738746546869_1738746538114_image_5.jpeg",
  "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746546869_1738746538114_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67a32abaa2b18adef0cd5617",
    "name": "externallmg_1738746547417_1738746538114_image_6.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746547417_1738746538114_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd5618",
    "name": "externallmg_1738746547963_1738746538114_image_7.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746547963_1738746538114_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd5619",
    "name": "externallmg_1738746548722_1738746538114_image_8.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746548722_1738746538114_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd561a",
    "name": "externallmg_1738746549442_1738746538114_image_9.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746549442_1738746538114_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd561b",
    "name": "externallmg_1738746550273_1738746538114_image_10.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externallmg_1738746550273_1738746538114_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd561c",
```



```
    "name": "externalImg_1738746550636_1738746538114_image_11.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746550636_1738746538114_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd561d",
    "name": "externalImg_1738746551196_1738746538114_image_12.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746551196_1738746538114_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd561e",
    "name": "externalImg_1738746552130_1738746538114_image_13.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746552130_1738746538114_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd561f",
    "name": "externalImg_1738746552468_1738746538114_image_14.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746552468_1738746538114_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a32abaa2b18adef0cd5620",
    "name": "externalImg_1738746553197_1738746538114_image_15.jpeg",
    "path": "cases/67a2f0f4a92c39df2abd6dad/
externalImg_1738746553197_1738746538114_image_15.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
```

```

"remarks": [],
"createdAt": "2025-02-05T05:02:44.580Z",
"updatedAt": "2025-02-05T09:09:14.118Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 105, 1st Floor, Darya Apartment, Village -
Gaskopari, Virar, Taluka - Vasai, District - Thane",
"updatedAtBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Pradeep Yashwant Rahatwal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "8758661331"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			