

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "r. Mohanty",
    "type": "CREDITOFFICER",
    "_id": "646dc536b05e530fb6c47b3d",
    "lastName": " Sir",
    "mobileNo": "",
    "workMobileNo": "8411020137",
    "email": "rlf.nasik@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
```

```
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
```

```
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "AM161706-3",
"label": "Chartered Engineer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.982832238779107",
  "longitude": "73.75296989612202"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "6/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamatwade",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "3",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "14",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": " Amrutganga Co-Op Housing Society",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Trimurti Chowk, Kamatwade Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Herambh Ganesh Mandir",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "51/1/2P + 51/1/1+51/2P",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "11",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "422010",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value": "Open_Conduit_Plumbing_With_Concealed_Electrification",
    "label": "Open Conduit Plumbing With Concealed Electrification"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Proposed_Purchaser_-_Joint_Ownership",
    "label": "Proposed Purchaser - Joint Ownership"
  },
  "populationClassList": {
    "value": "UpperClass",
    "label": "Upper Class"
  }
}
```

```
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Nashik_Municipal_Corporation_",
  "label": "Nashik Municipal Corporation "
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Bungalow",
  "west": "Road",
  "south": "Building",
  "east": "Building"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 12 & 13",
  "west": "6 M. Colony Road",
  "south": "Plot No. 16 & 17",
  "east": "Plot No. 18 & 19"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Marginal Space",
    "south": "Flat No. 12",
    "west": "Passage & Staircase"
  },
  "asPerDocument": {
    "north": "Open Space ",
    "east": "Path Apartment",
    "south": "Flat No. 12",
    "west": "Passage & Staircase"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
```

```
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Accoupaining
Commencement Certificate No.CD/1032 Dated 23.10.2000 issued by Executive
Engineer Town Planning, Nashik Municipal Corporation.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "36",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "3880",
  "depreciatedBuildingRate": "1280"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "32000",
  "landRate": "9000",
  "igrImage": "cases/67a486cba2b18adef0ce521f/igr_1738836185121_Image.png",
  "squareMeterGuideLineRate": "27200.00",
  "squareFeetGuideLineRate": "2527.00"
},
"igrFinalRate": {
  "floorRatePercentage": "85",
  "depreciationPercentage": "76",
  "rate": "2121.00",
  "squareFeetGuideLineRate": "2121.00",
  "squareMeterGuideLineRate": "22832.00"
},
```

```
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details Not Provided",
  "taxPaidHolderName": "Details Not Provided",
  "taxAmount": "Details Not Provided",
  "electricityServiceConnectionNo": "Details Not Provided",
  "meterCardHolderName": "Details Not Provided",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Average"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
```

```
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2001",
  "fullDate": "1/1/2001"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "average",
  "label": "Average"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
```



```
"estimatedAge": "36",
"ageOfBuilding": "24",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "3",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "427.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Notarized Agreement for Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67a486cba2b18adef0ce521f/
routeMap_1738837924073_Image.png",
    "routeLat": "19.982832",
    "routeLng": "73.752970",
    "stationName": "Nashik Road",
    "routeDistance": "12.8 KM",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "113wr",
    "name": "113wr",
    "image": "cases/67a486cba2b18adef0ce521f/
routeMap_1738837867985_Image.png"
```

```
}
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "1656760.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "1656760.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
}
```

```
"datetime": "2025-02-06T11:50:41.745Z",
"date": "Thu Feb 06 2025 11:50:41 GMT+0000 (Coordinated Universal Time)",
"number": "2310424",
"dayCount": "12",
"monthCount": "74",
"generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "905667.00",
  "selectedBuildUpValue": "427.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "67a48712c6108fdeef49b80a",
  "name":
"externallmg_1738835729603_WhatsApp_Image_20250203_at_42347_PM.jpeg",
  "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729603_WhatsApp_Image_20250203_at_42347_PM.jpeg",
  "orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "67a49327a92c39df2abe9a43",
    "name":
"externallmg_1738838821985_WhatsApp_Image_20250206_at_41322_PM.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738838821985_WhatsApp_Image_20250206_at_41322_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "67a48712c6108fdeef49b809",
    "name":
"externallmg_1738835729568_WhatsApp_Image_20250203_at_42346_PM.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729568_WhatsApp_Image_20250203_at_42346_PM.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "67a48712c6108fdeef49b813",
    "name":
"externallmg_1738835729820_WhatsApp_Image_20250203_at_42352_PM.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729820_WhatsApp_Image_20250203_at_42352_PM.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
```

```
    "status": false,
    "_id": "67a48712c6108fdeef49b80e",
    "name": "Living Room",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729704_WhatsApp_Image_20250203_at_42349_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67a48712c6108fdeef49b811",
    "name": "Kitchen",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729784_WhatsApp_Image_20250203_at_42350_PM.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "4847.00",
    "max": "5902.00"
  },
  "builtUpRateRange": {
    "min": "4039.00",
    "max": "4919.00"
  },
  "saleableRateRange": {
    "min": "3366.00",
    "max": "4099.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```

```
"value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "427.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67a486cba2b18adef0ce521f",
"ownerName": "Shri. Nandu Dadaji Nikam ",
"ownerPhoneNo": "9363027488",
"fullAddress": "Residential Flat No. 11, 3rd Floor, Amrutganga Co-Op Housing
Society, Near Herambh Ganesh Mandir, Plot No. 14, Trimurti Chowk, Kamatwade Road,
Village - Kamatwade, Taluka - Nashik, District - Nashik, Nashik, 422010, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "inputs": {
      "documentDate": "20/01/2025",
      "from": {
        "value": "Owner",
        "label": "Owner"
      },
      "Owner": "Shri. Nandu Dadaji Nikam",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Shri. Kiran Sahebrao Surywanshi & Sau. Ranjana Sahebrao
Surywanshi "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "112103",
```

```
"path": "cases/67a486cba2b18adef0ce521f/
document_1738835409058_Kiran_Suryawanshi_60_Khat.pdf",
"fileName": "document_1738835409058_Kiran_Suryawanshi_60_Khat.pdf"
},
{
  "documentType": {
    "value": "60ae126caa6d152c1801b395",
    "label": "Correction Deed"
  },
  "inputs": {
    "documentDate": "16/01/2025",
    "from": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Shri. Ravindra Waman Chitte",
    "to": {
      "value": "buyer",
      "label": "buyer"
    },
    "buyer": "Shri. Nandu Dadaji Nikam"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738835531145_Kiran_Suryawanshi_Corection.pdf",
  "path": "cases/67a486cba2b18adef0ce521f/
document_1738835531145_Kiran_Suryawanshi_Corection.pdf",
  "id": "483025",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Feb 06 2025 09:54:19 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "23/10/2000",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "CD/1032"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738835613746_Kiran_Suryawanshi_Bilding_Plan3.pdf",
  "path": "cases/67a486cba2b18adef0ce521f/
document_1738835613746_Kiran_Suryawanshi_Bilding_Plan3.pdf",
  "id": "430675",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Feb 06 2025 09:54:19 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "28/06/2001",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "Javak Number / Nagarrachana /CIDCO / 130"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738835656844_222983.pdf",
  "path": "cases/67a486cba2b18adef0ce521f/
document_1738835656844_222983.pdf",
  "id": "315568",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Feb 06 2025 09:54:19 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014169",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
```

```
"id": "177501",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Thu Feb 06 2025 09:54:19 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Shri. Nandu Dadaji Nikam ",
"phone": "9363027488",
"ownershipShare": "",
"email": "",
"id": "389539"
}
],
"proposePurchasers": [
{
"name": "Shri. Kiran Sahebrao Surywanshi & Sau. Ranjana Sahebrao Surywanshi "
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "447709",
"name": "Living Room",
"length": "11.00",
"length1": "11",
"length2": "00",
"width": "12.00",
"width1": "12",
"width2": "00",
"totalArea": "132.00",
"images": [],
"extraAreas": [],
"finalArea": "132.00"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
```

```
"name": "Kitchen",
"length": "7.00",
"length1": "7",
"length2": "00",
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "56.00",
"images": [],
"extraAreas": [],
"finalArea": "56.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
```

```
    "finalArea": "100.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "39.67",
    "totalAreaDocument": "427",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "901501"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "433.33",
      "squareMeterArea": "40.26",
      "expectedRate": "4846.19",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "520.00",
      "squareMeterArea": "48.31",
      "expectedRate": "4038.46",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "624.00",
      "squareMeterArea": "57.97",
      "expectedRate": "3365.38",
```

```
    "percentage": "20."
  },
  "printlnReport": true,
  "_id": "67a488e3a92c39df2abe89fc",
  "property": "Flat",
  "area": "520",
  "builtUpPercentage": "20",
  "saleablePercentage": "20.",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "2100000",
  "expectedRate": "4846.19",
  "builtUpExpectedRate": "2100000",
  "image": "cases/67a486cba2b18adef0ce521f/
indicator_1738836122115_Image.png",
  "squareMeter": "48.31",
  "id": "765963"
},
{
  "carpetArea": {
    "area": "423.61",
    "squareMeterArea": "39.35",
    "expectedRate": "5901.65",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "508.33",
    "squareMeterArea": "47.23",
    "expectedRate": "4918.07",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "610.00",
    "squareMeterArea": "56.67",
    "expectedRate": "4098.36",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67a488e3a92c39df2abe89fd",
  "property": "Flat",
  "area": "610",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
```



```
"areaType": "Saleable",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "2500000",
"expectedRate": "4098.360655737705",
"builtUpExpectedRate": "4918.07",
"image": "cases/67a486cba2b18adef0ce521f/
indicator_1738836147977_Image.png",
"squareMeter": "56.67",
"id": "638486"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67a48712c6108fdeef49b807",
"name":
"externalImg_1738835729441_WhatsApp_Image_20250203_at_42345_PM.jpeg",
"path": "cases/67a486cba2b18adef0ce521f/
externalImg_1738835729441_WhatsApp_Image_20250203_at_42345_PM.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67a48712c6108fdeef49b808",
"name":
"externalImg_1738835729520_WhatsApp_Image_20250203_at_42346_PM_1.jpeg",
"path": "cases/67a486cba2b18adef0ce521f/
externalImg_1738835729520_WhatsApp_Image_20250203_at_42346_PM_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67a48712c6108fdeef49b809",
"name":
"externalImg_1738835729568_WhatsApp_Image_20250203_at_42346_PM.jpeg",
"path": "cases/67a486cba2b18adef0ce521f/
externalImg_1738835729568_WhatsApp_Image_20250203_at_42346_PM.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```

```
    "_id": "67a48712c6108fdeef49b80a",
    "name":
"externallmg_1738835729603_WhatsApp_Image_20250203_at_42347_PM.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729603_WhatsApp_Image_20250203_at_42347_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a48712c6108fdeef49b80b",
    "name":
"externallmg_1738835729624_WhatsApp_Image_20250203_at_42348_PM_1.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729624_WhatsApp_Image_20250203_at_42348_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a48712c6108fdeef49b80c",
    "name":
"externallmg_1738835729673_WhatsApp_Image_20250203_at_42348_PM_2.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729673_WhatsApp_Image_20250203_at_42348_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a48712c6108fdeef49b80d",
    "name":
"externallmg_1738835729699_WhatsApp_Image_20250203_at_42348_PM.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729699_WhatsApp_Image_20250203_at_42348_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a48712c6108fdeef49b80e",
    "name":
"externallmg_1738835729704_WhatsApp_Image_20250203_at_42349_PM_1.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729704_WhatsApp_Image_20250203_at_42349_PM_1.jpeg",
    "orientation": "landscape"
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a48712c6108fdeef49b80f",
      "name":
"externallmg_1738835729747_WhatsApp_Image_20250203_at_42349_PM.jpeg",
      "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729747_WhatsApp_Image_20250203_at_42349_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a48712c6108fdeef49b810",
      "name":
"externallmg_1738835729763_WhatsApp_Image_20250203_at_42350_PM_1.jpeg",
      "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729763_WhatsApp_Image_20250203_at_42350_PM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a48712c6108fdeef49b811",
      "name":
"externallmg_1738835729784_WhatsApp_Image_20250203_at_42350_PM.jpeg",
      "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729784_WhatsApp_Image_20250203_at_42350_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a48712c6108fdeef49b812",
      "name":
"externallmg_1738835729788_WhatsApp_Image_20250203_at_42351_PM.jpeg",
      "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729788_WhatsApp_Image_20250203_at_42351_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67a48712c6108fdeef49b813",
      "name":
"externallmg_1738835729820_WhatsApp_Image_20250203_at_42352_PM.jpeg",
```

```
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738835729820_WhatsApp_Image_20250203_at_42352_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a49327a92c39df2abe9a43",
    "name":
"externallmg_1738838821985_WhatsApp_Image_20250206_at_41322_PM.jpeg",
    "path": "cases/67a486cba2b18adef0ce521f/
externallmg_1738838821985_WhatsApp_Image_20250206_at_41322_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "calc.xlsx",
    "filename": "1738836201577_calc.xlsx",
    "path": "cases/67a486cba2b18adef0ce521f/
processingDocuments/1738836201577_calc.xlsx",
    "size": "346866",
    "createdAt": "Thu Feb 06 2025 10:03:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "BOB - Shri. Kiran Sahebrao Surywanshi.pdf",
    "filename": "1738840233871_BOB__Shri__Kiran_Sahebrao_Surywanshi.pdf",
    "path": "cases/67a486cba2b18adef0ce521f/processingDocuments/1738840233871_
BOB__Shri__Kiran_Sahebrao_Surywanshi.pdf",
    "size": "6216691",
    "createdAt": "Thu Feb 06 2025 11:10:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-06T09:54:19.760Z",
"updatedAt": "2025-02-06T12:09:17.126Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Shri. Nandu Dadaji Nikam ",
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Shri. Kiran Sahebrao Surywanshi & Sau. Ranjana
Sahebrao Surywanshi ",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9363027488",
"buildingServicesRate": "2000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Notarized Agreement for Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 427.00",
"flatRate": "4600",
"landOtherRate": "2600",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Thu Feb 06 2025 10:03:49 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-02-03",
"briefDescOfProperty": "Living Room + Kitchen + Bathroom + Passage",
"carpetTotal": "300.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "330.00",
"finalCarpetArea": "300.00",
"finalSalableArea": "363.00",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
```

```

    },
    "leaseDetails": {
      "lessorName": "",
      "lesseeName": "",
      "leasePremium": "",
      "leaseRent": "",
      "leasePeriod": 0,
      "leaseFrom": "",
      "leaseTo": "",
      "remainingLeasePeriod": 0,
      "leaseDate": ""
    }
  },
  "otherCompositionBuiltUpTotal": "0.00",
  "otherCompositionCarpetTotal": "0.00",
  "otherCompositionSaleableTotal": "0.00"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	11'00"	12'00"	132.00
Kitchen	7'00"	8'00"	56.00
Bathroom	4'0"	3'0"	12.00
Passage	10'00"	10'00"	100.00
Other Composition :			