

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b984"
    },
    "firstName": "Nanda ",
    "type": "CREDITOFFICER",
    "_id": "67a6f0caa2b18adef0cfac4f",
    "email": "jssblgw@mtnl.ne.in",
    "lastName": "Salve",
    "mobileNo": "",
    "workMobileNo": "9819159912"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4505420",
    "discussWithPerson": "Macchindra S Sonawane",
    "expectedFees": 2252.71,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank (Borivali) LTD",
  "displayName": "Janaseva Sahakari Bank (Borivali) LTD",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b984",
  "branchCode": "000004",
  "type": "BRANCH",
  "name": "Goregaon (West) Branch",
  "email": "jssblgw@mtnl.ne.in",
  "mobileNo": "02228712103",
  "alternateMobileNo": "",
  "address": "Ekveera Prasad Co-Operative Housing Society Limited, Plot No. 75,
Mahatma Gandhi Road, Goregaon (West), Mumbai- 400062, State - Maharashtra,
Country - India ",
  "ledgerName": "",
  "fax": null,
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "663da98cfcea71232186f142",
  "role": "ACCOUNTANT",
  "firstName": "SONAL ",
```

```
"email": "sonal.ambekar19@gmail.com",
"lastName": " SHIVGAN",
"mobileNo": "9773395869",
"designation": "",
"shortName": "SO",
"workWithDocumentMaker": "",
"profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.16754656826881",
  "longitude": "72.95987591988892"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.95987591988892,
19.16754656826881
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-08",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-07",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Pahadi Goregaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "4",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Borivali",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Swami Samarth Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "M. G. Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sane Guruji Nagar, Teen Dongri",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "48/A (Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "305",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```

    "status": false,
    "name": "Gut No.",
    "key": "GUTNo",
    "value": "",
    "label": true
  },
  "postalCode": {
    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "400 104",
    "label": false
  },
  "suburb": {
    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Goregoan (West) ",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "MosiactileFlooring",
    "label": "Mosiactile Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Open_Windows",
    "label": "Aluminium Open Windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}

```

```
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Sane Guruji Nagar Marg",
    "west": "Building No. 5",
    "south": "Slum Area",
    "east": "Building No. 3"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Entrance of Flat No. 305",
      "east": "Flat No. 306",
      "south": "Passage Area",
      "west": "Marginal Space"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
    }
  }
}
```

```
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As MHADA itself is planning authority, building
construction permission is assumed to be available.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "21000",
  "depreciatedBuildingRate": "2800"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "160470",
  "landRate": "76820",
  "igrImage": "cases/67a6f1d6a92c39df2abf9e26/igr_1739182325674_Image.png",
  "squareMeterGuideLineRate": "136400.00",
```

```
"squareFeetGuideLineRate": "12672.00"
},
"igrFinalRate": {
  "floorRatePercentage": "85",
  "depreciationPercentage": "50",
  "rate": "9904.00",
  "squareFeetGuideLineRate": "9904.00",
  "squareMeterGuideLineRate": "106610.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "9000 0042 9224",
  "meterCardHolderName": "Mr. Gangaram Keru Bhoir",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MCGM norms\n",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
}
```

```
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1975",
  "fullDate": "1/1/1975"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
```



```
    "value": "ground",
    "label": "Ground"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_site_information",
    "label": "As per site information"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "10",
  "ageOfBuilding": "50",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "4",
  "flatFloorNo": "3",
  "noOfLifts": "-",
  "noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "236.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67a6f1d6a92c39df2abf9e26/
routeMap_1739251922570_Image.png",
    "routeLat": "19.165870",
    "routeLng": "72840184",
    "stationName": "Bangur Nagar",
    "routeDistance": "1 Km",
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
```

```
"latlng": false,
"finallatlng": false
},
"locationMapImg": [
  {
    "id": "gl3zs",
    "name": "gl3zs",
    "image": "cases/67a6f1d6a92c39df2abf9e26/
routeMap_1739251862857_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "4137000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4137000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2341306.00",
"selectedBuildUpValue": "236.40",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67a736eac6108fdeef4b33b0",
      "name": "externallmg_1739011813834_1739011803798_image_5.jpeg",
      "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011813834_1739011803798_image_5.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67a7370aa92c39df2abffa80",
      "name": "externallmg_1739011846697_1739011836666_image_5.jpeg",
      "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011846697_1739011836666_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67a7370aa92c39df2abffa82",
      "name": "externallmg_1739011848280_1739011836666_image_7.jpeg",
      "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011848280_1739011836666_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67a7370aa92c39df2abffa83",
      "name": "externallmg_1739011848923_1739011836666_image_8.jpeg",
      "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011848923_1739011836666_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67a736eac6108fdeef4b33b5",
      "name": "externallmg_1739011816067_1739011803798_image_10.jpeg",
      "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011816067_1739011803798_image_10.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "67a7370aa92c39df2abffa7d",
  "name": "externallmg_1739011845763_1739011836666_image_2.jpeg",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011845763_1739011836666_image_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67a7370aa92c39df2abffa7b",
  "name": "externallmg_1739011842418_1739011836666_image_0.jpeg",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011842418_1739011836666_image_0.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67a736eac6108fdeef4b33ad",
  "name": "externallmg_1739011813193_1739011803797_image_2.jpeg",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011813193_1739011803797_image_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67a736eac6108fdeef4b33af",
  "name": "externallmg_1739011813640_1739011803798_image_4.jpeg",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011813640_1739011803798_image_4.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18275.00",
    "max": "22800.00"
  },
  "builtUpRateRange": {
    "min": "15229.00",
    "max": "19000.00"
  }
},
}
```

```
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
    "isEditable": false
  }
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "197.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67a6f1d6a92c39df2abf9e26",
"ownerName": "Mr. Gangaram Keru Bhoir",
"ownerPhoneNo": "9819272821",
"appAddress": "Flat no 305 3rd floor Bldg no 4 Sane Guruji nagar M G road Near
Police Quotres Goregoan West Mumbai 400062",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "28/01/2025",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "9000 0042 9224"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "626723",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
document_1739191473365_Electricity_Bill__Bhoir.pdf",
  "fileName": "document_1739191473365_Electricity_Bill__Bhoir.pdf"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b37e",
    "label": "MHADA Allotment Letter"
  },
  "inputs": {
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. Gangaram Keru Bhoir",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "02474"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1739191908822_MHADA_Allotment_letter.pdf",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
document_1739191908822_MHADA_Allotment_letter.pdf",
  "id": "735634",
  "uploadedBy": "663da98cfcea71232186f142",
  "createdAt": "Mon Feb 10 2025 12:51:48 GMT+0000 (Coordinated Universal Time)"
},
}
```

```
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "01/04/2005",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "48"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1739192049158_Share_Certificate.pdf",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
document_1739192049158_Share_Certificate.pdf",
  "id": "925445",
  "uploadedBy": "663da98cfcea71232186f142",
  "createdAt": "Mon Feb 10 2025 12:54:09 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae12b6aa6d152c1801b4ec",
    "label": "Title Clearance Certificate"
  },
  "inputs": {
    "documentDate": "03/02/2025",
    "remark": "issued by Vijay Singh & Associates"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1739250466386_Title_Certificate__Bhoir.pdf",
  "path": "cases/67a6f1d6a92c39df2abf9e26/
document_1739250466386_Title_Certificate__Bhoir.pdf",
  "id": "176134",
  "uploadedBy": "663da98cfcea71232186f142",
  "createdAt": "Tue Feb 11 2025 05:07:46 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014197",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "783617",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Sat Feb 08 2025 05:55:34 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Gangaram Keru Bhoir",
"phone": "9819272821",
"ownershipShare": "",
"email": "",
"id": "766455"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "141966",
"name": "Living Room",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "10.17",
"width1": "10",
"width2": "2",
"totalArea": "101.67",
"images": [],
"extraAreas": [],
"finalArea": "101.67"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "6.00",
```

```
"width1": "6",
"width2": "00",
"totalArea": "60.00",
"images": [],
"extraAreas": [],
"finalArea": "60.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "24.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "12.93",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.93"
}
],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae12b6aa6d152c1801b4ec",
      "label": "Title Clearance Certificate"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "438247",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "197",
    "squareMeterArea": "18.3",
    "docFinalBuiltUp": "236.4",
    "docFinalBuiltUpSquareMeter": "21.96",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "188.00",
      "squareMeterArea": "17.47",
      "expectedRate": "21276.60",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "225.60",
      "squareMeterArea": "20.96",
      "expectedRate": "17730.50",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "67a9d1e9c6108fdeef4bceba",
  "property": "Flat",
```

```
"area": "188",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "4000000",
"expectedRate": "21276.60",
"builtUpExpectedRate": "17730.50",
"image": "cases/67a6f1d6a92c39df2abf9e26/
indicator_1739182041542_Image.png",
"squareMeter": "17.47",
"id": "232885"
},
{
"carpetArea": {
"area": "250.00",
"squareMeterArea": "23.23",
"expectedRate": "22800.00",
"percentage": ""
},
"builtUpArea": {
"area": "300.00",
"squareMeterArea": "27.87",
"expectedRate": "19000.00",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67a9d1e9c6108fdeef4bcebb",
"property": "Flat",
"area": "250",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "5700000",
"expectedRate": "22800.00",
```



```
"builtUpExpectedRate": "19000.00",
"image": "cases/67a6f1d6a92c39df2abf9e26/
indicator_1739182134624_Image.png",
"squareMeter": "23.23",
"id": "823983"
},
{
"carpetArea": {
"area": "197.00",
"squareMeterArea": "18.30",
"expectedRate": "18274.11",
"percentage": ""
},
"builtUpArea": {
"area": "236.40",
"squareMeterArea": "21.96",
"expectedRate": "15228.43",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "67a9d1e9c6108fdeef4bcebc",
"property": "Flat",
"area": "197",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "3600000",
"expectedRate": "18274.11",
"builtUpExpectedRate": "15228.43",
"image": "cases/67a6f1d6a92c39df2abf9e26/
indicator_1739182163042_Image.png",
"squareMeter": "18.30",
"id": "253922"
},
{
"carpetArea": {
"area": "164.00",
```

```
    "squareMeterArea": "15.24",
    "expectedRate": "21341.46",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "196.80",
    "squareMeterArea": "18.28",
    "expectedRate": "17784.55",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67a9d1e9c6108fdeef4bcebd",
  "property": "Flat",
  "area": "164",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3500000",
  "expectedRate": "21341.46",
  "builtUpExpectedRate": "17784.55",
  "image": "cases/67a6f1d6a92c39df2abf9e26/
indicator_1739182210414_Image.png",
  "squareMeter": "15.24",
  "id": "660188"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa7b",
    "name": "externalImg_1739011842418_1739011836666_image_0.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externalImg_1739011842418_1739011836666_image_0.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa7c",
    "name": "externallmg_1739011843216_1739011836666_image_1.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011843216_1739011836666_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa7d",
    "name": "externallmg_1739011845763_1739011836666_image_2.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011845763_1739011836666_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa7e",
    "name": "externallmg_1739011845781_1739011836666_image_3.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011845781_1739011836666_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa7f",
    "name": "externallmg_1739011845961_1739011836666_image_4.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011845961_1739011836666_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa80",
    "name": "externallmg_1739011846697_1739011836666_image_5.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011846697_1739011836666_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67a7370aa92c39df2abffa81",
    "name": "externallmg_1739011847771_1739011836666_image_6.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011847771_1739011836666_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa82",
    "name": "externallmg_1739011848280_1739011836666_image_7.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011848280_1739011836666_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa83",
    "name": "externallmg_1739011848923_1739011836666_image_8.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011848923_1739011836666_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a7370aa92c39df2abffa84",
    "name": "externallmg_1739011849323_1739011836666_image_9.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011849323_1739011836666_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33ab",
    "name": "externallmg_1739011810751_1739011803797_image_0.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011810751_1739011803797_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "67a736eac6108fdeef4b33ac",
    "name": "externallmg_1739011812395_1739011803797_image_1.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011812395_1739011803797_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33ad",
    "name": "externallmg_1739011813193_1739011803797_image_2.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011813193_1739011803797_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33ae",
    "name": "externallmg_1739011813542_1739011803797_image_3.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011813542_1739011803797_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33af",
    "name": "externallmg_1739011813640_1739011803798_image_4.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011813640_1739011803798_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b0",
    "name": "externallmg_1739011813834_1739011803798_image_5.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011813834_1739011803798_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b1",
```

```
    "name": "externallmg_1739011814553_1739011803798_image_6.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011814553_1739011803798_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b2",
    "name": "externallmg_1739011814887_1739011803798_image_7.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011814887_1739011803798_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b3",
    "name": "externallmg_1739011815317_1739011803798_image_8.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011815317_1739011803798_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b4",
    "name": "externallmg_1739011815557_1739011803798_image_9.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011815557_1739011803798_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b5",
    "name": "externallmg_1739011816067_1739011803798_image_10.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externallmg_1739011816067_1739011803798_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b6",
    "name": "externallmg_1739011816222_1739011803798_image_11.jpeg",
```

```
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externalImg_1739011816222_1739011803798_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b7",
    "name": "externalImg_1739011816976_1739011803798_image_12.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externalImg_1739011816976_1739011803798_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67a736eac6108fdeef4b33b8",
    "name": "externalImg_1739011817882_1739011803798_image_13.jpeg",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
externalImg_1739011817882_1739011803798_image_13.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "2025-02-08 13-36.pdf",
    "filename": "1739182435027_20250208_1336.pdf",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
processingDocuments/1739182435027_20250208_1336.pdf",
    "size": "6055276",
    "createdAt": "Mon Feb 10 2025 10:13:55 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  },
  {
    "originalname": "Janseva Goregoan West Gangaram Bhoir Legal report (1).pdf",
    "filename":
"1739182435142_Janseva_Goregoan_West_Gangaram_Bhoir_Legal_report_1.pdf",
    "path": "cases/67a6f1d6a92c39df2abf9e26/processingDocuments/1739182435142_
Janseva_Goregoan_West_Gangaram_Bhoir_Legal_report_1.pdf",
    "size": "2224476",
    "createdAt": "Mon Feb 10 2025 10:13:55 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  },
  {
    "originalname": "Gangaram Bhoir (Cal).xlsx",
```

```
    "filename": "1739182444288_Gangaram_Bhoir_Cal.xlsx",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
processingDocuments/1739182444288_Gangaram_Bhoir_Cal.xlsx",
    "size": "1799834",
    "createdAt": "Mon Feb 10 2025 10:14:04 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  },
  {
    "originalName": "RateSheet.xlsx",
    "filename": "1739182489870_RateSheet.xlsx",
    "path": "cases/67a6f1d6a92c39df2abf9e26/
processingDocuments/1739182489870_RateSheet.xlsx",
    "size": "1861610",
    "createdAt": "Mon Feb 10 2025 10:14:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9147bf3dd69653a591e8c"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f9147bf3dd69653a591e8c",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Vinita",
      "lastName": "Surve",
      "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67a7475da2b18adef0d04194",
    "note": "Pending for documents only Electricity Bill only",
    "taskId": "67a6f346c6108fdeef4adadb",
    "createdAt": "2025-02-08T12:00:29.665Z"
  }
],
"createdAt": "2025-02-08T05:55:34.762Z",
"updatedAt": "2025-02-11T06:15:41.130Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 305, 3rd Floor, Building No 4, Shree Swami
```


Samarth Co-Op. Hsg. Soc. Ltd., M. G. Road, Sane Guruji Nagar, Teen Dongri, Village - Pahadi Goregaon, Goregaon (West) , Taluka - Borivali, District - Mumbai Suburban, Mumbai, 400 104, State - Maharashtra, India",

```
"updatedBy": "60f9147bf3dd69653a591e8c",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Gangaram Keru Bhoir",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Self",
"rerald": "",
"siteVisitContactNo": "9819272821",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Title Clearance Certificate",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 197.00",
"flatRate": "21000",
"landOtherRate": "18200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "Living Room + Kitchen + Bathroom + WC",
"carpetTotal": "198.66",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "218.53",
"finalCarpetArea": "198.66",
"finalSalableArea": "240.38",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
```

```

"holdType": {
  "label": "Free Hold",
  "value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Tue Feb 11 2025 05:02:32 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-02-07"
}

```

Name	Length	Width	Total
Composition :			
Living Room	10'00"	10'2"	101.67
Kitchen	10'00"	6'00"	60.00
Bathroom	6'5"	3'9"	24.06
WC	4'1"	3'2"	12.93
Other Composition :			