

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "67aada3919ca979ae946d46d"
    },
    "firstName": "Vivek ",
    "type": "CREDITOFFICER",
    "_id": "67aada7036a56c9b5f653a11",
    "email": "thane@janatabankpune.com",
    "lastName": "Kyatam",
    "mobileNo": "",
    "workMobileNo": "9168610226"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Vivek ",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "645c92ba7f94762ec7884195",
  "type": "BANK",
  "name": "Janta Sahkari Bank LTD",
  "displayName": "Janta Sahkari Bank LTD\t",
  "initial": "JSB"
},
"branch": {
  "_id": "67aada3919ca979ae946d46d",
  "name": "Thane West Branch",
  "branchCode": "",
  "mobileNo": "9892159132",
  "alternateMobileNo": "",
  "email": "thane@janatabankpune.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No. 2, Lokmanya Society, Veer Savarkar Marg, Gajanan Maharaj
Chowk, Near Ram Maruti Road, Thane (West), Thane - 400 602, Maharashtra, India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "645c93d47f94762ec788472a",
  "zoneName": "Mumbai Metro"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "665ac13f42f4717ae30de3d5",
    "role": "PICKUPPERSON",
    "firstName": "NIDHI",
```

```
"email": "nidhi.kajwe97@gmail.com",
"lastName": "KAJWE",
"mobileNo": "8850520881",
"shortName": "NIDHI",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.93666424413766",
  "longitude": "72.83637906006996"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.83637906006996,
18.93666424413766
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "11/02/2025 12:00 pm",
      "remark": ""
    },
    {
      "dateTime": "11/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",

```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Modi Street Fort",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "104, 106,108",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "1033",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400001",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Fort",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
```



```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67aae958d716769af0d45413",
"ownerName": "M/s Papier 365 Global Pvt Ltd ",
"ownerPhoneNo": "9892159132",
"appAddress": "1033 A.D.J.M /607/2013 sarti 486/2013 Jamin & Bandhkam Hissa
104, 106,108 Modi Street Fort Mumbai - 400001",
"remark": "Please get the visit done by today...banker will also be there at the time of
visit...please call the banker for scheduling the visit.",
"documents": [
  {
    "documentType": {
      "label": "Deed of Conveyance",
      "value": "60ae1253aa6d152c1801b321"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67aae958d716769af0d45413/document_1739253348403_17392533
44609_6_DEED_OF_CONVEYANCE_200_MAYURIKA_BHANKHARIA.pdf",
    "fileName": "document_1739253348403_1739253344609_6_DEED_OF_CONVEYA
```

```
NCE_200_MAYURIKA_BHANKHARIA.pdf",
  "id": "945412",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Tue Feb 11 2025 06:08:24 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Deed of Conveyance",
    "value": "60ae1253aa6d152c1801b321"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67aae958d716769af0d45413/document_1739253692297_1739253688217_7_DEED_OF_CONVEYANCE_200_ASHISH_BHANKHARIA.pdf",
  "fileName": "document_1739253692297_1739253688217_7_DEED_OF_CONVEYANCE_200_ASHISH_BHANKHARIA.pdf",
  "id": "276873",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Tue Feb 11 2025 06:08:24 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014234",
"createdBy": "665ac13f42f4717ae30de3d5",
"caseHistory": [
  {
    "id": "985639",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 11 2025 06:08:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "M/s Papier 365 Global Pvt Ltd ",
    "phone": "9892159132",
    "ownershipShare": "",
    "email": "",
    "id": "131466"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
```

```
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3b5",
    "name": "externalimg_1739338099463_1739338095553_image_0.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalimg_1739338099463_1739338095553_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3b6",
    "name": "externalimg_1739338100085_1739338095553_image_1.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalimg_1739338100085_1739338095553_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3b7",
    "name": "externalimg_1739338100482_1739338095553_image_2.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalimg_1739338100482_1739338095553_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3b8",
    "name": "externalimg_1739338100895_1739338095553_image_3.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalimg_1739338100895_1739338095553_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3b9",
    "name": "externalimg_1739338101305_1739338095553_image_4.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalimg_1739338101305_1739338095553_image_4.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3ba",
  "name": "externallmg_1739338101559_1739338095553_image_5.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338101559_1739338095553_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3bb",
  "name": "externallmg_1739338101842_1739338095553_image_6.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338101842_1739338095553_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3bc",
  "name": "externallmg_1739338102090_1739338095553_image_7.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338102090_1739338095553_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3bd",
  "name": "externallmg_1739338102344_1739338095553_image_8.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338102344_1739338095553_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3be",
  "name": "externallmg_1739338102549_1739338095553_image_9.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338102549_1739338095553_image_9.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3bf",
    "name": "externallmg_1739338102742_1739338095554_image_10.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338102742_1739338095554_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3c0",
    "name": "externallmg_1739338103037_1739338095554_image_11.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338103037_1739338095554_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3c1",
    "name": "externallmg_1739338103361_1739338095554_image_12.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338103361_1739338095554_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3c2",
    "name": "externallmg_1739338103748_1739338095554_image_13.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338103748_1739338095554_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac317a36a56c9b5f65f3c3",
    "name": "externallmg_1739338104087_1739338095554_image_14.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338104087_1739338095554_image_14.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3c4",
  "name": "externallmg_1739338104442_1739338095554_image_15.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338104442_1739338095554_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3c5",
  "name": "externallmg_1739338104723_1739338095554_image_16.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338104723_1739338095554_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3c6",
  "name": "externallmg_1739338105126_1739338095554_image_17.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338105126_1739338095554_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac317a36a56c9b5f65f3c7",
  "name": "externallmg_1739338105519_1739338095554_image_18.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338105519_1739338095554_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac323e36a56c9b5f65f4e8",
  "name": "externallmg_1739338296760_1739338293405_image_0.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338296760_1739338293405_image_0.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4e9",
    "name": "externallmg_1739338297262_1739338293406_image_1.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338297262_1739338293406_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4ea",
    "name": "externallmg_1739338297325_1739338293406_image_2.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338297325_1739338293406_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4eb",
    "name": "externallmg_1739338297606_1739338293406_image_3.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338297606_1739338293406_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4ec",
    "name": "externallmg_1739338297848_1739338293406_image_4.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338297848_1739338293406_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4ed",
    "name": "externallmg_1739338297956_1739338293406_image_5.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338297956_1739338293406_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67ac323e36a56c9b5f65f4ee",
  "name": "externallmg_1739338298397_1739338293406_image_6.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338298397_1739338293406_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac323e36a56c9b5f65f4ef",
  "name": "externallmg_1739338298699_1739338293406_image_7.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338298699_1739338293406_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac323e36a56c9b5f65f4f0",
  "name": "externallmg_1739338299036_1739338293406_image_8.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338299036_1739338293406_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac323e36a56c9b5f65f4f1",
  "name": "externallmg_1739338299375_1739338293406_image_9.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338299375_1739338293406_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac323e36a56c9b5f65f4f2",
  "name": "externallmg_1739338299783_1739338293406_image_10.jpeg",
  "path": "cases/67aae958d716769af0d45413/
externallmg_1739338299783_1739338293406_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "67ac323e36a56c9b5f65f4f3",
    "name": "externallmg_1739338300069_1739338293406_image_11.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338300069_1739338293406_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4f4",
    "name": "externallmg_1739338300320_1739338293406_image_12.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338300320_1739338293406_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4f5",
    "name": "externallmg_1739338300584_1739338293406_image_13.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338300584_1739338293406_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4f6",
    "name": "externallmg_1739338300905_1739338293406_image_14.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338300905_1739338293406_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4f7",
    "name": "externallmg_1739338301103_1739338293406_image_15.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externallmg_1739338301103_1739338293406_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4f8",
```

```
    "name": "externalImg_1739338301442_1739338293406_image_16.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalImg_1739338301442_1739338293406_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4f9",
    "name": "externalImg_1739338301709_1739338293406_image_17.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalImg_1739338301709_1739338293406_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4fa",
    "name": "externalImg_1739338301827_1739338293406_image_18.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalImg_1739338301827_1739338293406_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac323e36a56c9b5f65f4fb",
    "name": "externalImg_1739338302087_1739338293406_image_19.jpeg",
    "path": "cases/67aae958d716769af0d45413/
externalImg_1739338302087_1739338293406_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-11T06:08:24.826Z",
"updatedAt": "2025-02-12T05:31:42.739Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Land and Building No. 1033, Ground Floor, Modi Street
```

Fort, Sector 104, 106,108, Fort, 400001, State - Maharashtra, India",
"updatedBy": "62550ed0aba01e0af98f2f75",
"addressForMap": "",
"caseReferredBy": "665ac13f42f4717ae30de3d5",
"contactPersonName": "M/s Papier 365 Global Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9892159132"

}

Name	Length	Width	Total
Composition :			
Other Composition :			