

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Sushant",
    "type": "CREDITOFFICER",
    "_id": "6588fc67b7b4df714da9091b",
    "lastName": "More",
    "mobileNo": "",
    "workMobileNo": "9768177407",
    "email": "sushantmore.racpcSION@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Sushant",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      }
    }
  ]
}
```

```
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.164359501641727",
  "longitude": "72.95820008960551"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.95820008960551,
    19.164359501641727
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-12",
      "remark": ""
    }
  ]
},
],
```

```
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulund",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "7",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
}
```

```
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Supremo Phase - II",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "90 Feet Road, Near Kelkar College",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C, Building No. 1, Sakura",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```



```
"status": false,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1289 (Pt.), 1290 (Pt.), 1292 (Pt.), 1293(Pt.) & others ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "704",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
```

```
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 081",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund (East)",
  "label": false
}
},
"flatSpecifications": {
```

```
"roof": {
  "value": "Proposed_R.C.C._Slab",
  "label": "Proposed R.C.C. Slab"
},
"flooring": {
  "value": "Proposed_Vitrified_tiles_flooring",
  "label": "Proposed Vitrified tiles flooring"
},
"doors": {
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
  "label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
  "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
},
"finishing": {
  "value": "Proposed_Cement_Plastering",
  "label": "Proposed Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
```

```
"label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Internal Road",
  "south": "Open Plot ",
  "east": "Under Construction Building "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building is under construction ",
    "east": "Building is under construction ",
    "south": "Building is under construction ",
    "west": "Building is under construction "
  },
  "asPerDocument": {
    "north": "Marginal Space ",
    "east": "Marginal Space ",
    "south": "Staircase ",
    "west": "Flat No. 703"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of Flat will be 1 Bedrooms + Living Room + Kitchen + Passage + 2 Toilets. (i.e. 1BHK)",
```

```
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. CHE / ES / 2027 /  
T / 337 (New) / 337 / 4 Amend dated 05.02.2025 issued by MCGM.",  
"approvePlanVerified": "Yes",  
"empanelledOfApprovePlan": "Building is under construction ",  
"unauthorizedConstruction": "",  
"extraDetailOfBuilding": "",  
"compoundWall": ""  
},  
"apfDetails": {  
  "buildings": [],  
  "compositions": []  
},  
"compositeRate": {  
  "remark": "",  
  "depreciationPercentage": "0",  
  "depreciationRatioOfBuilding": "",  
  "salvageValue": "",  
  "buildingServicesDepreciatedRate": "0",  
  "depreciatedCostOfConstruction": "21000.00",  
  "depreciatedBuildingRate": "3000"  
},  
"igrRate": {  
  "propertyName": "Residential Flat",  
  "rate": "133330",  
  "landRate": "67520",  
  "igrImage": "cases/67ab255a19ca979ae9473b97/igr_1739363238612_Image.png",  
  "squareMeterGuideLineRate": "139997.00",  
  "squareFeetGuideLineRate": "13006.00"  
},  
"igrFinalRate": {  
  "floorRatePercentage": "5",  
  "depreciationPercentage": "0",  
  "rate": "133330.00",  
  "squareMeterGuideLineRate": "139997.00",  
  "squareFeetGuideLineRate": "13006.00"  
},  
"outgoingDetail": {  
  "areaStatusList": {  
    "value": "Medium",  
    "label": "Medium"  
  },  
  "propertyTypeOfUseList": {  
    "value": "Proposed_Residential_Purpose",  
    "label": "Proposed Residential Purpose"  
  },  
  "propertyOccupiedByList": {
```

```
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MCGM norms ",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Open / Covered Car Parking Space ",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2030",
  "fullDate": "1/1/2030"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
```

```
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "6",
"noOfAmenityFloors": "1",
"noOfFloors": "47",
"flatFloorNo": "7",
"noOfLifts": "5",
"noOfDwellingUnitsInBuilding": "8"
},
```



```
"finalPlinthArea": {
  "area": "536.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67ab255a19ca979ae9473b97/
routeMap_1739426421513_Image.png",
    "routeLat": "19.163647",
    "routeLng": "72.958857",
    "stationName": "Mulund",
    "routeDistance": "1.00 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "ieby09",
      "name": "ieby09",
      "image": "cases/67ab255a19ca979ae9473b97/
routeMap_1739426334259_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    }
  },
}
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "10248000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "10248000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "Complete",
  "percentage": "5",
  "isHideFloor": false,
  "status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "22",
  "percentage": "15.714285714285715",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "14",
  "percentage": "1.75",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "27.46",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6981621.00",
  "selectedBuildUpValue": "536.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67ac3f7736a56c9b5f660ab2",
      "name": "externalImg_1739341685048_1739341681711_image_1.jpeg",
      "path": "cases/67ab255a19ca979ae9473b97/externalImg_1739341685048_1739341681711_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67ac3f7736a56c9b5f660ab2",
      "name": "externalImg_1739341685048_1739341681711_image_1.jpeg",
      "path": "cases/67ab255a19ca979ae9473b97/externalImg_1739341685048_1739341681711_image_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ac3f7736a56c9b5f660ab4",
    "name": "externallmg_1739341686294_1739341681711_image_3.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341686294_1739341681711_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ac3f7736a56c9b5f660ab5",
    "name": "externallmg_1739341686412_1739341681711_image_4.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341686412_1739341681711_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ac3f7736a56c9b5f660ab6",
    "name": "externallmg_1739341686626_1739341681711_image_5.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341686626_1739341681711_image_5.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "19823.00",
    "max": "21905.00"
  },
  "builtUpRateRange": {
    "min": "18021.00",
    "max": "19914.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
}
```



```
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "488.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67ab255a19ca979ae9473b97",
"ownerName": "Vijesh Vithoba Mahadik & Roshani Baban Kate",
"ownerPhoneNo": "9819097108",
"appAddress": "Flat no. 704, 7th Floor, Wing - C, Sakura, Building no 1, Supremo
Phase 2, Mulund East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    }
  },
  "inputs": {
```

```
"remark": " made in the year 2025",
"from": {
  "value": "Developers",
  "label": "Developers"
},
"Developers": "M/s. K.V. Buildhome LLP.",
"to": {
  "value": "Allottee",
  "label": "Allottee"
},
"Allottee": "Vijesh Vithoba Mahadik & Roshani Baban Kate"
},
"isHardCopy": false,
"displayStatus": true,
"id": "929496",
"path": "cases/67ab255a19ca979ae9473b97/
document_1739269453583_1739269451438_C_704_Agreement.pdf",
"fileName": "document_1739269453583_1739269451438_C_704_Agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/03/2024",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE/ES/2027/T/337(NEW)/FCC/1/Amend"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739424121977_1739363292171_CC.pdf",
  "path": "cases/67ab255a19ca979ae9473b97/
document_1739424121977_1739363292171_CC.pdf",
  "id": "399508",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Feb 13 2025 05:22:02 GMT+0000 (Coordinated Universal Time)"
},
{
```

```
"documentType": {
  "value": "60ae1277aa6d152c1801b3cc",
  "label": "Approved Building Plan"
},
"inputs": {
  "documentDate": "05/02/2025",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_of_Greater_Mumbai",
    "label": "Municipal Corporation of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "CHE / ES / 2027 / T / 337 (New) / 337 / 4 Amend "
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1739424194347_1739363281271_Approved_plan.pdf",
"path": "cases/67ab255a19ca979ae9473b97/
document_1739424194347_1739363281271_Approved_plan.pdf",
"id": "717059",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Feb 13 2025 05:23:17 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "05/10/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800052921"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739424235925_1739363294224_Rera_Certificate.pdf",
  "path": "cases/67ab255a19ca979ae9473b97/
document_1739424235925_1739363294224_Rera_Certificate.pdf",
```

```
"id": "683113",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Feb 13 2025 05:23:56 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014245",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
"id": "149719",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Tue Feb 11 2025 10:24:26 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Vijesh Vithoba Mahadik & Roshani Baban Kate",
"phone": "9819097108",
"ownershipShare": "",
"email": "",
"id": "976752"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60ae1256aa6d152c1801b330",
"label": "Draft Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
}
},
{id": "840914",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "488",
"squareMeterArea": "45.34",
"docFinalBuiltUp": "536.8",
"docFinalBuiltUpSquareMeter": "49.874",
"docBultupPercentage": "10",
```

```
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "630.00",
"squareMeterArea": "58.53",
"expectedRate": "21904.76",
"percentage": ""
},
"builtUpArea": {
"area": "693.00",
"squareMeterArea": "64.38",
"expectedRate": "19913.42",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67ac93b1d716769af0d5e0e4",
"property": "Residential Flat",
"area": "630",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.proptiger.com/",
"expectedPrice": "13800000",
"expectedRate": "21904.76",
"builtUpExpectedRate": "19913.42",
"image": "cases/67ab255a19ca979ae9473b97/
indicator_1739363003619_Image.png",
"squareMeter": "58.53",
"id": "143271"
},
{
"carpetArea": {
```

```
"area": "427.00",
"squareMeterArea": "39.67",
"expectedRate": "21311.48",
"percentage": ""
},
"builtUpArea": {
"area": "469.70",
"squareMeterArea": "43.64",
"expectedRate": "19374.07",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67ac93b1d716769af0d5e0e5",
"property": "Residential Flat",
"area": "427",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "9100000",
"expectedRate": "21311.48",
"builtUpExpectedRate": "19374.07",
"image": "cases/67ab255a19ca979ae9473b97/
indicator_1739362682412_Image.png",
"squareMeter": "39.67",
"id": "990155"
},
{
"carpetArea": {
"area": "660",
"squareMeterArea": "61.32",
"expectedRate": "19822.95",
"percentage": ""
},
"builtUpArea": {
"area": "726.00",
"squareMeterArea": "67.45",
"expectedRate": "18020.87",
```

```
"percentage": ""
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67ac93b1d716769af0d5e0e6",
"property": "Residential Flat",
"area": "726",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "13083148",
"expectedRate": "19822.95",
"builtUpExpectedRate": "13083148",
"image": "cases/67ab255a19ca979ae9473b97/
indicator_1739362832594_Image.png",
"squareMeter": "67.45",
"id": "939274"
},
{
  "carpetArea": {
    "area": "660",
    "squareMeterArea": "61.32",
    "expectedRate": "19822.95",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "726.00",
    "squareMeterArea": "67.45",
    "expectedRate": "18020.87",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
```

```
    "_id": "67ac93b1d716769af0d5e0e7",
    "property": "Residential Flat",
    "area": "726",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "13083148",
    "expectedRate": "19822.95",
    "builtUpExpectedRate": "13083148",
    "image": "cases/67ab255a19ca979ae9473b97/
indicator_1739362876914_Image.png",
    "squareMeter": "67.45",
    "id": "254872"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac3f7736a56c9b5f660ab1",
    "name": "externallmg_1739341683790_1739341681711_image_0.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341683790_1739341681711_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac3f7736a56c9b5f660ab2",
    "name": "externallmg_1739341685048_1739341681711_image_1.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341685048_1739341681711_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac3f7736a56c9b5f660ab3",
    "name": "externallmg_1739341685621_1739341681711_image_2.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341685621_1739341681711_image_2.jpeg",
    "orientation": "portrait"
  },
]
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac3f7736a56c9b5f660ab4",
  "name": "externallmg_1739341686294_1739341681711_image_3.jpeg",
  "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341686294_1739341681711_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac3f7736a56c9b5f660ab5",
  "name": "externallmg_1739341686412_1739341681711_image_4.jpeg",
  "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341686412_1739341681711_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac3f7736a56c9b5f660ab6",
  "name": "externallmg_1739341686626_1739341681711_image_5.jpeg",
  "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341686626_1739341681711_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac3f5d19ca979ae947a953",
  "name": "externallmg_1739341630689_1739341627181_image_0.jpeg",
  "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341630689_1739341627181_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac3f5d19ca979ae947a954",
  "name": "externallmg_1739341632312_1739341627181_image_1.jpeg",
  "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341632312_1739341627181_image_1.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac3f5d19ca979ae947a955",
    "name": "externallmg_1739341636857_1739341627181_image_2.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341636857_1739341627181_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac3f5d19ca979ae947a956",
    "name": "externallmg_1739341639829_1739341627181_image_3.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341639829_1739341627181_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac3f5d19ca979ae947a957",
    "name": "externallmg_1739341642232_1739341627181_image_4.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341642232_1739341627181_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac3f5d19ca979ae947a958",
    "name": "externallmg_1739341645629_1739341627181_image_5.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341645629_1739341627181_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac3f5d19ca979ae947a959",
    "name": "externallmg_1739341648981_1739341627181_image_6.jpeg",
    "path": "cases/67ab255a19ca979ae9473b97/
externallmg_1739341648981_1739341627181_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "67ac3f5d19ca979ae947a95a",
  "name": "externalImg_1739341657286_1739341627181_image_7.jpeg",
  "path": "cases/67ab255a19ca979ae9473b97/
externalImg_1739341657286_1739341627181_image_7.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1709275509675_Calculation_Sheet_NEW.xlsx",
    "filename": "1739363279744_1709275509675_Calculation_Sheet_NEW.xlsx",
    "path": "cases/67ab255a19ca979ae9473b97/processingDocuments/173936327974
4_1709275509675_Calculation_Sheet_NEW.xlsx",
    "size": "3256637",
    "createdAt": "Wed Feb 12 2025 12:28:14 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Approved plan.pdf",
    "filename": "1739363281271_Aproved_plan.pdf",
    "path": "cases/67ab255a19ca979ae9473b97/
processingDocuments/1739363281271_Aproved_plan.pdf",
    "size": "22863564",
    "createdAt": "Wed Feb 12 2025 12:28:14 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1739363292171_CC.pdf",
    "path": "cases/67ab255a19ca979ae9473b97/
processingDocuments/1739363292171_CC.pdf",
    "size": "131440",
    "createdAt": "Wed Feb 12 2025 12:28:14 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Reference Report.pdf",
    "filename": "1739363292577_Reference_Report.pdf",
    "path": "cases/67ab255a19ca979ae9473b97/
processingDocuments/1739363292577_Reference_Report.pdf",
    "size": "1619493",
    "createdAt": "Wed Feb 12 2025 12:28:14 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
}
```

```
{
  "originalname": "Rera Certificate.pdf",
  "filename": "1739363294224_Rera_Certificate.pdf",
  "path": "cases/67ab255a19ca979ae9473b97/
processingDocuments/1739363294224_Rera_Certificate.pdf",
  "size": "703340",
  "createdAt": "Wed Feb 12 2025 12:28:14 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67ac8e7cd716769af0d5dc36",
    "note": "Value given for confirmation",
    "taskId": "67ab351519ca979ae9475344",
    "createdAt": "2025-02-12T12:05:16.374Z"
  }
],
"createdAt": "2025-02-11T10:24:26.036Z",
"updatedAt": "2025-02-13T06:04:34.903Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 704, 7th Floor, Wing - C, Building No. 1, Sakura,
Supremo Phase - II, 90 Feet Road, Near Kelkar College, Village - Mulund, Mulund
(East), Taluka - Kurla, District - Mumbai Suburban, PIN - 400 081, State - Maharashtra,
Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Habib Sayyed "
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person ",
"rerald": "",
"siteVisitContactNo": "7304686730",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 488.00",
"flatRate": "21000",
"landOtherRate": "18000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 442.00\nBalcony / Deck Area
in Sq. Ft. = 28.00\nKitchen Balcony / Deck Area in Sq. Ft. = 18.00\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
```

```
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
}
}
```

Name	Length	Width	Total
Composition :			
Other Composition :			