

```
{
  "typeOfReport": {
    "label": "Land",
    "value": "Land"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "firstName": "Paresh Shirude",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230eb4",
    "email": "0_default_paresh.shirude@cosmosbank.in",
    "mobileNo": "0_DEFAULT_022-24391501",
    "workMobileNo": "0_DEFAULT_91-9820196523"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "64813151",
    "discussWithPerson": "Paresh Shirude",
    "expectedFees": 32406.5755,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.074228212790636",
  "longitude": "73.01431072084944"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    73.01431072084944,
    19.074228212790636
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "11/02/2025 06:00 pm",
      "remark": ""
    },
    {
      "dateTime": "11/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "1",
  "lumpsumValue": "1",
  "rateMax": "1",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1438",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "KWC, Kalamboli",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "ACC Sheet Roofing",
    "value": "ACC_Sheet_Roofing"
  },
  "flooring": {
    "label": "Vitrified tile flooring",
    "value": "Vitrified_tile_flooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
  "windows": {
    "label": "M.S. Grill Fixed Windows",
    "value": "M.S._Grill_Fixed_Windows"
  },
  "fittings": {
```

```
"label": "Concealed Plumbing with Conduit & Concealed Electrical wiring",
"value": "Concealed_Plumbing_with_Conduit_&_Concealed_Electrical_wiring"
},
"finishing": {
  "label": "Cement plastering",
  "value": "Cement_plastering"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Semi Urban",
    "value": "Semi_Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "plot no 1437",
    "west": "road no 15/2",
    "south": "plot no 1439",
    "east": "road no 16/2"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  },
}
```

```
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial Purpose",
    "value": "Commercial_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
```

```
"label": "CIDCO",
"value": "CIDCO"
},
"pavementLaid": {
"label": "No",
"value": "No"
},
"carParking": {
"label": "Open Parking",
"value": "Open_Parking"
},
"constructionWorkStatus": {
"label": "Completed",
"value": "Completed"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2025",
"fullDate": "1/1/2025"
},
"propertyTypeList": {
"label": "Residential",
"value": "Residential"
},
"planningArea": {
"label": "Residential",
"value": "Residential"
},
"typeOfStructure": {
"label": "Semi/ Half Pukka Structure",
"value": "Semi/_Half_Pukka_Structure"
},
"qualityOfConstruction": {
"label": "Normal",
"value": "Normal"
},
"walls": {
"label": "Yes",
"value": "1"
},
"appearanceOfTheBuilding": {
"label": "Normal",
"value": "Normal"
},
"maintenanceOfTheBuilding": {
```

```
"label": "Normal",
"value": "Normal"
},
"visibleDamageInBuilding": {
"label": "No",
"value": "0"
},
"groundStilt": {
"label": "Ground",
"value": "ground"
},
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0"
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
"coordinates": []
},
"locationMapImg": []
},
"valuation": {
"fairMarketValue": {
"costOfConstruction": "",
"depreciationPercentage": "",
"depreciatedCostOfConstruction": "",
"totalFairMarketValue": ""
}
```

```
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```



```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67ab2cc019ca979ae94747e0",
"ownerName": "Sushil daruka ",
"ownerPhoneNo": "0000000000",
"appAddress": "plot 1438, KWC, Kalam boli, Navi Mumbai, ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1739274185232_plot_no_1438_1.pdf",
    "path": "cases/67ab2cc019ca979ae94747e0/
document_1739274185232_plot_no_1438_1.pdf",
    "id": "625211",
    "uploadedBy": "62691c48afd7d55eddecfd3",
    "createdAt": "Tue Feb 11 2025 11:43:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014248",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "272860",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 11 2025 10:56:00 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Sushil daruka ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "624704"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "67acef25d716769af0d5f0e5",
    "area": "9363",
    "providedByName": "Sushil daruka ",
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "325341",
    "name": "Unit Area",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f2",
```

```
    "name": "externalImg_1739386873055_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_1739386873055_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f3",
    "name": "externalImg_1739386874780_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_1739386874780_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f4",
    "name": "externalImg_1739387003630_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_1739387003630_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f5",
    "name": "externalImg_r_1739386810472_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_r_1739386810472_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f6",
    "name": "externalImg_r_1739386823345_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_r_1739386823345_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f7",
    "name": "externalImg_r_1739386845551_image.jpeg",
```

```
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386845551_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f8",
    "name": "externallmg_r_1739386791897_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386791897_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690f9",
    "name": "externallmg_r_1739386876245_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386876245_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690fa",
    "name": "externallmg_r_1739386858481_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386858481_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690fb",
    "name": "externallmg_r_1739386904082_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386904082_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f6690fc",
    "name": "externallmg_r_1739386889281_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386889281_image.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f6690fd",
  "name": "externallmg_r_1739386913142_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386913142_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f6690fe",
  "name": "externallmg_r_1739386923560_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386923560_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f6690ff",
  "name": "externallmg_r_1739386950475_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386950475_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669100",
  "name": "externallmg_r_1739386936776_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386936776_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669101",
  "name": "externallmg_r_1739386975480_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386975480_image.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669102",
  "name": "externalImg_r_1739386963376_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_r_1739386963376_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669103",
  "name": "externalImg_r_1739386981492_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_r_1739386981492_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669104",
  "name": "externalImg_r_1739386988109_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_r_1739386988109_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669105",
  "name": "externalImg_r_1739386996109_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_r_1739386996109_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669106",
  "name": "externalImg_1739386896390_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalImg_1739386896390_image.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669107",
  "name": "externallmg_1739386898981_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_1739386898981_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669108",
  "name": "externallmg_1739387017579_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_1739387017579_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669109",
  "name": "externallmg_r_1739386813276_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386813276_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f66910a",
  "name": "externallmg_r_1739386791626_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386791626_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f66910b",
  "name": "externallmg_r_1739386831701_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386831701_image.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f66910c",
    "name": "externallmg_r_1739386851917_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386851917_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f66910d",
    "name": "externallmg_r_1739386901705_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386901705_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f66910e",
    "name": "externallmg_r_1739386874860_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386874860_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f66910f",
    "name": "externallmg_r_1739386949290_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386949290_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f669110",
    "name": "externallmg_r_1739386923885_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externallmg_r_1739386923885_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67acf09036a56c9b5f669111",
  "name": "externalimg_r_1739386966275_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739386966275_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669112",
  "name": "externalimg_r_1739386977191_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739386977191_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669113",
  "name": "externalimg_r_1739386991860_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739386991860_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669114",
  "name": "externalimg_r_1739386985307_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739386985307_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67acf09036a56c9b5f669115",
  "name": "externalimg_r_1739386997292_image.jpeg",
  "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739386997292_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67acf09036a56c9b5f669116",
    "name": "externalimg_r_1739387003531_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739387003531_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f669117",
    "name": "externalimg_r_1739387011108_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739387011108_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f669118",
    "name": "externalimg_r_1739387007301_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739387007301_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67acf09036a56c9b5f669119",
    "name": "externalimg_r_1739387014723_image.jpeg",
    "path": "cases/67ab2cc019ca979ae94747e0/
externalimg_r_1739387014723_image.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-11T10:56:00.137Z",
"updatedAt": "2025-02-12T19:04:17.783Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
}
```

"fullAddress": "Residential Land No. Basement Floor, Plot No. 1438, KWC, Kalamboli,  
 Navi Mumbai, State - Maharashtra, India",  
 "updatedBy": "65829f7c65d49d78457ec7be",  
 "addressForMap": "",  
 "caseReferredBy": "62723addafd7d55eddeddfe4",  
 "contactPersonName": "Sushil daruka ",  
 "email": "",  
 "isExternal": "false",  
 "isUrgent": "false",  
 "ownershipShare": "",  
 "proposePurchaserName": "",  
 "purchaseValueAsPerDocument": "",  
 "relationWithOwner": "self",  
 "rerald": "",  
 "siteVisitContactNo": "0000000000",  
 "briefDescOfProperty": "Unit Area",  
 "carpetTotal": "1",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "0"

Name	Length	Width	Total
Composition :			
Unit Area	1'00"	1'00"	1.00
Other Composition :			