

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba90"
    },
    "firstName": "Punit",
    "type": "CREDITOFFICER",
    "_id": "6698dd71e4681c3f5822a92c",
    "email": "sbi.06613@sbi.co.in",
    "lastName": "P.Lohia",
    "mobileNo": "",
    "workMobileNo": "8625914492"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9484648",
    "discussWithPerson": "Punit",
    "expectedFees": 4742.3240000000005,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba90",
  "branchCode": "000279",
  "type": "BRANCH",
  "name": "Industrial Finance Branch Sakinaka",
  "email": "sbi.06613@sbi.co.in",
  "mobileNo": "02228527554",
  "alternateMobileNo": "",
  "address": "1st Floor, Lekhraj Bhawan, Sakivihar Road, Andheri (East), Mumbai -
400072, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
```

```
"latitude": "19.5424793525883",
"longitude": "73.1385499343089"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.1385499343089,
    19.5424793525883
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "4/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Kondhale",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Wada",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "398",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```

```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```



```
"status": false,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421312",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Wada",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
}
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67ab313836a56c9b5f65ad0a",
"ownerName": "Orson Resins And Coatings Private limited ",
"ownerPhoneNo": "0000000000",
"appAddress": "Gut no - 398/2, kondhale, Wada, Palghar ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    }
  },
  "attachInReport": false,
```

```
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67ab313836a56c9b5f65ad0a/
document_1739272407060_2_Wada.pdf",
    "fileName": "document_1739272407060_2_Wada.pdf",
    "id": "658324",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Tue Feb 11 2025 11:15:03 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014249",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "399149",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 11 2025 11:15:04 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Orson Resins And Coatings Private limited ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "797261"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b4ef",
    "name": "externalImg_1741606907513_1741606897043_image_0.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externalImg_1741606907513_1741606897043_image_0.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f0",
  "name": "externallmg_1741606908129_1741606897043_image_1.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606908129_1741606897043_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f1",
  "name": "externallmg_1741606908450_1741606897043_image_2.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606908450_1741606897043_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f2",
  "name": "externallmg_1741606908660_1741606897043_image_3.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606908660_1741606897043_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f3",
  "name": "externallmg_1741606909136_1741606897043_image_4.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606909136_1741606897043_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f4",
  "name": "externallmg_1741606909554_1741606897043_image_5.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606909554_1741606897043_image_5.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f5",
  "name": "externallmg_1741606909856_1741606897043_image_6.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606909856_1741606897043_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f6",
  "name": "externallmg_1741606910244_1741606897043_image_7.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606910244_1741606897043_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f7",
  "name": "externallmg_1741606910558_1741606897043_image_8.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606910558_1741606897043_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f8",
  "name": "externallmg_1741606910924_1741606897043_image_9.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606910924_1741606897043_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ced0057e0bb1d5cc32b4f9",
  "name": "externallmg_1741606911259_1741606897043_image_10.jpeg",
  "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606911259_1741606897043_image_10.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b4fa",
    "name": "externallmg_1741606911641_1741606897043_image_11.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606911641_1741606897043_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b4fb",
    "name": "externallmg_1741606912037_1741606897043_image_12.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606912037_1741606897043_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b4fc",
    "name": "externallmg_1741606912376_1741606897043_image_13.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606912376_1741606897043_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b4fd",
    "name": "externallmg_1741606914473_1741606897043_image_14.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606914473_1741606897043_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b4fe",
    "name": "externallmg_1741606915291_1741606897043_image_15.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606915291_1741606897043_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b4ff",
    "name": "externallmg_1741606916191_1741606897043_image_16.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606916191_1741606897043_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b500",
    "name": "externallmg_1741606916623_1741606897043_image_17.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606916623_1741606897043_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ced0057e0bb1d5cc32b501",
    "name": "externallmg_1741606917091_1741606897043_image_18.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606917091_1741606897043_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e23",
    "name": "externallmg_1741606949585_1741606947014_image_0.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606949585_1741606947014_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e24",
    "name": "externallmg_1741606950999_1741606947014_image_1.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606950999_1741606947014_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "67ced033021414d63ce01e25",
    "name": "externallmg_1741606952701_1741606947014_image_2.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606952701_1741606947014_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e26",
    "name": "externallmg_1741606953967_1741606947014_image_3.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606953967_1741606947014_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e27",
    "name": "externallmg_1741606954616_1741606947014_image_4.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606954616_1741606947014_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e28",
    "name": "externallmg_1741606957328_1741606947014_image_5.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606957328_1741606947014_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e29",
    "name": "externallmg_1741606958411_1741606947014_image_6.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externallmg_1741606958411_1741606947014_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e2a",
```

```
    "name": "externalImg_1741606959046_1741606947014_image_7.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externalImg_1741606959046_1741606947014_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e2b",
    "name": "externalImg_1741606959487_1741606947014_image_8.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externalImg_1741606959487_1741606947014_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e2c",
    "name": "externalImg_1741606961072_1741606947014_image_9.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externalImg_1741606961072_1741606947014_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ced033021414d63ce01e2d",
    "name": "externalImg_1741606962464_1741606947014_image_10.jpeg",
    "path": "cases/67ab313836a56c9b5f65ad0a/
externalImg_1741606962464_1741606947014_image_10.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-11T11:15:04.239Z",
"updatedAt": "2025-03-10T11:42:43.041Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Land and Building No. Basement Floor, Plot No. 398,
```


Village - Kondhale, Wada, Taluka - Wada, District - Palghar, 421312, State - Maharashtra, India",

"updatedBy": "62550ed0aba01e0af98f2f75",

"addressForMap": "",

"caseReferredBy": "62723addafd7d55eddeddfe4",

"contactPersonName": "Orson Resins And Coatings Private limited ",

"email": "",

"isExternal": "false",

"isUrgent": "false",

"ownershipShare": "",

"proposePurchaserName": "",

"purchaseValueAsPerDocument": "",

"relationWithOwner": "self",

"reId": "",

"siteVisitContactNo": "0000000000"

}

Name

Length

Width

Total

Composition :

Other

Composition :
