

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "677908cfa5477d50e7dcfbaf"
    },
    "firstName": "Abhishek",
    "type": "CREDITOFFICER",
    "_id": "677908f182ea0d50e10160c8",
    "email": "cb7065@canarabank.com",
    "lastName": "Arora",
    "mobileNo": "",
    "workMobileNo": "7718873563"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4500000",
    "discussWithPerson": "Abhishek",
    "expectedFees": 2250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "676544371f06b62faf373ec8",
  "type": "BANK",
  "name": "Canara Bank",
  "displayName": "Canara Bank",
  "initial": "CNB"
},
"branch": {
  "_id": "677908cfa5477d50e7dcfbaf",
  "name": "Retail Asset Hub, Vasai",
  "branchCode": "7065",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "cb7065@canarabank.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "God's Gift Bunglow, Mary Villa Stuo, Stela, Manickpur, Vasai-401202"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "6765457131b0132fc5831fcc",
  "zoneName": "MUMBAI"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "659ccce98f39506e83489828",
    "role": "DELIVERYPERSON",
    "firstName": "Amit",
    "email": "amitsalvi2909@gmail.com",
```

```
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "67776d60a5477d50e7dbc213",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "AJAY",
"email": "ajayrewale503@gmail.com",
"lastName": "REWALE",
"mobileNo": "9766640171",
"designation": "",
"shortName": "AJAY",
"workWithDocumentMaker": "",
"profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
},
"rateVerifier": null,
"maker": {
"type": "EMPLOYEE",
"_id": "663da98cfcea71232186f142",
"role": "ACCOUNTANT",
"firstName": "SONAL ",
"email": "sonal.ambekar19@gmail.com",
"lastName": " SHIVGAN",
"mobileNo": "9773395869",
"designation": "",
"shortName": "SO",
"workWithDocumentMaker": "",
"profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
],
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
```

```
    }
  ]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.450915143651383",
  "longitude": "72.82475032636853"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82475032636853,
    19.450915143651383
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "12/02/2025 09:00 am",
      "remark": ""
    },
    {
      "dateTime": "12/02/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Samrth Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shree Swami Samarth Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401 303",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar (East)",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67ab5ec519ca979ae9477552",
"ownerName": "Mr. Pankaj Bhalcharndra Vartak",
"ownerPhoneNo": "9967707727",
"appAddress": "FLAT NO 102 1ST FLOOR D WING BLDG NO 2 SHREE SAMARTH
```

```
APARTMENT SHREE SWAMI SAMARTH NAGAR VIRAR EAST PALGHAR 401303",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67ab5ec519ca979ae9477552/
document_1739284060135_1739284057574_Pankaj_vartak_agreement.pdf",
    "fileName":
"document_1739284060135_1739284057574_Pankaj_vartak_agreement.pdf",
    "id": "729074",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Tue Feb 11 2025 14:29:25 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014256",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "663222",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 11 2025 14:29:25 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Pankaj Bhalcharndra Vartak",
    "phone": "9967707727",
    "ownershipShare": "",
    "email": "",
    "id": "597421"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac409836a56c9b5f660c10",
    "name": "externalImg_1739341918508_1739341915543_image_0.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739341918508_1739341915543_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac409836a56c9b5f660c11",
    "name": "externalImg_1739341924906_1739341915543_image_1.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739341924906_1739341915543_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac409836a56c9b5f660c12",
    "name": "externalImg_1739341936227_1739341915543_image_2.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739341936227_1739341915543_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac409836a56c9b5f660c13",
    "name": "externalImg_1739341937844_1739341915543_image_3.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739341937844_1739341915543_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac409836a56c9b5f660c14",
    "name": "externalImg_1739341940136_1739341915543_image_4.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739341940136_1739341915543_image_4.jpeg",
    "orientation": "portrait"
  },
  },
]
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac409836a56c9b5f660c15",
  "name": "externallmg_1739341945464_1739341915543_image_5.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341945464_1739341915543_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac409836a56c9b5f660c16",
  "name": "externallmg_1739341948795_1739341915543_image_6.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341948795_1739341915543_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac409836a56c9b5f660c17",
  "name": "externallmg_1739341954532_1739341915543_image_7.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341954532_1739341915543_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac409836a56c9b5f660c18",
  "name": "externallmg_1739341962576_1739341915543_image_8.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341962576_1739341915543_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac409836a56c9b5f660c19",
  "name": "externallmg_1739341966780_1739341915543_image_9.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341966780_1739341915543_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac409836a56c9b5f660c1a",
    "name": "externallmg_1739341967782_1739341915543_image_10.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341967782_1739341915543_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac409836a56c9b5f660c1b",
    "name": "externallmg_1739341971681_1739341915543_image_11.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341971681_1739341915543_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d1b",
    "name": "externallmg_1739341989940_1739341943902_image_0.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341989940_1739341943902_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d1c",
    "name": "externallmg_1739341991000_1739341943902_image_1.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341991000_1739341943902_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d1d",
    "name": "externallmg_1739341992476_1739341943902_image_2.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341992476_1739341943902_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67ac40d336a56c9b5f660d1e",
  "name": "externallmg_1739341994140_1739341943902_image_3.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341994140_1739341943902_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac40d336a56c9b5f660d1f",
  "name": "externallmg_1739341994574_1739341943902_image_4.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341994574_1739341943902_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac40d336a56c9b5f660d20",
  "name": "externallmg_1739341995944_1739341943902_image_5.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341995944_1739341943902_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac40d336a56c9b5f660d21",
  "name": "externallmg_1739341998697_1739341943902_image_6.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341998697_1739341943902_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac40d336a56c9b5f660d22",
  "name": "externallmg_1739341999776_1739341943902_image_7.jpeg",
  "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739341999776_1739341943902_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67ac40d336a56c9b5f660d23",
    "name": "externallmg_1739342009333_1739341943902_image_8.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739342009333_1739341943902_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d24",
    "name": "externallmg_1739342009806_1739341943902_image_9.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739342009806_1739341943902_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d25",
    "name": "externallmg_1739342012293_1739341943902_image_10.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739342012293_1739341943902_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d26",
    "name": "externallmg_1739342015217_1739341943902_image_11.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739342015217_1739341943902_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d27",
    "name": "externallmg_1739342016716_1739341943902_image_12.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externallmg_1739342016716_1739341943902_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d28",
```

```
    "name": "externalImg_1739342018872_1739341943902_image_13.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739342018872_1739341943902_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d29",
    "name": "externalImg_1739342021232_1739341943902_image_14.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739342021232_1739341943902_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac40d336a56c9b5f660d2a",
    "name": "externalImg_1739342023693_1739341943902_image_15.jpeg",
    "path": "cases/67ab5ec519ca979ae9477552/
externalImg_1739342023693_1739341943902_image_15.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-11T14:29:25.722Z",
"updatedAt": "2025-02-12T06:33:55.052Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 102, 1st Floor, Wing - D, Shree Samrth Apartment,
Shree Swami Samarth Nagar, Virar (East), 401 303, State - Maharashtra, India",
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Pankaj Bhalcharndra Vartak",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
```



```
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"rerald": "",  
"siteVisitContactNo": "9967707727"
```

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			