

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63fc957bce84bf289baa55ec"
    },
    "firstName": "Rambhau",
    "type": "CREDITOFFICER",
    "_id": "67776c1382ea0d50e1005de8",
    "email": "sbi.051168@sbi.co.in",
    "lastName": "Taktewale",
    "mobileNo": "",
    "workMobileNo": "9561064635"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
  }
}
```

```
"discussWithPerson": "Rambhau",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63fc957bce84bf289baa55ec",
  "name": "SARB Churchgate",
  "branchCode": "",
  "mobileNo": "02222053163",
  "alternateMobileNo": "",
  "email": "sarc.mumbai@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "6th Floor, International 16, Maharshi Karve Road, Churchgate, Mumbai -
400020, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
```

```
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "67776d60a5477d50e7dbc213",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "AJAY",
    "email": "ajayrewale503@gmail.com",
    "lastName": "REWALE",
    "mobileNo": "9766640171",
    "designation": "",
    "shortName": "AJAY",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "663da98cfcea71232186f142",
```

```
"role": "ACCOUNTANT",
"firstName": "SONAL ",
"email": "sonal.ambekar19@gmail.com",
"lastName": " SHIVGAN",
"mobileNo": "9773395869",
"designation": "",
"shortName": "SO",
"workWithDocumentMaker": "",
"profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
},
_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
```

```
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.227159730675705",
  "longitude": " 72.85171991623118"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85171991623118,
    19.227159730675705
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-12",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-11",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-11",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Eksar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai City & Mumbai Suburban",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "132 (4), TPS-III",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Hansh Priya Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "62nd Road",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off Factory Lane, Chikuwadi",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```



```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "528 (Part), 687 (Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```

```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 092",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  }
}
```

```
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "Alluminum_sliding_windows_with_M._S._Grills",
  "label": "Alluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Amar - I Apartment & Factory Lane",
    "west": "V. D. Valia College",
    "south": "V. D. Valia College",
    "east": "Dr. D. G. Palkar Road"
  },
}
```

```
"asPerDocumentAgreement": {
  "north": "62nd Road & Final Plot No. 131",
  "west": "Final Plot No. 131 & 129",
  "south": "Final Plot No. 129",
  "east": "Final Plot No. 140 & 141"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Staircase & Flat No. 402",
    "east": "Marginal Space",
    "south": "Marginal Space",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved Building Plan were not provided & not verified",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
```

```
"compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "21786",
  "depreciatedBuildingRate": "2086"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "134430",
  "landRate": "58240",
  "igrImage": "cases/67ac427819ca979ae947ac38/igr_1739426655452_Image.png",
  "squareMeterGuideLineRate": "134430.00",
  "squareFeetGuideLineRate": "12489.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "83",
  "rate": "11286.00",
  "squareFeetGuideLineRate": "11286.00",
  "squareMeterGuideLineRate": "121478.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant_Bank_Possession",
    "label": "Vacant- Bank Possession"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "Information not available",
```

```
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2008",
    "fullDate": "1/1/2008"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  }
}
```

```
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
```

```
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "43",
"ageOfBuilding": "17",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
"area": "1132.00",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area as per Agreement"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/67ac427819ca979ae947ac38/
routeMap_1739516220633_Image.png",
"routeLat": "19.226958",
```



```
"routeLng": "72.851792",
"stationName": "Borivali",
"routeDistance": "700 Mtr.",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "k8nc18",
    "name": "k8nc18",
    "image": "cases/67ac427819ca979ae947ac38/
routeMap_1739516170493_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "24661752.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "24661752.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "12775752.00",
  "selectedBuildUpValue": "1132.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67ac64b919ca979ae947d457",
      "name": "externalImg_1739351082443_1739351045074_image_6.jpeg",
      "path": "cases/67ac427819ca979ae947ac38/
externalImg_1739351082443_1739351045074_image_6.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67ac64c536a56c9b5f663764",
      "name": "externalImg_1739351155999_1739351127194_image_0.jpeg",
      "path": "cases/67ac427819ca979ae947ac38/
externalImg_1739351155999_1739351127194_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67ac64c536a56c9b5f663767",
      "name": "externalImg_1739351167777_1739351127194_image_3.jpeg",
      "path": "cases/67ac427819ca979ae947ac38/
externalImg_1739351167777_1739351127194_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "67ac64c536a56c9b5f663768",
  "name": "externallmg_1739351169893_1739351127194_image_4.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351169893_1739351127194_image_4.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67ac64c536a56c9b5f66376b",
  "name": "externallmg_1739351178948_1739351127194_image_7.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351178948_1739351127194_image_7.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67ac64c536a56c9b5f66376f",
  "name": "externallmg_1739351191943_1739351127194_image_11.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351191943_1739351127194_image_11.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67ac64c536a56c9b5f663772",
  "name": "externallmg_1739351202887_1739351127194_image_14.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351202887_1739351127194_image_14.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67ac64b919ca979ae947d462",
  "name": "externallmg_1739351190718_1739351045074_image_17.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351190718_1739351045074_image_17.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67ac64b919ca979ae947d460",
  "name": "externallmg_1739351149153_1739351045074_image_15.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351149153_1739351045074_image_15.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ac64b919ca979ae947d456",
    "name": "externallmg_1739351075912_1739351045074_image_5.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351075912_1739351045074_image_5.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26455.00",
    "max": "35573.00"
  },
  "builtUpRateRange": {
    "min": "22046.00",
    "max": "29644.00"
  },
  "saleableRateRange": {
    "min": "18372.00",
    "max": "24704.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```

```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1132.00",
"empanelmentNo": [
  "SME/TCC/2021-22/85/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67ac427819ca979ae947ac38",
"ownerName": "Mrs. Nita P. Jain & Mr. Pravinchand P. Jain",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 403,4Floor,Hansh Priya ,Chiku wadi Borivali West",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "14/11/2006",
      "amount": "Rs. 26,89,160.00",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Raghuvanshi Developers",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mrs. Nita P. Jain & Mr. Pravinchand P. Jain",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "9031/2006"
    }
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1739514434374_Agreement___Neta_P_Jain.pdf",
    "path": "cases/67ac427819ca979ae947ac38/
document_1739514434374_Agreement___Neta_P_Jain.pdf",
    "id": "731244",
    "uploadedBy": "663da98cfcea71232186f142",
    "createdAt": "Fri Feb 14 2025 06:27:17 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014262",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "361931",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Feb 12 2025 06:40:56 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Nita P. Jain & Mr. Pravinchand P. Jain",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "134513"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "342754",
    "name": "Living Room",
    "length": "21.33",
    "length1": "21",
    "length2": "4",
    "width": "10.25",
    "width1": "10",
    "width2": "3",
```

```
"totalArea": "218.67",
"images": [],
"extraAreas": [],
"finalArea": "218.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "11.25",
  "width1": "11",
  "width2": "3",
  "totalArea": "115.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "115.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "7.08",
  "width1": "7",
  "width2": "1",
  "totalArea": "85.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "3",
"name": "Bedroom",
"length": "12.58",
"length1": "12",
"length2": "7",
"width": "10.17",
"width1": "10",
"width2": "2",
"totalArea": "127.93",
"images": [],
"extraAreas": [],
"finalArea": "127.93"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.42",
  "length1": "5",
  "length2": "5",
  "width": "6.25",
  "width1": "6",
  "width2": "3",
  "totalArea": "33.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.85"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "17.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "17.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "13.33",
  "length1": "13",
  "length2": "4",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
  "totalArea": "138.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "138.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "5.42",
  "length1": "5",
  "length2": "5",
  "width": "6.17",
  "width1": "6",
  "width2": "2",
  "totalArea": "33.40",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.40"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
```

```
"length": "7.58",
"length1": "7",
"length2": "7",
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "29.07",
"images": [],
"extraAreas": [],
"finalArea": "29.07"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "13.67",
  "length1": "13",
  "length2": "8",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "132.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "132.11"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "105.17",
    "totalAreaDocument": "1132",
    "docBuiltpPercentage": ""
  }
]
```

```
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "131278"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "716.67",
"squareMeterArea": "66.58",
"expectedRate": "34185.89",
"percentage": ""
},
"builtUpArea": {
"area": "860.00",
"squareMeterArea": "79.90",
"expectedRate": "28488.37",
"percentage": "20"
},
"saleableArea": {
"area": "1032.00",
"squareMeterArea": "95.88",
"expectedRate": "23740.31",
"percentage": "20"
},
"printlnReport": true,
"_id": "67ad8b9119ca979ae9485529",
"property": "Residential Flat",
"area": "860",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "24500000",
"expectedRate": "34185.89",
"builtUpExpectedRate": "24500000",
"image": "cases/67ac427819ca979ae947ac38/
indicator_1739426320100_Image.png",
"squareMeter": "79.90",
"id": "188774"
```



```
},
{
  "carpetArea": {
    "area": "655.00",
    "squareMeterArea": "60.85",
    "expectedRate": "35572.52",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "786.00",
    "squareMeterArea": "73.02",
    "expectedRate": "29643.77",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "943.20",
    "squareMeterArea": "87.63",
    "expectedRate": "24703.14",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67ad8b9119ca979ae948552a",
  "property": "Residential Flat",
  "area": "786",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "23300000",
  "expectedRate": "35572.52",
  "builtUpExpectedRate": "23300000",
  "image": "cases/67ac427819ca979ae947ac38/
indicator_1739426363436_Image.png",
  "squareMeter": "73.02",
  "id": "432184"
},
{
  "carpetArea": {
    "area": "883.62",
    "squareMeterArea": "82.09",
    "expectedRate": "28405.88",
    "percentage": ""
  },
  "builtUpArea": {
```

```
    "area": "1060.35",
    "squareMeterArea": "98.51",
    "expectedRate": "23671.43",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1272.42",
    "squareMeterArea": "118.21",
    "expectedRate": "19726.19",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67ad8b9119ca979ae948552b",
  "property": "Residential Flat",
  "area": "1060.35",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "25100000",
  "expectedRate": "28405.88",
  "builtUpExpectedRate": "25100000",
  "image": "cases/67ac427819ca979ae947ac38/
indicator_1739426439492_Image.png",
  "squareMeter": "98.51",
  "id": "178934"
},
{
  "carpetArea": {
    "area": "1100.00",
    "squareMeterArea": "102.19",
    "expectedRate": "26454.55",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1320.00",
    "squareMeterArea": "122.63",
    "expectedRate": "22045.45",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1584.00",
    "squareMeterArea": "147.16",
    "expectedRate": "18371.21",
```

```
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67ad8b9119ca979ae948552c",
  "property": "Residential Flat",
  "area": "1100",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "29100000",
  "expectedRate": "26454.55",
  "builtUpExpectedRate": "22045.45",
  "image": "cases/67ac427819ca979ae947ac38/
indicator_1739426603392_Image.png",
  "squareMeter": "102.19",
  "id": "546522"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac64c536a56c9b5f663764",
    "name": "externallmg_1739351155999_1739351127194_image_0.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351155999_1739351127194_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac64c536a56c9b5f663765",
    "name": "externallmg_1739351162323_1739351127194_image_1.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351162323_1739351127194_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac64c536a56c9b5f663766",
    "name": "externallmg_1739351166738_1739351127194_image_2.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351166738_1739351127194_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663767",
  "name": "externallmg_1739351167777_1739351127194_image_3.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351167777_1739351127194_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663768",
  "name": "externallmg_1739351169893_1739351127194_image_4.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351169893_1739351127194_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663769",
  "name": "externallmg_1739351172547_1739351127194_image_5.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351172547_1739351127194_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f66376a",
  "name": "externallmg_1739351177117_1739351127194_image_6.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351177117_1739351127194_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f66376b",
  "name": "externallmg_1739351178948_1739351127194_image_7.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351178948_1739351127194_image_7.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f66376c",
  "name": "externallmg_1739351184408_1739351127194_image_8.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351184408_1739351127194_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f66376d",
  "name": "externallmg_1739351186970_1739351127194_image_9.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351186970_1739351127194_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f66376e",
  "name": "externallmg_1739351189798_1739351127194_image_10.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351189798_1739351127194_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f66376f",
  "name": "externallmg_1739351191943_1739351127194_image_11.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351191943_1739351127194_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663770",
  "name": "externallmg_1739351194878_1739351127194_image_12.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351194878_1739351127194_image_12.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663771",
  "name": "externallmg_1739351199248_1739351127194_image_13.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351199248_1739351127194_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663772",
  "name": "externallmg_1739351202887_1739351127194_image_14.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351202887_1739351127194_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663773",
  "name": "externallmg_1739351206374_1739351127194_image_15.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351206374_1739351127194_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663774",
  "name": "externallmg_1739351208797_1739351127194_image_16.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351208797_1739351127194_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ac64c536a56c9b5f663775",
  "name": "externallmg_1739351218678_1739351127194_image_17.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351218678_1739351127194_image_17.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ac64c536a56c9b5f663776",
    "name": "externallmg_1739351227079_1739351127194_image_18.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351227079_1739351127194_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d451",
    "name": "externallmg_1739351049640_1739351045074_image_0.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351049640_1739351045074_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d452",
    "name": "externallmg_1739351057473_1739351045074_image_1.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351057473_1739351045074_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d453",
    "name": "externallmg_1739351061772_1739351045074_image_2.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351061772_1739351045074_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d454",
    "name": "externallmg_1739351068759_1739351045074_image_3.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351068759_1739351045074_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "67ac64b919ca979ae947d455",
  "name": "externallmg_1739351069939_1739351045074_image_4.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351069939_1739351045074_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac64b919ca979ae947d456",
  "name": "externallmg_1739351075912_1739351045074_image_5.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351075912_1739351045074_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac64b919ca979ae947d457",
  "name": "externallmg_1739351082443_1739351045074_image_6.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351082443_1739351045074_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac64b919ca979ae947d458",
  "name": "externallmg_1739351086779_1739351045074_image_7.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351086779_1739351045074_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ac64b919ca979ae947d459",
  "name": "externallmg_1739351096947_1739351045074_image_8.jpeg",
  "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351096947_1739351045074_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```



```
    "_id": "67ac64b919ca979ae947d45a",
    "name": "externallmg_1739351104353_1739351045074_image_9.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351104353_1739351045074_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d45b",
    "name": "externallmg_1739351110053_1739351045074_image_10.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351110053_1739351045074_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d45c",
    "name": "externallmg_1739351115762_1739351045074_image_11.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351115762_1739351045074_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d45d",
    "name": "externallmg_1739351129527_1739351045074_image_12.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351129527_1739351045074_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d45e",
    "name": "externallmg_1739351137648_1739351045074_image_13.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351137648_1739351045074_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d45f",
```

```
    "name": "externallmg_1739351145303_1739351045074_image_14.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351145303_1739351045074_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d460",
    "name": "externallmg_1739351149153_1739351045074_image_15.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351149153_1739351045074_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d461",
    "name": "externallmg_1739351167880_1739351045074_image_16.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351167880_1739351045074_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d462",
    "name": "externallmg_1739351190718_1739351045074_image_17.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351190718_1739351045074_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d463",
    "name": "externallmg_1739351194854_1739351045074_image_18.jpeg",
    "path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351194854_1739351045074_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ac64b919ca979ae947d464",
    "name": "externallmg_1739351202472_1739351045074_image_19.jpeg",
```

```
"path": "cases/67ac427819ca979ae947ac38/
externallmg_1739351202472_1739351045074_image_19.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Nita P Jain - Flat No. 403 - State Bank of India ( SARB
Churchgate ).xlsx",
  "filename": "1739426688039_Nita_P_Jain___Flat_No_403___State_Bank_of_India
__SARB_Churchgate_.xlsx",
  "path": "cases/67ac427819ca979ae947ac38/processingDocuments/1739426688039
_Nita_P_Jain___Flat_No_403___State_Bank_of_India__SARB_Churchgate_.xlsx",
  "size": "773209",
  "createdAt": "Thu Feb 13 2025 06:04:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67ac8ca636a56c9b5f667f07",
  "note": "Value given for confirmation",
  "taskId": "67ac4feed716769af0d56984",
  "createdAt": "2025-02-12T11:57:26.355Z"
}
],
"createdAt": "2025-02-12T06:40:56.211Z",
"updatedAt": "2025-02-14T07:40:00.777Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"fullAddress": "Residential Flat No. 403, 4th Floor, Hansh Priya Co-Op. Hsg. Soc. Ltd.,
Plot No. 132 (4), TPS-III, 62nd Road, Off Factory Lane, Chikuwadi, Village - Eksar,
Borivali (West), Taluka - Borivali, District - Mumbai City & Mumbai Suburban, Mumbai,
400 092, State - Maharashtra, India",
"updatedBy": "663da98cfcea71232186f142",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Rambhau Taktewale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Banker",
"rerald": "",
"siteVisitContactNo": "9561064635",
"siteVisitDate": "2025-02-11",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1132.00",
"flatRate": "22500",
"landOtherRate": "19700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + 3 Toilet +
Passage",
"carpetTotal": "931.23",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1024.35",
"finalCarpetArea": "931.23",
"finalSalableArea": "1126.79",
"salablePercentage": "10",
"toBeAdded": "",
```

```

"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Feb 14 2025 06:16:18 GMT+0000 (Coordinated Universal Time)"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	21'4"	10'3"	218.67
Dining	10'3"	11'3"	115.31
Kitchen	12'00"	7'1"	85.00
Bedroom	12'7"	10'2"	127.93
Toilet	5'5"	6'3"	33.85
Passage	4'3"	4'00"	17.00
Bedroom	13'4"	10'5"	138.89
Toilet	5'5"	6'2"	33.40
Toilet	7'7"	3'10"	29.07
Bedroom	13'8"	9'8"	132.11

Other  
Composition :

---