

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b98b"
    },
    "firstName": "Vinod Kumar",
    "type": "CREDITOFFICER",
    "_id": "679ca5067dd57116683e434b",
    "email": "Khar.MumbaiNorth@bankofindia.co.in",
    "lastName": "Taur",
    "mobileNo": "",
    "workMobileNo": "9923992304"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6484648",
```

```
"discussWithPerson": "Vinod Kumar",
"expectedFees": 3242.324,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b98b",
  "branchCode": "000024",
  "type": "BRANCH",
  "name": "Khar (West) Branch",
  "email": "Khar.MumbaiNorth@bankofindia.co.in",
  "mobileNo": "02226495008",
  "alternateMobileNo": null,
  "address": "Khar Telephone Exchange Building,Ground Floor,Khar Pali Road,Khar
(West) Mumbai-400052, State - Maharashtra, Country - India",
  "ledgerName": null,
  "fax": null,
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4336576061dae469362",
```

```
"zoneName": "Mumbai South Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65829f7c65d49d78457ec7be",
    "role": "SITEENGINEER",
    "firstName": "Vaibhav",
    "email": "vaib1234b@gmail.com",
    "lastName": "Bhagat",
    "mobileNo": "8779534609",
    "designation": "Bachlore Of Engireeing",
    "shortName": "Vaibhav",
    "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "62fe044a48a26047e6552796",
    "role": "MAKER",
```

```
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "[N]C.C.I.T/I -14/52/2008-09",
      "label": "Wealth Tax"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": " Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
```

```
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.252032535549493",
  "longitude": "72.98333764374513"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.98333764374513,
    19.252032535549493
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "13/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-13T08:38:59.141Z",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "20000",
  "lumpsumValue": "1",
  "rateMax": "21000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "2.5BHK",
```

```
"label": "2.5 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kolshet",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Thane ",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Eden Castle",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "G.B. Road, Behind Hiranandani Hospital",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B, Building No. 2",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Platinum Heritage",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```



```
"value": "136/1, 137/6, 137/11",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 607",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
```

```
},
"flooring": {
  "label": "Vitrified tile flooring",
  "value": "Vitrified_tile_flooring"
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "Aluminium_Sliding_Windows_with_window_grills",
  "label": "Aluminium Sliding Windows with window grills"
},
"fittings": {
  "label": "Concealed Plumbing with Conduit & Concealed Electrical wiring",
  "value": "Concealed_Plumbing_with_Conduit_&_Concealed_Electrical_wiring"
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Club House ",
    "west": "Hiranandani Hospital ",
```

```
"south": "Internal Road & Open Plot ",
"east": "Open Plot "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Passage ",
    "east": "Staircase ",
    "south": "Flat No. 602",
    "west": "Flat No. 603"
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
```

```
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "312",
  "depreciatedCostOfConstruction": "16988.00",
  "depreciatedBuildingRate": "2288"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "118200",
  "landRate": "21300",
  "igrImage": "cases/67acb853d716769af0d5edfa/igr_1742204235860_Image.png",
  "squareMeterGuideLineRate": "124110.00",
  "squareFeetGuideLineRate": "11530.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "92",
  "rate": "10766.00",
  "squareFeetGuideLineRate": "10766.00",
  "squareMeterGuideLineRate": "115885.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
```

```
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per TMC norms ",
"tenantName": "",
"maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": "Along with One Car Parking Space ",
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2017",
```

```
"fullDate": "1/1/2017"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "14",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "840.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
```



```
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67acb853d716769af0d5edfa/
routeMap_1742276328362_Image.png",
    "routeLat": "19.250361",
    "routeLng": "72.983056",
    "stationName": "Thane ",
    "routeDistance": "8.1 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "u6fubh",
      "name": "u6fubh",
      "image": "cases/67acb853d716769af0d5edfa/
routeMap_1742276256607_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```

```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "12978832.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "12978832.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "9047746.00",
  "selectedBuildUpValue": "840.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67adaf8fd716769af0d654e0",
      "name": "externalimg_r_1739435773053_image.jpeg",
      "path": "cases/67acb853d716769af0d5edfa/
externalimg_r_1739435773053_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67adae8636a56c9b5f66e4d5",
      "name": "externalimg_r_1739435452616_image.jpeg",
      "path": "cases/67acb853d716769af0d5edfa/
externalimg_r_1739435452616_image.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67adae8636a56c9b5f66e4d3",
```

```
    "name": "externallmg_r_1739435449805_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435449805_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67adae8636a56c9b5f66e4dd",
    "name": "externallmg_r_1739435477551_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435477551_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67adae8636a56c9b5f66e4df",
    "name": "externallmg_r_1739435515349_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435515349_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67adae8636a56c9b5f66e4e0",
    "name": "externallmg_r_1739435538231_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435538231_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67adae8636a56c9b5f66e4de",
    "name": "externallmg_r_1739435496930_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435496930_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67adae8636a56c9b5f66e4e1",
    "name": "externallmg_r_1739435554831_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435554831_image.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "status": false,
    "_id": "67adae8636a56c9b5f66e4e3",
    "name": "externallmg_r_1739435575036_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435575036_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67adaf8fd716769af0d654df",
    "name": "externallmg_1739435890976_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_1739435890976_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67adaf8fd716769af0d654e9",
    "name": "externallmg_r_1739435892246_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435892246_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67adaf8fd716769af0d654e5",
    "name": "externallmg_r_1739435870928_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435870928_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67adaf8fd716769af0d654e0",
    "name": "externallmg_r_1739435773053_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435773053_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67adaf8fd716769af0d654e1",
    "name": "externallmg_r_1739435798506_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435798506_image.jpeg",
    "orientation": "portrait"
  }
```

```
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16165.00",
    "max": "19048.00"
  },
  "builtUpRateRange": {
    "min": "14696.00",
    "max": "17317.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```



```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
  "presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "764.00",
"empanelmentNo": [
  "KZO /CR/19-20/582"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67acb853d716769af0d5edfa",
"ownerName": "Mr. Pramod Vitthal Kubal",
"ownerPhoneNo": "9320303251",
"appAddress": "flat no - 604, 6th floor, Bldg no 2, wing B, Eden, castle platinumheritag
kolshet,Thane West ",
"remark": "tomorrow morning visit ",
"documents": [
  {
    "documentType": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "22/01/2019",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Darshan Sagar Developers ",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Pramod Vitthal Kubal",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "1056 / 2019"
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "836414",
    "path": "cases/67acb853d716769af0d5edfa/
document_1742200931999_1742200924022_Pramod_Kubal__BOI_khar.pdf",
    "fileName":
"document_1742200931999_1742200924022_Pramod_Kubal__BOI_khar.pdf"
  },
  {
    "documentType": {
      "label": "Commencement Certificate",
      "value": "60ae1247aa6d152c1801b2ea"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "16/01/2015",
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    },
    "No": "S05 / 0051 / 12 / TMC / TDD / 1333 / 15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1742271748455_940961.pdf",
  "path": "cases/67acb853d716769af0d5edfa/
document_1742271748455_940961.pdf",
  "id": "357922",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Mar 18 2025 04:22:28 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014277",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "626245",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Wed Feb 12 2025 15:03:47 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Pramod Vitthal Kubal",
"phone": "9320303251",
"ownershipShare": "",
"email": "",
"id": "929468"
}
],
"proposePurchasers": [],
"siteInspection": [
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
}_id": "67adacf436a56c9b5f66e45a",
"area": "798",
"providedByName": "Pramod Vitthal kubal ",
"providedByContactNo": "9320303251"
}
],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "8",
"name": "Living Room",
"length": "",
"length1": "14",
"length2": "11",
"width": "",
"width1": "9",
"width2": "11",
"totalArea": "147.92",
```

```
"images": [],
"finalArea": "211.92",
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "67d8ff2a700ebc688493bdce",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "10.00"
  }
],
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "70.59",
  "images": [],
  "extraAreas": [],
  "finalArea": "70.59"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
```

```
"length": "13.92",
"length1": "13",
"length2": "11",
"width": "3.67",
"width1": "3",
"width2": "8",
"totalArea": "51.03",
"images": [],
"extraAreas": [],
"finalArea": "51.03"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "9.33",
  "width1": "9",
  "width2": "4",
  "totalArea": "92.56",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "67d8fd78700ebc688493ba2d",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "11.00",
      "length1": "11",
      "length2": "00",
      "width": "1.00",
      "width1": "1",
      "width2": "00",
      "totalArea": "11.00"
    }
  ],
  "finalArea": "103.56"
},
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "13.00",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "67d8fe0601f1c07601e44c1c",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "4.42",
      "length1": "4",
      "length2": "5",
      "width": "3.75",
      "width1": "3",
      "width2": "9",
      "totalArea": "16.56"
    }
  ],
  "finalArea": "29.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "8.75",
  "length1": "8",
  "length2": "9",
  "width": "8.17",
```



```
"width1": "8",
"width2": "2",
"totalArea": "71.46",
"images": [],
"extraAreas": [],
"finalArea": "71.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "11.92",
  "width1": "11",
  "width2": "11",
  "totalArea": "116.19",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "67d8fea5700ebc688493bd13",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "6.75",
      "length1": "6",
      "length2": "9",
      "width": "1.92",
      "width1": "1",
      "width2": "11",
      "totalArea": "12.94"
    }
  ],
  "finalArea": "129.13"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "7",
  "name": "Toilet",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "27.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.19"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "9.92",
    "length1": "9",
    "length2": "11",
    "width": "1.75",
    "width1": "1",
    "width2": "9",
    "totalArea": "17.35",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
          "value": "Square_Feet",
          "label": "Square Feet"
        },
        "_id": "67d8fd8401f1c07601e44af1",
        "name": "Extra "
      }
    ]
  }
]
```

```
"extraAreaType": "Add",
"length": "7.00",
"length1": "7",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "7.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "67d8fe6101f1c07601e44d12",
  "name": "Etra ",
  "extraAreaType": "Add",
  "length": "18.00",
  "length1": "18",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "18.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "67d8fec901f1c07601e44e39",
  "name": "Extra ",
  "extraAreaType": "Add",
  "length": "2.92",
  "length1": "2",
  "length2": "11",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "28.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
    "_id": "67d8fed101f1c07601e44e5d",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "2.00",
    "length1": "2",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "2.00"
  }
],
"finalArea": "73.27",
"percentageBeforeTotal": "73.27",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "1.75",
  "length1": "1",
  "length2": "9",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "15.31",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "67d8fe18700ebc688493bb9b",
      "name": "Extr "
```

```
    "extraAreaType": "Add",
    "length": "15.00",
    "length1": "15",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "15.00"
  }
],
"finalArea": "30.31",
"percentageBeforeTotal": "30.31",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "70.98",
    "totalAreaDocument": "764",
    "docBuiltpPercentage": "10",
    "docFinalBuiltp": "840.40",
    "docFinalBuiltpSquareMeter": "78.08",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "500033"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "735.00",
      "squareMeterArea": "68.28",
      "expectedRate": "19047.62",
      "percentage": ""
    }
  }
]
```

```
},
"builtUpArea": {
  "area": "808.50",
  "squareMeterArea": "75.11",
  "expectedRate": "17316.02",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "67d7ed6cdf28417602b9f6ab",
"property": "Flat",
"area": "735",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "14000000",
"expectedRate": "19047.62",
"builtUpExpectedRate": "17316.02",
"image": "cases/67acb853d716769af0d5edfa/
indicator_1742203936791_Image.png",
"squareMeter": "68.28",
"id": "934540"
},
{
  "carpetArea": {
    "area": "701.00",
    "squareMeterArea": "65.13",
    "expectedRate": "18544.94",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "771.10",
    "squareMeterArea": "71.64",
    "expectedRate": "16859.03",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
```

```
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67d7ed6cdf28417602b9f6ac",
  "property": "Flat",
  "area": "701",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "13000000",
  "expectedRate": "18544.94",
  "builtUpExpectedRate": "16859.03",
  "image": "cases/67acb853d716769af0d5edfa/
indicator_1742203965724_Image.png",
  "squareMeter": "65.13",
  "id": "280346"
},
{
  "carpetArea": {
    "area": "700.00",
    "squareMeterArea": "65.03",
    "expectedRate": "18857.14",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "770.00",
    "squareMeterArea": "71.54",
    "expectedRate": "17142.86",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67d7ed6cdf28417602b9f6ad",
  "property": "Flat",
  "area": "700",
  "builtUpPercentage": "10",
```

```
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "13200000",
"expectedRate": "18857.14",
"builtUpExpectedRate": "17142.86",
"image": "cases/67acb853d716769af0d5edfa/
indicator_1742204005193_Image.png",
"squareMeter": "65.03",
"id": "881620"
},
{
  "carpetArea": {
    "area": "764.00",
    "squareMeterArea": "70.98",
    "expectedRate": "16164.92",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "840.40",
    "squareMeterArea": "78.08",
    "expectedRate": "14695.38",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67d7ed6cdf28417602b9f6ae",
  "property": "Flat",
  "area": "764",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "12350000.00",
  "expectedRate": "16164.92",
  "builtUpExpectedRate": "14695.38",
  "image": "cases/67acb853d716769af0d5edfa/
indicator_1742204028841_Image.png",
```



```
    "squareMeter": "70.98",
    "id": "518519"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d2",
    "name": "externalImg_1739435449072_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externalImg_1739435449072_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d3",
    "name": "externalImg_r_1739435449805_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435449805_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d4",
    "name": "externalImg_r_1739435444017_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435444017_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d5",
    "name": "externalImg_r_1739435452616_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435452616_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d6",
    "name": "externalImg_r_1739435437521_image.jpeg",
```

```
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435437521_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d7",
    "name": "externallmg_r_1739435456945_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435456945_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d8",
    "name": "externallmg_r_1739435460136_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435460136_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4d9",
    "name": "externallmg_r_1739435464005_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435464005_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4da",
    "name": "externallmg_r_1739435469467_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435469467_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adae8636a56c9b5f66e4db",
    "name": "externallmg_r_1739435466587_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435466587_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4dc",
  "name": "externallmg_r_1739435472320_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435472320_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4dd",
  "name": "externallmg_r_1739435477551_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435477551_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4de",
  "name": "externallmg_r_1739435496930_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435496930_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4df",
  "name": "externallmg_r_1739435515349_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435515349_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4e0",
  "name": "externallmg_r_1739435538231_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435538231_image.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4e1",
  "name": "externalimg_r_1739435554831_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalimg_r_1739435554831_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4e2",
  "name": "externalimg_r_1739435565878_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalimg_r_1739435565878_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4e3",
  "name": "externalimg_r_1739435575036_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalimg_r_1739435575036_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4e4",
  "name": "externalimg_r_1739435593260_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalimg_r_1739435593260_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adae8636a56c9b5f66e4e5",
  "name": "externalimg_r_1739435615973_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalimg_r_1739435615973_image.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adaf8fd716769af0d654df",
  "name": "externalImg_1739435890976_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalImg_1739435890976_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adaf8fd716769af0d654e0",
  "name": "externalImg_r_1739435773053_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435773053_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adaf8fd716769af0d654e1",
  "name": "externalImg_r_1739435798506_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435798506_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adaf8fd716769af0d654e2",
  "name": "externalImg_r_1739435816244_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435816244_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67adaf8fd716769af0d654e3",
  "name": "externalImg_r_1739435785649_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435785649_image.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adaf8fd716769af0d654e4",
    "name": "externallmg_r_1739435845004_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435845004_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adaf8fd716769af0d654e5",
    "name": "externallmg_r_1739435870928_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435870928_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adaf8fd716769af0d654e6",
    "name": "externallmg_r_1739435858161_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435858161_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adaf8fd716769af0d654e7",
    "name": "externallmg_r_1739435829885_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435829885_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67adaf8fd716769af0d654e8",
    "name": "externallmg_r_1739435882576_image.jpeg",
    "path": "cases/67acb853d716769af0d5edfa/
externallmg_r_1739435882576_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67adaf8fd716769af0d654e9",
  "name": "externalImg_r_1739435892246_image.jpeg",
  "path": "cases/67acb853d716769af0d5edfa/
externalImg_r_1739435892246_image.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2) - kubal.xlsx",
    "filename": "1742203595343_Calculation_2__kubal.xlsx",
    "path": "cases/67acb853d716769af0d5edfa/
processingDocuments/1742203595343_Calculation_2__kubal.xlsx",
    "size": "16094",
    "createdAt": "Mon Mar 17 2025 09:26:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - kubal.xlsx",
    "filename": "1742204260208_Summary__kubal.xlsx",
    "path": "cases/67acb853d716769af0d5edfa/
processingDocuments/1742204260208_Summary__kubal.xlsx",
    "size": "2057121",
    "createdAt": "Mon Mar 17 2025 09:37:40 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67ad955bd716769af0d635b1",
    "note": "pending for docs.",
  }
]
```

```
"taskId": "67ad658836a56c9b5f669294",
"createdAt": "2025-02-13T06:46:51.654Z"
},
{
  "createdBy": {
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67d7eae6700ebc6884933e57",
  "note": "value shared",
  "taskId": "67ad658836a56c9b5f669294",
  "createdAt": "2025-03-17T09:27:02.773Z"
}
],
"createdAt": "2025-02-12T15:03:47.683Z",
"updatedAt": "2025-03-18T05:42:14.633Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 604, 6th Floor, Wing - B, Building No. 2, Eden
Castle, Platinum Heritage, G.B. Road, Behind Hiranandani Hospital, Village - Kolshet,
Thane (West), Taluka - Thane , District - Thane , PIN - 400 607, State - Maharashtra,
Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mr. Pramod Vitthal Kubal\n",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"rerad": "",
"siteVisitContactNo": "9320303251",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
```



```
"carpetTotal": "694.44",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2025-02-13",
"buildingServicesRate": "2600",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 764.00",
"flatRate": "17300",
"landOtherRate": "14700",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 666.00\nEnclosed Balcony Area in
Sq. Ft. = 82.00\nDry Balcony Area in Sq. Ft. = 16.00",
"finalBuiltupArea": "877.82",
"finalCarpetArea": "798.02",
"finalSalableArea": "965.60",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 695.00\nBalcony Area in Sq. Ft.
= 73.00\nDry Balcony Area in Sq. Ft. = 30.00\n\n",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "103.58",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
```

}
}
}

Name	Length	Width	Total
Composition :			
Living Room	14'11"	9'11"	147.92
Kitchen	8'11"	7'11"	70.59
Passage	13'11"	3'8"	51.03
Bedroom	9'11"	9'4"	92.56
Toilet	3'3"	4'00"	13.00
Bedroom	8'9"	8'2"	71.46
Bedroom	9'9"	11'11"	116.19
Toilet	3'8"	7'5"	27.19
Other Composition :			
Balcony Area	9'11"	1'9"	17.35
Dry Balcony Area	1'9"	8'9"	15.31