

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba90"
    },
    "firstName": "Punit",
    "type": "CREDITOFFICER",
    "_id": "6698dd71e4681c3f5822a92c",
    "email": "sbi.06613@sbi.co.in",
    "lastName": "P.Lohia",
    "mobileNo": "",
    "workMobileNo": "8625914492"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "94843184",
    "discussWithPerson": "Punit",
    "expectedFees": 47421.592000000004,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba90",
  "branchCode": "000279",
  "type": "BRANCH",
  "name": "Industrial Finance Branch Sakinaka",
  "email": "sbi.06613@sbi.co.in",
  "mobileNo": "02228527554",
  "alternateMobileNo": "",
  "address": "1st Floor, Lekhraj Bhawan, Sakivihar Road, Andheri (East), Mumbai -
400072, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
```

```
"latitude": "19.5279313594836",
"longitude": "73.13983802858351"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.13983802858351,
    19.5279313594836
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "4/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Kondhale",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Wada",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "398",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```

```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```



```
"status": false,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421312",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Wada",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
}
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67adb3dbd716769af0d65d15",
"ownerName": "Orson Resins And Coatings Private limited ",
"ownerPhoneNo": "0000000000",
"appAddress": "Gat no - 398/1, village - Kondhale, Wada, Palghar ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    }
  },
  "attachInReport": false,
```

```
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67adb3dbd716769af0d65d15/
document_1739437001026_1739436997406_Land_at_Wada_Sale_Agreement_1.pdf",
    "fileName": "document_1739437001026_1739436997406_Land_at_Wada_Sale_Ag
reement_1.pdf",
    "id": "254782",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Thu Feb 13 2025 08:56:58 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014294",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "577933",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Feb 13 2025 08:56:59 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Orson Resins And Coatings Private limited ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "335989"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32adce",
    "name": "externalImg_1741605637788_1741605631436_image_0.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605637788_1741605631436_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32adcf",
  "name": "externallmg_1741605638256_1741605631436_image_1.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605638256_1741605631436_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32add0",
  "name": "externallmg_1741605638734_1741605631436_image_2.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605638734_1741605631436_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32add1",
  "name": "externallmg_1741605638811_1741605631436_image_3.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605638811_1741605631436_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32add2",
  "name": "externallmg_1741605639631_1741605631436_image_4.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605639631_1741605631436_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32add3",
  "name": "externallmg_1741605640096_1741605631436_image_5.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605640096_1741605631436_image_5.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32add4",
    "name": "externallmg_1741605640468_1741605631436_image_6.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605640468_1741605631436_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32add5",
    "name": "externallmg_1741605640714_1741605631436_image_7.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605640714_1741605631436_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32add6",
    "name": "externallmg_1741605641098_1741605631436_image_8.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605641098_1741605631436_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32add7",
    "name": "externallmg_1741605641465_1741605631436_image_9.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605641465_1741605631436_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32add8",
    "name": "externallmg_1741605641740_1741605631436_image_10.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605641740_1741605631436_image_10.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32add9",
  "name": "externallmg_1741605642195_1741605631436_image_11.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605642195_1741605631436_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32adda",
  "name": "externallmg_1741605642713_1741605631436_image_12.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605642713_1741605631436_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32addb",
  "name": "externallmg_1741605643086_1741605631436_image_13.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605643086_1741605631436_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32addc",
  "name": "externallmg_1741605643328_1741605631436_image_14.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605643328_1741605631436_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cecb0d7e0bb1d5cc32addd",
  "name": "externallmg_1741605643667_1741605631436_image_15.jpeg",
  "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605643667_1741605631436_image_15.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32adde",
    "name": "externalImg_1741605643983_1741605631436_image_16.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605643983_1741605631436_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32addf",
    "name": "externalImg_1741605644276_1741605631436_image_17.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605644276_1741605631436_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32ade0",
    "name": "externalImg_1741605644639_1741605631436_image_18.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605644639_1741605631436_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cecb0d7e0bb1d5cc32ade1",
    "name": "externalImg_1741605644952_1741605631436_image_19.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605644952_1741605631436_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243943a",
    "name": "externalImg_1741605708648_1741605705434_image_0.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605708648_1741605705434_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67cecb538037ced5d243943b",
    "name": "externallmg_1741605708828_1741605705434_image_1.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605708828_1741605705434_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243943c",
    "name": "externallmg_1741605709073_1741605705434_image_2.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605709073_1741605705434_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243943d",
    "name": "externallmg_1741605709262_1741605705434_image_3.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605709262_1741605705434_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243943e",
    "name": "externallmg_1741605709673_1741605705434_image_4.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605709673_1741605705434_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243943f",
    "name": "externallmg_1741605709947_1741605705434_image_5.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605709947_1741605705434_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "67cecb538037ced5d2439440",
    "name": "externallmg_1741605710159_1741605705434_image_6.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605710159_1741605705434_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439441",
    "name": "externallmg_1741605710517_1741605705434_image_7.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605710517_1741605705434_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439442",
    "name": "externallmg_1741605710740_1741605705434_image_8.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605710740_1741605705434_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439443",
    "name": "externallmg_1741605711046_1741605705434_image_9.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605711046_1741605705434_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439444",
    "name": "externallmg_1741605711348_1741605705434_image_10.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605711348_1741605705434_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439445",
```



```
    "name": "externallmg_1741605711885_1741605705434_image_11.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605711885_1741605705434_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439446",
    "name": "externallmg_1741605712303_1741605705434_image_12.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605712303_1741605705434_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439447",
    "name": "externallmg_1741605712720_1741605705434_image_13.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605712720_1741605705434_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439448",
    "name": "externallmg_1741605713058_1741605705434_image_14.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605713058_1741605705434_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d2439449",
    "name": "externallmg_1741605713484_1741605705434_image_15.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externallmg_1741605713484_1741605705434_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243944a",
    "name": "externallmg_1741605713824_1741605705434_image_16.jpeg",
```

```
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605713824_1741605705434_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243944b",
    "name": "externalImg_1741605714285_1741605705434_image_17.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605714285_1741605705434_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243944c",
    "name": "externalImg_1741605714740_1741605705434_image_18.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605714740_1741605705434_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cecb538037ced5d243944d",
    "name": "externalImg_1741605714992_1741605705434_image_19.jpeg",
    "path": "cases/67adb3dbd716769af0d65d15/
externalImg_1741605714992_1741605705434_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-13T08:56:59.149Z",
"updatedAt": "2025-03-10T11:21:55.658Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62550ed0aba01e0af98f2f75",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
}
```

"fullAddress": "Residential Land and Building No. Ground Floor, Plot No. 398, Village -
Kondhale, Wada, Taluka - Wada, District - Palghar, 421312, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Orson Resins And Coatings Private limited ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "0000000000"

}

| Name | Length | Width | Total |
|---------------|---------------|--------------|--------------|
| <hr/> | | | |
| Composition : | | | |
| <hr/> | | | |
| Other | | | |
| Composition : | | | |
| <hr/> | | | |