

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "firstName": "Amruta ",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f5a",
    "email": "amruta.pathak@cosmosbank.in",
    "mobileNo": "-",
    "workMobileNo": "9769900929",
    "lastName": "Pathak"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) ",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhudurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
( East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82",
  "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {

```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.218145947156227",
  "longitude": "73.08222551491208"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-13",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-12",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-13",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "New Dombivli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivli (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sonal Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "Shastri Nagar, Devi Chowk",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "42",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "53",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "6",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 202",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Partly_Kota_Stone___Ceramic_tiles flooring",
    "label": "Partly Kota Stone / Ceramic tiles flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
    "label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
  },
  "finishing": {
```

```
    "value": "Cement_Plastering+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Joshi Bungalow",
    "west": "Aishwarya CHSL",
    "south": "Internal Road",
    "east": "Ayush Apartment"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
      "north": "Details not available",
```

```
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "ordinary",
  "label": "Ordinary"
},
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "55.5",
  "depreciationRatioOfBuilding": ""
}
```

```
"salvageValue": "10",
"depreciatedCostOfConstruction": "7112.5",
"depreciatedBuildingRate": "1112.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "65200",
  "landRate": "23400",
  "igrImage": "cases/67adbfcd716769af0d67902/igr_1739527870812_Image.png",
  "squareMeterGuideLineRate": "65200.00",
  "squareFeetGuideLineRate": "6057.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "63",
  "rate": "4620.00",
  "squareFeetGuideLineRate": "4620.00",
  "squareMeterGuideLineRate": "49734.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
```

```
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1988",
    "fullDate": "1/1/1988"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
```

```
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
}
```



```
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "23",
"ageOfBuilding": "37",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67adbfcad716769af0d67902/
routeMap_1739529820415_Image.png",
    "routeLat": "19.218114",
    "routeLng": "73.082235",
    "stationName": "Dombivli",
    "routeDistance": "350M",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
```

```
"coordinates": [
  0,
  0
],
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "7kjkvr",
    "name": "7kjkvr",
    "image": "cases/67adbfcad716769af0d67902/
routeMap_1739529697867_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "1162500.00",
    "depreciationPercentage": "55.5",
    "depreciatedCostOfConstruction": "645187.50",
    "totalFairMarketValue": "3307312.50"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```

```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3952500.00",
"finalValue": "3952500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "datetime": "2025-02-14T12:31:09.839Z",
  "date": "Fri Feb 14 2025 12:31:09 GMT+0000 (Coordinated Universal Time)",
  "number": "2310570",
  "dayCount": "21",
  "monthCount": "220",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2148300.00",
  "selectedBuildUpValue": "465.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67ae1f0ed716769af0d6c973",
      "name": "externallmg_1739464456248_1739464442670_image_10.jpeg",
      "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464456248_1739464442670_image_10.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67ae1f0ed716769af0d6c973",
      "name": "externallmg_1739464456248_1739464442670_image_10.jpeg",
      "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464456248_1739464442670_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67ae1f0ed716769af0d6c96c",
      "name": "externallmg_1739464451093_1739464442670_image_3.jpeg",
      "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464451093_1739464442670_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  {
```

```
    "status": false,
    "_id": "67ae1f0ed716769af0d6c96a",
    "name": "externallmg_1739464450028_1739464442670_image_1.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464450028_1739464442670_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67ae1f0ed716769af0d6c96f",
    "name": "externallmg_1739464453768_1739464442670_image_6.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464453768_1739464442670_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67ae1eb6d716769af0d6c937",
    "name": "externallmg_1739464372091_1739464369894_image_3.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464372091_1739464369894_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67ae1f0ed716769af0d6c971",
    "name": "externallmg_1739464455078_1739464442670_image_8.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464455078_1739464442670_image_8.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7428.00",
    "max": "15556.00"
  },
  "builtUpRateRange": {
    "min": "7428.00",
    "max": "12963.00"
  },
  "saleableRateRange": {
```

```
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
```



```
"title": "Interior Decorations",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "465.00",
"empanelmentNo": [
  "HO/Credit/87/2022-23"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67adbfcad716769af0d67902",
"ownerName": "Mr. Aakash Munnilal Kanojiya & Mrs. Karishma Aakash Kanojiya",
"ownerPhoneNo": "9967090451",
"fullAddress": "Residential Flat No. 6, 1st Floor, Sonal Co-Op. Hsg. Soc. Ltd., Shastri
Nagar, Devi Chowk, Village - New Dombivli, Taluka - Kalyan, District - Thane, Dombivli
(West), PIN Code - 421 202, State - Maharashtra, India",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "10/02/2025",
    "from": {
      "value": "Transferor",
      "label": "Transferor"
    },
    "Transferor": "Mr. Sriram Aghoramurthy Iyer & Mrs. Revathy Sriram Iyer Alies Miss.
Revathy Balasubramanian Iyer",
    "to": {
      "value": "transferee",
      "label": "transferee"
    },
    "transferee": "Mr. Aakash Munnilal Kanojiya & Mrs. Karishma Aakash Kanojiya",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "2262/2025"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "714394",
  "path": "cases/67adbfcad716769af0d67902/
document_1739440067681_Aakash_K_Cos_D.pdf",
  "fileName": "document_1739440067681_Aakash_K_Cos_D.pdf"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014298",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "750557",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Feb 13 2025 09:47:54 GMT+0000 (Coordinated Universal Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mr. Aakash Munnial Kanojiya & Mrs. Karishma Aakash Kanojiya",
    "phone": "9967090451",
    "ownershipShare": "",
    "email": "",
    "id": "450574"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "647083",
    "name": "Living Room",
    "length": "15.00",
    "length1": "15",
    "length2": "00",
    "width": "7.00",
    "width1": "7",
    "width2": "00",
    "totalArea": "105.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "105.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Bedroom",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "8.00",
    "width1": "8",
    "width2": "00",
    "totalArea": "96.00",
    "images": [],
    "extraAreas": [],
```

```
"finalArea": "96.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "90.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "90.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "WC",
  "length": "3.00",
```

```
"length1": "3",
"length2": "0",
"width": "3.00",
"width1": "3",
"width2": "0",
"totalArea": "9.00",
"images": [],
"finalArea": "9.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "14.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.00"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "43.20",
    "totalAreaDocument": "465",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "551472"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"carpetArea": {
  "area": "450",
  "squareMeterArea": "41.81",
  "expectedRate": "1555.56",
  "percentage": ""
},
"builtUpArea": {
  "area": "540.00",
  "squareMeterArea": "50.17",
  "expectedRate": "12962.96",
  "percentage": ""
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "67af16cb7c27b2b299b54667",
"property": "Residential Flat",
"area": "540",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "7000000",
"expectedRate": "1555.56",
"builtUpExpectedRate": "7000000",
"image": "cases/67adbfcd716769af0d67902/
indicator_1739527306492_Image.png",
"squareMeter": "50.17",
"id": "592797"
},
{
  "carpetArea": {
    "area": "590.00",
    "squareMeterArea": "54.81",
    "expectedRate": "12203.39",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "708.00",
    "squareMeterArea": "65.78",
```



```
    "expectedRate": "10169.49",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "67af16cb7c27b2b299b54668",
  "property": "Residential Flat",
  "area": "590",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7200000",
  "expectedRate": "12203.39",
  "builtUpExpectedRate": "10169.49",
  "image": "cases/67adbfcd716769af0d67902/
indicator_1739527357612_Image.png",
  "squareMeter": "54.81",
  "id": "297386"
},
{
  "carpetArea": {
    "area": "465.00",
    "squareMeterArea": "43.20",
    "expectedRate": "7427.96",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "465.00",
    "squareMeterArea": "43.20",
    "expectedRate": "7427.96",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
}
```

```
"printlnReport": true,
  "_id": "67af16cb7c27b2b299b54669",
  "property": " Residential Flat",
  "area": "465",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3454000",
  "expectedRate": "7427.96",
  "builtUpExpectedRate": "3454000",
  "image": "cases/67adbfcad716769af0d67902/
indicator_1739527443435_Image.png",
  "squareMeter": "43.20",
  "id": "710005"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ae1f0ed716769af0d6c969",
    "name": "externalImg_1739464449306_1739464442670_image_0.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464449306_1739464442670_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ae1f0ed716769af0d6c96a",
    "name": "externalImg_1739464450028_1739464442670_image_1.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464450028_1739464442670_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ae1f0ed716769af0d6c96b",
    "name": "externalImg_1739464450593_1739464442670_image_2.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464450593_1739464442670_image_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67ae1f0ed716769af0d6c96c",
      "name": "externallmg_1739464451093_1739464442670_image_3.jpeg",
      "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464451093_1739464442670_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67ae1f0ed716769af0d6c96d",
      "name": "externallmg_1739464451993_1739464442670_image_4.jpeg",
      "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464451993_1739464442670_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67ae1f0ed716769af0d6c96e",
      "name": "externallmg_1739464452693_1739464442670_image_5.jpeg",
      "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464452693_1739464442670_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67ae1f0ed716769af0d6c96f",
      "name": "externallmg_1739464453768_1739464442670_image_6.jpeg",
      "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464453768_1739464442670_image_6.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67ae1f0ed716769af0d6c970",
      "name": "externallmg_1739464454454_1739464442670_image_7.jpeg",
      "path": "cases/67adbfcad716769af0d67902/
externallmg_1739464454454_1739464442670_image_7.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ae1f0ed716769af0d6c971",
  "name": "externallmg_1739464455078_1739464442670_image_8.jpeg",
  "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464455078_1739464442670_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ae1f0ed716769af0d6c972",
  "name": "externallmg_1739464455613_1739464442670_image_9.jpeg",
  "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464455613_1739464442670_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ae1f0ed716769af0d6c973",
  "name": "externallmg_1739464456248_1739464442670_image_10.jpeg",
  "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464456248_1739464442670_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ae1f0ed716769af0d6c975",
  "name": "externallmg_1739464458323_1739464442670_image_12.jpeg",
  "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464458323_1739464442670_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ae1f0ed716769af0d6c976",
  "name": "externallmg_1739464459573_1739464442670_image_13.jpeg",
  "path": "cases/67adbfcd716769af0d67902/
externallmg_1739464459573_1739464442670_image_13.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ae1eb6d716769af0d6c934",
    "name": "externalImg_1739464371235_1739464369894_image_0.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464371235_1739464369894_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ae1eb6d716769af0d6c935",
    "name": "externalImg_1739464371586_1739464369894_image_1.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464371586_1739464369894_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ae1eb6d716769af0d6c936",
    "name": "externalImg_1739464371951_1739464369894_image_2.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464371951_1739464369894_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ae1eb6d716769af0d6c937",
    "name": "externalImg_1739464372091_1739464369894_image_3.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464372091_1739464369894_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ae1eb6d716769af0d6c938",
    "name": "externalImg_1739464373055_1739464369894_image_4.jpeg",
    "path": "cases/67adbfcad716769af0d67902/
externalImg_1739464373055_1739464369894_image_4.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [
  {
    "originalName": "Cosmos - Calculation Sheet.xlsx",
    "filename": "1739527898995_Cosmos__Calculation_Sheet.xlsx",
    "path": "cases/67adbfcad716769af0d67902/
processingDocuments/1739527898995_Cosmos__Calculation_Sheet.xlsx",
    "size": "560910",
    "createdAt": "Fri Feb 14 2025 10:11:39 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67aedc28d716769af0d72902",
    "note": "Value given for confirmation",
    "taskId": "67adc0b519ca979ae9489a38",
    "createdAt": "2025-02-14T06:01:12.561Z"
  }
],
"createdAt": "2025-02-13T09:47:54.149Z",
"updatedAt": "2025-02-14T12:37:17.564Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Sriram Aghoramurthy Iyer",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Seller",
```

```
"rerald": "",
"siteVisitContactNo": "9773553397",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 465.00",
"flatRate": "8500",
"landOtherRate": "6000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Fri Feb 14 2025 10:16:20 GMT+0000 (Coordinated Universal Time)",
"siteVisitDate": "2025-02-13",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + WC + 2 Passage + Balcony",
"carpetTotal": "387.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "425.70",
```

"finalCarpetArea": "387.00",
 "finalSalableArea": "468.27",
 "salablePercentage": "10",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 352.00\nBalcony Area in Sq. Ft.=
 35.00\n\n\n"

Name	Length	Width	Total
Composition :			
Living Room	15'00"	7'00"	105.00
Bedroom	12'00"	8'00"	96.00
Kitchen	9'00"	10'00"	90.00
Bathroom	5'00"	4'00"	20.00
WC	3'0"	3'0"	9.00
Passage	3'00"	6'00"	18.00
Passage	2'00"	7'00"	14.00
Balcony	5'00"	7'00"	35.00
Other Composition :			