

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63afbcbda191f7b344b006040"
    },
    "firstName": "Parul",
    "type": "CREDITOFFICER",
    "_id": "67692d47fe1fd12ff215de07",
    "email": "bom164@mahabank.co.in",
    "lastName": "bansel",
    "mobileNo": "",
    "workMobileNo": "9958111061"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9404618",
  }
}
```

```
"discussWithPerson": "Parul",
"expectedFees": 4702.309,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63afbcda191f7b344b006040",
  "name": "BANDRA (EAST)",
  "branchCode": "",
  "mobileNo": "26591333",
  "alternateMobileNo": "",
  "email": "bom164@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "MHADA Building, Kalanagar, Bandra (East), Mumbai - 400 051"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60f91b6f344e052188ffd1fc",
    "role": "MAKER",
```

```
    "firstName": "Jayaraja",
    "email": "jayaraja@vastukala.org",
    "lastName": "Acharya",
    "mobileNo": "9867664219",
    "designation": "",
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": []
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.115235951359733",
  "longitude": "72.83259489446384"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83259489446384,
    19.115235951359733
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "14/02/2025 12:00 am",
```

```
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2015-02-15",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-02-15",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "4BHK",
  "label": "4 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Vile Parle West",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "12",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vile Parle (West), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Juhu Sheetal Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Samarth Ramdas Marg",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "J.V.P.D. Scheme, Near Juhu Shopping Centre",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```

```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "287",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "19(pt)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```



```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "801",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "K/W",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 049",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Juhu",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "ItalianMarbleFlooring",
    "label": "Italian Marble Flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Samarth Ramdas Marg",
  "west": "Gurukrupa Vyom",
  "south": "Under Construction Building",
  "east": "Open Plot & Cross Road No. 9"
},
"asPerDocumentAgreement": {
  "north": "By 60 Feet Wide Road",
  "west": "By Building No. 13",
  "south": "By Building No. 10",
  "east": "By Building No. 11"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Flat No. 803",
    "south": "Lift",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Marginal Space",
    "east": "Flat No. 803",
    "south": "Lift",
    "west": "Marginal Space"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "Wardrobe + Dry Balcony Area.\n",
"dateOfIssusApprovePlan": "Copy of Full Occupation Certificate No. MH/EE/(B.P.)/
GM/MHADA-104/104/2019 Dated 29.07.2019 issued by\nMaharashtra Housing And
Area Development Authority",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "As per Site Inspection, Residential Flat No. 801 & 802 are internally
amalgamated with common entrance. Two flats are internally amalgamated to form a
single flat. For the purpose of valuation, we have considered area as per documents of
Flat No. 801 only.",
  "depreciationPercentage": "9",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "54730",
  "depreciatedBuildingRate": "2730"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "294940",
  "landRate": "153550",
  "igrImage": "cases/67af2a7ce1b0fbb7b7ebb356/igr_1740827720319_Image.png",
  "squareMeterGuideLineRate": "309687.00",
```

```
"squareFeetGuideLineRate": "28771.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "94",
  "rate": "27901.00",
  "squareFeetGuideLineRate": "27901.00",
  "squareMeterGuideLineRate": "300319.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "1,25,000/- (Expected rental income per month)\n",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Excellent"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  }
},
```

```
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "2 Car Parking Space in Stilt",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2019",
  "fullDate": "1/1/2019"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
}
```

```
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
```

```
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "54",
"ageOfBuilding": "6",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "11",
"flatFloorNo": "8",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
"area": "1102.80",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/67af2a7ce1b0fbb7b7ebb356/
routeMap_1739779527561_Image.png",
"routeLat": "19.11436",
"routeLng": "72.833472",
"stationName": "Andheri",
"routeDistance": "1.9 km. ",
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
0
],
"type": "Point"
},
"showLocation": {
```



```
"latlng": false,
"finallatlng": false
},
"locationMapImg": [
  {
    "id": "8byan8",
    "name": "8byan8",
    "image": "cases/67af2a7ce1b0fbb7b7ebb356/
routeMap_1739779136212_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "50296870.00",
"finalValue": "50296870.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "30769223.00",
```

```
"selectedBuildUpValue": "1102.80",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67c2f5997018387a18174f28",
      "name": "externallmg_1740830103899_externallmg_1739622830881_1739622826
279_image_4.jpeg",
      "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830103899_external
lmg_1739622830881_1739622826279_image_4.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "67c2f5997018387a18174f2d",
      "name": "externallmg_1740830104295_externallmg_1739622832313_1739622826
279_image_9.jpeg",
      "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104295_external
lmg_1739622832313_1739622826279_image_9.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67c2f5997018387a18174f28",
      "name": "externallmg_1740830103899_externallmg_1739622830881_1739622826
279_image_4.jpeg",
      "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830103899_external
lmg_1739622830881_1739622826279_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67c2f5997018387a18174f26",
      "name": "externallmg_1740830103815_externallmg_1739622829820_1739622826
279_image_2.jpeg",
      "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830103815_external
lmg_1739622829820_1739622826279_image_2.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "67c2f5997018387a18174f2b",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830104227_external
Img_1739622831804_1739622826279_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5997018387a18174f2f",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830104428_external
Img_1739622853913_1739622850988_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5aa7018387a18174f91",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830121175_external
Img_1739622855044_1739622850989_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5aa7018387a18174f94",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830121263_external
Img_1739622855582_1739622850989_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5aa7018387a18174f99",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830121447_external
Img_1739622856534_1739622850989_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5aa7018387a18174f9c",
```

```
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830121565_external
Img_1739622857040_1739622850989_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5aa7018387a18174f9e",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830121639_external
Img_1739622857413_1739622850989_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5997018387a18174f32",
    "name": "Bedroom",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830104578_external
Img_1739622854711_1739622850988_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5997018387a18174f30",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830104454_external
Img_1739622854268_1739622850988_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5997018387a18174f2e",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830104391_external
Img_1739622832501_1739622826279_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2f5997018387a18174f31",
    "name": "Living Room",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalImg_1740830104523_external
Img_1739622854393_1739622850988_image_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "47929.00",
    "max": "59975.00"
  },
  "builtUpRateRange": {
    "min": "39941.00",
    "max": "49979.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```



```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "919.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
```

```
"paymentIds": [],
"_id": "67af2a7ce1b0fbb7b7ebb356",
"ownerName": "Mrs. Seema Dipesh Janani",
"ownerPhoneNo": "9820847905",
"appAddress": "flat no - 801, 8th floor, Juhu Shital , samarth Ramdas Marg , co
operative housing society Ltd, jvpd schem, near - Juhu shopping centre, Juhu, vileparle
West, Mumbai - 400049",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1251aa6d152c1801b317",
      "label": "Gift Deed"
    },
    "inputs": {
      "documentDate": "25/03/2022",
      "remark": " (Registration No. 10922-2022)",
      "from": {
        "value": "Donor",
        "label": "Donor"
      },
      "Donor": "Mr. Hasmukh Alias Hasmukhrai Shantilal Janani",
      "to": {
        "value": "donee",
        "label": "donee"
      },
      "donee": "Mr. Dipesh Hasmukh Janani"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "749817",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/
document_1739532954225_1739532951342_Dipesh_janani__BOM_mhada.pdf",
    "fileName":
"document_1739532954225_1739532951342_Dipesh_janani__BOM_mhada.pdf"
  },
  {
    "documentType": {
      "value": "60ae1258aa6d152c1801b337",
      "label": "Full Occupation Certificate"
    },
    "inputs": {
      "documentDate": "29/07/2019",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Housing_And_Area_Development_Authority",
        "label": "Maharashtra Housing And Area Development Authority"
      }
    }
  }
]
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " MH/EE/(B.P.)/GM/MHADA-104/104/2019"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "905523",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/
document_1739780671503_Full_OC.pdf",
  "fileName": "document_1739780671503_Full_OC.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "22/05/2014",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " CHE/WS/1053/K/337(NEW)"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "763995",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/document_1739780791434_CC.pdf",
  "fileName": "document_1739780791434_CC.pdf"
},
{
  "documentType": {
    "value": "652d16a0316e1359cebd3c15",
    "label": " Agreement"
  },
  "inputs": {
    "documentDate": "17/11/2014",
    "from": {
      "value": "Developers",
```

```
    "label": "Developers"
  },
  "Developers": "Amal Realtors Private Limited",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Hasmukh Shantilal Janani & Mr. Dipesh Hasmukh Janani",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": " 8558/2014"
},
"isHardCopy": false,
"displayStatus": false,
"id": "305240",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/
document_1740978447459_Agreement.pdf",
"fileName": "document_1740978447459_Agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1251aa6d152c1801b317",
    "label": "Gift Deed"
  },
  "inputs": {
    "documentDate": "29/03/2022",
    "from": {
      "value": "Donor",
      "label": "Donor"
    },
    "Donor": "Mr. Dipesh Hasmukh Janani",
    "to": {
      "value": "donee",
      "label": "donee"
    },
    "donee": "Mrs. Seema Dipesh Janai"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "563196",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/
document_1740978468731_Gift_Deed.pdf",
  "fileName": "document_1740978468731_Gift_Deed.pdf"
}
```

```
],
"caseNumber": "014333",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "740451",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Feb 14 2025 11:35:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Seema Dipesh Janani",
    "phone": "9820847905",
    "ownershipShare": "",
    "email": "",
    "id": "111489"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "712853",
    "name": "Living Room",
    "length": "28.58",
    "length1": "28",
    "length2": "7",
    "width": "21.00",
    "width1": "21",
    "width2": "00",
    "totalArea": "600.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "600.25"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
]
```

```
"id": "12",
"name": "Kitchen",
"length": "",
"length1": "12",
"length2": "2",
"width": "",
"width1": "9",
"width2": "0",
"totalArea": "109.50",
"images": [],
"finalArea": "109.50",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Passage",
  "length": "",
  "length1": "15",
  "length2": "3",
  "width": "",
  "width1": "3",
  "width2": "1",
  "totalArea": "47.02",
  "images": [],
  "finalArea": "47.02",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "",
  "length1": "11",
  "length2": "5",
  "width": "",
  "width1": "10",
  "width2": "1",
  "totalArea": "115.12",
  "images": [],
```

```
"finalArea": "115.12",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "WC",
  "length": "",
  "length1": "4",
  "length2": "3",
  "width": "",
  "width1": "4",
  "width2": "4",
  "totalArea": "18.42",
  "images": [],
  "finalArea": "18.42",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "",
  "length1": "17",
  "length2": "4",
  "width": "",
  "width1": "10",
  "width2": "0",
  "totalArea": "173.33",
  "images": [],
  "finalArea": "173.33",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Toilet",
```



```
"length": "",
"length1": "9",
"length2": "3",
"width": "",
"width1": "3",
"width2": "9",
"totalArea": "34.69",
"images": [],
"finalArea": "34.69",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Passage",
  "length": "",
  "length1": "13",
  "length2": "6",
  "width": "",
  "width1": "3",
  "width2": "2",
  "totalArea": "42.75",
  "images": [],
  "finalArea": "42.75",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "",
  "length1": "15",
  "length2": "2",
  "width": "",
  "width1": "10",
  "width2": "0",
  "totalArea": "151.67",
  "images": [],
  "finalArea": "151.67",
  "extraAreas": []
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Toilet",
  "length": "",
  "length1": "10",
  "length2": "9",
  "width": "",
  "width1": "3",
  "width2": "10",
  "totalArea": "41.21",
  "images": [],
  "finalArea": "41.21",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "11.58",
  "width1": "11",
  "width2": "7",
  "totalArea": "143.83",
  "images": [],
  "extraAreas": [],
  "finalArea": "143.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Toilet",
  "length": "",
  "length1": "4",
```

```
"length2": "1",
"width": "",
"width1": "7",
"width2": "8",
"totalArea": "31.31",
"images": [],
"finalArea": "31.31",
"extraAreas": []
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Wardrobes",
    "value": "Wardrobes"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "",
  "length1": "11",
  "length2": "9",
  "width": "",
  "width1": "8",
  "width2": "2",
  "totalArea": "95.96",
  "images": [],
  "extraAreas": [],
  "finalArea": "95.96",
  "percentageBeforeTotal": "95.96",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  }
}
```

```
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "length": "5.25",
    "length1": "5",
    "length2": "3",
    "width": "2.33",
    "width1": "2",
    "width2": "4",
    "totalArea": "12.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "12.25",
    "percentageBeforeTotal": "12.25",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1251aa6d152c1801b317",
      "label": "Gift Deed"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "870890",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "919",
    "squareMeterArea": "85.38",
    "docFinalBuiltUp": "1102.8",
    "docFinalBuiltUpSquareMeter": "102.45599999999999",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"carpetArea": {
  "area": "945.00",
  "squareMeterArea": "87.79",
  "expectedRate": "5555.56",
  "percentage": ""
},
"builtUpArea": {
  "area": "1134.00",
  "squareMeterArea": "105.35",
  "expectedRate": "46296.30",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "67c2ecbd7018387a18174306",
"property": "Juhu Sheetal, Juhu JVPD Scheme",
"area": "945",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "7",
"source": "magic_bricks",
"expectedPrice": "52500000",
"expectedRate": "5555.56",
"builtUpExpectedRate": "46296.30",
"image": "cases/67af2a7ce1b0fbb7b7ebb356/
indicator_1740827049222_Image.png",
"squareMeter": "87.79",
"id": "214886"
},
{
  "carpetArea": {
    "area": "787.00",
    "squareMeterArea": "73.11",
    "expectedRate": "59974.59",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "944.40",
    "squareMeterArea": "87.74",
```

```
    "expectedRate": "49978.82",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "67c2ecbd7018387a18174307",
  "property": "Juhu JVPD Scheme",
  "area": "787",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "7",
  "source": "https://www.99acres.com/",
  "expectedPrice": "47200000",
  "expectedRate": "59974.59",
  "builtUpExpectedRate": "49978.82",
  "image": "cases/67af2a7ce1b0fbb7b7ebb356/
indicator_1740827169538_Image.png",
  "squareMeter": "73.11",
  "id": "448804"
},
{
  "carpetArea": {
    "area": "757.00",
    "squareMeterArea": "70.33",
    "expectedRate": "47928.67",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "908.40",
    "squareMeterArea": "84.39",
    "expectedRate": "39940.55",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
}
```

```
"printlnReport": true,
"_id": "67c2ecbd7018387a18174308",
"property": "Juhu Sheetal, Juhu JVPD Scheme",
"area": "757",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "6",
"source": "Index_no.2",
"expectedPrice": "36282000",
"expectedRate": "47928.67",
"builtUpExpectedRate": "39940.55",
"image": "cases/67af2a7ce1b0fbb7b7ebb356/
indicator_1740827378143_Image.png",
"squareMeter": "70.33",
"id": "104397"
},
{
  "carpetArea": {
    "area": "916.00",
    "squareMeterArea": "85.10",
    "expectedRate": "48635.37",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1099.20",
    "squareMeterArea": "102.12",
    "expectedRate": "40529.48",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67c2ecbd7018387a18174309",
  "property": "Juhu Sheetal, Juhu JVPD Scheme",
  "area": "916",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "3",
```

```
"source": "Index_no.2",
"expectedPrice": "44550000",
"expectedRate": "48635.37",
"builtUpExpectedRate": "40529.48",
"image": "cases/67af2a7ce1b0fbb7b7ebb356/
indicator_1740827473946_Image.png",
"squareMeter": "85.10",
"id": "504736"
}
],
"externallimages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67c2f5997018387a18174f26",
"name": "externallmg_1740830103815_externallmg_1739622829820_17396228262
79_image_2.jpeg",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830103815_externall
mg_1739622829820_1739622826279_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67c2f5997018387a18174f27",
"name": "externallmg_1740830103863_externallmg_1739622830295_17396228262
79_image_3.jpeg",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830103863_externall
mg_1739622830295_1739622826279_image_3.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67c2f5997018387a18174f28",
"name": "externallmg_1740830103899_externallmg_1739622830881_17396228262
79_image_4.jpeg",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830103899_externall
mg_1739622830881_1739622826279_image_4.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67c2f5997018387a18174f29",
"name": "externallmg_1740830104102_externallmg_1739622831480_17396228262
```



```
79_image_5.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104102_externallmg_1739622831480_1739622826279_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5997018387a18174f2a",
  "name": "externallmg_1740830104207_externallmg_1739622831628_1739622826279_image_6.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104207_externallmg_1739622831628_1739622826279_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5997018387a18174f2b",
  "name": "externallmg_1740830104227_externallmg_1739622831804_1739622826279_image_7.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104227_externallmg_1739622831804_1739622826279_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5997018387a18174f2c",
  "name": "externallmg_1740830104277_externallmg_1739622832026_1739622826279_image_8.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104277_externallmg_1739622832026_1739622826279_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5997018387a18174f2d",
  "name": "externallmg_1740830104295_externallmg_1739622832313_1739622826279_image_9.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104295_externallmg_1739622832313_1739622826279_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5997018387a18174f2e",
    "name": "externallmg_1740830104391_externallmg_1739622832501_1739622826279_image_10.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104391_externallmg_1739622832501_1739622826279_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5997018387a18174f2f",
    "name": "externallmg_1740830104428_externallmg_1739622853913_1739622850988_image_0.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104428_externallmg_1739622853913_1739622850988_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5997018387a18174f30",
    "name": "externallmg_1740830104454_externallmg_1739622854268_1739622850988_image_1.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104454_externallmg_1739622854268_1739622850988_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5997018387a18174f31",
    "name": "externallmg_1740830104523_externallmg_1739622854393_1739622850988_image_2.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104523_externallmg_1739622854393_1739622850988_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5997018387a18174f32",
    "name": "externallmg_1740830104578_externallmg_1739622854711_1739622850988_image_3.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104578_externallmg_1739622854711_1739622850988_image_3.jpeg",
    "orientation": "portrait"
  }
]
```

```
mg_1739622854711_1739622850988_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5997018387a18174f33",
  "name": "externallmg_1740830104601_externallmg_1739622854871_17396228509
89_image_4.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830104601_externall
mg_1739622854871_1739622850989_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f91",
  "name": "externallmg_1740830121175_externallmg_1739622855044_17396228509
89_image_5.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121175_externall
mg_1739622855044_1739622850989_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f92",
  "name": "externallmg_1740830121187_externallmg_1739622855264_17396228509
89_image_6.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121187_externall
mg_1739622855264_1739622850989_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f93",
  "name": "externallmg_1740830121199_externallmg_1739622855481_17396228509
89_image_7.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121199_externall
mg_1739622855481_1739622850989_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67c2f5aa7018387a18174f94",
    "name": "externalimg_1740830121263_externalimg_1739622855582_17396228509
89_image_8.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalimg_1740830121263_external
mg_1739622855582_1739622850989_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5aa7018387a18174f95",
    "name": "externalimg_1740830121299_externalimg_1739622855801_17396228509
89_image_9.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalimg_1740830121299_external
mg_1739622855801_1739622850989_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5aa7018387a18174f96",
    "name": "externalimg_1740830121306_externalimg_1739622855994_17396228509
89_image_10.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalimg_1740830121306_external
mg_1739622855994_1739622850989_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5aa7018387a18174f97",
    "name": "externalimg_1740830121385_externalimg_1739622856168_17396228509
89_image_11.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalimg_1740830121385_external
mg_1739622856168_1739622850989_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2f5aa7018387a18174f98",
    "name": "externalimg_1740830121393_externalimg_1739622856359_17396228509
89_image_12.jpeg",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/externalimg_1740830121393_external
mg_1739622856359_1739622850989_image_12.jpeg",
    "orientation": "portrait"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f99",
  "name": "externallmg_1740830121447_externallmg_1739622856534_17396228509
89_image_13.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121447_externall
mg_1739622856534_1739622850989_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f9a",
  "name": "externallmg_1740830121455_externallmg_1739622856748_17396228509
89_image_14.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121455_externall
mg_1739622856748_1739622850989_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f9b",
  "name": "externallmg_1740830121526_externallmg_1739622856922_17396228509
89_image_15.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121526_externall
mg_1739622856922_1739622850989_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f9c",
  "name": "externallmg_1740830121565_externallmg_1739622857040_17396228509
89_image_16.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121565_externall
mg_1739622857040_1739622850989_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f9d",
  "name": "externallmg_1740830121597_externallmg_1739622857247_17396228509
```

```
89_image_17.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121597_externallmg_1739622857247_1739622850989_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f9e",
  "name": "externallmg_1740830121639_externallmg_1739622857413_1739622850989_image_18.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121639_externallmg_1739622857413_1739622850989_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2f5aa7018387a18174f9f",
  "name": "externallmg_1740830121667_externallmg_1739622857587_1739622850989_image_19.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/externallmg_1740830121667_externallmg_1739622857587_1739622850989_image_19.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr_9407.pdf",
    "filename": "1740827794006_igr_9407.pdf",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/processingDocuments/1740827794006_igr_9407.pdf",
    "size": "204865",
    "createdAt": "Sat Mar 01 2025 11:16:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1719386343043_1717159298325_Calculation_1.xlsx",
    "filename": "1740827794026_1719386343043_1717159298325_Calculation_1.xlsx",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/processingDocuments/1740827794026_1719386343043_1717159298325_Calculation_1.xlsx",
    "size": "1724730",
    "createdAt": "Sat Mar 01 2025 11:16:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
]
```

```
  },
  {
    "originalname":
"document_1739537066954_Valuation_Report__Mr_Dipesh_Janani_FlatNo_802.pdf",
    "filename": "1740827794173_document_1739537066954_Valuation_Report__Mr_D
ipesh_Janani_FlatNo_802.pdf",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/processingDocuments/1740827794173
_document_1739537066954_Valuation_Report__Mr_Dipesh_Janani_FlatNo_802.pdf",
    "size": "2711036",
    "createdAt": "Sat Mar 01 2025 11:16:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname":
"document_1739537470974_Valuation_Report__Mr_Dipesh_Janani_Flat_No_801.pdf",
    "filename": "1740827794503_document_1739537470974_Valuation_Report__Mr_D
ipesh_Janani_Flat_No_801.pdf",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/processingDocuments/1740827794503
_document_1739537470974_Valuation_Report__Mr_Dipesh_Janani_Flat_No_801.pdf",
    "size": "2676177",
    "createdAt": "Sat Mar 01 2025 11:16:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_7067.pdf",
    "filename": "1740827795088_igr_7067.pdf",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740827795088_igr_7067.pdf",
    "size": "155279",
    "createdAt": "Sat Mar 01 2025 11:16:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1740983529630_CC.pdf",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983529630_CC.pdf",
    "size": "858620",
    "createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Full OC.pdf",
    "filename": "1740983529683_Full_OC.pdf",
    "path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983529683_Full_OC.pdf",
```

```
"size": "601816",
"createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Gift Deed - 25-03-2022.pdf",
"filename": "1740983529698_Gift_Deed__25032022.pdf",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983529698_Gift_Deed__25032022.pdf",
"size": "1824371",
"createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Gift Deed - 29-03-2022.pdf",
"filename": "1740983529844_Gift_Deed__29032022.pdf",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983529844_Gift_Deed__29032022.pdf",
"size": "2304997",
"createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Previous Report 2022.pdf",
"filename": "1740983529887_Previous_Report_2022.pdf",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983529887_Previous_Report_2022.pdf",
"size": "2676177",
"createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Sale De3ed - 2014.pdf",
"filename": "1740983530258_Sale_De3ed__2014.pdf",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983530258_Sale_De3ed__2014.pdf",
"size": "2615759",
"createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Sale Deed - 2022.pdf",
"filename": "1740983530301_Sale_Deed__2022.pdf",
"path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983530301_Sale_Deed__2022.pdf",
"size": "24357099",
```



```
"createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Site Details.jpeg",
  "filename": "1740983531208_Site_Details.jpeg",
  "path": "cases/67af2a7ce1b0fbb7b7ebb356/
processingDocuments/1740983531208_Site_Details.jpeg",
  "size": "1158741",
  "createdAt": "Mon Mar 03 2025 06:32:13 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-14T11:35:24.497Z",
"updatedAt": "2025-03-03T10:19:14.457Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f915d3f3dd69653a592199",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 801, 8th Floor, Building No 12, Juhu Sheetal Co-op.
Hsg. Soc. Ltd., Samarth Ramdas Marg, J.V.P.D. Scheme, Near Juhu Shopping Centre,
Village - Vile Parle West, Municipality Ward No. K/W, Juhu, Taluka - Andheri, District -
Mumbai Suburban, Vile Parle (West), Mumbai, PIN - 400 049, State - Maharashtra,
India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": " Mrs. Seema Dipesh Janani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"rerald": "",
"siteVisitContactNo": "9820847905",
"builtupPercentage": "20",
"carpetTotal": "1509.1",
"extendOfSiteRemark": "",
"finalBuiltupArea": "1940.77",
```

```
"finalCarpetArea": "1617.31",
"finalSalableArea": "1940.77",
"otherCarpetTotal": "108.21",
"salablePercentage": "0",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 1509.10 \nWardrobes in Sq. Ft.
= 95.96\nDry Balcony Area in Sq. Ft. = 12.25\n<br />\n",
"toBeAdded": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Gift Deed",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 919.00",
"buildingServicesRate": "3000",
"flatRate": "55000",
"landOtherRate": "52000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "4 Bedroom + Living Room + Kitchen + 2 Passage + WC + 3
Toilet",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "108.21",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Mon Mar 03 2025 05:10:27 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-02-15",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
```

}  
}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	28'7"	21'00"	600.25
Kitchen	12'2"	9'0"	109.50
Passage	15'3"	3'1"	47.02
Bedroom	11'5"	10'1"	115.12
WC	4'3"	4'4"	18.42
Bedroom	17'4"	10'0"	173.33
Toilet	9'3"	3'9"	34.69
Passage	13'6"	3'2"	42.75
Bedroom	15'2"	10'0"	151.67
Toilet	10'9"	3'10"	41.21
Bedroom	12'5"	11'7"	143.83
Toilet	4'1"	7'8"	31.31
Other Composition :			
Wardrobes	11'9"	8'2"	95.96
Dry Balcony Area	5'3"	2'4"	12.25