

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63afbcbda191f7b344b006040"
    },
    "firstName": "Parul",
    "type": "CREDITOFFICER",
    "_id": "67692d47fe1fd12ff215de07",
    "email": "bom164@mahabank.co.in",
    "lastName": "bansel",
    "mobileNo": "",
    "workMobileNo": "9958111061"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6484648",
  }
}
```

```
"discussWithPerson": "Parul",
"expectedFees": 3242.324,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63afbcda191f7b344b006040",
  "name": "BANDRA (EAST)",
  "branchCode": "",
  "mobileNo": "26591333",
  "alternateMobileNo": "",
  "email": "bom164@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "MHADA Building, Kalanagar, Bandra (East), Mumbai - 400 051"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60f91b6f344e052188ffd1fc",
    "role": "MAKER",
```

```
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": []
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.114790389728245",
  "longitude": "72.83306696866984"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83306696866984,
    19.114790389728245
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
```

```
    "status": "COMPLETED",
    "dateTime": "2025-02-15",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-02-14",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "4BHK",
  "label": "4 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vile Parle West",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "8",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "12",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vile Parle (West), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Juhu Sheetal Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Samarth Ramdas Marg",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "J.V.P.D. Scheme, Near Juhu Shopping Centre",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "287",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "19(pt)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "802",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "K/W",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "PIN - 400 049",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Juhu",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "ItalianMarbleFlooring",
    "label": "Italian Marble Flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
```

```
"label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Samarth Ramdas Marg",
  "west": "Gurukrupa Vyom",
  "south": "Under Construction Building",
  "east": "Open Plot & Cross Road No. 9"
},
"asPerDocumentAgreement": {
  "north": "By 60 Feet Wide Road",
  "west": "By Building No. 13",
  "south": "By Building No. 10",
  "east": "By Building No. 11"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Flat No. 803",
    "south": "Lift",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Marginal Space",
    "east": "Flat No. 803",
    "south": "Lift",
    "west": "Marginal Space"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  }
},
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "Wardrobe + Dry Balcony Area.\n",
"dateOfIssusApprovePlan": "Copy of Full Occupation Certificate No. MH/EE/(B.P.)/GM/MHADDA-104/104/2019 Dated 29.07.2019 issued by\nMaharashtra Housing And Area Development Authority",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "As per Site Inspection, Residential Flat No. 801 & 802 are internally amalgamated with common entrance. Two flats are internally amalgamated to form a single flat. For the purpose of valuation, we have considered area as per documents of Flat No. 802 only.",
  "depreciationPercentage": "9",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "54730",
  "depreciatedBuildingRate": "2730"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "294940",
  "landRate": "153550",
  "igrImage": "cases/67af2bf0e1b0fbb7b7ebb704/igr_1740827652523_Image.png",
  "squareMeterGuideLineRate": "309687.00",
  "squareFeetGuideLineRate": "28771.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "94",
```

```
"rate": "27901.00",
"squareFeetGuideLineRate": "27901.00",
"squareMeterGuideLineRate": "300319.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": " 1,00,000/- (Expected rental income per month)",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Excellent"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
```

```
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "One Car Parking Space in Stilt",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2019",
"fullDate": "1/1/2019"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
}
```

```
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
```

```
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "6",
"totalLifeBuilding": "60",
"estimatedAge": "54",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "11",
"flatFloorNo": "8",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "888.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67af2bf0e1b0fbb7b7ebb704/
routeMap_1740830671655_Image.png",
    "routeLat": "19.11436",
    "routeLng": "72.833472",
    "stationName": "Andheri",
    "routeDistance": "1.9 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
```



```
    "id": "vf6r1g",
    "name": "vf6r1g",
    "image": "cases/67af2bf0e1b0fbb7b7ebb704/
routeMap_1740830479484_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "40500200.00",
  "finalValue": "40500200.00",
  "distressValuePercentage": "70",
  "realizableValuePercentage": "85",
  "bookValueDocument": null,
```

```
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "24776088.00",
  "selectedBuildUpValue": "888.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
```

```
{
  "status": false,
  "_id": "67b089b0e1b0fbb7b7ec94c2",
  "name": "externallmg_1739622830881_1739622826279_image_4.jpeg",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622830881_1739622826279_image_4.jpeg",
  "orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c7",
    "name": "externallmg_1739622832313_1739622826279_image_9.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622832313_1739622826279_image_9.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c2",
    "name": "externallmg_1739622830881_1739622826279_image_4.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622830881_1739622826279_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c0",
    "name": "externallmg_1739622829820_1739622826279_image_2.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622829820_1739622826279_image_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb0",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622853913_1739622850988_image_0.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb1",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622854268_1739622850988_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c5",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622831804_1739622826279_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cc0",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622857040_1739622850989_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cc2",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622857413_1739622850989_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cbd",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622856534_1739622850989_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb8",
    "name": "Bedroom",
```

```
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855582_1739622850989_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb5",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855044_1739622850989_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb3",
    "name": "Bedroom",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622854711_1739622850988_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb2",
    "name": "Living Room",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622854393_1739622850988_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c8",
    "name": "Living Room",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622832501_1739622826279_image_10.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "47929.00",
    "max": "59975.00"
  },
  "builtUpRateRange": {
    "min": "39941.00",
    "max": "49979.00"
  }
}
```

```
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```



```
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
```

```
"status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "740.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67af2bf0e1b0fbb7b7ebb704",
"ownerName": "Mrs. Seema Dipesh Janani",
"ownerPhoneNo": "9820847905",
"appAddress": "flat no 802,8th floor, Juhu Shital co-operative housing society Ltd,
samarth Ramdas Marg, jvpd schem, near Juhu shopping centre, Juhu, vileparle West,
Mumbai - 400049",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "value": "60ae1251aa6d152c1801b317",
    "label": "Gift Deed"
  },
  "inputs": {
    "documentDate": "29/03/2022",
    "remark": "(Registration No. 12617/2022)",
    "from": {
      "value": "Donor",
      "label": "Donor"
    },
    "Donor": "Mr. Dipesh Hasmukh Janai",
    "to": {
      "value": "donee",
      "label": "donee"
    },
    "donee": "Mrs. Seema Dipesh Janai"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "256387",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
document_1740977025510_Gift_Deed_2022.pdf",
  "fileName": "document_1740977025510_Gift_Deed_2022.pdf"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b337",
    "label": "Full Occupation Certificate"
  },
  "inputs": {
    "documentDate": "29/07/2019",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MH/EE/(B.P.)/GM/MHADA-104/104/2019"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1740977105996_Full_OC.pdf",
```

```
"path": "cases/67af2bf0e1b0fbb7b7ebb704/
document_1740977105996_Full_OC.pdf",
"id": "771158",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Mar 03 2025 04:45:06 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "22/05/2014",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE/WS/1053/K/337(NEW)"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1740977170702_CC.pdf",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/document_1740977170702_CC.pdf",
  "id": "821744",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Mon Mar 03 2025 04:46:10 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "652d16a0316e1359cebd3c15",
    "label": "Agreement"
  },
  "inputs": {
    "documentDate": "17/11/2014",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "Amal Realtors Private Limited",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    }
  }
}
```

```
    },
    "Purchasers": "Mrs. Hasmukh Shantilal Janani",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "8559/2014"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "306064",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
document_1740978496773_Agreement.pdf",
  "fileName": "document_1740978496773_Agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1251aa6d152c1801b317",
    "label": "Gift Deed"
  },
  "inputs": {
    "documentDate": "25/03/2022",
    "from": {
      "value": "Donor",
      "label": "Donor"
    },
    "Donor": "Mr. Hasmukh Alias Hasmukhrai Shantilal Janai",
    "to": {
      "value": "donee",
      "label": "donee"
    },
    "donee": "Mr. Dipesh Hasmukh Janani"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1740980168911_Other_2.pdf",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
document_1740980168911_Other_2.pdf",
  "id": "210901",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Mon Mar 03 2025 05:36:09 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014335",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
```

```
{
  "id": "351211",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Fri Feb 14 2025 11:41:36 GMT+0000 (Coordinated Universal Time)"
},
"owners": [
  {
    "name": "Mrs. Seema Dipesh Janani",
    "phone": "9820847905",
    "ownershipShare": "",
    "email": "",
    "id": "213163"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "178318",
    "name": "Living Room",
    "length": "28.58",
    "length1": "28",
    "length2": "7",
    "width": "21.00",
    "width1": "21",
    "width2": "00",
    "totalArea": "600.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "600.25"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "12.17",
    "length1": "12",
```

```
"length2": "2",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "109.50",
"images": [],
"extraAreas": [],
"finalArea": "109.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "15.25",
  "length1": "15",
  "length2": "3",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "47.02",
  "images": [],
  "extraAreas": [],
  "finalArea": "47.02"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "11.42",
  "length1": "11",
  "length2": "5",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "115.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "115.12"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "4",
"name": "WC",
"length": "4.25",
"length1": "4",
"length2": "3",
"width": "4.33",
"width1": "4",
"width2": "4",
"totalArea": "18.42",
"images": [],
"extraAreas": [],
"finalArea": "18.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "17.33",
  "length1": "17",
  "length2": "4",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "173.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "173.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "3.75",
```



```
"width1": "3",
"width2": "9",
"totalArea": "34.69",
"images": [],
"extraAreas": [],
"finalArea": "34.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "13.50",
  "length1": "13",
  "length2": "6",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "42.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "42.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "15.17",
  "length1": "15",
  "length2": "2",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "151.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "151.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "41.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "41.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "11.58",
  "width1": "11",
  "width2": "7",
  "totalArea": "143.83",
  "images": [],
  "extraAreas": [],
  "finalArea": "143.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "7.67",
  "width1": "7",
  "width2": "8",
```

```
"totalArea": "31.31",
"images": [],
"extraAreas": [],
"finalArea": "31.31"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Wardrobes",
    "value": "Wardrobes"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "11.75",
  "length1": "11",
  "length2": "9",
  "width": "8.17",
  "width1": "8",
  "width2": "2",
  "totalArea": "95.96",
  "images": [],
  "extraAreas": [],
  "finalArea": "95.96",
  "percentageBeforeTotal": "95.96",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
    },
    "id": "1",
    "length": "5.25",
    "length1": "5",
    "length2": "3",
    "width": "2.33",
    "width1": "2",
    "width2": "4",
    "totalArea": "12.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "12.25",
    "percentageBeforeTotal": "12.25",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1251aa6d152c1801b317",
      "label": "Gift Deed"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "922820",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "740",
    "squareMeterArea": "68.75",
    "docFinalBuiltUp": "888",
    "docFinalBuiltUpSquareMeter": "82.5",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "787.00",
      "squareMeterArea": "73.11",
      "expectedRate": "59974.59",
```

```
"percentage": ""
},
"builtUpArea": {
  "area": "944.40",
  "squareMeterArea": "87.74",
  "expectedRate": "49978.82",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67c2ecc87018387a18174325",
"property": "JVPD Scheme, Juhu",
"area": "787",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "7",
"source": "https://www.99acres.com/",
"expectedPrice": "47200000",
"expectedRate": "59974.59",
"builtUpExpectedRate": "49978.82",
"image": "cases/67af2bf0e1b0fbb7b7ebb704/
indicator_1740827198014_Image.png",
"squareMeter": "73.11",
"id": "413889"
},
{
  "carpetArea": {
    "area": "945.00",
    "squareMeterArea": "87.79",
    "expectedRate": "55555.56",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1134.00",
    "squareMeterArea": "105.35",
    "expectedRate": "46296.30",
    "percentage": "20"
  },
  "saleableArea": {
```

```
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67c2ecc87018387a18174326",
"property": "Juhu Sheetal, Juhu JVPD Scheme",
"area": "945",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "7",
"source": "magic_bricks",
"expectedPrice": "52500000",
"expectedRate": "5555.56",
"builtUpExpectedRate": "46296.30",
"image": "cases/67af2bf0e1b0fbb7b7ebb704/
indicator_1740827250086_Image.png",
"squareMeter": "87.79",
"id": "167148"
},
{
"carpetArea": {
"area": "757.00",
"squareMeterArea": "70.33",
"expectedRate": "47928.67",
"percentage": ""
},
"builtUpArea": {
"area": "908.40",
"squareMeterArea": "84.39",
"expectedRate": "39940.55",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67c2ecc87018387a18174327",
"property": "Juhu Sheetal, Juhu JVPD Scheme",
"area": "757",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "6",
"source": "Index_no.2",
"expectedPrice": "36282000",
"expectedRate": "47928.67",
"builtUpExpectedRate": "39940.55",
"image": "cases/67af2bf0e1b0fbb7b7ebb704/
indicator_1740827400569_Image.png",
"squareMeter": "70.33",
"id": "167642"
},
{
  "carpetArea": {
    "area": "916.00",
    "squareMeterArea": "85.10",
    "expectedRate": "48635.37",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1099.20",
    "squareMeterArea": "102.12",
    "expectedRate": "40529.48",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67c2ecc87018387a18174328",
  "property": "Juhu Sheetal, Juhu JVPD Scheme",
  "area": "916",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "3",
  "source": "Index_no.2",
  "expectedPrice": "44550000",
  "expectedRate": "48635.37",
  "builtUpExpectedRate": "40529.48",
```

```
    "image": "cases/67af2bf0e1b0fbb7b7ebb704/
indicator_1740827515851_Image.png",
    "squareMeter": "85.10",
    "id": "170913"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb0",
    "name": "externalImg_1739622853913_1739622850988_image_0.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externalImg_1739622853913_1739622850988_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb1",
    "name": "externalImg_1739622854268_1739622850988_image_1.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externalImg_1739622854268_1739622850988_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb2",
    "name": "externalImg_1739622854393_1739622850988_image_2.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externalImg_1739622854393_1739622850988_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb3",
    "name": "externalImg_1739622854711_1739622850988_image_3.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externalImg_1739622854711_1739622850988_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "67b089c9dc5b7cb7d2fa7cb4",
    "name": "externallmg_1739622854871_1739622850989_image_4.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622854871_1739622850989_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb5",
    "name": "externallmg_1739622855044_1739622850989_image_5.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855044_1739622850989_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb6",
    "name": "externallmg_1739622855264_1739622850989_image_6.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855264_1739622850989_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb7",
    "name": "externallmg_1739622855481_1739622850989_image_7.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855481_1739622850989_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb8",
    "name": "externallmg_1739622855582_1739622850989_image_8.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855582_1739622850989_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cb9",
```

```
    "name": "externallmg_1739622855801_1739622850989_image_9.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855801_1739622850989_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cba",
    "name": "externallmg_1739622855994_1739622850989_image_10.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622855994_1739622850989_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cbb",
    "name": "externallmg_1739622856168_1739622850989_image_11.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622856168_1739622850989_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cbc",
    "name": "externallmg_1739622856359_1739622850989_image_12.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622856359_1739622850989_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cbd",
    "name": "externallmg_1739622856534_1739622850989_image_13.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622856534_1739622850989_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cbe",
    "name": "externallmg_1739622856748_1739622850989_image_14.jpeg",
```

```
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622856748_1739622850989_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cbf",
    "name": "externallmg_1739622856922_1739622850989_image_15.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622856922_1739622850989_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cc0",
    "name": "externallmg_1739622857040_1739622850989_image_16.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622857040_1739622850989_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cc1",
    "name": "externallmg_1739622857247_1739622850989_image_17.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622857247_1739622850989_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cc2",
    "name": "externallmg_1739622857413_1739622850989_image_18.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622857413_1739622850989_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b089c9dc5b7cb7d2fa7cc3",
    "name": "externallmg_1739622857587_1739622850989_image_19.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externallmg_1739622857587_1739622850989_image_19.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94be",
    "name": "externallmg_1739622828831_1739622826279_image_0.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622828831_1739622826279_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94bf",
    "name": "externallmg_1739622829547_1739622826279_image_1.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622829547_1739622826279_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c0",
    "name": "externallmg_1739622829820_1739622826279_image_2.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622829820_1739622826279_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c1",
    "name": "externallmg_1739622830295_1739622826279_image_3.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622830295_1739622826279_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c2",
    "name": "externallmg_1739622830881_1739622826279_image_4.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622830881_1739622826279_image_4.jpeg",
    "orientation": "portrait"
  }
}
```

```
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c3",
    "name": "externallmg_1739622831480_1739622826279_image_5.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622831480_1739622826279_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c4",
    "name": "externallmg_1739622831628_1739622826279_image_6.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622831628_1739622826279_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c5",
    "name": "externallmg_1739622831804_1739622826279_image_7.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622831804_1739622826279_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c6",
    "name": "externallmg_1739622832026_1739622826279_image_8.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622832026_1739622826279_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b089b0e1b0fbb7b7ec94c7",
    "name": "externallmg_1739622832313_1739622826279_image_9.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/externallmg_1739622832313_1739622826279_image_9.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b089b0e1b0fbb7b7ec94c8",
  "name": "externalimg_1739622832501_1739622826279_image_10.jpeg",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
externalimg_1739622832501_1739622826279_image_10.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"document_1739537470974_Valuation_Report__Mr_Dipesh_Janani_Flat_No_801.pdf",
    "filename": "1740827770657_document_1739537470974_Valuation_Report__Mr_D
ipesh_Janani_Flat_No_801.pdf",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/processingDocuments/1740827770657_
document_1739537470974_Valuation_Report__Mr_Dipesh_Janani_Flat_No_801.pdf",
    "size": "2676177",
    "createdAt": "Sat Mar 01 2025 11:16:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_7067.pdf",
    "filename": "1740827770890_igr_7067.pdf",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740827770890_igr_7067.pdf",
    "size": "155279",
    "createdAt": "Sat Mar 01 2025 11:16:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_9407.pdf",
    "filename": "1740827771137_igr_9407.pdf",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740827771137_igr_9407.pdf",
    "size": "204865",
    "createdAt": "Sat Mar 01 2025 11:16:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1719386343043_1717159298325_Calculation_1.xlsx",
    "filename":
"1740827771143_1719386343043_1717159298325_Calculation_1.xlsx",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/processingDocuments/1740827771143_
```

```
1719386343043_1717159298325_Calculation_1.xlsx",
  "size": "1724730",
  "createdAt": "Sat Mar 01 2025 11:16:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname":
"document_1739537066954_Valuation_Report__Mr_Dipesh_Janani_FlatNo_802.pdf",
  "filename": "1740827771200_document_1739537066954_Valuation_Report__Mr_D
ipesh_Janani_FlatNo_802.pdf",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/processingDocuments/1740827771200_
document_1739537066954_Valuation_Report__Mr_Dipesh_Janani_FlatNo_802.pdf",
  "size": "2711036",
  "createdAt": "Sat Mar 01 2025 11:16:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "CC.pdf",
  "filename": "1740983654665_CC.pdf",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983654665_CC.pdf",
  "size": "858620",
  "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Dimention.jpeg",
  "filename": "1740983654757_Dimention.jpeg",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983654757_Dimention.jpeg",
  "size": "584634",
  "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Full OC.pdf",
  "filename": "1740983654768_Full_OC.pdf",
  "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983654768_Full_OC.pdf",
  "size": "601816",
  "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Gift Deed - 25-22.pdf",
  "filename": "1740983654892_Gift_Deed__2522.pdf",
```

```
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983654892_Gift_Deed__2522.pdf",
    "size": "1983168",
    "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Gift Deed - 29-22.pdf",
    "filename": "1740983654927_Gift_Deed__2922.pdf",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983654927_Gift_Deed__2922.pdf",
    "size": "2602133",
    "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Gift Deed 2022.pdf",
    "filename": "1740983655155_Gift_Deed_2022.pdf",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983655155_Gift_Deed_2022.pdf",
    "size": "22464186",
    "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Previous Report.pdf",
    "filename": "1740983655591_Previous_Report.pdf",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983655591_Previous_Report.pdf",
    "size": "2711036",
    "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2014.pdf",
    "filename": "1740983655645_Sale_Deed__2014.pdf",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983655645_Sale_Deed__2014.pdf",
    "size": "3119174",
    "createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1740983657779_Site_Details.jpeg",
    "path": "cases/67af2bf0e1b0fbb7b7ebb704/
processingDocuments/1740983657779_Site_Details.jpeg",
```



```
"size": "1158741",
"createdAt": "Mon Mar 03 2025 06:34:18 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"lastName": "Kuperkar",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "67b6b9b2e1b0fbb7b7ef0bd2",
"note": "Rate verification done pending for bank confirmatin",
"taskId": "67af3ab1e1b0fbb7b7ebce8e",
"createdAt": "2025-02-20T05:12:18.940Z"
}
],
"createdAt": "2025-02-14T11:41:36.784Z",
"updatedAt": "2025-03-03T10:20:38.169Z",
"__v": 0,
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 802, 8th Floor, Building No 12, Juhu Sheetal Co-op.
Hsg. Soc. Ltd., Samarth Ramdas Marg, J.V.P.D. Scheme, Near Juhu Shopping Centre,
Village - Vile Parle West, Municipality Ward No. K/W, Juhu, Taluka - Andheri, Vile Parle
(West), Mumbai, PIN - 400 049, State - Maharashtra, India",
"updatedAt": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": " Mrs. Seema Dipesh Janani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

```
"purchaseValueAsPerDocument": "",
"relationWithOwner": "selfOwner",
"rerald": "",
"siteVisitContactNo": "9820847905",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Gift Deed",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 740.00",
"flatRate": "55000",
"landOtherRate": "52000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2025-02-14",
"briefDescOfProperty": "4 Bedroom + Living Room + Kitchen + 2 Passage + WC + 3
Toilet",
"carpetTotal": "1509.10",
"otherCarpetTotal": "108.21",
"builtupPercentage": "20",
"extendOfSiteRemark": "",
"finalBuiltupArea": "1940.77",
"finalCarpetArea": "1617.31",
"finalSalableArea": "1940.77",
"salablePercentage": "0",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 1509.10 \nWardrobes in Sq. Ft.
= 95.96\nDry Balcony Area Area in Sq. Ft. = 12.25\n<br />\n",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "108.21",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
```

```

    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Mon Mar 03 2025 05:10:02 GMT+0000 (Coordinated
Universal Time)"
}

```

Name	Length	Width	Total
Composition :			
Living Room	28'7"	21'00"	600.25
Kitchen	12'2"	9'00"	109.50
Passage	15'3"	3'1"	47.02
Bedroom	11'5"	10'1"	115.12
WC	4'3"	4'4"	18.42
Bedroom	17'4"	10'00"	173.33
Toilet	9'3"	3'9"	34.69
Passage	13'6"	3'2"	42.75
Bedroom	15'2"	10'00"	151.67
Toilet	10'9"	3'10"	41.21
Bedroom	12'5"	11'7"	143.83
Toilet	4'1"	7'8"	31.31
Other Composition :			
Wardrobes	11'9"	8'2"	95.96
Dry Balcony Area	5'3"	2'4"	12.25