

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64ec3372eb1f822256d7a6c0"
    },
    "firstName": "Abhimanyu",
    "type": "CREDITOFFICER",
    "_id": "64ec3372eb1f822256d7a6c2",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8763993948",
    "email": "bmmsro2197@centralbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "20000000",
    "discussWithPerson": "Abhimanyu",
    "expectedFees": 10000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64ec3372eb1f822256d7a6c0",
  "name": "Goregaon West Branch",
  "branchCode": "",
  "mobileNo": "022 28720068",
  "alternateMobileNo": "",
  "email": "bmmsro2197@centralbank.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Nirala House. Pt. Dayal Upadhyay Chowk, 36. Jawahar Nahar, Goregaon
West, Mumbai - 400 104"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62550ed0aba01e0af98f2f75",
"role": "SITEENGINEER",
"firstName": "Chandan",
"email": "ck06806@gmail.com",
"lastName": "Singh",
"mobileNo": "8454863607",
"designation": "",
"shortName": "CH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordination",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.160399094505486",
  "longitude": "72.84731151652299"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84731151652299,
    19.160399094505486
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-17",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pahadi Goregaon",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Goregaon (West), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "14",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "New Vivek Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shree Nagar Estate",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "11/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "276A & 152",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "701",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```

    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN - 400 104",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
},

```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Shri Nagar Vasahat Marg",
  "west": "Christina CHSL",
  "south": "Open Land",
  "east": "Jai Hari Kunj CHSL"
},
"asPerDocumentAgreement": {
  "north": "By 20 Ft Wide Road",
  "west": "By Plot No. 15 (Christina CHSL)",
  "south": "By Vacant Plot",
  "east": "By Plot No. 13 (Jai Hari Kunj CHSL)"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Marginal Space",
    "south": "Staircase & Lift Lobby",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Marginal Space",
    "east": "Marginal Space",
    "south": "Staircase & Lift Lobby",
    "west": "Marginal Space"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
```

```
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "+ Dry Area.",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "336",
  "depreciatedCostOfConstruction": "20664.00",
  "depreciatedBuildingRate": "2464"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "160470",
  "landRate": "76820",
  "igrImage": "cases/67b2fdf9e1b0fbb7b7ed2185/igr_1739878404994_Image.png",
  "squareMeterGuideLineRate": "168494.00",
  "squareFeetGuideLineRate": "15654.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "92",
  "rate": "14972.00",
```

```
"squareMeterGuideLineRate": "161160.00",
"squareFeetGuideLineRate": "14972.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
```

```
"label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "One Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
```

```
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
}
```



```
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "900.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67b2fdf9e1b0fbb7b7ed2185/
routeMap_1739941898006_Image.png",
    "routeLat": "19.161585",
    "routeLng": "72.843102",
    "stationName": "Goregaon",
    "routeDistance": "1.8 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "713s77",
```

```
    "name": "713s77",
    "image": "cases/67b2fdf9e1b0fbb7b7ed2185/
routeMap_1739941746494_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "18597600.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "18597600.00"
},
```

```
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "datetime": "2025-02-19T08:36:13.249Z",
  "date": "Wed Feb 19 2025 08:36:13 GMT+0000 (Coordinated Universal Time)",
  "number": "2310639",
  "dayCount": "4",
  "monthCount": "289",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "13474800.00",
"selectedBuildUpValue": "900.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67b5669adc5b7cb7d2fbe364",
      "name": "externallmg_1739941529480_externallmg_1739787571737_1739787564735_image_9.jpeg",
      "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529480_externallmg_1739787571737_1739787564735_image_9.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "67b5669adc5b7cb7d2fbe35f",
      "name": "externallmg_1739941529429_externallmg_1739787570827_1739787564735_image_4.jpeg",
      "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529429_externallmg_1739787570827_1739787564735_image_4.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67b5669adc5b7cb7d2fbe368",
      "name": "externallmg_1739941529541_externallmg_1739787573568_1739787564735_image_13.jpeg",
      "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529541_externallmg_1739787573568_1739787564735_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67b5669adc5b7cb7d2fbe367",
      "name": "externallmg_1739941529515_externallmg_1739787573189_1739787564735_image_12.jpeg",
      "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529515_externallmg_1739787573189_1739787564735_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67b5669adc5b7cb7d2fbe363",
```

```
    "name": "externallmg_1739941529466_externallmg_1739787571284_1739787564735_image_8.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529466_externallmg_1739787571284_1739787564735_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe364",
    "name": "externallmg_1739941529480_externallmg_1739787571737_1739787564735_image_9.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529480_externallmg_1739787571737_1739787564735_image_9.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe360",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529432_externallmg_1739787570926_1739787564735_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe369",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529545_externallmg_1739787603779_1739787598934_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe36a",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529571_externallmg_1739787604008_1739787598934_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b566a6c594f0b7b656a7a8",
```

```
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541674_externallmg_1739787604133_1739787598934_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b566a6c594f0b7b656a7a9",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541678_externallmg_1739787604328_1739787598934_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b566a6c594f0b7b656a7ab",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541695_externallmg_1739787604786_1739787598934_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b566a6c594f0b7b656a7ad",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541710_externallmg_1739787605823_1739787598934_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b566a6c594f0b7b656a7af",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541739_externallmg_1739787605903_1739787598934_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b566a6c594f0b7b656a7aa",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541681_externallmg_1739787604598_1739787598934_image_4.jpeg",
    "orientation": "portrait"
  },
  {

```



```
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe35d",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529401_externallmg_1739787570188_1739787564735_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe35e",
    "name": "Living Room",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529404_externallmg_1739787570364_1739787564735_image_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "22026.00",
    "max": "30858.00"
  },
  "builtUpRateRange": {
    "min": "18363.00",
    "max": "25715.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "900.00",
"empanelmentNo": [
  "SMRO /CREDIT/2017-18/1311"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b2fdf9e1b0fbb7b7ed2185",
"ownerName": "Mr. Paramajit Bhogilal Shethiya",
"ownerPhoneNo": "9819866744",
"appAddress": "FLAT NO 701 B WING 7TH FLOOR NEW VIVEK CHS LTD CTS 276/
A P S PAHADI GOREGAON MUMBAI 400104",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "20/06/2017",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Omkar Developers, a Proprietor firm",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": " Mr. Paramajit Bhogilal Shethiya & Smt. Vibha Paramajit Shethiya",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      }
    }
  }
]
```

```
    },
    "Registration_No": " 6826/2017"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "329630",
  "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
document_1739783527727_1739783524229_paramjeet_shethia_agreement.pdf",
  "fileName":
"document_1739783527727_1739783524229_paramjeet_shethia_agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "13/06/2016",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " CHE/WS-II/0248/P/337(NEW)"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "627038",
  "path": "cases/67b2fdf9e1b0fbb7b7ed2185/document_1739943619061_CC.pdf",
  "fileName": "document_1739943619061_CC.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/04/2017",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": " CHE/WSII/0248/P/337(NEW)"
},
"isHardCopy": false,
"displayStatus": false,
"id": "636310",
"path": "cases/67b2fdf9e1b0fbb7b7ed2185/document_1739943707178_OC.pdf",
"fileName": "document_1739943707178_OC.pdf"
}
],
"caseNumber": "014372",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "856363",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Feb 17 2025 09:14:33 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Paramajit Bhogilal Shethiya",
    "phone": "9819866744",
    "ownershipShare": "",
    "email": "",
    "id": "761612"
  },
  {
    "name": "Smt. Vibha Paramajit Shethiya",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "panNo": "",
    "aadharNo": "",
    "id": "154319"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
    }
  }
]
```

```
    "label": "Square Feet"
  },
  "id": "704247",
  "name": "Living Room",
  "length": "17.92",
  "length1": "17",
  "length2": "11",
  "width": "13.25",
  "width1": "13",
  "width2": "3",
  "totalArea": "237.40",
  "images": [],
  "extraAreas": [],
  "finalArea": "237.40"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "12.58",
  "length1": "12",
  "length2": "7",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "120.59",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.59"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "6.92",
  "length1": "6",
  "length2": "11",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
```

```
"totalArea": "28.24",
"images": [],
"extraAreas": [],
"finalArea": "28.24"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "12.75",
  "length1": "12",
  "length2": "9",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "111.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "111.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "14.64",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```



```
"id": "5",
"name": "Bedroom",
"length": "11.33",
"length1": "11",
"length2": "4",
"width": "9.50",
"width1": "9",
"width2": "6",
"totalArea": "107.67",
"images": [],
"extraAreas": [],
"finalArea": "107.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "35.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Kitchen",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "75.00",
  "images": [],
```

```
    "extraAreas": [],
    "finalArea": "75.00"
  }
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony Area",
      "value": "Dry_Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "5.08",
    "length1": "5",
    "length2": "1",
    "width": "3.25",
    "width1": "3",
    "width2": "3",
    "totalArea": "16.52",
    "images": [],
    "extraAreas": [],
    "finalArea": "16.52",
    "percentageBeforeTotal": "16.52",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "274265",
    "selectAreaTypeDocument": "Built_Up",
```

```
"totalAreaDocument": "900",
"squareMeterArea": "83.61",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "475.00",
    "squareMeterArea": "44.13",
    "expectedRate": "29473.68",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "570.00",
    "squareMeterArea": "52.95",
    "expectedRate": "24561.40",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "67b4709fe1b0fbb7b7ee27f1",
  "property": "Residential Flat ",
  "area": "475",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "14000000",
  "expectedRate": "29473.68",
  "builtUpExpectedRate": "24561.40",
  "image": "cases/67b2fdf9e1b0fbb7b7ed2185/
indicator_1739878146846_Image.png",
```

```
"squareMeter": "44.13",
"id": "425039"
},
{
  "carpetArea": {
    "area": "875.00",
    "squareMeterArea": "81.29",
    "expectedRate": "30857.14",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1050.00",
    "squareMeterArea": "97.55",
    "expectedRate": "25714.29",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67b4709fe1b0fbb7b7ee27f2",
  "property": " Residential Flat",
  "area": "875",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "27000000",
  "expectedRate": "30857.14",
  "builtUpExpectedRate": "25714.29",
  "image": "cases/67b2fdf9e1b0fbb7b7ed2185/
indicator_1739878180772_Image.png",
  "squareMeter": "81.29",
  "id": "123058"
},
{
  "carpetArea": {
    "area": "649.00",
    "squareMeterArea": "60.29",
    "expectedRate": "22696.46",
    "percentage": ""
  },
```

```
},
"builtUpArea": {
  "area": "778.80",
  "squareMeterArea": "72.35",
  "expectedRate": "18913.71",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "67b6b589e1b0fbb7b7ef0148",
"property": "Residential Flat",
"area": "649",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "14730000",
"expectedRate": "22696.46",
"builtUpExpectedRate": "18913.71",
"image": "cases/67b2fdf9e1b0fbb7b7ed2185/
indicator_1739878225880_Image.png",
"squareMeter": "60.29",
"id": "897606"
},
{
  "carpetArea": {
    "area": "396",
    "squareMeterArea": "36.79",
    "expectedRate": "22025.25",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "475.00",
    "squareMeterArea": "44.13",
    "expectedRate": "18362.11",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
```

```
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67b4709fe1b0fbb7b7ee27f4",
  "property": "Residential Flat",
  "area": "475",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "8722000",
  "expectedRate": "22025.25",
  "builtUpExpectedRate": "8722000",
  "image": "cases/67b2fdf9e1b0fbb7b7ed2185/
indicator_1739878265169_Image.png",
  "squareMeter": "44.13",
  "id": "834542"
}
],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b30d36c594f0b7b655c70d",
    "name": "externalImg_1739787569940_1739787564735_image_0.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
externalImg_1739787569940_1739787564735_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b30d36c594f0b7b655c710",
    "name": "externalImg_1739787570551_1739787564735_image_3.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
externalImg_1739787570551_1739787564735_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe35d",
```

```
    "name": "externallmg_1739941529401_externallmg_1739787570188_1739787564735_image_1.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529401_externallmg_1739787570188_1739787564735_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe35e",
    "name": "externallmg_1739941529404_externallmg_1739787570364_1739787564735_image_2.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529404_externallmg_1739787570364_1739787564735_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe35f",
    "name": "externallmg_1739941529429_externallmg_1739787570827_1739787564735_image_4.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529429_externallmg_1739787570827_1739787564735_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe360",
    "name": "externallmg_1739941529432_externallmg_1739787570926_1739787564735_image_5.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529432_externallmg_1739787570926_1739787564735_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe361",
    "name": "externallmg_1739941529448_externallmg_1739787571027_1739787564735_image_6.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529448_externallmg_1739787571027_1739787564735_image_6.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b5669adc5b7cb7d2fbe362",
  "name": "externallmg_1739941529449_externallmg_1739787571126_17397875647
35_image_7.jpeg",
  "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529449_externall
mg_1739787571126_1739787564735_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b5669adc5b7cb7d2fbe363",
  "name": "externallmg_1739941529466_externallmg_1739787571284_17397875647
35_image_8.jpeg",
  "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529466_externall
mg_1739787571284_1739787564735_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b5669adc5b7cb7d2fbe364",
  "name": "externallmg_1739941529480_externallmg_1739787571737_17397875647
35_image_9.jpeg",
  "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529480_externall
mg_1739787571737_1739787564735_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b5669adc5b7cb7d2fbe365",
  "name": "externallmg_1739941529484_externallmg_1739787572125_17397875647
35_image_10.jpeg",
  "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529484_externall
mg_1739787572125_1739787564735_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b5669adc5b7cb7d2fbe366",
  "name": "externallmg_1739941529512_externallmg_1739787572959_17397875647
35_image_11.jpeg",
```



```
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529512_externallmg_1739787572959_1739787564735_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe367",
    "name": "externallmg_1739941529515_externallmg_1739787573189_1739787564735_image_12.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529515_externallmg_1739787573189_1739787564735_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe368",
    "name": "externallmg_1739941529541_externallmg_1739787573568_1739787564735_image_13.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529541_externallmg_1739787573568_1739787564735_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe369",
    "name": "externallmg_1739941529545_externallmg_1739787603779_1739787598934_image_0.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529545_externallmg_1739787603779_1739787598934_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b5669adc5b7cb7d2fbe36a",
    "name": "externallmg_1739941529571_externallmg_1739787604008_1739787598934_image_1.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941529571_externallmg_1739787604008_1739787598934_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67b566a6c594f0b7b656a7a8",
    "name": "externallmg_1739941541674_externallmg_1739787604133_17397875989
34_image_2.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541674_externall
mg_1739787604133_1739787598934_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b566a6c594f0b7b656a7a9",
    "name": "externallmg_1739941541678_externallmg_1739787604328_17397875989
34_image_3.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541678_externall
mg_1739787604328_1739787598934_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b566a6c594f0b7b656a7aa",
    "name": "externallmg_1739941541681_externallmg_1739787604598_17397875989
34_image_4.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541681_externall
mg_1739787604598_1739787598934_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b566a6c594f0b7b656a7ab",
    "name": "externallmg_1739941541695_externallmg_1739787604786_17397875989
34_image_5.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541695_externall
mg_1739787604786_1739787598934_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b566a6c594f0b7b656a7ac",
    "name": "externallmg_1739941541697_externallmg_1739787605766_17397875989
34_image_6.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541697_externall
mg_1739787605766_1739787598934_image_6.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b566a6c594f0b7b656a7ad",
    "name": "externallmg_1739941541710_externallmg_1739787605823_17397875989
34_image_7.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541710_externall
mg_1739787605823_1739787598934_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b566a6c594f0b7b656a7ae",
    "name": "externallmg_1739941541735_externallmg_1739787605837_17397875989
34_image_8.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541735_externall
mg_1739787605837_1739787598934_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b566a6c594f0b7b656a7af",
    "name": "externallmg_1739941541739_externallmg_1739787605903_17397875989
34_image_9.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/externallmg_1739941541739_externall
mg_1739787605903_1739787598934_image_9.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "Paramajit Bhogilal Shethiya.pdf",
    "filename": "1739964202075_Paramajit_Bhogilal_Shethiya.pdf",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
externalDocuments/1739964202075_Paramajit_Bhogilal_Shethiya.pdf",
    "size": "6297917",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    }
  },
  "createdAt": "Wed Feb 19 2025 11:23:22 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9589345132d6a6bddcc3a"
```

```
}
],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1739878444249_Calculation_Sheet_NEW.xlsx",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
processingDocuments/1739878444249_Calculation_Sheet_NEW.xlsx",
    "size": "957172",
    "createdAt": "Tue Feb 18 2025 11:34:05 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1739944422310_CC.pdf",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
processingDocuments/1739944422310_CC.pdf",
    "size": "1414056",
    "createdAt": "Wed Feb 19 2025 05:53:43 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1739944422331_OC.pdf",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
processingDocuments/1739944422331_OC.pdf",
    "size": "376932",
    "createdAt": "Wed Feb 19 2025 05:53:43 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2017.pdf",
    "filename": "1739944422459_Sale_Deed__2017.pdf",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
processingDocuments/1739944422459_Sale_Deed__2017.pdf",
    "size": "10228876",
    "createdAt": "Wed Feb 19 2025 05:53:43 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1739944422601_Site_Details.jpeg",
    "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
processingDocuments/1739944422601_Site_Details.jpeg",
    "size": "760692",
    "createdAt": "Wed Feb 19 2025 05:53:43 GMT+0000 (Coordinated Universal Time)",
```

```
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sketch & Dimention.jpeg",
  "filename": "1739944422616_Sketch__Dimention.jpeg",
  "path": "cases/67b2fdf9e1b0fbb7b7ed2185/
processingDocuments/1739944422616_Sketch__Dimention.jpeg",
  "size": "462745",
  "createdAt": "Wed Feb 19 2025 05:53:43 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67b44662c594f0b7b656408b",
    "note": "Value given for confirmation ",
    "taskId": "67b3027dc594f0b7b655b998",
    "createdAt": "2025-02-18T08:35:46.229Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67b470aae1b0fbb7b7ee27ff",
    "note": "Value confirm",
```

```
"taskId": "67b3027dc594f0b7b655b998",
"createdAt": "2025-02-18T11:36:10.326Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "MAKER",
  "display": true,
  "status": true,
  "_id": "67b6b422c594f0b7b65728c4",
  "note": "changes in report (Task Reopen)",
  "taskId": "67b470b4dc5b7cb7d2fbbcac",
  "createdAt": "2025-02-20T04:48:34.774Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "PRINT",
  "display": true,
  "status": true,
  "_id": "67b6b42cc594f0b7b657294d",
  "note": "changes in report (Task Reopen)",
  "taskId": "67b5be3bdc5b7cb7d2fc37f0",
  "createdAt": "2025-02-20T04:48:44.750Z"
},
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
}
```

```
"workType": "CHECKER",
"display": true,
"status": true,
"_id": "67b6b563e1b0fbb7b7ef00d1",
"note": "Rvised (Task Reopen)",
"taskId": "67b57464e1b0fbb7b7ee6918",
"createdAt": "2025-02-20T04:53:55.127Z"
}
],
"createdAt": "2025-02-17T09:14:33.655Z",
"updatedAt": "2025-02-20T04:54:48.655Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 701, 7th Floor, Wing - B, New Vivek Co-op. Hsg.
Soc. Ltd., Plot No. 14, Shree Nagar Estate, Village - Pahadi Goregaon, Taluka -
Borivali, District - Mumbai Suburban, Goregaon (West), Mumbai, PIN - 400 104, State -
Maharashtra, India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Smt. Vibha Paramajit Shethiya",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"rerald": "",
"siteVisitContactNo": "9819866744",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 900.00",
"flatRate": "21000",
"landOtherRate": "18200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
```

```

    },
    "roadFacing": false,
    "mall": false
  },
  "briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
  "carpetTotal": "730.35",
  "otherCarpetTotal": "16.52",
  "otherCompositionBuiltUpTotal": "0.00",
  "otherCompositionCarpetTotal": "16.52",
  "otherCompositionSaleableTotal": "0.00",
  "builtupPercentage": "20",
  "finalBuiltupArea": "896.24",
  "finalCarpetArea": "746.87",
  "finalSalableArea": "896.24",
  "salablePercentage": "0",
  "toBeAdded": "",
  "extendOfSiteRemark": "",
  "siteMeasurementRemark": "",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    }
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'11"	13'3"	237.40
Bedroom	12'7"	9'7"	120.59
Toilet	6'11"	4'1"	28.24

Bedroom	12'9"	8'9"	111.56
Passage	2'10"	5'2"	14.64
Bedroom	11'4"	9'6"	107.67
Toilet	7'10"	4'6"	35.25
Kitchen	11'3"	6'8"	75.00
Other Composition :			
Dry Balcony Area	5'1"	3'3"	16.52