

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "firstName": "Amruta ",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f5a",
    "email": "amruta.pathak@cosmosbank.in",
    "mobileNo": "-",
    "workMobileNo": "9769900929",
    "lastName": "Pathak"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) ",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhudurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
( East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82",
  "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "_id": "5fc78e26625ecd20ec1f88e9",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "firstName": "Vaishali",
  "lastName": "Sarmalkar",
  "shortName": "VS",
  "email": "v.sarmalkar@vastukala.org",
  "designation": "",
  "mobileNo": "9004437379",
  "role": "MAKER+CHECKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "1"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.195794998572048",
  "longitude": "73.08666538565777"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-14",
      "remark": "Lead not create flat no. 106 & Flat No-105 , Internal Merged "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-13",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-14",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-13",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-14",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nandivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Dombivli (East)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aishwarya Kiran Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bhopar Road",
  "label": false
},
"street2": {
```



```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Desale Pada",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "06/13",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```

```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B-106",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 201",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Partly_Vitrified___Partly Ceramic",
    "label": "Partly Vitrified / Partly Ceramic"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  }
}
```

```

},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Celling",
  "label": "Cement Plastering with POP false Celling"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Mahanagar_Palika",
    "label": "Kalyan Mahanagar Palika"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Gurukrupa Royal CHSL",
    "west": "Internal Road",
    "south": "Wing – A / Guardian Sports Academy",
    "east": "Garden / Neel Residency"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",

```

```
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "ordinary",
  "label": "Ordinary"
}
```

```
    },
    "compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
  },
  "apfDetails": {
    "buildings": [],
    "compositions": []
  },
  "compositeRate": {
    "remark": "As per Site Inspection, Residential Flat No. 105 & 106 internally amalgamated with separate entrances. Two flats are internally amalgamated to form a single flat but can be demarcated individually. The said valuation for Flat No. 106, For the purpose of valuation, we have considered area as per Agreement for Sale of Flat No. 106 only.",
    "depreciationPercentage": "28.5",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "depreciatedCostOfConstruction": "5587.5",
    "depreciatedBuildingRate": "1787.5"
  },
  "igrRate": {
    "propertyName": "Flat",
    "rate": "56400",
    "landRate": "21400",
    "igrImage": "cases/67b45873e1b0fbb7b7edef6d/igr_1739858738436_Image.png",
    "squareMeterGuideLineRate": "56400.00",
    "squareFeetGuideLineRate": "5240.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "0",
    "depreciationPercentage": "81",
    "rate": "4622.00",
    "squareFeetGuideLineRate": "4622.00",
    "squareMeterGuideLineRate": "49750.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Vacant",
      "label": "Vacant"
    }
  }
}
```

```
},
"monthlyRent": "N.A.",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
},
```

```
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2006",
  "fullDate": "1/1/2006"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
}
```



```
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "41",
"ageOfBuilding": "19",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "600.00",
```

```
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67b45873e1b0fbb7b7edef6d/
routeMap_1739864199525_Image.png",
    "routeLat": "19.195914",
    "routeLng": "73.086741",
    "stationName": "Dombivali",
    "routeDistance": "3.6 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "4i48n",
      "name": "4i48n",
      "image": "cases/67b45873e1b0fbb7b7edef6d/
routeMap_1739864039176_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "1500000.00",
      "depreciationPercentage": "28.5",
      "depreciatedCostOfConstruction": "427500.00",
      "totalFairMarketValue": "3352500.00"
    },
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
```

```
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3780000.00",
"finalValue": "3780000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "datetime": "2025-02-18T10:28:57.593Z",
  "date": "Tue Feb 18 2025 10:28:57 GMT+0000 (Coordinated Universal Time)",
  "number": "2310630",
  "dayCount": "16",
  "monthCount": "280",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2773200.00",
  "selectedBuildUpValue": "600.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67af6676dc5b7cb7d2f9e602",
      "name": "externalImg_1739548277333_1739548262395_image_13.jpeg",
      "path": "cases/67b45873e1b0fbb7b7edef6d/
externalImg_1739548277333_1739548262395_image_13.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],

```

```
"externalPhotos": [
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e602",
    "name": "externallmg_1739548277333_1739548262395_image_13.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548277333_1739548262395_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e601",
    "name": "externallmg_1739548275207_1739548262395_image_12.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548275207_1739548262395_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5f5",
    "name": "externallmg_1739548265469_1739548262395_image_0.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548265469_1739548262395_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5f8",
    "name": "externallmg_1739548268473_1739548262395_image_3.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548268473_1739548262395_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fe",
    "name": "externallmg_1739548272938_1739548262395_image_9.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548272938_1739548262395_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fd",
    "name": "externallmg_1739548272155_1739548262395_image_8.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548272155_1739548262395_image_8.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5f9",
    "name": "externallmg_1739548269798_1739548262395_image_4.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548269798_1739548262395_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5f7",
    "name": "externallmg_1739548267653_1739548262395_image_2.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548267653_1739548262395_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fc",
    "name": "externallmg_1739548271698_1739548262395_image_7.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548271698_1739548262395_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fb",
    "name": "externallmg_1739548271178_1739548262395_image_6.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548271178_1739548262395_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5f6",
    "name": "externallmg_1739548266602_1739548262395_image_1.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548266602_1739548262395_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fa",
    "name": "externallmg_1739548270743_1739548262395_image_5.jpeg",
```



```
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548270743_1739548262395_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67af661ae1b0fbb7b7ebdc91",
    "name": "externallmg_1739548183492_1739548179708_image_3.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548183492_1739548179708_image_3.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7044.00",
    "max": "8800.00"
  },
  "builtUpRateRange": {
    "min": "5870.00",
    "max": "7334.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "600.00",
"empanelmentNo": [
  "HO/Credit/87/2022-23"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b45873e1b0fbb7b7edef6d",
"ownerName": "Mr. Mehul Jethalal Lalka & Mrs. Malini Mehul Lalka",
"ownerPhoneNo": "9833637483",
"fullAddress": "Residential Flat No. B-106, 1st Floor, Wing - B, Aishwarya Kiran Co.-
Op. Hsg. Soc. Ltd., Desale Pada, Bhopar Road, Village - Nandivali, Taluka - Kalyan,
District - Thane, Dombivli (East), PIN Code - 421 201, State - Maharashtra, India",
"remark": "Lead not create flat no. 106 & Flat No-105 , Internal Merged ",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "10/02/2025",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "\tMr. Shyam Shivaji Shinde & Mrs. Rachana Shyam Shinde",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Mehul Jethalal Lalka & Mrs. Malini Mehul Lalka ",
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "2246/2025"
},
"isHardCopy": false,
"displayStatus": true,
"id": "732677",
"path": "cases/67b45873e1b0fbb7b7edef6d/
document_1739531482107_DocScanner_Feb_14_2025_1456.pdf",
"fileName": "document_1739531482107_DocScanner_Feb_14_2025_1456.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "07/12/1996",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_MahanagarPalika",
      "label": "Kalyan MahanagarPalika"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KMC / NRV / BP / DOV / 512 - 163"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1739868203315_180865.pdf",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
document_1739868203315_180865.pdf",
  "id": "303462",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Tue Feb 18 2025 08:43:23 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "04/08/2006",
    "remark": " issued by Zilla Parishad Thane",
    "number": {
```

```
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "SPV / GP / PRADHIKARAN / 25 /2006"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1739868471368_140788.pdf",
"path": "cases/67b45873e1b0fbb7b7edef6d/
document_1739868471368_140788.pdf",
"id": "157981",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Feb 18 2025 08:47:51 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014402",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "810080",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Feb 14 2025 11:11:26 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Mehul Jethalal Lalka & Mrs. Malini Mehul Lalka",
    "phone": "9833637483",
    "ownershipShare": "",
    "email": "",
    "id": "574195"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
],
```

```
"id": "7",
"name": "Living Room",
"length": "11.00",
"length1": "11",
"length2": "0",
"width": "16.00",
"width1": "16",
"width2": "0",
"totalArea": "176.00",
"images": [],
"finalArea": "176.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "11.00",
  "length1": "11",
  "length2": "0",
  "width": "11.00",
  "width1": "11",
  "width2": "0",
  "totalArea": "121.00",
  "images": [],
  "finalArea": "121.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Kitchen",
  "length": "7.00",
  "length1": "7",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
  "width2": "0",
  "totalArea": "70.00",
  "images": [],
```

```
"finalArea": "70.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bathroom",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "8.00",
  "width1": "8",
  "width2": "0",
  "totalArea": "24.00",
  "images": [],
  "finalArea": "24.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "9.00",
  "images": [],
  "finalArea": "9.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
```



```
"length": "3.00",
"length1": "3",
"length2": "0",
"width": "7.00",
"width1": "7",
"width2": "0",
"totalArea": "21.00",
"images": [],
"finalArea": "21.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "573308",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "600",
    "squareMeterArea": "55.74",
```

```
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "500.00",
"squareMeterArea": "46.45",
"expectedRate": "8800.00",
"percentage": ""
},
"builtUpArea": {
"area": "600.00",
"squareMeterArea": "55.74",
"expectedRate": "7333.33",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67b423bac594f0b7b6561fa5",
"property": "Flat",
"area": "500",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "4400000",
"expectedRate": "8800.00",
"builtUpExpectedRate": "7333.33",
"image": "cases/67b45873e1b0fbb7b7edef6d/
indicator_1739857295998_Image.png",
"squareMeter": "46.45",
"id": "292116"
```

```
},
{
  "carpetArea": {
    "area": "430.00",
    "squareMeterArea": "39.95",
    "expectedRate": "7906.98",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "516.00",
    "squareMeterArea": "47.94",
    "expectedRate": "6589.15",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67b423bac594f0b7b6561fa6",
  "property": "Flat",
  "area": "430",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3400000",
  "expectedRate": "7906.98",
  "builtUpExpectedRate": "6589.15",
  "image": "cases/67b45873e1b0fbb7b7edef6d/
indicator_1739857318242_Image.png",
  "squareMeter": "39.95",
  "id": "878085"
},
{
  "carpetArea": {
    "area": "383.33",
    "squareMeterArea": "35.61",
    "expectedRate": "7043.54",
    "percentage": ""
  },
  "builtUpArea": {
```

```
    "area": "460.00",
    "squareMeterArea": "42.74",
    "expectedRate": "5869.57",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67b423bac594f0b7b6561fa7",
  "property": "Flat",
  "area": "460",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "2700000",
  "expectedRate": "7043.54",
  "builtUpExpectedRate": "2700000",
  "image": "cases/67b45873e1b0fbb7b7edef6d/
indicator_1739857725702_Image.png",
  "squareMeter": "42.74",
  "id": "148316"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5f5",
    "name": "externalimg_1739548265469_1739548262395_image_0.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externalimg_1739548265469_1739548262395_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5f6",
    "name": "externalimg_1739548266602_1739548262395_image_1.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externalimg_1739548266602_1739548262395_image_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af6676dc5b7cb7d2f9e5f7",
  "name": "externallmg_1739548267653_1739548262395_image_2.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548267653_1739548262395_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af6676dc5b7cb7d2f9e5f8",
  "name": "externallmg_1739548268473_1739548262395_image_3.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548268473_1739548262395_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af6676dc5b7cb7d2f9e5f9",
  "name": "externallmg_1739548269798_1739548262395_image_4.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548269798_1739548262395_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af6676dc5b7cb7d2f9e5fa",
  "name": "externallmg_1739548270743_1739548262395_image_5.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548270743_1739548262395_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af6676dc5b7cb7d2f9e5fb",
  "name": "externallmg_1739548271178_1739548262395_image_6.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548271178_1739548262395_image_6.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fc",
    "name": "externallmg_1739548271698_1739548262395_image_7.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548271698_1739548262395_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fd",
    "name": "externallmg_1739548272155_1739548262395_image_8.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548272155_1739548262395_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5fe",
    "name": "externallmg_1739548272938_1739548262395_image_9.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548272938_1739548262395_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e5ff",
    "name": "externallmg_1739548273512_1739548262395_image_10.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548273512_1739548262395_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af6676dc5b7cb7d2f9e600",
    "name": "externallmg_1739548274402_1739548262395_image_11.jpeg",
    "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548274402_1739548262395_image_11.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af6676dc5b7cb7d2f9e601",
  "name": "externallmg_1739548275207_1739548262395_image_12.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548275207_1739548262395_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af6676dc5b7cb7d2f9e602",
  "name": "externallmg_1739548277333_1739548262395_image_13.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548277333_1739548262395_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67af661ae1b0fbb7b7ebdc8e",
  "name": "externallmg_1739548181615_1739548179708_image_0.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548181615_1739548179708_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67af661ae1b0fbb7b7ebdc8f",
  "name": "externallmg_1739548182188_1739548179708_image_1.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548182188_1739548179708_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67af661ae1b0fbb7b7ebdc90",
  "name": "externallmg_1739548182757_1739548179708_image_2.jpeg",
  "path": "cases/67b45873e1b0fbb7b7edef6d/
externallmg_1739548182757_1739548179708_image_2.jpeg",
  "orientation": "portrait"
},
{
```

```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67af661ae1b0fbb7b7ebdc91",
"name": "externalImg_1739548183492_1739548179708_image_3.jpeg",
"path": "cases/67b45873e1b0fbb7b7edef6d/
externalImg_1739548183492_1739548179708_image_3.jpeg",
"orientation": "landscape"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67af661ae1b0fbb7b7ebdc92",
"name": "externalImg_1739548184802_1739548179708_image_4.jpeg",
"path": "cases/67b45873e1b0fbb7b7edef6d/
externalImg_1739548184802_1739548179708_image_4.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67af661ae1b0fbb7b7ebdc93",
"name": "externalImg_1739548185052_1739548179708_image_5.jpeg",
"path": "cases/67b45873e1b0fbb7b7edef6d/
externalImg_1739548185052_1739548179708_image_5.jpeg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "cosmos - calculation - Mehul.xlsx",
"filename": "1739858777733_cosmos__calculation__Mehul.xlsx",
"path": "cases/67b45873e1b0fbb7b7edef6d/
processingDocuments/1739858777733_cosmos__calculation__Mehul.xlsx",
"size": "17302",
"createdAt": "Tue Feb 18 2025 06:06:18 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "Summary - Mehul.xlsx",
"filename": "1739858777734_Summary__Mehul.xlsx",
"path": "cases/67b45873e1b0fbb7b7edef6d/
processingDocuments/1739858777734_Summary__Mehul.xlsx",
"size": "1359581",
"createdAt": "Tue Feb 18 2025 06:06:18 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
```



```
    },
    {
      "originalname": "WhatsApp Image 2025-02-18 at 10.21.33 AM (1).jpeg",
      "filename":
"1739858777769_WhatsApp_Image_20250218_at_102133_AM_1.jpeg",
      "path": "cases/67b45873e1b0fbb7b7edef6d/processingDocuments/1739858777769
_WhatsApp_Image_20250218_at_102133_AM_1.jpeg",
      "size": "147769",
      "createdAt": "Tue Feb 18 2025 06:06:18 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "WhatsApp Image 2025-02-18 at 10.21.33 AM (2).jpeg",
      "filename":
"1739858777891_WhatsApp_Image_20250218_at_102133_AM_2.jpeg",
      "path": "cases/67b45873e1b0fbb7b7edef6d/processingDocuments/1739858777891
_WhatsApp_Image_20250218_at_102133_AM_2.jpeg",
      "size": "173308",
      "createdAt": "Tue Feb 18 2025 06:06:18 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "WhatsApp Image 2025-02-18 at 10.21.33 AM.jpeg",
      "filename": "1739858777896_WhatsApp_Image_20250218_at_102133_AM.jpeg",
      "path": "cases/67b45873e1b0fbb7b7edef6d/processingDocuments/1739858777896
_WhatsApp_Image_20250218_at_102133_AM.jpeg",
      "size": "133807",
      "createdAt": "Tue Feb 18 2025 06:06:18 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "5fc78e26625ecd20ec1f88e9",
        "role": "MAKER+CHECKER",
        "firstName": "Vaishali",
        "lastName": "Sarmalkar",
        "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
    }
  ]
}
```

```
    "_id": "67b0299ce1b0fbb7b7ec03fd",
    "note": "working done. visit pendig.",
    "taskId": "67af24e6c594f0b7b6547c4a",
    "createdAt": "2025-02-15T05:43:56.347Z"
  },
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67b02ab1c594f0b7b654cb73",
    "note": "working done. pending for oc",
    "taskId": "67af24e6c594f0b7b6547c4a",
    "createdAt": "2025-02-15T05:48:33.069Z"
  }
],
"createdAt": "2025-02-18T09:52:52.324Z",
"updatedAt": "2025-02-18T11:40:39.748Z",
"__v": 0,
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mrs. Malini Mehul Lalka",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9833637483",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 600.00",
```

```

"flatRate": "6300",
"landOtherRate": "3800",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + WC + 2
Passage",
"carpetTotal": "433",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "476.30",
"finalCarpetArea": "433.00",
"finalSalableArea": "523.93",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "\n",
"siteMeasurementRemark": "\n",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Tue Feb 18 2025 06:21:29 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-02-14",
"refCaselId": "67af24dec594f0b7b6547c04"
}

```

Name	Length	Width	Total
Composition :			

Living Room	11'0"	16'0"	176.00
Bedroom	11'0"	11'0"	121.00
Kitchen	7'0"	10'0"	70.00
Bathroom	3'0"	8'0"	24.00
WC	3'0"	3'0"	9.00
Passage	3'0"	7'0"	21.00
Passage	3'0"	4'0"	12.00
Other Composition :			