

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb60"
    },
    "firstName": "Vitthal",
    "type": "CREDITOFFICER",
    "_id": "6526806e703d7c40db9adf56",
    "lastName": "Mane",
    "mobileNo": "",
    "workMobileNo": "8108129226",
    "email": "vitthal.mane@janasevabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Vitthal",
    "expectedFees": 3000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank (Borivali) LTD",
  "displayName": "Janaseva Sahakari Bank (Borivali) LTD",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb60",
  "branchCode": "0000010",
  "type": "BRANCH",
  "name": "Bhayander (East) Branch",
  "email": "vitthal.mane@janasevabank.in",
  "mobileNo": "02228171617",
  "alternateMobileNo": "02228171618",
  "address": "Janki Avaneue 1st floor, phatak road, Bhayander East Thane-401105",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "66850df5d9f18310ed2e5d98",
"role": "SITEENGINEER",
"firstName": "Krishna",
"email": "krishnagawade9@gmail.com",
"lastName": "Gawde",
"mobileNo": "9821646373",
"designation": "Site Engg",
"shortName": "Krishna",
"workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": ""
```

```
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.304438955651808",
  "longitude": "72.85228616567353"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85228616567353,
    19.304438955651808
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "20/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-20",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-21",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-20",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "Country - India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bhayander ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Rajul Apartment Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Devchand Nagar Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Jain Mandir",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": ""
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "24/7, 28/2, 29/1, 31/3, 31/1 , New Survey No. 2/7, 3/2, 4/1, 6/3, 6/1",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "304",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 101",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhayander (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
```

```
"value": "Cement_Plastering+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mira_Bhayander_Municipal_Corporation",
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Badrinath Building ",
"west": "60 Feet Road ",
"south": "Internal Road ",
"east": "Neminath Apartment "
},
"asPerDocumentAgreement": {
"north": "Details not available ",
"west": "Details not available ",
"south": "Details not available ",
"east": "Details not available "
},
"unitBoundaries": {
"asPerActual": {
"north": "Staircase",
"east": "Marginal Space",
"south": "Marginal Space",
"west": "Flat No. 303"
},
"asPerDocument": {
"north": "Details not available ",
```

```
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "12000",
  "depreciatedBuildingRate": "2300"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "58700",
  "landRate": "20400",
```

```
"igrImage": "cases/67b6c201dc5b7cb7d2fc83e6/igr_1740376052209_Image.png",
"squareMeterGuideLineRate": "49895.00",
"squareFeetGuideLineRate": "4635.00"
},
"igrFinalRate": {
  "floorRatePercentage": "85",
  "depreciationPercentage": "62",
  "rate": "3594.00",
  "squareFeetGuideLineRate": "3594.00",
  "squareMeterGuideLineRate": "38687.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "12,000/- Present rental income per month ",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per local norms ",
  "tenantName": "Mr. Hardik Jain<br />Occupied Since - Last 2 Years ",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1987",
  "fullDate": "1/1/1987"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
```

```
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
}
```



```
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "22",
"ageOfBuilding": "38",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "3",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "405.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67b6c201dc5b7cb7d2fc83e6/
routeMap_1740378639481_Image.png",
    "routeLat": "19.304310",
    "routeLng": "72.852316",
    "stationName": "Bhayander ",
    "routeDistance": "900 Mtrs. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
}
```

```
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "8oluv6",
    "name": "8oluv6",
    "image": "cases/67b6c201dc5b7cb7d2fc83e6/
routeMap_1740378548777_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
```

```
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4860000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4860000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1455570.00",
```

```
"selectedBuildUpValue": "405.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67bc1239178be87ad41d7cfb",
      "name":
"externallmg_1740378680588_WhatsApp_Image_20250224_at_113841_AM.jpeg",
      "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740378680588_WhatsApp_Image_20250224_at_113841_AM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67bc1239178be87ad41d7cfb",
      "name":
"externallmg_1740378680588_WhatsApp_Image_20250224_at_113841_AM.jpeg",
      "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740378680588_WhatsApp_Image_20250224_at_113841_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67b80effc594f0b7b65801fc",
      "name":
"externallmg_1740115711513_WhatsApp_Image_20250220_at_230343_2.jpeg",
      "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711513_WhatsApp_Image_20250220_at_230343_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67b80effc594f0b7b6580201",
      "name":
"externallmg_1740115711556_WhatsApp_Image_20250220_at_230345_1.jpeg",
      "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711556_WhatsApp_Image_20250220_at_230345_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
```

```
    "_id": "67b80effc594f0b7b6580200",
    "name":
"externallmg_1740115711553_WhatsApp_Image_20250220_at_230344.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711553_WhatsApp_Image_20250220_at_230344.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b80effc594f0b7b6580207",
    "name":
"externallmg_1740115711615_WhatsApp_Image_20250220_at_230346.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711615_WhatsApp_Image_20250220_at_230346.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67bc1239178be87ad41d7cfa",
    "name":
"externallmg_1740378680559_WhatsApp_Image_20250224_at_113840_AM.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740378680559_WhatsApp_Image_20250224_at_113840_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b80effc594f0b7b6580202",
    "name":
"externallmg_1740115711574_WhatsApp_Image_20250220_at_230345_2.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711574_WhatsApp_Image_20250220_at_230345_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67bc13cd16c8bb7a9102d67b",
    "name": "externallmg_1740379084877_Picture2.jpg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740379084877_Picture2.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11173.00",
    "max": "15741.00"
  },
  "builtUpRateRange": {
    "min": "9311.00",
    "max": "13118.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```



```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "405.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
```

```
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b6c201dc5b7cb7d2fc83e6",
"ownerName": "Mrs. Mamta Kamlesh Jain & Mr. Kanish Kamlesh Jain",
"ownerPhoneNo": "8655637631",
"appAddress": "FLAT NO 304 A WING 3RD FLOOR RAJUL APARTMENT CHS LTD
DEVCHAND NAGAR ROAD NEAR JAIN MANDIR BHAYNDER WEST THANE
401101",
"remark": "Urgent visit",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "03/01/2025",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Dimpalkumar Rameshchandra Jogatar",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mrs. Mamta Kamlesh Jain & Mr. Kanish Kamlesh Jain",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "735 / 2025"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "328082",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
document_1740030429413_1740030426434_Mamta_jan_agreement.pdf",
    "fileName":
"document_1740030429413_1740030426434_Mamta_jan_agreement.pdf"
  }
],
"caseNumber": "014464",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
```

```
{
  "id": "421086",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Feb 20 2025 05:47:45 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
  {
    "name": "Mrs. Mamta Kamlesh Jain & Mr. Kanish Kamlesh Jain",
    "phone": "8655637631",
    "ownershipShare": "",
    "email": "",
    "id": "170607"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Living Room",
    "length": "11.42",
    "length1": "11",
    "length2": "5",
    "width": "10.58",
    "width1": "10",
    "width2": "7",
    "totalArea": "120.83",
    "images": [],
    "finalArea": "120.83",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Kitchen",
    "length": "10.50",
    "length1": "10",
```

```
"length2": "6",
"width": "8.42",
"width1": "8",
"width2": "5",
"totalArea": "88.37",
"images": [],
"finalArea": "88.37",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "25.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "12.15",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.15"
},
{

```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "4",
"name": "Bathroom",
"length": "4.17",
"length1": "4",
"length2": "2",
"width": "3.92",
"width1": "3",
"width2": "11",
"totalArea": "16.32",
"images": [],
"extraAreas": [],
"finalArea": "16.32"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "77.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "77.19"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "37.63",
  "totalAreaDocument": "405",
  "docBuiltupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "390667"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "383.33",
      "squareMeterArea": "35.61",
      "expectedRate": "15652.31",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "460.00",
      "squareMeterArea": "42.74",
      "expectedRate": "13043.48",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "0.00",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "67bc081c9af7e67a8b91a97c",
    "property": "Devchand Nagar, Bhayander West",
    "area": "460",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "-",
    "source": "Nobroker.com",
    "expectedPrice": "6000000",
```

```
"expectedRate": "15652.31",
"builtUpExpectedRate": "6000000",
"image": "cases/67b6c201dc5b7cb7d2fc83e6/
indicator_1740375517633_Image.png",
"squareMeter": "42.74",
"id": "998743"
},
{
  "carpetArea": {
    "area": "590.00",
    "squareMeterArea": "54.81",
    "expectedRate": "14406.78",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "678.50",
    "squareMeterArea": "63.03",
    "expectedRate": "12527.63",
    "percentage": "15"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67bc081c9af7e67a8b91a97d",
  "property": "Devchand Nagar, Bhayander West",
  "area": "590",
  "builtUpPercentage": "15",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "-",
  "source": "Nobroker.com",
  "expectedPrice": "8500000",
  "expectedRate": "14406.78",
  "builtUpExpectedRate": "12527.63",
  "image": "cases/67b6c201dc5b7cb7d2fc83e6/
indicator_1740375728439_Image.png",
  "squareMeter": "54.81",
  "id": "300515"
},
{
  "carpetArea": {
```



```
"area": "270.00",
"squareMeterArea": "25.08",
"expectedRate": "15740.74",
"percentage": ""
},
"builtUpArea": {
"area": "324.00",
"squareMeterArea": "30.10",
"expectedRate": "13117.28",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67bc081c9af7e67a8b91a97e",
"property": "Devchand Nagar, Bhayander West",
"area": "270",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "-",
"source": "Index_no.2",
"expectedPrice": "4250000",
"expectedRate": "15740.74",
"builtUpExpectedRate": "13117.28",
"image": "cases/67b6c201dc5b7cb7d2fc83e6/
indicator_1740375839158_Image.png",
"squareMeter": "25.08",
"id": "553446"
},
{
"carpetArea": {
"area": "241.67",
"squareMeterArea": "22.45",
"expectedRate": "11172.26",
"percentage": ""
},
"builtUpArea": {
"area": "290.00",
"squareMeterArea": "26.94",
"expectedRate": "9310.34",
```

```
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67bc081c9af7e67a8b91a97f",
  "property": "Devchand Nagar, Bhayander West",
  "area": "290",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "4",
  "source": "Index_no.2",
  "expectedPrice": "2700000",
  "expectedRate": "11172.26",
  "builtUpExpectedRate": "2700000",
  "image": "cases/67b6c201dc5b7cb7d2fc83e6/
indicator_1740375893558_Image.png",
  "squareMeter": "26.94",
  "id": "185374"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80effc594f0b7b65801fb",
    "name":
"externallmg_1740115711504_WhatsApp_Image_20250220_at_230343_1.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711504_WhatsApp_Image_20250220_at_230343_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80effc594f0b7b65801fc",
    "name":
"externallmg_1740115711513_WhatsApp_Image_20250220_at_230343_2.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711513_WhatsApp_Image_20250220_at_230343_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80effc594f0b7b65801fd",
    "name":
"externallmg_1740115711521_WhatsApp_Image_20250220_at_230343.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711521_WhatsApp_Image_20250220_at_230343.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80effc594f0b7b65801fe",
    "name":
"externallmg_1740115711536_WhatsApp_Image_20250220_at_230344_1.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711536_WhatsApp_Image_20250220_at_230344_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80effc594f0b7b65801ff",
    "name":
"externallmg_1740115711552_WhatsApp_Image_20250220_at_230344_2.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711552_WhatsApp_Image_20250220_at_230344_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80effc594f0b7b6580200",
    "name":
"externallmg_1740115711553_WhatsApp_Image_20250220_at_230344.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711553_WhatsApp_Image_20250220_at_230344.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80effc594f0b7b6580201",
```

```
"name":
"externallmg_1740115711556_WhatsApp_Image_20250220_at_230345_1.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711556_WhatsApp_Image_20250220_at_230345_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80effc594f0b7b6580202",
  "name":
"externallmg_1740115711574_WhatsApp_Image_20250220_at_230345_2.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711574_WhatsApp_Image_20250220_at_230345_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80effc594f0b7b6580203",
  "name":
"externallmg_1740115711576_WhatsApp_Image_20250220_at_230345.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711576_WhatsApp_Image_20250220_at_230345.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80effc594f0b7b6580204",
  "name":
"externallmg_1740115711591_WhatsApp_Image_20250220_at_230346_1.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711591_WhatsApp_Image_20250220_at_230346_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80effc594f0b7b6580205",
  "name":
"externallmg_1740115711594_WhatsApp_Image_20250220_at_230346_2.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711594_WhatsApp_Image_20250220_at_230346_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80effc594f0b7b6580206",
  "name":
"externallmg_1740115711610_WhatsApp_Image_20250220_at_230346_3.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711610_WhatsApp_Image_20250220_at_230346_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80effc594f0b7b6580207",
  "name":
"externallmg_1740115711615_WhatsApp_Image_20250220_at_230346.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711615_WhatsApp_Image_20250220_at_230346.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80effc594f0b7b6580208",
  "name":
"externallmg_1740115711631_WhatsApp_Image_20250220_at_230347.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115711631_WhatsApp_Image_20250220_at_230347.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80f28c594f0b7b6580261",
  "name":
"externallmg_1740115752239_WhatsApp_Image_20250220_at_230343_1.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752239_WhatsApp_Image_20250220_at_230343_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b80f28c594f0b7b6580262",
  "name":
"externallmg_1740115752265_WhatsApp_Image_20250220_at_230343_2.jpeg",
```

```
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752265_WhatsApp_Image_20250220_at_230343_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b6580263",
    "name":
"externallmg_1740115752285_WhatsApp_Image_20250220_at_230343.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752285_WhatsApp_Image_20250220_at_230343.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b6580264",
    "name":
"externallmg_1740115752301_WhatsApp_Image_20250220_at_230344_1.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752301_WhatsApp_Image_20250220_at_230344_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b6580265",
    "name":
"externallmg_1740115752311_WhatsApp_Image_20250220_at_230344_2.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752311_WhatsApp_Image_20250220_at_230344_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b6580266",
    "name":
"externallmg_1740115752312_WhatsApp_Image_20250220_at_230344.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752312_WhatsApp_Image_20250220_at_230344.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67b80f28c594f0b7b6580267",
    "name":
"externallmg_1740115752315_WhatsApp_Image_20250220_at_230345_1.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752315_WhatsApp_Image_20250220_at_230345_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b6580268",
    "name":
"externallmg_1740115752331_WhatsApp_Image_20250220_at_230345_2.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752331_WhatsApp_Image_20250220_at_230345_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b6580269",
    "name":
"externallmg_1740115752334_WhatsApp_Image_20250220_at_230345.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752334_WhatsApp_Image_20250220_at_230345.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b658026a",
    "name":
"externallmg_1740115752372_WhatsApp_Image_20250220_at_230346_1.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752372_WhatsApp_Image_20250220_at_230346_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b658026b",
    "name":
"externallmg_1740115752374_WhatsApp_Image_20250220_at_230346_2.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752374_WhatsApp_Image_20250220_at_230346_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b658026c",
    "name":
"externallmg_1740115752391_WhatsApp_Image_20250220_at_230346_3.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752391_WhatsApp_Image_20250220_at_230346_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b658026d",
    "name":
"externallmg_1740115752403_WhatsApp_Image_20250220_at_230346.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752403_WhatsApp_Image_20250220_at_230346.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f28c594f0b7b658026e",
    "name":
"externallmg_1740115752406_WhatsApp_Image_20250220_at_230347.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115752406_WhatsApp_Image_20250220_at_230347.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b80f48dc5b7cb7d2fd3e8a",
    "name":
"externallmg_1740115784569_23680e9510854a4ba5c92e65977a25e4.jpeg",
    "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740115784569_23680e9510854a4ba5c92e65977a25e4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc1239178be87ad41d7cf8",
```



```
"name":
"externallmg_1740378680508_WhatsApp_Image_20250224_at_113840_AM_1.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740378680508_WhatsApp_Image_20250224_at_113840_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc1239178be87ad41d7cf9",
  "name":
"externallmg_1740378680537_WhatsApp_Image_20250224_at_113840_AM_2.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740378680537_WhatsApp_Image_20250224_at_113840_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc1239178be87ad41d7cfa",
  "name":
"externallmg_1740378680559_WhatsApp_Image_20250224_at_113840_AM.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740378680559_WhatsApp_Image_20250224_at_113840_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc1239178be87ad41d7cfb",
  "name":
"externallmg_1740378680588_WhatsApp_Image_20250224_at_113841_AM.jpeg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740378680588_WhatsApp_Image_20250224_at_113841_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc13799af7e67a8b91b828",
  "name": "externallmg_1740379001022_Picture1.jpg",
  "path": "cases/67b6c201dc5b7cb7d2fc83e6/
externallmg_1740379001022_Picture1.jpg",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67bc13cd16c8bb7a9102d67b",
"name": "externalImg_1740379084877_Picture2.jpg",
"path": "cases/67b6c201dc5b7cb7d2fc83e6/
externalImg_1740379084877_Picture2.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "1722838296456_1718776194681_1716026508753_17153236343
39_1711606660630_1700891975573_1695465043548_1694516251783_16942415908
59_Calculation_1_2.xlsx",
"filename": "1740376106391_1722838296456_1718776194681_1716026508753_1
715323634339_1711606660630_1700891975573_1695465043548_1694516251783_1
694241590859_Calculation_1_2.xlsx",
"path": "cases/67b6c201dc5b7cb7d2fc83e6/processingDocuments/1740376106391
_1722838296456_1718776194681_1716026508753_1715323634339_1711606660630
_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2
.xlsx",
"size": "1658661",
"createdAt": "Mon Feb 24 2025 05:48:26 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "igr_6638.pdf",
"filename": "1740376106535_igr_6638.pdf",
"path": "cases/67b6c201dc5b7cb7d2fc83e6/
processingDocuments/1740376106535_igr_6638.pdf",
"size": "150309",
"createdAt": "Mon Feb 24 2025 05:48:26 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "igr_8525.pdf",
"filename": "1740376106682_igr_8525.pdf",
"path": "cases/67b6c201dc5b7cb7d2fc83e6/
processingDocuments/1740376106682_igr_8525.pdf",
"size": "187655",
"createdAt": "Mon Feb 24 2025 05:48:26 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "igr_11846.pdf",
```

```
"filename": "1740376106687_igr_11846.pdf",
"path": "cases/67b6c201dc5b7cb7d2fc83e6/
processingDocuments/1740376106687_igr_11846.pdf",
"size": "155268",
"createdAt": "Mon Feb 24 2025 05:48:26 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-20T05:47:45.735Z",
"updatedAt": "2025-02-24T08:31:22.129Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 304, 3rd Floor, Wing - B, Rajul Apartment Co-Op.
Hsg. Soc. Ltd., Devchand Nagar Road, Near Jain Mandir, Village - Bhayander ,
Bhayander (West), Taluka - Thane, District - Thane, PIN - 401 101, State -
Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Hardik Jain",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant ",
"rerald": "",
"siteVisitContactNo": "9028613343",
"buildingServicesRate": "2300",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 405.00",
"flatRate": "12000",
"landOtherRate": "9700",
"shopDetails": {
  "typeOfShops": null,
```

```

    "roadFacing": false,
    "mall": false
  },
  "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC + Bathroom",
  "carpetTotal": "340.05",
  "otherCarpetTotal": "0.00",
  "builtupPercentage": "10",
  "finalBuiltupArea": "374.06",
  "finalCarpetArea": "340.05",
  "finalSalableArea": "411.46",
  "salablePercentage": "10",
  "toBeAdded": "",
  "extendOfSiteRemark": "",
  "siteMeasurementRemark": "",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    }
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Mon Feb 24 2025 05:50:43 GMT+0000 (Coordinated Universal Time)",
"siteVisitDate": "2025-02-20"
}

```

Name	Length	Width	Total
Composition :			
Living Room	11'5"	10'7"	120.83
Kitchen	10'6"	8'5"	88.37
Passage	7'9"	3'3"	25.19

WC	4'2"	2'11"	12.15
Bathroom	4'2"	3'11"	16.32
Bedroom	9'9"	7'11"	77.19
Other Composition :			