

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b800"
    },
    "firstName": "Krushna ",
    "type": "CREDITOFFICER",
    "_id": "65ba192e6635d840ef56c043",
    "lastName": "Dhanvij",
    "mobileNo": "",
    "workMobileNo": "8600786009",
    "email": "sbi.15521@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3159000",
    "discussWithPerson": "Krushna ",
    "expectedFees": 1579.5,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b800",
  "branchCode": "000073",
  "type": "BRANCH",
  "name": "SME Credit Centre Borivali (West)",
  "email": "sbi.15781@sbi.co.in",
  "mobileNo": "022-28954966",
  "alternateMobileNo": "",
  "address": "SME Centre Borivali (15521) 101, 1st floor,
Landmark Building, S. V. Road, Near Petrol Pump, Borivali (West), Mumbai – 400 092,
State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA-SMECCC BORIVALI",
  "fax": "022-28909092",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc575ece84bf289ba9e82d",
  "role": "SITEENGINEER",
  "firstName": "Deepak ",
  "email": "daksh7831@gmail.com",
  "lastName": "Jain ",
  "mobileNo": "9022815908",
  "designation": "",
  "shortName": "DJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": null,
"checker": {
  "_id": "64dc7184ccaf1e7b7f637f47",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg",
  "firstName": "Binumon",
  "lastName": "Moozhickal",
```

```
"shortName": "BS",
"email": "binu@vastukala.org",
"designation": "Back Office Team Leader",
"mobileNo": "9930252906",
"role": "FRONTDESK",
"type": "EMPLOYEE",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.191792646074404",
  "longitude": "72.84508658060928"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84508658060928,
    19.191792646074404
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "20/02/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
```

```
    "dateTime": "2025-03-01",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-02-27",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-03-01",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-03-02",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-03-01",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-03-01",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Malad South",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "12",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Trimurti Apartment Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mamlatdar Wadi, 6th Cross Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```



```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C, Trimurti Apartments",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```

```
"status": true,
"name": "CTS No.",
"key": "CTSNo",
"value": "160",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1217",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 064",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
```

```

    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement Plastering + POP Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Ami Dhara Apartment",
    "west": "Trimurti Apartment ",
    "south": "Internal Road ",
    "east": "Shree Vasudev Apartment "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {

```

```
"asPerActual": {
  "north": "Passage ",
  "east": "Marginal Space ",
  "south": "Marginal Space ",
  "west": "Flat No. 1215"
},
"asPerDocument": {
  "north": "Passage \n",
  "east": "Marginal Space \n",
  "south": "\nMarginal Space \n",
  "west": "Flat No. 1215"
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received, we assumed that
the construction is as per Sanction Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "36",
  "depreciationRatioOfBuilding": ""
```

```
"salvageValue": "10",
"buildingServicesDepreciatedRate": "1008",
"depreciatedCostOfConstruction": "22992.00",
"depreciatedBuildingRate": "1792"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "134160",
  "landRate": "58650",
  "igrImage": "cases/67b70167dc5b7cb7d2fcd840/igr_1741155567777_Image.png",
  "squareMeterGuideLineRate": "147576.00",
  "squareFeetGuideLineRate": "13710.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "76",
  "rate": "11728.00",
  "squareFeetGuideLineRate": "11728.00",
  "squareMeterGuideLineRate": "126234.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
```

```
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area ",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt / Open Car Parking Space ",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2001",
"fullDate": "1/1/2001"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
}
```

```
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
```



```
"label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "36",
"ageOfBuilding": "24",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "13",
"flatFloorNo": "12",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "480.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67b70167dc5b7cb7d2fcd840/
routeMap_1740998153710_Image.png",
    "routeLat": "19.186528",
    "routeLng": "72.844639",
    "stationName": "Malad",
    "routeDistance": "850 Mtrs.",
    "routeStation": {
      "value": "Railway_Station",
```

```
    "label": "Railway Station"
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "wvs749",
    "name": "wvs749",
    "image": "cases/67b70167dc5b7cb7d2fcd840/
routeMap_1740998072057_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11036160.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "11036160.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "datetime": "2025-03-05T08:06:40.085Z",
  "date": "Wed Mar 05 2025 08:06:40 GMT+0000 (Coordinated Universal Time)",
  "number": "2310863",
  "dayCount": "8",
  "monthCount": "60",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5629440.00",
  "selectedBuildUpValue": "480.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67c5249f80561479e1f4d6c6",
      "name": "externallmg_1740973214706_IMG20250302WA0017.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214706_IMG20250302WA0017.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67c524907018387a18176a67",
      "name": "externallmg_1740973200379_IMG20250302WA0012.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200379_IMG20250302WA0012.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67c524907018387a18176a69",
      "name": "externallmg_1740973200456_IMG20250302WA0014.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200456_IMG20250302WA0014.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "67c524907018387a18176a6b",
      "name": "externallmg_1740973200519_IMG20250302WA0024.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200519_IMG20250302WA0024.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67c524907018387a18176a6d",
      "name": "externallmg_1740973200598_IMG20250302WA0026.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200598_IMG20250302WA0026.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67c524907018387a18176a6e",
      "name": "externallmg_1740973200627_IMG20250302WA0028.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200627_IMG20250302WA0028.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67c5249f80561479e1f4d6bf",
      "name": "externallmg_1740973214221_IMG20250302WA0037.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214221_IMG20250302WA0037.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67c5249f80561479e1f4d6c6",
      "name": "externallmg_1740973214706_IMG20250302WA0017.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214706_IMG20250302WA0017.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67c5249f80561479e1f4d6cd",
      "name": "externallmg_1740973214904_IMG20250302WA0038.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214904_IMG20250302WA0038.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c586e3b68bc2f4276a3880",
    "name": "externallmg_1740998369943_Picture1.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740998369943_Picture1.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24195.00",
    "max": "30509.00"
  },
  "builtUpRateRange": {
    "min": "20162.00",
    "max": "25424.00"
  },
  "saleableRateRange": {
    "min": "16802.00",
    "max": "21187.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
  "presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "480.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b70167dc5b7cb7d2fcd840",
"ownerName": "Shri. Kiran Bhawanji Furia & Smt. Ramita Kiran Furia",
"ownerPhoneNo": "9867493542",
"appAddress": "Flat no 1217 C-wing 12 th floor Trimurti Apartment Shree Trimurti
Apartment Co-op HSG Soc Ltd Mamlatdar Wadi 6 th Cross road Malad West Mumbai
400064",
"remark": "Deepak Furia - 9821699776",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "11/06/2012",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Rajesh Shantilal Vora ",

```

```
"to": {
  "value": "Transferee",
  "label": "Transferee"
},
"Transferee": "Shri. Kiran Bhawanji Furia & Smt. Ramita Kiran Furia ",
"number": {
  "value": "No",
  "label": "No"
},
"No": "4926 / 2012"
},
"isHardCopy": false,
"displayStatus": true,
"id": "834577",
"path": "cases/67b70167dc5b7cb7d2fcd840/document_1740046546570_174004654
4044_Kiran_B_Furia_SBI_SME_borivali_west_12.pdf",
"fileName": "document_1740046546570_1740046544044_Kiran_B_Furia_SBI_SME
_borivali_west_12.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "27/11/2001",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / 4782 / BP(WS) / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "279852",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
document_1740977928988_324023.pdf",
```

```
"fileName": "document_1740977928988_324023.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "23/12/1991",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 4782 / BSII / AP"
},
"isHardCopy": false,
"displayStatus": false,
"id": "969749",
"path": "cases/67b70167dc5b7cb7d2fcd840/
document_1740978157450_327365.pdf",
"fileName": "document_1740978157450_327365.pdf"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
"No": "1 dated 10.04.2005 in the name of Shri. Kiran Bhawanji Furia & Smt.
Ramita Kiran Furia issued by Shree Trimurti Apartment Co-Op. Hsg. Soc. Ltd"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1740978277188_324023.pdf",
"path": "cases/67b70167dc5b7cb7d2fcd840/
document_1740978277188_324023.pdf",
"id": "713549",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Mar 03 2025 05:04:37 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014480",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
{
"id": "407264",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Thu Feb 20 2025 10:18:15 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Shri. Kiran Bhawanji Furia & Smt. Ramita Kiran Furia",
"phone": "9867493542",
"ownershipShare": "",
"email": "",
"id": "457398"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "168220",
"name": "Living Room",
"length": "16.33",
"length1": "16",
"length2": "4",
"width": "9.92",
```

```
"width1": "9",
"width2": "11",
"totalArea": "161.97",
"images": [],
"extraAreas": [],
"finalArea": "161.97"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "23.82",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.82"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "25.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "32.08",
  "length1": "32",
  "length2": "1",
  "width": "1.00",
  "width1": "1",
  "width2": "0",
  "totalArea": "32.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "6.25",
  "length1": "6",
  "length2": "3",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "22.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
```



```
"totalArea": "135.42",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "67c5822ab68bc2f4276a2cb4",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "8.42",
    "length1": "8",
    "length2": "5",
    "width": "1.67",
    "width1": "1",
    "width2": "8",
    "totalArea": "14.03"
  }
],
"finalArea": "149.45"
},
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "763031",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "480",
    "squareMeterArea": "44.59",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBultupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  },

```

```
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "44.59",
  "totalAreaDocument": "480",
  "docBUILTUPPercentage": "",
  "docFinalBUILTUP": "0.00",
  "docFinalBUILTUPSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "365853"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "632.00",
      "squareMeterArea": "58.71",
      "expectedRate": "27531.65",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "758.40",
      "squareMeterArea": "70.46",
      "expectedRate": "22943.04",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "910.08",
      "squareMeterArea": "84.55",
      "expectedRate": "19119.20",
      "percentage": "20"
    },
    "printlnReport": true,
    "_id": "67c7ed15a9f50d92cdf32bd2",
    "property": "Residential Flat",
    "area": "632",
  }
]
```

```
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "17400000",
"expectedRate": "27531.65",
"builtUpExpectedRate": "22943.04",
"image": "cases/67b70167dc5b7cb7d2fcd840/
indicator_1741155385872_Image.png",
"squareMeter": "58.71",
"id": "155082"
},
{
  "carpetArea": {
    "area": "583.00",
    "squareMeterArea": "54.16",
    "expectedRate": "30017.15",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "699.60",
    "squareMeterArea": "65.00",
    "expectedRate": "25014.29",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "839.52",
    "squareMeterArea": "77.99",
    "expectedRate": "20845.24",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67c7ed15a9f50d92cdf32bd3",
  "property": "Residential Flat",
  "area": "583",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "17500000",
  "expectedRate": "30017.15",
  "builtUpExpectedRate": "25014.29",
```

```
"image": "cases/67b70167dc5b7cb7d2fcd840/
indicator_1741155461558_Image.png",
"squareMeter": "54.16",
"id": "422376"
},
{
"carpetArea": {
"area": "295.00",
"squareMeterArea": "27.41",
"expectedRate": "30508.47",
"percentage": ""
},
"builtUpArea": {
"area": "354.00",
"squareMeterArea": "32.89",
"expectedRate": "25423.73",
"percentage": "20"
},
"saleableArea": {
"area": "424.80",
"squareMeterArea": "39.47",
"expectedRate": "21186.44",
"percentage": "20"
},
"printlnReport": true,
"_id": "67c7ed15a9f50d92cdf32bd4",
"property": "Residential Flat",
"area": "295",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "9000000",
"expectedRate": "30508.47",
"builtUpExpectedRate": "25423.73",
"image": "cases/67b70167dc5b7cb7d2fcd840/
indicator_1741155513859_Image.png",
"squareMeter": "27.41",
"id": "516436"
},
{
"carpetArea": {
"area": "679.00",
"squareMeterArea": "63.08",
```

```
    "expectedRate": "24194.26",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "814.80",
    "squareMeterArea": "75.70",
    "expectedRate": "20161.88",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "977.76",
    "squareMeterArea": "90.84",
    "expectedRate": "16801.57",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67c80924d63c0e928fbb7269",
  "property": "Residential Flat",
  "area": "679",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "16427900",
  "expectedRate": "24194.26",
  "builtUpExpectedRate": "20161.88",
  "image": "cases/67b70167dc5b7cb7d2fcd840/
indicator_1741162701037_Image.png",
  "squareMeter": "63.08",
  "id": "739588"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c524907018387a18176a67",
    "name": "externalImg_1740973200379_IMG20250302WA0012.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externalImg_1740973200379_IMG20250302WA0012.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67c524907018387a18176a68",
  "name": "externalimg_1740973200408_IMG20250302WA0013.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externalimg_1740973200408_IMG20250302WA0013.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c524907018387a18176a69",
  "name": "externalimg_1740973200456_IMG20250302WA0014.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externalimg_1740973200456_IMG20250302WA0014.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c524907018387a18176a6a",
  "name": "externalimg_1740973200478_IMG20250302WA0023.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externalimg_1740973200478_IMG20250302WA0023.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c524907018387a18176a6b",
  "name": "externalimg_1740973200519_IMG20250302WA0024.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externalimg_1740973200519_IMG20250302WA0024.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c524907018387a18176a6c",
  "name": "externalimg_1740973200564_IMG20250302WA0025.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externalimg_1740973200564_IMG20250302WA0025.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67c524907018387a18176a6d",
    "name": "externallmg_1740973200598_IMG20250302WA0026.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200598_IMG20250302WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c524907018387a18176a6e",
    "name": "externallmg_1740973200627_IMG20250302WA0028.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200627_IMG20250302WA0028.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c524907018387a18176a6f",
    "name": "externallmg_1740973200636_IMG20250302WA0030.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200636_IMG20250302WA0030.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c524907018387a18176a70",
    "name": "externallmg_1740973200693_IMG20250302WA0031.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973200693_IMG20250302WA0031.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6be",
    "name": "externallmg_1740973214197_IMG20250302WA0036.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214197_IMG20250302WA0036.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6bf",
```

```
    "name": "externallmg_1740973214221_IMG20250302WA0037.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214221_IMG20250302WA0037.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c0",
    "name": "externallmg_1740973214349_IMG20250302WA0008.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214349_IMG20250302WA0008.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c1",
    "name": "externallmg_1740973214539_IMG20250302WA0009.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214539_IMG20250302WA0009.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c2",
    "name": "externallmg_1740973214572_IMG20250302WA0010.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214572_IMG20250302WA0010.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c3",
    "name": "externallmg_1740973214595_IMG20250302WA0011.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214595_IMG20250302WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c4",
    "name": "externallmg_1740973214625_IMG20250302WA0015.jpg",
```



```
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214625_IMG20250302WA0015.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c5",
    "name": "externallmg_1740973214668_IMG20250302WA0016.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214668_IMG20250302WA0016.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c6",
    "name": "externallmg_1740973214706_IMG20250302WA0017.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214706_IMG20250302WA0017.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c7",
    "name": "externallmg_1740973214719_IMG20250302WA0019.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214719_IMG20250302WA0019.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c8",
    "name": "externallmg_1740973214772_IMG20250302WA0021.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214772_IMG20250302WA0021.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c5249f80561479e1f4d6c9",
    "name": "externallmg_1740973214776_IMG20250302WA0022.jpg",
    "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214776_IMG20250302WA0022.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c5249f80561479e1f4d6ca",
  "name": "externallmg_1740973214832_IMG20250302WA0033.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214832_IMG20250302WA0033.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c5249f80561479e1f4d6cb",
  "name": "externallmg_1740973214859_IMG20250302WA0034.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214859_IMG20250302WA0034.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c5249f80561479e1f4d6cc",
  "name": "externallmg_1740973214895_IMG20250302WA0035.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214895_IMG20250302WA0035.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c5249f80561479e1f4d6cd",
  "name": "externallmg_1740973214904_IMG20250302WA0038.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_1740973214904_IMG20250302WA0038.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c5249f80561479e1f4d6ce",
  "name": "externallmg_r_1740973214294_20250302_220434.jpg",
  "path": "cases/67b70167dc5b7cb7d2fcd840/
externallmg_r_1740973214294_20250302_220434.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67c5249f80561479e1f4d6cf",
      "name": "externalImg_r_1740973214225_20250302_220432.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externalImg_r_1740973214225_20250302_220432.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67c586e3b68bc2f4276a3880",
      "name": "externalImg_1740998369943_Picture1.jpg",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
externalImg_1740998369943_Picture1.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "Calculation (2) - kiran.xlsx",
      "filename": "1740976966326_Calculation_2__kiran.xlsx",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
processingDocuments/1740976966326_Calculation_2__kiran.xlsx",
      "size": "16025",
      "createdAt": "Mon Mar 03 2025 04:42:46 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "Summary - Kiran.xlsx",
      "filename": "1740976966327_Summary__Kiran.xlsx",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
processingDocuments/1740976966327_Summary__Kiran.xlsx",
      "size": "1527335",
      "createdAt": "Mon Mar 03 2025 04:42:46 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "1740976966327_Summary__Kiran.xlsx",
      "filename": "1741155602632_1740976966327_Summary__Kiran.xlsx",
      "path": "cases/67b70167dc5b7cb7d2fcd840/
processingDocuments/1741155602632_1740976966327_Summary__Kiran.xlsx",
      "size": "1659303",
```

```
"createdAt": "Wed Mar 05 2025 06:20:02 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67b83ce2083734618e5fd5a1",
  "note": "working done. visit pending",
  "taskId": "67b711a1c594f0b7b657b5be",
  "createdAt": "2025-02-21T08:44:18.515Z"
},
{
  "createdBy": {
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67c533323b4dfe0fe68fc997",
  "note": "1.10 cr. shred",
  "taskId": "67b711a1c594f0b7b657b5be",
  "createdAt": "2025-03-03T04:42:26.005Z"
}
],
"createdAt": "2025-02-20T10:18:15.907Z",
"updatedAt": "2025-03-05T08:19:48.938Z",
"__v": 0,
"assignmentType": {
```

```
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 1217, 12th Floor, Wing - C, Trimurti Apartments,
Shree Trimurti Apartment Co-Op. Hsg. Soc. Ltd., Mamlatdar Wadi, 6th Cross Road,
Village - Malad South, Malad (West), Taluka - Borivali, District - Mumbai Suburban ,
PIN - 400 064, State - Maharashtra, Country - India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Smt. Ramita Kiran Furia",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"rerald": "",
"siteVisitContactNo": "9867493542",
"builtupPercentage": "10",
"carpetTotal": "256.96",
"extendOfSiteRemark": "",
"finalBuiltupArea": "456.83",
"finalCarpetArea": "415.30",
"finalSalableArea": "502.51",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"finalMeasurementType": "Sq. Ft.",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 480.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
```

```

    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Mar 05 2025 00:00:00 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-03-01",
"buildingServicesRate": "2800",
"flatRate": "24000",
"landOtherRate": "21200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
}
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	16'4"	9'11"	161.97
Passage	8'2"	2'11"	23.82
Toilet	7'4"	3'5"	25.06
Kitchen	32'1"	1'0"	32.08
Toilet	6'3"	3'8"	22.92
Bedroom	13'00"	10'5"	135.42
Other Composition :			