

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "India Mart",
    "value": "india_mart"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "677908cfa5477d50e7dcfbaf"
    },
    "firstName": "Abhishek",
    "type": "CREDITOFFICER",
    "_id": "677908f182ea0d50e10160c8",
    "email": "cb7065@canarabank.com",
    "lastName": "Arora",
    "mobileNo": "",
    "workMobileNo": "7718873563"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Abhishek",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "676544371f06b62faf373ec8",
  "type": "BANK",
  "name": "Canara Bank",
  "displayName": "Canara Bank",
  "initial": "CNB"
},
"branch": {
  "_id": "677908cfa5477d50e7dcfbaf",
  "name": "Retail Asset Hub, Vasai",
  "branchCode": "7065",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "cb7065@canarabank.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "God's Gift Bunglow, Mary Villa Stuo, Stela, Manickpur, Vasai-401202"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "6765457131b0132fc5831fcc",
  "zoneName": "MUMBAI"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "659ccce98f39506e83489828",
    "role": "DELIVERYPERSON",
    "firstName": "Amit",
    "email": "amitsalvi2909@gmail.com",
```

```
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "67776d60a5477d50e7dbc213",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "AJAY",
"email": "ajayrewale503@gmail.com",
"lastName": "REWALE",
"mobileNo": "9766640171",
"designation": "",
"shortName": "AJAY",
"workWithDocumentMaker": "",
"profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
],
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
```

```
    }
  ]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.415639008475825",
  "longitude": "72.86248496662101"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86248496662101,
    19.415639008475825
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "20/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Waliv",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Janavi Plaza Building No 1",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```



```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"apfDetails": {
  "buildings": [],
```

```
"compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
```



```
    "status": true,
    "isEditable": false
  }
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b719e1e1b0fbb7b7efbe74",
"ownerName": "MRS NEELAM GANESH PATIL",
"ownerPhoneNo": "9822895917",
"appAddress": "FLAT NO 101 1ST FLOOR JANHVI PLAZA BLDG NO 1 VALIV VASAI
EAST PALGHAR ",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "label": "Agreement For Sale",
  "value": "60ae1254aa6d152c1801b326"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/67b719e1e1b0fbb7b7efbe74/
document_1740052887456_1740052838417_flat_Ganesh_Patil_papers.pdf",
"fileName":
"document_1740052887456_1740052838417_flat_Ganesh_Patil_papers.pdf",
"id": "437467",
"uploadedBy": "659ccce98f39506e83489828",
"createdAt": "Thu Feb 20 2025 12:02:41 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014481",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
{
  "id": "241019",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Feb 20 2025 12:02:41 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
  "name": "MRS NEELAM GANESH PATIL",
  "phone": "9822895917",
  "ownershipShare": "",
  "email": "",
  "id": "478487"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,

```

```
    "_id": "67b8c494b417399c9d8e095c",
    "name": "externallmg_1740162062224_1740162058882_image_0.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162062224_1740162058882_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e095d",
    "name": "externallmg_1740162069349_1740162058882_image_1.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162069349_1740162058882_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e095e",
    "name": "externallmg_1740162078438_1740162058882_image_2.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162078438_1740162058882_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e095f",
    "name": "externallmg_1740162079283_1740162058882_image_3.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162079283_1740162058882_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0960",
    "name": "externallmg_1740162080588_1740162058882_image_4.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162080588_1740162058882_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0961",
```

```
    "name": "externallmg_1740162086513_1740162058882_image_5.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162086513_1740162058882_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0962",
    "name": "externallmg_1740162090998_1740162058882_image_6.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162090998_1740162058882_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0963",
    "name": "externallmg_1740162097203_1740162058882_image_7.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162097203_1740162058882_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0964",
    "name": "externallmg_1740162105648_1740162058882_image_8.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162105648_1740162058882_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0965",
    "name": "externallmg_1740162114009_1740162058882_image_9.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162114009_1740162058882_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0966",
    "name": "externallmg_1740162124778_1740162058882_image_10.jpeg",
```

```
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162124778_1740162058882_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0967",
    "name": "externallmg_1740162126218_1740162058882_image_11.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162126218_1740162058882_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0968",
    "name": "externallmg_1740162133610_1740162058882_image_12.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162133610_1740162058882_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e0969",
    "name": "externallmg_1740162138409_1740162058882_image_13.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162138409_1740162058882_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e096a",
    "name": "externallmg_1740162147294_1740162058882_image_14.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162147294_1740162058882_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c494b417399c9d8e096b",
    "name": "externallmg_1740162163029_1740162058882_image_15.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162163029_1740162058882_image_15.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b8c494b417399c9d8e096c",
  "name": "externallmg_1740162175029_1740162058882_image_16.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162175029_1740162058882_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b8c494b417399c9d8e096d",
  "name": "externallmg_1740162184831_1740162058882_image_17.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162184831_1740162058882_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b8c494b417399c9d8e096e",
  "name": "externallmg_1740162190986_1740162058882_image_18.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162190986_1740162058882_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b8c4f19abe929c64fd18ef",
  "name": "externallmg_1740162145842_1740162099465_image_0.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162145842_1740162099465_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b8c4f19abe929c64fd18f0",
  "name": "externallmg_1740162158816_1740162099465_image_1.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162158816_1740162099465_image_1.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b8c4f19abe929c64fd18f1",
      "name": "externallmg_1740162169186_1740162099465_image_2.jpeg",
      "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162169186_1740162099465_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b8c4f19abe929c64fd18f2",
      "name": "externallmg_1740162180072_1740162099465_image_3.jpeg",
      "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162180072_1740162099465_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b8c4f19abe929c64fd18f3",
      "name": "externallmg_1740162190481_1740162099465_image_4.jpeg",
      "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162190481_1740162099465_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b8c4f19abe929c64fd18f4",
      "name": "externallmg_1740162196426_1740162099465_image_5.jpeg",
      "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162196426_1740162099465_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b8c4f19abe929c64fd18f5",
      "name": "externallmg_1740162200337_1740162099465_image_6.jpeg",
      "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162200337_1740162099465_image_6.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b8c4f19abe929c64fd18f6",
  "name": "externallmg_1740162204331_1740162099465_image_7.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162204331_1740162099465_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b8c4f19abe929c64fd18f7",
  "name": "externallmg_1740162206402_1740162099465_image_8.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162206402_1740162099465_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b8c4f19abe929c64fd18f8",
  "name": "externallmg_1740162208842_1740162099465_image_9.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162208842_1740162099465_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b8c4f19abe929c64fd18f9",
  "name": "externallmg_1740162211297_1740162099465_image_10.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162211297_1740162099465_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b8c4f19abe929c64fd18fa",
  "name": "externallmg_1740162215178_1740162099465_image_11.jpeg",
  "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162215178_1740162099465_image_11.jpeg",
  "orientation": "portrait"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b8c4f19abe929c64fd18fb",
    "name": "externallmg_1740162220530_1740162099465_image_12.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162220530_1740162099465_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b8c4f19abe929c64fd18fc",
    "name": "externallmg_1740162223923_1740162099465_image_13.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162223923_1740162099465_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b8c4f19abe929c64fd18fd",
    "name": "externallmg_1740162240477_1740162099465_image_14.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162240477_1740162099465_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b8c4f19abe929c64fd18fe",
    "name": "externallmg_1740162254407_1740162099465_image_15.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162254407_1740162099465_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b8c4f19abe929c64fd18ff",
    "name": "externallmg_1740162265732_1740162099465_image_16.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externallmg_1740162265732_1740162099465_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "67b8c4f19abe929c64fd1900",
    "name": "externalImg_1740162282934_1740162099465_image_17.jpeg",
    "path": "cases/67b719e1e1b0fbb7b7efbe74/
externalImg_1740162282934_1740162099465_image_17.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-20T12:02:41.873Z",
"updatedAt": "2025-02-21T18:24:49.370Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 101, 1st Floor, Building No 1, Janavi Plaza Building
No 1, Village - Waliv, Vasai East, State - Maharashtra, India",
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "MRS NEELAM GANESH PATIL",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9822895917"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			