

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6735c162ad18723b9c17d8ac"
    },
    "firstName": "Rajnish ",
    "type": "CREDITOFFICER",
    "_id": "6735c18877990f3be0114d81",
    "email": "bom110@mahabank.co.in",
    "lastName": "Jaiswal",
    "mobileNo": "",
    "workMobileNo": "9730000483"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6735c162ad18723b9c17d8ac",
  "name": "Naupada Branch",
  "branchCode": "",
  "mobileNo": "02225408783",
  "alternateMobileNo": "02225404673",
  "email": "brmgr110@mahabank.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Gr Floor, Raunak Tower, Gokhale Road, Naupda, Thane West 400602"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90ffff3dd69653a591ae9",
  "zoneName": "THANE ZONE"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "64abdb2806d6ec174986d16b",
```

```
"role": "PICKUPPERSON",
"firstName": "Sahadu",
"email": "thoratsahadu8679@gmail.com",
"lastName": "Thorat",
"mobileNo": "9422389642",
"shortName": "ST",
"workWithDocumentMaker": "",
"profilePhoto": "users/64abdb2806d6ec174986d16b/
profilePhoto_1731563513029_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "67776d60a5477d50e7dbc213",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "AJAY",
"email": "ajayrewale503@gmail.com",
"lastName": "REWALE",
"mobileNo": "9766640171",
"designation": "",
"shortName": "AJAY",
"workWithDocumentMaker": "",
"profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "FRONTDESK",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvanta",
"mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.268654412124782",
  "longitude": "72.87039944913006"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-22",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-21",
```

```
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "4BHK",
  "label": "4 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Penkarpada (Previously known as Mira) ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "30",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Srishti Sector 2A",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Srishti Complex",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "E",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "233 (Pt), 235 (Pt) & 256 (Pt)",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "66 (Part), 68 (Part) & 69 (Part)",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "E3006",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 401 107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```
"key": "suburb",
"value": "",
"label": false
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mira_Bhayander_Municipal_Corporation",
```

```
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Poonam Estate Cluster III",
  "west": "Srishti Road",
  "south": "Wing - D",
  "east": "MHADA Building"
},
"asPerDocumentAgreement": {
  "north": "Partly touching to Wing F and partly New S. No. 66(Pt) of village
Penkarpada \n",
  "west": "New S.No. 66(Pt) of village Penkarpada ",
  "south": "New S. No.66(Pt) of village Penkarpada\n",
  "east": "New S.No. 66(Pt) of village Penkarpada"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
```

```
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Plan / Brochure, The Composition of flat will be, Living Room + 4 Bedrooms + Study Room + Kitchen + 4 Toilets + Passage + Balcony (i.e., 4 BHK Flat).",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MBMNP / NR / 1561 / 2023 - 2024 Dated 14.08.2023 issued by Mira Bhayandar Municipal Corporation.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "At the time of visit, Builder has not allowed for site inspection and internal Photographs. The details about the work progress status has been provided by Sales Person Mr. Ritesh Bharange - Sale Person (Contact No. 8454922616).\n",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "94500",
  "landRate": "36400",
  "igrImage": "cases/67b80c77dc5b7cb7d2fd39fd/igr_1740222566072_Image.png",
  "squareMeterGuideLineRate": "108675.00",
  "squareFeetGuideLineRate": "10096.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "0",
  "rate": "94500.00",
  "squareMeterGuideLineRate": "108675.00",
  "squareFeetGuideLineRate": "10096.00"
},
"outgoingDetail": {
  "areaStatusList": {
```

```
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"monthlyRent": "N.A.",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MBMC norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "Proposed_RCC_SLab",
"label": "Proposed RCC SLab"
},
"partitions": {
"value": "Proposed_6\"_Thk._Brick_Masonry",
"label": "Proposed 6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
}
```

```
},
"carParking": "Proposed Along with Two Vehicle Parking Spaces ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2028",
  "fullDate": "1/1/2028"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
```

```
"label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
```



```
"noOfBasement": "2",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "36",
"flatFloorNo": "30",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "1746.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67b80c77dc5b7cb7d2fd39fd/
routeMap_1740226985198_Image.png",
    "routeLat": "19.272792",
    "routeLng": "72.869493",
    "stationName": "Mira Road",
    "routeDistance": "2.2 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "8xc89g",
    "name": "8xc89g",
    "image": "cases/67b80c77dc5b7cb7d2fd39fd/
routeMap_1740226894604_Image.png"
  }
]
```

```
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "2",
  "othersRate": "600000.00",
  "totalothersRate": "1200000",
  "finaltotal": "31372000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "95",
  "bookValue": "0",
  "finalValue": "30172000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "5",
    "percentage": "4.761904761904762",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "14.76",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "17635693.00",
  "selectedBuildUpValue": "1746.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67b94dba9abe929c64fd20f6",
      "name": "externalImg_1740197248222_1740197142020_image_17.jpeg",
      "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externalImg_1740197248222_1740197142020_image_17.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "67b94dba9abe929c64fd20f4",
    "name": "externallmg_1740197240998_1740197142020_image_15.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197240998_1740197142020_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b94dba9abe929c64fd20f7",
    "name": "externallmg_1740197255988_1740197142020_image_18.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197255988_1740197142020_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b94dba9abe929c64fd20f6",
    "name": "externallmg_1740197248222_1740197142020_image_17.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197248222_1740197142020_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b94dba9abe929c64fd20f0",
    "name": "externallmg_1740197223018_1740197142020_image_11.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197223018_1740197142020_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67b94dba9abe929c64fd20f5",
    "name": "externallmg_1740197246923_1740197142020_image_16.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197246923_1740197142020_image_16.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17038.00",
    "max": "20917.00"
  },
  "builtUpRateRange": {
    "min": "15493.00",
    "max": "19016.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "1588.00",
"empanelmentNo": [
  "AX33 /CREMON/Valuer/Empanelment/Sr No.55/2019-20"
],
"isAdvanceInvoice": false,
"status": true,
```

```
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b80c77dc5b7cb7d2fd39fd",
"ownerName": "Eversmile Properties Private Limited",
"ownerPhoneNo": "9321516398",
"fullAddress": "Residential Flat No. E3006, 30th Floor, Wing - E, Srishti Sector 2A,
Srishti Complex, Village - Penkarpada (Previously known as Mira) , Taluka - Thane,
District - Thane, Mira Road (East), PIN Code - 401 107, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "inputs": {
      "documentDate": "01/01/2025",
      "remark": "for the Year - 2025",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Eversmile Properties Private Limited",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Nitish Shivprakash Dube, Mr. Manish Shivprakash Dube & Mrs.
Kusum Shivprakash Dube"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "249862",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
document_1740114998192_Sector_2_Wing_E_ATS_3006.pdf",
    "fileName": "document_1740114998192_Sector_2_Wing_E_ATS_3006.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "16/10/2023",
```

```

"nameOfApprovingAuthority": {
  "value": "Maharashtra_Real_Estate_Regulatory_Authority",
  "label": "Maharashtra Real Estate Regulatory Authority"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "P51700053089"
},
"isHardCopy": false,
"displayStatus": true,
"id": "921726",
"path": "cases/67b80c77dc5b7cb7d2fd39fd/
document_1740115028968_Sector_2_Wing_E_RERA_certificate.pdf",
"fileName": "document_1740115028968_Sector_2_Wing_E_RERA_certificate.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "14/08/2023",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MNP / NR / 1561 / 2023 - 2024"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1740382301749_CC.pdf",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/document_1740382301749_CC.pdf",
  "id": "471829",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Mon Feb 24 2025 07:31:43 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  }
}

```

```
},
"inputs": {
  "documentDate": "14/08/2023",
  "nameOfApprovingAuthority": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MBMNP / NR / 1561 / 2023 - 2024"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1740382456076_Approved_Plan.pdf",
"path": "cases/67b80c77dc5b7cb7d2fd39fd/
document_1740382456076_Approved_Plan.pdf",
"id": "242831",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Feb 24 2025 07:34:18 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014489",
"createdBy": "64abdb2806d6ec174986d16b",
"caseHistory": [
  {
    "id": "108305",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Feb 21 2025 05:17:43 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Eversmile Properties Private Limited",
    "phone": "9321516398",
    "ownershipShare": "",
    "email": "",
    "id": "141795"
  }
],
```

```
"proposePurchasers": [
  {
    "name": "Mr. Nitish Shivprakash Dube, Mr. Manish Shivprakash Dube & Mrs. Kusum
Shivprakash Dube"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "147.53",
    "totalAreaDocument": "1588",
    "docBuiltpupPercentage": "10",
    "docFinalBUILTUp": "1746.80",
    "docFinalBUILTUpSquareMeter": "162.28",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "262331"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "851.00",
      "squareMeterArea": "79.06",
      "expectedRate": "20916.57",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "936.10",
      "squareMeterArea": "86.97",
      "expectedRate": "19015.06",
      "percentage": "10"
    }
  }
]
```

```
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67b9b10ced5955e83d033c8c",
"property": "Residential Flat",
"area": "851",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Dwello.com",
"expectedPrice": "17800000",
"expectedRate": "20916.57",
"builtUpExpectedRate": "19015.06",
"image": "cases/67b80c77dc5b7cb7d2fd39fd/
indicator_1740222197304_Image.png",
"squareMeter": "79.06",
"id": "309374"
},
{
  "carpetArea": {
    "area": "979.00",
    "squareMeterArea": "90.95",
    "expectedRate": "20326.86",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1076.90",
    "squareMeterArea": "100.05",
    "expectedRate": "18478.97",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67b9b10ced5955e83d033c8d",
```

```
"property": "Residential Flat",
"area": "979",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "19900000",
"expectedRate": "20326.86",
"builtUpExpectedRate": "18478.97",
"image": "cases/67b80c77dc5b7cb7d2fd39fd/
indicator_1740222234360_Image.png",
"squareMeter": "90.95",
"id": "338226"
},
{
"carpetArea": {
"area": "690.00",
"squareMeterArea": "64.10",
"expectedRate": "17256.52",
"percentage": ""
},
"builtUpArea": {
"area": "759.00",
"squareMeterArea": "70.51",
"expectedRate": "15687.75",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67b9b10ced5955e83d033c8e",
"property": "Residential Flat",
"area": "690",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "11907000",
```

```
    "expectedRate": "17256.52",
    "builtUpExpectedRate": "15687.75",
    "image": "cases/67b80c77dc5b7cb7d2fd39fd/
indicator_1740222293196_Image.png",
    "squareMeter": "64.10",
    "id": "486832"
  },
  {
    "carpetArea": {
      "area": "903",
      "squareMeterArea": "83.89",
      "expectedRate": "17037.10",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "993.00",
      "squareMeterArea": "92.25",
      "expectedRate": "15492.95",
      "percentage": ""
    },
    "saleableArea": {
      "area": "0.00",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "67b9b10ced5955e83d033c8f",
    "property": "Residential Flat",
    "area": "993",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "15384500",
    "expectedRate": "17037.10",
    "builtUpExpectedRate": "15384500",
    "image": "cases/67b80c77dc5b7cb7d2fd39fd/
indicator_1740222385690_Image.png",
    "squareMeter": "92.25",
    "id": "935228"
  }
],
"externallImages": [
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20e5",
  "name": "externallmg_1740197145610_1740197142020_image_0.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197145610_1740197142020_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20e6",
  "name": "externallmg_1740197157004_1740197142020_image_1.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197157004_1740197142020_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20e7",
  "name": "externallmg_1740197162903_1740197142020_image_2.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197162903_1740197142020_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20e8",
  "name": "externallmg_1740197171007_1740197142020_image_3.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197171007_1740197142020_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20e9",
  "name": "externallmg_1740197178057_1740197142020_image_4.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197178057_1740197142020_image_4.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20ea",
    "name": "externallmg_1740197185513_1740197142020_image_5.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197185513_1740197142020_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20eb",
    "name": "externallmg_1740197192757_1740197142020_image_6.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197192757_1740197142020_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20ec",
    "name": "externallmg_1740197196903_1740197142020_image_7.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197196903_1740197142020_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20ed",
    "name": "externallmg_1740197201638_1740197142020_image_8.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197201638_1740197142020_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20ee",
    "name": "externallmg_1740197207160_1740197142020_image_9.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197207160_1740197142020_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67b94dba9abe929c64fd20ef",
  "name": "externallmg_1740197215827_1740197142020_image_10.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197215827_1740197142020_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20f0",
  "name": "externallmg_1740197223018_1740197142020_image_11.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197223018_1740197142020_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20f1",
  "name": "externallmg_1740197224237_1740197142020_image_12.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197224237_1740197142020_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20f2",
  "name": "externallmg_1740197229463_1740197142020_image_13.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197229463_1740197142020_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b94dba9abe929c64fd20f3",
  "name": "externallmg_1740197234133_1740197142020_image_14.jpeg",
  "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197234133_1740197142020_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67b94dba9abe929c64fd20f4",
    "name": "externallmg_1740197240998_1740197142020_image_15.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197240998_1740197142020_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20f5",
    "name": "externallmg_1740197246923_1740197142020_image_16.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197246923_1740197142020_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20f6",
    "name": "externallmg_1740197248222_1740197142020_image_17.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197248222_1740197142020_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20f7",
    "name": "externallmg_1740197255988_1740197142020_image_18.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197255988_1740197142020_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b94dba9abe929c64fd20f8",
    "name": "externallmg_1740197264453_1740197142020_image_19.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externallmg_1740197264453_1740197142020_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c59325e2779c634451b5",
```

```
    "name": "externalImg_1740162429950_1740162426954_image_0.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externalImg_1740162429950_1740162426954_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c59325e2779c634451b6",
    "name": "externalImg_1740162435017_1740162426954_image_1.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externalImg_1740162435017_1740162426954_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c60cb417399c9d8e09cc",
    "name": "externalImg_1740162565581_1740162559819_image_0.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externalImg_1740162565581_1740162559819_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b8c861b417399c9d8e09ef",
    "name": "externalImg_1740163157083_1740163153564_image_0.jpeg",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/
externalImg_1740163157083_1740163153564_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1732014451297_Calculation_Sheet_NEW.xlsx",
    "filename": "1740222722129_1732014451297_Calculation_Sheet_NEW.xlsx",
    "path": "cases/67b80c77dc5b7cb7d2fd39fd/processingDocuments/1740222722129_
1732014451297_Calculation_Sheet_NEW.xlsx",
    "size": "3346602",
    "createdAt": "Sat Feb 22 2025 11:12:08 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67b9a8f50d78bae83e9432bc",
    "note": "Value given for confirmation",
    "taskId": "67b80eeddc5b7cb7d2fd3de5",
    "createdAt": "2025-02-22T10:37:41.280Z"
  }
],
"createdAt": "2025-02-21T05:17:43.752Z",
"updatedAt": "2025-02-24T09:24:13.798Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Ritesh Bharange",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Mr. Nitish Shivprakash Dube, Mr. Manish Shivprakash
Dube & Mrs. Kusum Shivprakash Dube",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"rerald": "",
"siteVisitContactNo": "8454922616",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1588.00",
"flatRate": "19000",
"landOtherRate": "16000",
```

```

"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 1517.00\nBalcony Area in Sq.
Ft.= 71.00\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
},
"reportGeneratedDate": "Mon Feb 24 2025 07:29:17 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-02-21"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
