

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "67052253ba5e64b24a31812b"
    },
    "firstName": "Asha",
    "type": "CREDITOFFICER",
    "_id": "67052274ba5e64b24a318144",
    "email": "asha.kharat@cosmosbank.in",
    "lastName": "Kharat",
    "mobileNo": "",
    "workMobileNo": "9820865935"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Asha",
    "expectedFees": null,
    "quotedAmount": "1"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "67052253ba5e64b24a31812b",
  "name": "APMC Vashi Branch",
  "branchCode": "",
  "mobileNo": "02227802765",
  "alternateMobileNo": "02227802766",
  "email": "asha.kharat@cosmosbank.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "C-1, Phase-II, APMC Masala Market, Sector -19, Vashi Navi Mumbai
400703"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
```

```
"role": "PICKUPPERSON",
"firstName": "Saurabh",
"email": "saurabhvelonde143@gmail.com",
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "65829f7c65d49d78457ec7be",
"role": "SITEENGINEER",
"firstName": "Vaibhav",
"email": "vaib1234b@gmail.com",
"lastName": "Bhagat",
"mobileNo": "8779534609",
"designation": "Bachlore Of Engireeing",
"shortName": "Vaibhav",
"workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.071625506806747",
  "longitude": "73.02069640417336"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.02069640417336,
    19.071625506806747
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "25/02/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2025-02-25T19:34:25.961Z",
    "remark": ""
  }
]
```

```
]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "22000",
  "lumpsumValue": "1",
  "rateMax": "23000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Turbhe",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi MUmbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "6",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "20",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A 2/441",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "Vitrified_Tile_Flooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
  "windows": {
    "label": "Powder Coated Aluminium Sliding",
    "value": "PowderCoatedAluminiumSliding"
  },
  "fittings": {
    "label": "Concealed Plumbing with Conduit & Concealed Electrical wiring",
    "value": "Concealed_Plumbing_with_Conduit_&_Concealed_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement plastering",
    "value": "Cement_plastering"
  }
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
```

```
"value": "CIDCO"
},
"asPerActualAgreement": {
  "north": "row house no 440",
  "west": "row house no 422",
  "south": "row house no 442",
  "east": "row house "
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
},
"apfDetails": {
```

```
"buildings": [],
"compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2014",
```

```
"fullDate": "1/1/2014"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "No",
  "value": "0"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "49",
"ageOfBuilding": "11",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "02",
```

```
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```



```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
```

```
"lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67bd4045e5abf3974ecd7d0e",
"ownerName": "Mr. Raju Chandrakant Gaikwad ",
"ownerPhoneNo": "9029449318",
"appAddress": "Apartment no. A-2/441, Sector - 20, Vashi, Navi Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "CIDCO Letter",
      "value": "60ae1279aa6d152c1801b3d3"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67bd4045e5abf3974ecd7d0e/
document_1740455999804_83977.pdf",
```

```
"fileName": "document_1740455999804_83977.pdf",
"id": "610797",
"uploadedBy": "60b7177d2ffdf65bcd65882a",
"createdAt": "Tue Feb 25 2025 04:00:05 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1256aa6d152c1801b330",
    "label": "Draft Agreement for sale"
  },
  "inputs": {
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Smt. Seeta Raju Gaikwad, Mr. Swapnil Raju Gaikwad & Mr. Sunil Raju Gaikwad ",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Rushtam Munavarali Raeen, Mr. Roshan Babu Munowar Ali Rain & Mrs. Rubi Bano Rain after married her name Mrs. Rubi Bano Roshan Babu Rain"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1740812246414_A2441SECTOR20PART_PAYMENT_AGR
EEMENT_1.pdf",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
document_1740812246414_A2441SECTOR20PART_PAYMENT_AGREEMENT_1.pdf",
  "id": "874805",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Sat Mar 01 2025 06:57:26 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014537",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "398716",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 25 2025 04:00:05 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
```

```
{
  "name": "Mr. Raju Chandrakant Gaikwad ",
  "phone": "9029449318",
  "ownershipShare": "",
  "email": "",
  "id": "689632"
},
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "67be1a05c91f41075bfd3105",
    "area": "833",
    "providedByName": "Mr. Raju Chandrakant Gaikwad ",
    "providedByContactNo": "9029449318"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "348830",
    "name": "Living Room",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030de",
    "name": "externalImg_1740511915598_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externalImg_1740511915598_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030df",
    "name": "externalImg_1740511918488_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externalImg_1740511918488_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e0",
    "name": "externalImg_1740511920913_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externalImg_1740511920913_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e1",
    "name": "externalImg_1740511923473_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externalImg_1740511923473_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e2",
    "name": "externalImg_1740511925078_image.jpeg",
```



```
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511925078_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e3",
    "name": "externallmg_1740511927378_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511927378_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e4",
    "name": "externallmg_1740511928418_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511928418_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e5",
    "name": "externallmg_1740511929948_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511929948_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e6",
    "name": "externallmg_1740511931703_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511931703_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1ad81571e307233030e7",
    "name": "externallmg_1740511933388_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511933388_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030e8",
  "name": "externallmg_1740511934688_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511934688_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030e9",
  "name": "externallmg_1740511936117_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511936117_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030ea",
  "name": "externallmg_1740511937293_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511937293_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030eb",
  "name": "externallmg_1740511938853_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511938853_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030ec",
  "name": "externallmg_1740511940033_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511940033_image.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030ed",
  "name": "externallmg_1740511942368_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511942368_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030ee",
  "name": "externallmg_1740511944063_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511944063_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030ef",
  "name": "externallmg_1740511945713_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740511945713_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030f0",
  "name": "externallmg_r_1740511909342_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_r_1740511909342_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1ad81571e307233030f1",
  "name": "externallmg_r_1740511899476_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_r_1740511899476_image.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1b2bdfd37d0724172bef",
  "name": "externallmg_1740512015901_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740512015901_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1b2bdfd37d0724172bf0",
  "name": "externallmg_1740512017764_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740512017764_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1b2bdfd37d0724172bf1",
  "name": "externallmg_1740512019009_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740512019009_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1b2bdfd37d0724172bf2",
  "name": "externallmg_1740512020513_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740512020513_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67be1b2bdfd37d0724172bf3",
  "name": "externallmg_1740512022153_image.jpeg",
  "path": "cases/67bd4045e5abf3974ecd7d0e/
externallmg_1740512022153_image.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1b2bdfd37d0724172bf4",
    "name": "externalImg_1740512022743_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externalImg_1740512022743_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1b2bdfd37d0724172bf5",
    "name": "externalImg_1740512024460_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externalImg_1740512024460_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67be1b2bdfd37d0724172bf6",
    "name": "externalImg_1740512026025_image.jpeg",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
externalImg_1740512026025_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr_26841.pdf",
    "filename": "1740658542087_igr_26841.pdf",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
processingDocuments/1740658542087_igr_26841.pdf",
    "size": "155676",
    "createdAt": "Thu Feb 27 2025 12:15:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "2025-02-27 11-05.pdf",
    "filename": "1740658542115_20250227_1105.pdf",
    "path": "cases/67bd4045e5abf3974ecd7d0e/
processingDocuments/1740658542115_20250227_1105.pdf",
    "size": "17880284",
    "createdAt": "Thu Feb 27 2025 12:15:50 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
]
```

```
    },
    {
      "originalname": "1732779816326_Rajesh_Pandurang_Junghare.doc",
      "filename": "1740658548039_1732779816326_Rajesh_Pandurang_Junghare.doc",
      "path": "cases/67bd4045e5abf3974ecd7d0e/processingDocuments/1740658548039_1732779816326_Rajesh_Pandurang_Junghare.doc",
      "size": "6599168",
      "createdAt": "Thu Feb 27 2025 12:15:50 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    },
    {
      "originalname": "igr_2161.pdf",
      "filename": "1740658549911_igr_2161.pdf",
      "path": "cases/67bd4045e5abf3974ecd7d0e/processingDocuments/1740658549911_igr_2161.pdf",
      "size": "149663",
      "createdAt": "Thu Feb 27 2025 12:15:50 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    },
    {
      "originalname": "igr_20699.pdf",
      "filename": "1740658550480_igr_20699.pdf",
      "path": "cases/67bd4045e5abf3974ecd7d0e/processingDocuments/1740658550480_igr_20699.pdf",
      "size": "195607",
      "createdAt": "Thu Feb 27 2025 12:15:50 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    },
    {
      "originalname": "1725358587906_1718776194681_1716026508753_1715323634339_1711606660630_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
      "filename": "1740744882459_1725358587906_1718776194681_1716026508753_1715323634339_1711606660630_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
      "path": "cases/67bd4045e5abf3974ecd7d0e/processingDocuments/1740744882459_1725358587906_1718776194681_1716026508753_1715323634339_1711606660630_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
      "size": "1880837",
      "createdAt": "Fri Feb 28 2025 12:14:42 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
```

```
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67bf05518b4dad9a754dcf2e",
    "note": "Documents pending\n",
    "taskId": "67bd5dde669512bd49664a01",
    "createdAt": "2025-02-26T12:13:05.001Z"
  }
],
"createdAt": "2025-02-25T04:00:05.376Z",
"updatedAt": "2025-03-01T06:57:26.711Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. A 2/441, Ground Floor, Plot No. 6, Sector 20,
Village - Turbhe, Navi MUmbai, State - Maharashtra, India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Raju Chandrakant Gaikwad ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9029449318",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2025-02-25"
```

} Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			