

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "67beeb908d8cf89a3f8f2177",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "SMT. Lilabai Thakurdas Sajnani",
"displayName": "SMT. Lilabai Thakurdas Sajnani",
"initial": "S"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "67776d60a5477d50e7dbc213",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "AJAY",
    "email": "ajayrewale503@gmail.com",
    "lastName": "REWALE",
    "mobileNo": "9766640171",
    "designation": "",
    "shortName": "AJAY",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
```

```
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  }
],
```

```
"type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.237985086010696",
  "longitude": "72.8515485604954"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
```

```
    "dateTime": "26/02/2025 12:00 am",
    "remark": ""
  }
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "New Prem Nagar CHSL",
  "label": false
},
}
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "S V P Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```

```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "15",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```



```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400092",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali West",
```

```
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  }
},
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
```



```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67beeb908d8cf89a3f8f217d",
"ownerName": "SMT. Lilabai Thakurdas Sajnani",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9820022622",
"contactPersonName": "Suresh Chablani",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "SMT. Lilabai Thakurdas Sajnani",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "619975"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact Person",
"fullAddress": "Residential Flat No. 15, 3rd Floor, Wing - D, New Prem Nagar CHSL, S
V P Road, Borivali West, Mumbai, 400092, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
    "fileName": "document_1740565365131_IMG_0001_2.pdf",
    "path": "cases/67beeb908d8cf89a3f8f217d/
document_1740565365131_IMG_0001_2.pdf",
    "id": "986382",
    "uploadedBy": "6006d4ce5080a310ac1fd2",
    "createdAt": "Wed Feb 26 2025 10:23:12 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1740565387423_531577.pdf",
    "path": "cases/67beeb908d8cf89a3f8f217d/
document_1740565387423_531577.pdf",
    "id": "371760",
    "uploadedBy": "6006d4ce5080a310ac1fd2",
    "createdAt": "Wed Feb 26 2025 10:23:12 GMT+0000 (Coordinated Universal Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"reralid": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "014568",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "791329",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Feb 26 2025 10:23:12 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67bfea626d1e76c645a0429d",
    "name": "externalImg_1740630436312_1740628308354_image_0.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740630436312_1740628308354_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67bfea626d1e76c645a0429e",
    "name": "externalImg_1740630447276_1740628308354_image_1.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740630447276_1740628308354_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67bfea626d1e76c645a0429f",
    "name": "externalImg_1740630467645_1740628308354_image_2.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740630467645_1740628308354_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67bfea626d1e76c645a042a0",
    "name": "externalImg_1740630484505_1740628308354_image_3.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740630484505_1740628308354_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67bfea626d1e76c645a042a1",
    "name": "externalImg_1740630493361_1740628308354_image_4.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740630493361_1740628308354_image_4.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042a2",
  "name": "externallmg_1740630504281_1740628308354_image_5.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630504281_1740628308354_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042a3",
  "name": "externallmg_1740630516870_1740628308354_image_6.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630516870_1740628308354_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042a4",
  "name": "externallmg_1740630529691_1740628308354_image_7.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630529691_1740628308354_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042a5",
  "name": "externallmg_1740630532521_1740628308354_image_8.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630532521_1740628308354_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042a6",
  "name": "externallmg_1740630535671_1740628308354_image_9.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630535671_1740628308354_image_9.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67bfea626d1e76c645a042a7",
      "name": "externallmg_1740630548380_1740628308354_image_10.jpeg",
      "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630548380_1740628308354_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67bfea626d1e76c645a042a8",
      "name": "externallmg_1740630551976_1740628308354_image_11.jpeg",
      "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630551976_1740628308354_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67bfea626d1e76c645a042a9",
      "name": "externallmg_1740630553617_1740628308354_image_12.jpeg",
      "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630553617_1740628308354_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67bfea626d1e76c645a042aa",
      "name": "externallmg_1740630562766_1740628308354_image_13.jpeg",
      "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630562766_1740628308354_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67bfea626d1e76c645a042ab",
      "name": "externallmg_1740630580832_1740628308354_image_14.jpeg",
      "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630580832_1740628308354_image_14.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042ac",
  "name": "externallmg_1740630588851_1740628308354_image_15.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630588851_1740628308354_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042ad",
  "name": "externallmg_1740630597737_1740628308354_image_16.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630597737_1740628308354_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042ae",
  "name": "externallmg_1740630607417_1740628308354_image_17.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630607417_1740628308354_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042af",
  "name": "externallmg_1740630612967_1740628308354_image_18.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630612967_1740628308354_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67bfea626d1e76c645a042b0",
  "name": "externallmg_1740630619062_1740628308354_image_19.jpeg",
  "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740630619062_1740628308354_image_19.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045f3",
    "name": "externallmg_1740631201826_1740628371652_image_0.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631201826_1740628371652_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045f4",
    "name": "externallmg_1740631210163_1740628371652_image_1.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631210163_1740628371652_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045f5",
    "name": "externallmg_1740631218439_1740628371652_image_2.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631218439_1740628371652_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045f6",
    "name": "externallmg_1740631226149_1740628371652_image_3.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631226149_1740628371652_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045f7",
    "name": "externallmg_1740631237474_1740628371652_image_4.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631237474_1740628371652_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67bfed086d1e76c645a045f8",
    "name": "externallmg_1740631242439_1740628371652_image_5.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631242439_1740628371652_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045f9",
    "name": "externallmg_1740631246984_1740628371652_image_6.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631246984_1740628371652_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045fa",
    "name": "externallmg_1740631248079_1740628371652_image_7.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631248079_1740628371652_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045fb",
    "name": "externallmg_1740631251184_1740628371652_image_8.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631251184_1740628371652_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045fc",
    "name": "externallmg_1740631254514_1740628371652_image_9.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631254514_1740628371652_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "67bfed086d1e76c645a045fd",
    "name": "externallmg_1740631262121_1740628371652_image_10.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631262121_1740628371652_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045fe",
    "name": "externallmg_1740631264838_1740628371652_image_11.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631264838_1740628371652_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a045ff",
    "name": "externallmg_1740631268718_1740628371652_image_12.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631268718_1740628371652_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a04600",
    "name": "externallmg_1740631275393_1740628371652_image_13.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631275393_1740628371652_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a04601",
    "name": "externallmg_1740631281539_1740628371652_image_14.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externallmg_1740631281539_1740628371652_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a04602",
```

```
    "name": "externalImg_1740631287544_1740628371652_image_15.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740631287544_1740628371652_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a04603",
    "name": "externalImg_1740631292384_1740628371652_image_16.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740631292384_1740628371652_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a04604",
    "name": "externalImg_1740631296824_1740628371652_image_17.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740631296824_1740628371652_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bfed086d1e76c645a04605",
    "name": "externalImg_1740631300625_1740628371652_image_18.jpeg",
    "path": "cases/67beeb908d8cf89a3f8f217d/
externalImg_1740631300625_1740628371652_image_18.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-26T10:23:12.804Z",
"updatedAt": "2025-02-27T04:41:44.546Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "67776d60a5477d50e7dbc213"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			