

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2950"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "647ed1960ab64c23c9fcf71d",
```

```
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
```

```
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordination",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.047316",
  "longitude": "73.804149"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "26/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-02-22",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "Mhasrul",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
}
```

```
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "13",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shivratan Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off Vani - Dindori Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Jangalidas Maharaj Garden, Vaiduwadi",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
```



```
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "241/ 1C+ 1A/ 1-1/ 3-13",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "08",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```

```
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 422 003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "sole_ownership",
  "label": "sole ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Nashik_Municipal_Corporation_",
  "label": "Nashik Municipal Corporation "
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Out of the layout of 74.00 Ft plot No. 14",
  "west": "30.00 Ft Colony Road out of 40.00 Ft Layout",
  "south": "Out of the layout of 70.00 Ft plot No. 14",
  "east": "48.00 Ft Survey No. Adjacent Layout of 241"
},
"asPerDocumentAgreement": {
  "north": "Out of the layout of 74.00 Ft plot No. 14",
  "west": "30.00 Ft Colony Road out of 40.00 Ft Layout",
  "south": "Out of the layout of 70.00 Ft plot No. 14",
  "east": "48.00 Ft Survey No. Adjacent Layout of 241"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Plot No. 12 in same Layout",
    "east": "Community Terrace",
    "south": "Flat No. 07",
    "west": "Open Space"
  },
  "asPerDocument": {
    "north": "Plot No. 12 in same Layout",
    "east": "Community Terrace",
    "south": "Flat No. 07",
    "west": "Open Space"
  },
  "isDisplay": true,
```

```

    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan No. 286/1454 Dated.03.06.1992 issued by Nashik Municipal Corporation, Nashik",
  "approvePlanVerified": "Yes",
  "empanelledOfApprovePlan": "Yes - As Per Approved Building Plan the Compostion is Hall + Kitchen + Bedroom + WC + Bath + Balcony + Passage. But as per Site inspection there is intenal changes done on site passage area is converted into bedroom so as per site inspection the compostion is Hall + Kitchen + 2 Bedroom + WC + Bath + Balcony i.e. (2BHK)",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "As Per Approved Building Plan the Composition is Hall + Kitchen + Bedroom + WC + Bath + Balcony + Passage. But as per Site inspection there is intenal changes done on site passage area is converted into bedroom so as per site inspection the composition is Hall + Kitchen + 2 Bedroom + WC + Bath + Balcony i.e. (2BHK)",
  "depreciationPercentage": "42",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "3260",
  "depreciatedBuildingRate": "1160"
},
"igrRate": {
  "propertyName": "Flat",

```

```
"rate": "35000",
"landRate": "13500",
"igrImage": "cases/67bef1458d8cf89a3f8f2e99/igr_1740567619201_Image.png",
"squareMeterGuideLineRate": "31500.00",
"squareFeetGuideLineRate": "2926.00"
},
"igrFinalRate": {
  "floorRatePercentage": "90",
  "depreciationPercentage": "72",
  "rate": "2458.00",
  "squareFeetGuideLineRate": "2458.00",
  "squareMeterGuideLineRate": "26460.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details Not Provided",
  "taxPaidHolderName": "Details Not Provided",
  "taxAmount": "Details Not Provided",
  "electricityServiceConnectionNo": "Details Not Provided",
  "meterCardHolderName": "Details Not Provided",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As Per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developing area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
```

```
"roof": {
  "value": "rcc_Slab",
  "label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1997",
  "fullDate": "1/1/1997"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
```



```
"value": "0",
"label": "No"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "32",
"ageOfBuilding": "28",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "2",
"noOfLifts": "-",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
"area": "721.00",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area as per Notarized Agreement for Sale"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/67bef1458d8cf89a3f8f2e99/
routeMap_1740568261812_Image.png",
"routeLat": "20.047278",
"routeLng": "73.804139",
"stationName": "Nashik Road",
"routeDistance": "15.0",
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
0
```

```
],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "54enze",
    "name": "54enze",
    "image": "cases/67bef1458d8cf89a3f8f2e99/
routeMap_1740568220850_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
```

```
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2350460.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "2350460.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "datetime": "2025-02-26T12:19:41.649Z",
  "date": "Wed Feb 26 2025 12:19:41 GMT+0000 (Coordinated Universal Time)",
  "number": "2310763",
  "dayCount": "15",
  "monthCount": "413",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "1772218.00",
  "selectedBuildUpValue": "721.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67bef3a68b4dad9a754db62e",
      "name":
"externallmg_1740567460015_WhatsApp_Image_20250222_at_31757_PM.jpeg",
      "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567460015_WhatsApp_Image_20250222_at_31757_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "67bef3a68b4dad9a754db636",
      "name":
"externallmg_1740567461985_WhatsApp_Image_20250222_at_31813_PM.jpeg",
      "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567461985_WhatsApp_Image_20250222_at_31813_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67bef3a68b4dad9a754db633",
      "name":
"externallmg_1740567461512_WhatsApp_Image_20250222_at_31808_PM.jpeg",
      "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567461512_WhatsApp_Image_20250222_at_31808_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67bef3a68b4dad9a754db631",
      "name":
"externallmg_1740567460897_WhatsApp_Image_20250222_at_31804_PM.jpeg",
```

```
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567460897_WhatsApp_Image_20250222_at_31804_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67bef3a68b4dad9a754db634",
    "name":
"externallmg_1740567461713_WhatsApp_Image_20250222_at_31810_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567461713_WhatsApp_Image_20250222_at_31810_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67bef3a68b4dad9a754db632",
    "name":
"externallmg_1740567461128_WhatsApp_Image_20250222_at_31806_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567461128_WhatsApp_Image_20250222_at_31806_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67bef3a68b4dad9a754db62e",
    "name":
"externallmg_1740567460015_WhatsApp_Image_20250222_at_31757_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567460015_WhatsApp_Image_20250222_at_31757_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67bef3a68b4dad9a754db62c",
    "name":
"externallmg_1740567459142_WhatsApp_Image_20250222_at_31751_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567459142_WhatsApp_Image_20250222_at_31751_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67bef3a68b4dad9a754db62f",
    "name":
"externallmg_1740567460499_WhatsApp_Image_20250222_at_31800_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567460499_WhatsApp_Image_20250222_at_31800_PM.jpeg",
```

```
    "orientation": "landscape"
  }
],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "3667.00",
    "max": "5470.00"
  },
  "builtUpRateRange": {
    "min": "3056.00",
    "max": "4559.00"
  },
  "saleableRateRange": {
    "min": "2547.00",
    "max": "3799.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```



```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
  "label": "Lead",
  "value": "LEAD"
},
siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
```

```
"finalValuationArea": "721.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67bef1458d8cf89a3f8f2e99",
"ownerName": "Shri. Vidya Prakash Suryawanshi",
"ownerPhoneNo": "9923158288",
"fullAddress": "Residential Flat No. 08, 2nd Floor, Shivratn Apartment, Jangalidas
Maharaj Garden, Vaiduwadi, Plot No. 13, Off Vani - Dindori Road, Village - Mhasrul,
Taluka - Nashik, District - Nashik, Nashik, PIN Code - 422 003, State - Maharashtra,
Country - India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "inputs": {
      "documentDate": "21/02/2025",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Shri. Vidya Prakash Suryawanshi",
      "to": {
        "value": "buyer",
        "label": "buyer"
      },
      "buyer": "Shri. Vivek Manohar Bhavsar"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "417538",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
document_1740566570074_Vivek_bhavsar_sathekhat_kararnama.pdf",
    "fileName": "document_1740566570074_Vivek_bhavsar_sathekhat_kararnama.pdf"
  },
  {
    "documentType": {
```

```
"value": "60ae1247aa6d152c1801b2ea",
"label": "Commencement Certificate"
},
"inputs": {
  "documentDate": "13/12/1996",
  "nameOfApprovingAuthority": {
    "value": "Nashik_Municipal_Corporation",
    "label": "Nashik Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "LND/ BP/ 952/ 3675"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1740566677886_sanction_of_building_permit.pdf",
"path": "cases/67bef1458d8cf89a3f8f2e99/
document_1740566677886_sanction_of_building_permit.pdf",
"id": "545444",
"uploadedBy": "647ed1960ab64c23c9fcf71d",
"createdAt": "Wed Feb 26 2025 10:47:33 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "03/06/1992",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "286/ 1454"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1740566757609_plan2.pdf",
  "path": "cases/67bef1458d8cf89a3f8f2e99/document_1740566757609_plan2.pdf",
  "id": "364975",
```

```
"uploadedBy": "647ed1960ab64c23c9fcf71d",
"createdAt": "Wed Feb 26 2025 10:47:33 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "29/01/1999",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "Javak No/ NNRV/ 000932"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1740566833202_janral_mukhyataar_patra.pdf",
"path": "cases/67bef1458d8cf89a3f8f2e99/
document_1740566833202_janral_mukhyataar_patra.pdf",
"id": "799986",
"uploadedBy": "647ed1960ab64c23c9fcf71d",
"createdAt": "Wed Feb 26 2025 10:47:33 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014570",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "302223",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Feb 26 2025 10:47:33 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
```

```
"name": "Shri. Vidya Prakash Suryawanshi",
"phone": "9923158288",
"ownershipShare": "",
"email": "",
"id": "514572"
}
],
"proposePurchasers": [
  {
    "name": "Shri. Vivek Manohar Bhavsar"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "565624",
    "name": "Living Room",
    "length": "12.25",
    "length1": "12",
    "length2": "3",
    "width": "9.67",
    "width1": "9",
    "width2": "8",
    "totalArea": "118.42",
    "images": [],
    "extraAreas": [],
    "finalArea": "118.42"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "7",
    "name": "Kitchen",
    "length": "7.42",
    "length1": "7",
    "length2": "5",
    "width": "11.33",
    "width1": "11",
    "width2": "4",
    "totalArea": "84.06",
```

```
"images": [],
"finalArea": "84.06",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "13.17",
  "length1": "13",
  "length2": "2",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "119.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.60"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "11.17",
  "length1": "11",
  "length2": "2",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "107.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "107.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
```

```
"name": "WC",
"length": "7.33",
"length1": "7",
"length2": "4",
"width": "5.33",
"width1": "5",
"width2": "4",
"totalArea": "39.11",
"images": [],
"extraAreas": [],
"finalArea": "39.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "39.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "6.33",
  "length1": "6",
  "length2": "4",
  "width": "9.33",
  "width1": "9",
  "width2": "4",
  "totalArea": "59.11",
  "images": [],
  "finalArea": "59.11",
```



```
"extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae12adaa6d152c1801b4bf",
    "label": "Notarized Agreement for Sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "66.98",
  "totalAreaDocument": "721",
  "docBultupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "284145"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "886.67",
    "squareMeterArea": "82.37",
    "expectedRate": "3947.35",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1064.00",
    "squareMeterArea": "98.85",
    "expectedRate": "3289.47",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1276.80",
    "squareMeterArea": "118.62",
    "expectedRate": "2741.23",
```

```
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67bef6158b4dad9a754db8b4",
  "property": "Flat",
  "area": "1064",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "3500000",
  "expectedRate": "3947.35",
  "builtUpExpectedRate": "3500000",
  "image": "cases/67bef1458d8cf89a3f8f2e99/indicator_1740567748245_Image.png",
  "squareMeter": "98.85",
  "id": "647578"
},
{
  "carpetArea": {
    "area": "600.00",
    "squareMeterArea": "55.74",
    "expectedRate": "3666.67",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "720.00",
    "squareMeterArea": "66.89",
    "expectedRate": "3055.56",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "864.00",
    "squareMeterArea": "80.27",
    "expectedRate": "2546.30",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67bef6158b4dad9a754db8b5",
  "property": "Flat",
  "area": "720",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
```

```
"floor": "",
"source": "Housing.Com",
"expectedPrice": "2200000",
"expectedRate": "3666.67",
"builtUpExpectedRate": "2200000",
"image": "cases/67bef1458d8cf89a3f8f2e99/indicator_1740567955977_Image.png",
"squareMeter": "66.89",
"id": "813523"
},
{
  "carpetArea": {
    "area": "1000.00",
    "squareMeterArea": "92.90",
    "expectedRate": "5470.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1200.00",
    "squareMeterArea": "111.48",
    "expectedRate": "4558.33",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1440.00",
    "squareMeterArea": "133.78",
    "expectedRate": "3798.61",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67bef6158b4dad9a754db8b6",
  "property": "Flat",
  "area": "1440",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Saleable",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "5470000",
  "expectedRate": "3798.6111111111113",
  "builtUpExpectedRate": "4558.33",
  "image": "cases/67bef1458d8cf89a3f8f2e99/indicator_1740568026168_Image.png",
  "squareMeter": "133.78",
  "id": "244332"
}
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db62c",
    "name":
"externalImg_1740567459142_WhatsApp_Image_20250222_at_31751_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externalImg_1740567459142_WhatsApp_Image_20250222_at_31751_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db62d",
    "name":
"externalImg_1740567459506_WhatsApp_Image_20250222_at_31756_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externalImg_1740567459506_WhatsApp_Image_20250222_at_31756_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db62e",
    "name":
"externalImg_1740567460015_WhatsApp_Image_20250222_at_31757_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externalImg_1740567460015_WhatsApp_Image_20250222_at_31757_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db62f",
    "name":
"externalImg_1740567460499_WhatsApp_Image_20250222_at_31800_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externalImg_1740567460499_WhatsApp_Image_20250222_at_31800_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db630",
    "name":
"externalImg_1740567460686_WhatsApp_Image_20250222_at_31802_PM.jpeg",
```

```
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567460686_WhatsApp_Image_20250222_at_31802_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db631",
    "name":
"externallmg_1740567460897_WhatsApp_Image_20250222_at_31804_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567460897_WhatsApp_Image_20250222_at_31804_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db632",
    "name":
"externallmg_1740567461128_WhatsApp_Image_20250222_at_31806_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567461128_WhatsApp_Image_20250222_at_31806_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db633",
    "name":
"externallmg_1740567461512_WhatsApp_Image_20250222_at_31808_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567461512_WhatsApp_Image_20250222_at_31808_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bef3a68b4dad9a754db634",
    "name":
"externallmg_1740567461713_WhatsApp_Image_20250222_at_31810_PM.jpeg",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
externallmg_1740567461713_WhatsApp_Image_20250222_at_31810_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67bef3a68b4dad9a754db635",
  "name":
"externalImg_1740567461869_WhatsApp_Image_20250222_at_31811_PM.jpeg",
  "path": "cases/67bef1458d8cf89a3f8f2e99/
externalImg_1740567461869_WhatsApp_Image_20250222_at_31811_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bef3a68b4dad9a754db636",
  "name":
"externalImg_1740567461985_WhatsApp_Image_20250222_at_31813_PM.jpeg",
  "path": "cases/67bef1458d8cf89a3f8f2e99/
externalImg_1740567461985_WhatsApp_Image_20250222_at_31813_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "VivekCAI.xlsx",
    "filename": "1740568082287_VivekCAI.xlsx",
    "path": "cases/67bef1458d8cf89a3f8f2e99/
processingDocuments/1740568082287_VivekCAI.xlsx",
    "size": "36918",
    "createdAt": "Wed Feb 26 2025 11:08:02 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  },
  {
    "originalname": "BOB - Shri. Vidya Prakash Suryawanshi (1).pdf",
    "filename": "1740569920437_BOB__Shri_Vidya_Prakash_Suryawanshi_1.pdf",
    "path": "cases/67bef1458d8cf89a3f8f2e99/processingDocuments/1740569920437_
BOB__Shri_Vidya_Prakash_Suryawanshi_1.pdf",
    "size": "5075117",
    "createdAt": "Wed Feb 26 2025 11:38:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-26T10:47:33.737Z",
"updatedAt": "2025-02-26T12:28:50.831Z",
"__v": 0,
```

```
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Vivek Manohar Bhavsar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Shri. Vivek Manohar Bhavsar",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Proposed Purchaser",
"rerald": "",
"siteVisitContactNo": "9923158288",
"buildingServicesRate": "2000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Notarized Agreement for Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 721.00",
"flatRate": "4100",
"landOtherRate": "2100",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
```

```

},
"reportGeneratedDate": "Wed Feb 26 2025 11:08:28 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-02-22",
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + WC + Bathroom +
Balcony",
"carpetTotal": "567.35",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "624.09",
"finalCarpetArea": "567.35",
"finalSalableArea": "686.49",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": ""
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	12'3"	9'8"	118.42
Kitchen	7'5"	11'4"	84.06
Bedroom	13'2"	9'1"	119.60
Bedroom	11'2"	9'8"	107.94
WC	7'4"	5'4"	39.11
Bathroom	7'4"	5'4"	39.11
Balcony	6'4"	9'4"	59.11
Other Composition :			