

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "657172fa4999312746ce4fd7"
    },
    "firstName": "Brajesh ",
    "type": "CREDITOFFICER",
    "_id": "657172fa4999312746ce4fd9",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "8411003755",
    "email": "nasikc@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "657172fa4999312746ce4fd7",
  "name": "Nashik City Branch",
  "branchCode": "",
  "mobileNo": "91 2532501570",
  "alternateMobileNo": "",
  "email": "nasikc@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "City Nasik Branch,gauri Shankar Tilak Road, M.G. Road Nasik
City,nasik,422001"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62724142afd7d55eddede405",
"role": "FRONTDESK",
"firstName": "Sanjay",
"email": "sanjayrphadol@gmail.com",
"lastName": "Phadol",
"mobileNo": "9890380564",
"designation": "",
"shortName": "SP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62724142afd7d55eddede405/
profilePhoto_1689235732454_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
```

```
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
  "_id": "64dc7184ccaf1e7b7f637f47",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg",
  "firstName": "Binumon",
  "lastName": "Moozhickal",
  "shortName": "BS",
  "email": "binu@vastukala.org",
  "designation": "Back Office Team Leader",
  "mobileNo": "9930252906",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.021667",
  "longitude": "73.830796"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "6/11/2024 12:00 am"
    },
    {
      "dateTime": "6/11/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-06",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-06",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-05",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Nashik",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pavan Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off Meri - Rasbihari Link Road",
  "label": false
}
```



```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Bali Mandir, Near Rasbihari International School, Vrindavan Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "243/ 2/ 2",
  "label": true
},
"hisssaNo": {
  "status": false,
  "name": "Hissa No.",
```

```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "01",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 422 003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
```

```

    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Nashik_Municipal_Corporation_",
    "label": "Nashik Municipal Corporation "
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Road & Survey No. 243/ 2 Part",
    "west": "Adj. Plot No. 47",
    "south": "Adj. Survey No. 251",
    "east": "30.00 Mtr. D.P Road"
  },
  "asPerDocumentAgreement": {
    "north": "Road & Survey No. 243/ 2 Part",

```

```
"west": "Adj. Plot No. 47",
"south": "Adj. Survey No. 251",
"east": "30.00 Mtr. D.P Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space & Road",
    "east": "Marginal Space & Road",
    "south": "Flat No. 02",
    "west": "Lobby & Staircase"
  },
  "asPerDocument": {
    "north": "Details Not Provided in Document",
    "east": "Details Not Provided in Document",
    "south": "Details Not Provided in Document",
    "west": "Details Not Provided in Document"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Accompanying
Commencement Certificate No. C1/ 713/ 145 dated.04.04.2018 issued by Executive
Engineer Town Planning Nashik Municipal Corporation, Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "NA",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
```

```
"documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "6300.00",
  "depreciatedBuildingRate": "2000"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "38300",
  "landRate": "15450",
  "igrImage": "cases/672b42eed6092bb575128a93/igr_1730888939765_Image.png",
  "squareMeterGuideLineRate": "38300.00",
  "squareFeetGuideLineRate": "3558.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "95",
  "rate": "3452.00",
  "squareFeetGuideLineRate": "3452.00",
  "squareMeterGuideLineRate": "37158.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "8000",
  "assessmentNo": "Details Not Provided",
  "taxPaidHolderName": "Details Not Provided",
```

```
"taxAmount": "Details Not Provided",
"electricityServiceConnectionNo": "Details Not Provided",
"meterCardHolderName": "Details Not Provided",
"undividedAreaOfLandAsPerSaleDeed": "NA",
"floorSpaceIndex": "As Per NMC Norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developing area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2020",
```

```
"fullDate": "1/1/2020"
},
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```



```
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "4",
"totalLifeBuilding": "60",
"estimatedAge": "56",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "692.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
```

```
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/672b42eed6092bb575128a93/
routeMap_1730889161959_Image.png",
    "routeLat": "20.021667",
    "routeLng": "73.830796",
    "stationName": "Nashik Road",
    "routeDistance": "9.5",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "f38cd",
      "name": "f38cd",
      "image": "cases/672b42eed6092bb575128a93/
routeMap_1730889118096_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```

```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3635100.00",
"finalValue": "3635100.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "95",
"bookValueDocument": null,
"purchaseValueDocument": {
  "documentType": {
    "value": "60ae12adaa6d152c1801b4bf",
    "label": "Notarized Agreement for Sale"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1730888368592_Notary.pdf",
  "path": "cases/672b42eed6092bb575128a93/
document_1730888368592_Notary.pdf",
  "id": "419357",
  "uploadedBy": "647ed1960ab64c23c9cf71d",
  "createdAt": "Wed Nov 06 2024 10:20:29 GMT+0000 (Coordinated Universal Time)",
  "documentDate": "30/10/2024",
  "amount": "3100000",
  "from": {
    "value": "Owner",
    "label": "Owner"
  },
  "Owner": "Shri. Suresh Ramchandra Odhekar",
```

```
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "Shri. Shrikrushna Raghunath Gaikwad"
},
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Nov 06 2024 11:59:06 GMT+0000 (Coordinated Universal Time)",
  "number": "2308941",
  "dayCount": "11",
  "monthCount": "26",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2390165.00",
  "selectedBuildUpValue": "692.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "672b441dd6092bb575128edb",
      "name":
"externallmg_1730888723617_WhatsApp_Image_20241106_at_121126_PM_1.jpeg",
      "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888723617_WhatsApp_Image_20241106_at_121126_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "672b441dd6092bb575128ed3",
      "name": "Living Room",
      "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888714575_WhatsApp_Image_20241106_at_121033_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "672b441dd6092bb575128ed6",
      "name": "Living Room",
      "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888719470_WhatsApp_Image_20241106_at_121103_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "672b441dd6092bb575128ed9",
      "name": "Living Room",
      "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888722973_WhatsApp_Image_20241106_at_121125_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b441dd6092bb575128ed7",
    "name": "Living Room",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888720480_WhatsApp_Image_20241106_at_121124_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b441dd6092bb575128eda",
    "name": "Living Room",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888723239_WhatsApp_Image_20241106_at_121125_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b441dd6092bb575128ed8",
    "name": "Living Room",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888721771_WhatsApp_Image_20241106_at_121124_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b441dd6092bb575128ecf",
    "name": "Living Room",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888707107_WhatsApp_Image_20241105_at_45033_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b4afe0fd723b55b7c716c",
    "name": "Living Room",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730890489711_WhatsApp_Image_20241106_at_41243_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b441dd6092bb575128edf",
    "name": "Living Room",
```



```
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888727650_WhatsApp_Image_20241106_at_121232_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b441dd6092bb575128edb",
    "name": "Living Room",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888723617_WhatsApp_Image_20241106_at_121126_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672b4afe0fd723b55b7c716b",
    "name": "Living Room",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730890488251_WhatsApp_Image_20241106_at_41137_PM.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5858.00",
    "max": "6591.00"
  },
  "builtUpRateRange": {
    "min": "4881.00",
    "max": "5493.00"
  },
  "saleableRateRange": {
    "min": "4068.00",
    "max": "4577.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "577.00",
"empanelmentNo": [
  "ZO :MZ:ADV:46:941\t"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "672b42eed6092bb575128a93",
"ownerName": "Shri. Suresh Ramchandra Odhekar",
"ownerPhoneNo": "9420990854",
"fullAddress": "Residential Flat No. 01, 1st Floor, Pavan Apartment, Behind Bali
Mandir, Near Rasbihari International School, Vrindavan Nagar, Off Meri - Rasbihari
Link Road, Taluka - Nashik, District - Nashik, Nashik, PIN Code - 422 003, State -
Maharashtra, Country - India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "inputs": {
      "documentDate": "30/10/2024",
      "amount": "3100000",
      "from": {
        "value": "Owner",
        "label": "Owner"
      },
      "Owner": "Shri. Suresh Ramchandra Odhekar",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      }
    }
  }
],
```

```
    "purchaser": "Shri. Shrikrushna Raghunath Gaikwad"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1730888368592_Notary.pdf",
  "path": "cases/672b42eed6092bb575128a93/
document_1730888368592_Notary.pdf",
  "id": "419357",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Nov 06 2024 10:20:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "10/12/2020",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "Javak No. NRV/ C1/ 27326"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1730888427480_125468.pdf",
  "path": "cases/672b42eed6092bb575128a93/
document_1730888427480_125468.pdf",
  "id": "482762",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Wed Nov 06 2024 10:20:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "04/04/2018",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
```

```
    "label": "Nashik Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "C1/ 713/ 145"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1730893325442_410651.pdf",
"path": "cases/672b42eed6092bb575128a93/
document_1730893325442_410651.pdf",
"id": "707957",
"uploadedBy": "647ed1960ab64c23c9fcf71d",
"createdAt": "Wed Nov 06 2024 11:42:05 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "012201",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "544957",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 06 2024 10:20:30 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri. Suresh Ramchandra Odhekar",
    "phone": "9420990854",
    "ownershipShare": "",
    "email": "",
    "id": "651327"
  }
],
"proposePurchasers": [
  {
    "name": "Shri. Shrikrushna Raghunath Gaikwad",
    "phone": "",
    "email": "",
```

```
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Living Room",
    "length": "13.08",
    "length1": "13",
    "length2": "1",
    "width": "10.17",
    "width1": "10",
    "width2": "2",
    "totalArea": "133.01",
    "images": [],
    "finalArea": "133.01",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Bedroom",
    "length": "11.08",
    "length1": "11",
    "length2": "1",
    "width": "9.67",
    "width1": "9",
    "width2": "8",
    "totalArea": "107.14",
    "images": [],
    "finalArea": "107.14",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },

```

```
"id": "2",
"name": "Bedroom",
"length": "10.08",
"length1": "10",
"length2": "1",
"width": "9.67",
"width1": "9",
"width2": "8",
"totalArea": "97.47",
"images": [],
"extraAreas": [],
"finalArea": "97.47"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Kitchen",
  "length": "12.08",
  "length1": "12",
  "length2": "1",
  "width": "8.08",
  "width1": "8",
  "width2": "1",
  "totalArea": "97.67",
  "images": [],
  "finalArea": "97.67",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.08",
  "length1": "7",
  "length2": "1",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "29.51",
  "images": [],
```



```
"extraAreas": [],
"finalArea": "29.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "30.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "4.25",
  "width1": "4",
  "width2": "3",
  "totalArea": "18.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
```

```
"length": "4.08",
"length1": "4",
"length2": "1",
"width": "3.17",
"width1": "3",
"width2": "2",
"totalArea": "12.93",
"images": [],
"extraAreas": [],
"finalArea": "12.93"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "38.11",
  "images": [],
  "finalArea": "38.11",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "33.61",
  "images": [],
  "finalArea": "33.61",
  "extraAreas": []
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Balcony",
  "length": "8.08",
  "length1": "8",
  "length2": "1",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "33.68",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.68"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae12adaa6d152c1801b4bf",
      "label": "Notarized Agreement for Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "53.61",
    "totalAreaDocument": "577",
    "docBuiltpPercentage": "20",
    "docFinalBUILTUp": "692.40",
    "docFinalBUILTUpSquareMeter": "64.33",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "251471"
  }
],
"images": [],
"indicatorArr": [
```

```
{
  "carpetArea": {
    "area": "700.00",
    "squareMeterArea": "65.03",
    "expectedRate": "5857.14",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "840.00",
    "squareMeterArea": "78.04",
    "expectedRate": "4880.95",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1008.00",
    "squareMeterArea": "93.65",
    "expectedRate": "4067.46",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "672b45180fd723b55b7c6577",
  "property": "Flat",
  "area": "700",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4100000",
  "expectedRate": "5857.14",
  "builtUpExpectedRate": "4880.95",
  "image": "cases/672b42eed6092bb575128a93/
indicator_1730888845002_Image.png",
  "squareMeter": "65.03",
  "id": "535219"
},
{
  "carpetArea": {
    "area": "1138.00",
    "squareMeterArea": "105.72",
    "expectedRate": "6590.51",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1365.60",
```

```
    "squareMeterArea": "126.87",
    "expectedRate": "5492.09",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1638.72",
    "squareMeterArea": "152.24",
    "expectedRate": "4576.74",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "672b45180fd723b55b7c6578",
  "property": "Flat",
  "area": "1138",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "7500000",
  "expectedRate": "6590.51",
  "builtUpExpectedRate": "5492.09",
  "image": "cases/672b42eed6092bb575128a93/
indicator_1730888901079_Image.png",
  "squareMeter": "105.72",
  "id": "620386"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ecd",
    "name":
"externalImg_1730888705250_WhatsApp_Image_20241105_at_45030_PM_1.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externalImg_1730888705250_WhatsApp_Image_20241105_at_45030_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ece",
    "name":
"externalImg_1730888706800_WhatsApp_Image_20241105_at_45032_PM_2.jpeg",
```

```
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888706800_WhatsApp_Image_20241105_at_45032_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ecf",
    "name":
"externallmg_1730888707107_WhatsApp_Image_20241105_at_45033_PM_1.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888707107_WhatsApp_Image_20241105_at_45033_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ed0",
    "name":
"externallmg_1730888709665_WhatsApp_Image_20241105_at_51642_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888709665_WhatsApp_Image_20241105_at_51642_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ed1",
    "name":
"externallmg_1730888711196_WhatsApp_Image_20241105_at_51643_PM_1.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888711196_WhatsApp_Image_20241105_at_51643_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ed2",
    "name":
"externallmg_1730888713226_WhatsApp_Image_20241105_at_51643_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888713226_WhatsApp_Image_20241105_at_51643_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "672b441dd6092bb575128ed3",
  "name":
"externallmg_1730888714575_WhatsApp_Image_20241106_at_121033_PM.jpeg",
  "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888714575_WhatsApp_Image_20241106_at_121033_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672b441dd6092bb575128ed4",
  "name":
"externallmg_1730888716115_WhatsApp_Image_20241106_at_121050_PM.jpeg",
  "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888716115_WhatsApp_Image_20241106_at_121050_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672b441dd6092bb575128ed5",
  "name":
"externallmg_1730888717623_WhatsApp_Image_20241106_at_121059_PM.jpeg",
  "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888717623_WhatsApp_Image_20241106_at_121059_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672b441dd6092bb575128ed6",
  "name":
"externallmg_1730888719470_WhatsApp_Image_20241106_at_121103_PM.jpeg",
  "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888719470_WhatsApp_Image_20241106_at_121103_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672b441dd6092bb575128ed7",
  "name":
"externallmg_1730888720480_WhatsApp_Image_20241106_at_121124_PM_1.jpeg",
  "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888720480_WhatsApp_Image_20241106_at_121124_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ed8",
    "name":
"externallmg_1730888721771_WhatsApp_Image_20241106_at_121124_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888721771_WhatsApp_Image_20241106_at_121124_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ed9",
    "name":
"externallmg_1730888722973_WhatsApp_Image_20241106_at_121125_PM_1.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888722973_WhatsApp_Image_20241106_at_121125_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128eda",
    "name":
"externallmg_1730888723239_WhatsApp_Image_20241106_at_121125_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888723239_WhatsApp_Image_20241106_at_121125_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128edb",
    "name":
"externallmg_1730888723617_WhatsApp_Image_20241106_at_121126_PM_1.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888723617_WhatsApp_Image_20241106_at_121126_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128edc",
```



```
    "name":
"externallmg_1730888724871_WhatsApp_Image_20241106_at_121126_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888724871_WhatsApp_Image_20241106_at_121126_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128edd",
    "name":
"externallmg_1730888725987_WhatsApp_Image_20241106_at_121127_PM_1.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888725987_WhatsApp_Image_20241106_at_121127_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128ede",
    "name":
"externallmg_1730888726462_WhatsApp_Image_20241106_at_121127_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888726462_WhatsApp_Image_20241106_at_121127_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b441dd6092bb575128edf",
    "name":
"externallmg_1730888727650_WhatsApp_Image_20241106_at_121232_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730888727650_WhatsApp_Image_20241106_at_121232_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672b4afe0fd723b55b7c716b",
    "name":
"externallmg_1730890488251_WhatsApp_Image_20241106_at_41137_PM.jpeg",
    "path": "cases/672b42eed6092bb575128a93/
externallmg_1730890488251_WhatsApp_Image_20241106_at_41137_PM.jpeg",
    "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672b4afe0fd723b55b7c716c",
  "name":
"externallmg_1730890489711_WhatsApp_Image_20241106_at_41243_PM_1.jpeg",
  "path": "cases/672b42eed6092bb575128a93/
externallmg_1730890489711_WhatsApp_Image_20241106_at_41243_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672b4afe0fd723b55b7c716d",
  "name":
"externallmg_1730890492028_WhatsApp_Image_20241106_at_41243_PM.jpeg",
  "path": "cases/672b42eed6092bb575128a93/
externallmg_1730890492028_WhatsApp_Image_20241106_at_41243_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Gaikwad No .01.xlsx",
    "filename": "1730889019347_Gaikwad_No_01.xlsx",
    "path": "cases/672b42eed6092bb575128a93/
processingDocuments/1730889019347_Gaikwad_No_01.xlsx",
    "size": "466195",
    "createdAt": "Wed Nov 06 2024 10:30:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  },
  {
    "originalname": "BOB - Shri. Suresh Ramchandra Odhekar Flat No .01.pdf",
    "filename":
"1730893715319_BOB__Shri_Suresh_Ramchandra_Odhekar_Flat_No_01.pdf",
    "path": "cases/672b42eed6092bb575128a93/processingDocuments/173089371531
9_BOB__Shri_Suresh_Ramchandra_Odhekar_Flat_No_01.pdf",
    "size": "11046342",
    "createdAt": "Wed Nov 06 2024 11:48:49 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```

```
"createdAt": "2024-11-06T10:20:30.297Z",
"updatedAt": "2024-11-06T12:20:21.622Z",
"__v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Shri. Suresh Ramchandra Odhekar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Shri. Shrikrushna Raghunath Gaikwad",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"rerald": "",
"siteVisitContactNo": "9420990854",
"buildingServicesRate": "2000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Notarized Agreement for Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 577.00",
"flatRate": "6300",
"landOtherRate": "4300",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": ""
  }
}
```

```

    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + 2 Passage +
3 Balcony",
"carpetTotal": "631.7499999999999",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "694.92",
"finalCarpetArea": "631.75",
"finalSalableArea": "764.42",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"siteMeasurementRemark": "",
"reportGeneratedDate": "Wed Nov 06 2024 10:31:17 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-11-04"
}

```

| Name | Length | Width | Total |
|---------------|---------------|--------------|--------------|
| Composition : | | | |
| Living Room | 13'1" | 10'2" | 133.01 |
| Bedroom | 11'1" | 9'8" | 107.14 |
| Bedroom | 10'1" | 9'8" | 97.47 |
| Kitchen | 12'1" | 8'1" | 97.67 |
| Toilet | 7'1" | 4'2" | 29.51 |
| Toilet | 7'4" | 4'2" | 30.56 |
| Passage | 4'3" | 4'3" | 18.06 |
| Passage | 4'1" | 3'2" | 12.93 |
| Balcony | 9'4" | 4'1" | 38.11 |
| Balcony | 10'1" | 3'4" | 33.61 |

| | | | |
|---------|------|------|-------|
| Balcony | 8'1" | 4'2" | 33.68 |
|---------|------|------|-------|

Other
Composition :
