

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b262df191f7b344b00870b"
    },
    "firstName": "Arpita",
    "type": "CREDITOFFICER",
    "_id": "66f299a67d6d262b2ba75a6a",
    "email": "arpita.sagare@sbi.co.in",
    "lastName": "Sagare",
    "mobileNo": "",
    "workMobileNo": "9892512598"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Arpita",
    "expectedFees": null,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b262df191f7b344b00870b",
  "name": "SME GHATKOPAR",
  "branchCode": "",
  "mobileNo": "022-25159502",
  "alternateMobileNo": "",
  "email": "sbi.04832@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Hotel Roa Building, LBS Marg, Ghatkopar (West), Mumbai - 400 086."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
```

```
"role": "PICKUPPERSON",
"firstName": "Saurabh",
"email": "saurabhvelonde143@gmail.com",
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62550ed0aba01e0af98f2f75",
"role": "SITEENGINEER",
"firstName": "Chandan",
"email": "ck06806@gmail.com",
"lastName": "Singh",
"mobileNo": "8454863607",
"designation": "",
"shortName": "CH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
```

```
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.09923468725622",
  "longitude": "72.88298763334751"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88298763334751,
    19.09923468725622
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-01",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mohili",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban District",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Nandjyot Industrial Estate",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Safed Pool, Kurla Andheri Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Nand - Jyot Industrial Premises Co-op. Soc. Ltd.",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "8, Hissa No. 11, 14, Survey No. 9, Hissa No. 1 (Pt), 4 (Pt), 6 (Pt), 7 (Pt). 8
(Pt), 9 ,10 & others",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "47",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 072",
```

```
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Sakinaka, Andheri (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "KotaStoneTileFlooring",
    "label": "Kota Stone Tile Flooring"
  },
  "doors": {
    "value": "MS_Rolling_Shutter",
    "label": "MS Rolling Shutter"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
```

```
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Crescent Solitaire",
  "west": "Kanchan Industrial Estate",
  "south": "Aditya Mills Road",
  "east": "Andheri Kurla Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Passage",
    "east": "Unit No. 46",
    "south": "Unit No. 48",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  }
},
```

```

"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "As per Site Inspection, the composition of Industrial Gala is Reception Area + Working Area + 2 Cabins + 1 Store Room + Pantry + Toilet.",
"dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not verified",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "78",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "16660",
  "depreciatedBuildingRate": "660"
},
"igrRate": {
  "propertyName": "Industrial",
  "rate": "132030",
  "landRate": "53370",
  "igrImage": "cases/67c176d37e785c0f9644a905/igr_1741073108048_Image.png",
  "squareMeterGuideLineRate": "132030.00",
  "squareFeetGuideLineRate": "12266.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "48",
  "rate": "8466.00",
  "squareFeetGuideLineRate": "8466.00",
  "squareMeterGuideLineRate": "91127.00"
},
"outgoingDetail": {
  "areaStatusList": {

```

```
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Industrial",
"label": "Industrial"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
}
```

```
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1973",
  "fullDate": "1/1/1973"
},
"planningArea": {
  "value": "Industrial",
  "label": "Industrial"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
```

```
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "8",
"ageOfBuilding": "52",
```



```
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "21"
},
"finalPlinthArea": {
  "area": "1974.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Previous Valuation Report"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67c176d37e785c0f9644a905/
routeMap_1741078454452_Image.png",
    "routeLat": "19.099306",
    "routeLng": "72.882333",
    "stationName": "Sakinaka",
    "routeDistance": "850 Mt.",
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "8l8q8c",
    "name": "8l8q8c",
    "image": "cases/67c176d37e785c0f9644a905/
routeMap_1741078360405_Image.png"
  }
]
```

```
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "32886840.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "32886840.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "16711884.00",
  "selectedBuildUpValue": "1974.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67c2b5aa3b4dfe0fe68f5a97",
      "name": "externalImg_1740813727051_1740813684348_image_3.jpeg",
      "path": "cases/67c176d37e785c0f9644a905/externalImg_1740813727051_1740813684348_image_3.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9b",
    "name": "externallmg_1740813732164_1740813684348_image_7.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813732164_1740813684348_image_7.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa6",
    "name": "externallmg_1740813736810_1740813684348_image_18.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813736810_1740813684348_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9a",
    "name": "externallmg_1740813731009_1740813684348_image_6.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813731009_1740813684348_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a96",
    "name": "externallmg_1740813726082_1740813684348_image_2.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813726082_1740813684348_image_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "67c2b5ca80561479e1f453eb",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813764684_1740813763153_image_0.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5ca80561479e1f453ec",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813765217_1740813763153_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5ca80561479e1f453ed",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813766191_1740813763153_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5ca80561479e1f453ee",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813766498_1740813763153_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5ca80561479e1f453f4",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813769218_1740813763153_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5ca80561479e1f453f5",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813769514_1740813763153_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9f",
    "name": "Unit",
```

```
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813734193_1740813684348_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9c",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813732553_1740813684348_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9d",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813733135_1740813684348_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa0",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813734800_1740813684348_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa2",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813735553_1740813684348_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa3",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813735881_1740813684348_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
```



```
    "_id": "67c2b5aa3b4dfe0fe68f5aa4",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813736161_1740813684348_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa5",
    "name": "Unit",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813736482_1740813684348_image_17.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16847.00",
    "max": "25000.00"
  },
  "builtUpRateRange": {
    "min": "14039.00",
    "max": "20834.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
  "presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1974.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c176d37e785c0f9644a905",
"ownerName": "Mr. Subhash Kantilal Kadakia",
"ownerPhoneNo": "9604156541",
"appAddress": "Unit no. 47, 2nd Floor, Wing - A, Navjot Industrial Estate, Safed Pool,
Kurla ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "06/12/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "444005",
    "path": "cases/67c176d37e785c0f9644a905/
document_1740732066856_122170.pdf",
```

```
"fileName": "document_1740732066856_122170.pdf"
},
{
  "documentType": {
    "value": "60ae1278aa6d152c1801b3ce",
    "label": "Bank Letter for Re-Valuation of the Property"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "28/02/2025"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "152151",
  "path": "cases/67c176d37e785c0f9644a905/
document_1740732112248_1740732109840_Adobe_Scan_28Feb2025.pdf",
  "fileName":
"document_1740732112248_1740732109840_Adobe_Scan_28Feb2025.pdf"
},
{
  "documentType": {
    "value": "60ae125baa6d152c1801b348",
    "label": "Deed of Transfer"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "09/04/1997",
    "from": {
      "value": "Transferor",
      "label": "Transferor"
    },
    "Transferor": "Shri. Mohanlal Nathoo Shah & Mr. Keshavlal Hemraj Sumaria",
    "to": {
      "value": "Transferee",
      "label": "Transferee"
    },
    "Transferee": "Mr. Subhash Kantilal Kadakia"
  },
}
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "id": "908297",
    "path": "cases/67c176d37e785c0f9644a905/
document_1741080234906_SME_Ghatkopar_Kadokia_Plastic_unit_47.pdf",
    "fileName":
"document_1741080234906_SME_Ghatkopar_Kadokia_Plastic_unit_47.pdf"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "08/08/1997",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Subhash K. Kadokia",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "250"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1741080425117_130248.pdf",
    "path": "cases/67c176d37e785c0f9644a905/
document_1741080425117_130248.pdf",
    "id": "252337",
    "uploadedBy": "627221f4afd7d55eddeddcb4",
    "createdAt": "Tue Mar 04 2025 09:27:05 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014608",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "589915",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Fri Feb 28 2025 08:41:55 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Subhash Kantilal Kadakia",
"phone": "9604156541",
"ownershipShare": "",
"email": "",
"id": "467636"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "734767",
"name": "Unit",
"length": "80.00",
"length1": "80",
"length2": "00",
"width": "20.17",
"width1": "20",
"width2": "2",
"totalArea": "1613.33",
"images": [],
"extraAreas": [],
"finalArea": "1613.33"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"label": "Previous Valuation Report",
"value": "60ae1248aa6d152c1801b2ee"
},
"docMeasurementType": {
"value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "183.39",
  "totalAreaDocument": "1974",
  "docBultupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "131443"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "1000.00",
      "squareMeterArea": "92.90",
      "expectedRate": "25000.00",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1200.00",
      "squareMeterArea": "111.48",
      "expectedRate": "20833.33",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "67c6ab211b2b0747e201092b",
    "property": "Safed Pool, Sakinaka",
    "area": "1000",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "-",
    "source": "https://www.99acres.com/",
    "expectedPrice": "25000000",
```



```
"expectedRate": "25000.00",
"builtUpExpectedRate": "20833.33",
"image": "cases/67c176d37e785c0f9644a905/
indicator_1741072759886_Image.png",
"squareMeter": "92.90",
"id": "565154"
},
{
"carpetArea": {
"area": "666.67",
"squareMeterArea": "61.94",
"expectedRate": "22499.89",
"percentage": ""
},
"builtUpArea": {
"area": "800.00",
"squareMeterArea": "74.32",
"expectedRate": "18750.00",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67c6ab211b2b0747e201092c",
"property": "Nand Jyot Ind. Sakinaka",
"area": "800",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "-",
"source": "Nobroker.com",
"expectedPrice": "15000000",
"expectedRate": "22499.89",
"builtUpExpectedRate": "15000000",
"image": "cases/67c176d37e785c0f9644a905/
indicator_1741072823611_Image.png",
"squareMeter": "74.32",
"id": "562478"
},
{
"carpetArea": {
```

```
"area": "1780.83",
"squareMeterArea": "165.44",
"expectedRate": "16846.08",
"percentage": ""
},
"builtUpArea": {
"area": "2137.00",
"squareMeterArea": "198.53",
"expectedRate": "14038.37",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67c6ab211b2b0747e201092d",
"property": "Nand Jyot Ind. Sakinaka",
"area": "2137",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "Ground",
"source": "Index_no.2",
"expectedPrice": "30000000",
"expectedRate": "16846.08",
"builtUpExpectedRate": "30000000",
"image": "cases/67c176d37e785c0f9644a905/
indicator_1741072975736_Image.png",
"squareMeter": "198.53",
"id": "197262"
},
{
"carpetArea": {
"area": "660.00",
"squareMeterArea": "61.32",
"expectedRate": "18939.39",
"percentage": ""
},
"builtUpArea": {
"area": "792.00",
"squareMeterArea": "73.58",
"expectedRate": "15782.83",
```

```
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67c6ab211b2b0747e201092e",
  "property": "Nand Jyot Ind. Sakinaka",
  "area": "792",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "-",
  "source": "Index_no.2",
  "expectedPrice": "12500000",
  "expectedRate": "18939.39",
  "builtUpExpectedRate": "12500000",
  "image": "cases/67c176d37e785c0f9644a905/
indicator_1741073041694_Image.png",
  "squareMeter": "73.58",
  "id": "783613"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2b5ca80561479e1f453eb",
    "name": "externalImg_1740813764684_1740813763153_image_0.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externalImg_1740813764684_1740813763153_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2b5ca80561479e1f453ec",
    "name": "externalImg_1740813765217_1740813763153_image_1.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externalImg_1740813765217_1740813763153_image_1.jpeg",
    "orientation": "portrait"
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2b5ca80561479e1f453ed",
  "name": "externallmg_1740813766191_1740813763153_image_2.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813766191_1740813763153_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2b5ca80561479e1f453ee",
  "name": "externallmg_1740813766498_1740813763153_image_3.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813766498_1740813763153_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2b5ca80561479e1f453ef",
  "name": "externallmg_1740813766674_1740813763153_image_4.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813766674_1740813763153_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2b5ca80561479e1f453f0",
  "name": "externallmg_1740813767573_1740813763153_image_5.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813767573_1740813763153_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c2b5ca80561479e1f453f1",
  "name": "externallmg_1740813768000_1740813763153_image_6.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813768000_1740813763153_image_6.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2b5ca80561479e1f453f2",
    "name": "externallmg_1740813768295_1740813763153_image_7.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813768295_1740813763153_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2b5ca80561479e1f453f3",
    "name": "externallmg_1740813768879_1740813763153_image_8.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813768879_1740813763153_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2b5ca80561479e1f453f4",
    "name": "externallmg_1740813769218_1740813763153_image_9.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813769218_1740813763153_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2b5ca80561479e1f453f5",
    "name": "externallmg_1740813769514_1740813763153_image_10.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813769514_1740813763153_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c2b5ca80561479e1f453f6",
    "name": "externallmg_1740813770071_1740813763153_image_11.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813770071_1740813763153_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "67c2b5aa3b4dfe0fe68f5a94",
  "name": "externallmg_1740813722812_1740813684348_image_0.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813722812_1740813684348_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c2b5aa3b4dfe0fe68f5a95",
  "name": "externallmg_1740813723803_1740813684348_image_1.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813723803_1740813684348_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c2b5aa3b4dfe0fe68f5a96",
  "name": "externallmg_1740813726082_1740813684348_image_2.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813726082_1740813684348_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c2b5aa3b4dfe0fe68f5a97",
  "name": "externallmg_1740813727051_1740813684348_image_3.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813727051_1740813684348_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c2b5aa3b4dfe0fe68f5a98",
  "name": "externallmg_1740813728666_1740813684348_image_4.jpeg",
  "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813728666_1740813684348_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "67c2b5aa3b4dfe0fe68f5a99",
    "name": "externallmg_1740813729812_1740813684348_image_5.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813729812_1740813684348_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9a",
    "name": "externallmg_1740813731009_1740813684348_image_6.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813731009_1740813684348_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9b",
    "name": "externallmg_1740813732164_1740813684348_image_7.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813732164_1740813684348_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9c",
    "name": "externallmg_1740813732553_1740813684348_image_8.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813732553_1740813684348_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9d",
    "name": "externallmg_1740813733135_1740813684348_image_9.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813733135_1740813684348_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9e",
```

```
    "name": "externallmg_1740813733703_1740813684348_image_10.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813733703_1740813684348_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5a9f",
    "name": "externallmg_1740813734193_1740813684348_image_11.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813734193_1740813684348_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa0",
    "name": "externallmg_1740813734800_1740813684348_image_12.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813734800_1740813684348_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa1",
    "name": "externallmg_1740813735195_1740813684348_image_13.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813735195_1740813684348_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa2",
    "name": "externallmg_1740813735553_1740813684348_image_14.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813735553_1740813684348_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa3",
    "name": "externallmg_1740813735881_1740813684348_image_15.jpeg",
```



```
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813735881_1740813684348_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa4",
    "name": "externallmg_1740813736161_1740813684348_image_16.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813736161_1740813684348_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa5",
    "name": "externallmg_1740813736482_1740813684348_image_17.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813736482_1740813684348_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa6",
    "name": "externallmg_1740813736810_1740813684348_image_18.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813736810_1740813684348_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c2b5aa3b4dfe0fe68f5aa7",
    "name": "externallmg_1740813737235_1740813684348_image_19.jpeg",
    "path": "cases/67c176d37e785c0f9644a905/
externallmg_1740813737235_1740813684348_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1701774042667_1698233439717_1697718211173_16968543265
15_Calculation_1.xlsx",
```

```
"filename": "1741073153465_1701774042667_1698233439717_1697718211173_1696854326515_Calculation_1.xlsx",
"path": "cases/67c176d37e785c0f9644a905/processingDocuments/1741073153465_1701774042667_1698233439717_1697718211173_1696854326515_Calculation_1.xlsx",
"size": "3212599",
"createdAt": "Tue Mar 04 2025 07:25:53 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "igr_15405.pdf",
"filename": "1741073153792_igr_15405.pdf",
"path": "cases/67c176d37e785c0f9644a905/processingDocuments/1741073153792_igr_15405.pdf",
"size": "125556",
"createdAt": "Tue Mar 04 2025 07:25:53 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-28T08:41:55.342Z",
"updatedAt": "2025-03-04T12:16:13.188Z",
"__v": 0,
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Industrial Unit No. 47, 2nd Floor, Wing - A, Nandjyot Industrial Estate, Nand - Jyot Industrial Premises Co-op. Soc. Ltd., New/Current Survey No. 8, Hissa No. 11, 14, Survey No. 9, Hissa No. 1 (Pt), 4 (Pt), 6 (Pt), 7 (Pt). 8 (Pt), 9 ,10 & others, Safed Pool, Kurla Andheri Road, Village - Mohili, Sakinaka, Andheri (East), Taluka - Andheri, District - Mumbai Suburban District, PIN Code - 400 072, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Kamran",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person",
"rerald": ""
```

```
"siteVisitContactNo": "9604156541",
"buildingServicesRate": "3000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Previous Valuation Report",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1974.00",
"flatRate": "19000",
"landOtherRate": "16000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "Unit",
"carpetTotal": "1613.33",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1774.66",
"finalCarpetArea": "1613.33",
"finalSalableArea": "1952.13",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 1645.00\n(Area as per Deed of Transfer)",
"siteMeasurementRemark": "",
"otherCompositionBuiltUpTotal": "0.00",
```

"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Unit	80'00"	20'2"	1613.33
Other Composition :			