

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "100000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "67c55b8da7747af45e4a2ff5",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "YASHANAND DEVELOPERS",
"displayname": "YASHANAND DEVELOPERS",
"initial": "Y"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f91822f3dd69653a5922e3",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "Prayush ",
    "email": "prayush@vastukala.org",
    "lastName": "Parekh ",
    "mobileNo": "9767983840",
    "designation": "",
    "shortName": "PPP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f91822f3dd69653a5922e3",
    "role": "SITEENGINEER+MAKAR+CHECKER",
```

```
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
```

```
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
```

```
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "18.509741872800756",
  "longitude": "73.85538662156821"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "5/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Pune",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shukrawar Peth,",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
```

```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "201",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"apfDetails": {
```

```
"buildings": [],
"compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "RECEIVED",
"invoiceIds": [],
"paymentIds": [
  "67c986c17e0bb1d5cc307251"
],
"_id": "67c55b8ea7747af45e4a2ffb",
"ownerName": "YASHANAND DEVELOPERS",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": ""
```

```
"siteVisitContactNo": "0000000000",
"contactPersonName": "YASHANAND DEVELOPERS",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "YASHANAND DEVELOPERS",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "800834"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "self",
"fullAddress": "Residential Project Finance No. Ground Floor, CTS No. 201,
Shukrawar Peth,, Pune, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1740987339106_SANCTIONED_PLAN_201_232.pdf",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
document_1740987339106_SANCTIONED_PLAN_201_232.pdf",
    "id": "160172",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Mon Mar 03 2025 07:36:09 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    }
  },
]
```

```
"attachInReport": false,
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1740987349765_SANCTIONED_PLAN_201_33.pdf",
"path": "cases/67c55b8ea7747af45e4a2ffb/
document_1740987349765_SANCTIONED_PLAN_201_33.pdf",
"id": "991276",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Mon Mar 03 2025 07:36:09 GMT+0000 (Coordinated Universal Time)"
},
{
"documentType": {
"value": "60ae124eaa6d152c1801b30b",
"label": "Other"
},
"attachConfig": {
"fromPage": 0,
"toPage": 0
},
"attachInReport": false,
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1740987358345_AREA_STATEMENT_21720231.pdf",
"path": "cases/67c55b8ea7747af45e4a2ffb/
document_1740987358345_AREA_STATEMENT_21720231.pdf",
"id": "638706",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Mon Mar 03 2025 07:36:09 GMT+0000 (Coordinated Universal Time)"
},
{
"documentType": {
"value": "60ae124eaa6d152c1801b30b",
"label": "Other"
},
"attachConfig": {
"fromPage": 0,
"toPage": 0
},
"attachInReport": false,
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1740987367885_SANCTIONED_PLAN_201_131.pdf",
"path": "cases/67c55b8ea7747af45e4a2ffb/
document_1740987367885_SANCTIONED_PLAN_201_131.pdf",
"id": "339307",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
```

```
    "createdAt": "Mon Mar 03 2025 07:36:09 GMT+0000 (Coordinated Universal Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"reald": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "014640",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "488041",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Mon Mar 03 2025 07:34:38 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f66",
    "name": "externalImg_1741584044255_IMG_20250305142017358.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/externalImg_1741584044255_IMG_20250305142017358.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f67",
    "name": "externalImg_1741584044307_IMG_20250305142018610.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/externalImg_1741584044307_IMG_20250305142018610.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f68",
  "name": "externallmg_1741584044376_IMG_20250305142024911.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584044376_IMG_20250305142024911.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f69",
  "name": "externallmg_1741584044471_IMG_20250305142026938.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584044471_IMG_20250305142026938.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f6a",
  "name": "externallmg_1741584044578_IMG_20250305142031118.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584044578_IMG_20250305142031118.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f6b",
  "name": "externallmg_1741584044638_IMG_20250305142032813.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584044638_IMG_20250305142032813.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f6c",
  "name": "externallmg_1741584044791_IMG_20250305142033727.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584044791_IMG_20250305142033727.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f6d",
    "name": "externallmg_1741584044835_IMG_20250305142048553.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584044835_IMG_20250305142048553.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f6e",
    "name": "externallmg_1741584045025_IMG_20250305142059332.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045025_IMG_20250305142059332.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f6f",
    "name": "externallmg_1741584045036_IMG_20250305142100845.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045036_IMG_20250305142100845.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f70",
    "name": "externallmg_1741584045177_IMG_20250305142106500.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045177_IMG_20250305142106500.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f71",
    "name": "externallmg_1741584045200_IMG_20250305142108718.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045200_IMG_20250305142108718.jpg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f72",
  "name": "externallmg_1741584045361_IMG_20250305142111004.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045361_IMG_20250305142111004.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f73",
  "name": "externallmg_1741584045369_IMG_20250305142113814.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045369_IMG_20250305142113814.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f74",
  "name": "externallmg_1741584045513_IMG_20250305142122418.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045513_IMG_20250305142122418.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f75",
  "name": "externallmg_1741584045520_IMG_20250305142137372.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045520_IMG_20250305142137372.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ae7e0bb1d5cc321f76",
  "name": "externallmg_1741584045663_IMG_20250305142138267.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045663_IMG_20250305142138267.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f77",
    "name": "externallmg_1741584045674_IMG_20250305142157528.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045674_IMG_20250305142157528.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f78",
    "name": "externallmg_1741584045780_IMG_20250305142158267.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045780_IMG_20250305142158267.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ae7e0bb1d5cc321f79",
    "name": "externallmg_1741584045787_IMG_20250305142208441.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584045787_IMG_20250305142208441.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8872",
    "name": "externallmg_1741584055458_IMG_20250305142209672.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055458_IMG_20250305142209672.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8873",
    "name": "externallmg_1741584055512_IMG_20250305142216065.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055512_IMG_20250305142216065.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "67ce76b9021414d63cdf8874",
  "name": "externallmg_1741584055623_IMG_20250305142217810.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055623_IMG_20250305142217810.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76b9021414d63cdf8875",
  "name": "externallmg_1741584055734_IMG_20250305142219983.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055734_IMG_20250305142219983.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76b9021414d63cdf8876",
  "name": "externallmg_1741584055865_IMG_20250305142221615.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055865_IMG_20250305142221615.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76b9021414d63cdf8877",
  "name": "externallmg_1741584055873_IMG_20250305142310515.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055873_IMG_20250305142310515.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76b9021414d63cdf8878",
  "name": "externallmg_1741584055948_IMG_20250305142314120.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055948_IMG_20250305142314120.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67ce76b9021414d63cdf8879",
    "name": "externallmg_1741584055972_IMG_20250305142320619.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584055972_IMG_20250305142320619.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf887a",
    "name": "externallmg_1741584056113_IMG_20250305142321713.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056113_IMG_20250305142321713.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf887b",
    "name": "externallmg_1741584056143_IMG_20250305142327455.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056143_IMG_20250305142327455.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf887c",
    "name": "externallmg_1741584056286_IMG_20250305142410819.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056286_IMG_20250305142410819.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf887d",
    "name": "externallmg_1741584056302_IMG_20250305142411430.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056302_IMG_20250305142411430.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf887e",
```

```
    "name": "externallmg_1741584056440_IMG_20250305142422417.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056440_IMG_20250305142422417.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf887f",
    "name": "externallmg_1741584056536_IMG_20250305142431860.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056536_IMG_20250305142431860.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8880",
    "name": "externallmg_1741584056683_IMG_20250305142443391.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056683_IMG_20250305142443391.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8881",
    "name": "externallmg_1741584056696_IMG_20250305142450191.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056696_IMG_20250305142450191.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8882",
    "name": "externallmg_1741584056844_IMG_20250305142455044.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056844_IMG_20250305142455044.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8883",
    "name": "externallmg_1741584056853_IMG_20250305142456004.jpg",
```

```
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056853_IMG_20250305142456004.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8884",
    "name": "externallmg_1741584056953_IMG_20250305142506599.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056953_IMG_20250305142506599.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76b9021414d63cdf8885",
    "name": "externallmg_1741584056966_IMG_20250305142507568.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584056966_IMG_20250305142507568.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ca8037ced5d242e3d9",
    "name": "externallmg_1741584068503_IMG_20250305142517795.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584068503_IMG_20250305142517795.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ca8037ced5d242e3da",
    "name": "externallmg_1741584068575_IMG_20250305142518737.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584068575_IMG_20250305142518737.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ca8037ced5d242e3db",
    "name": "externallmg_1741584068672_IMG_20250305142519793.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584068672_IMG_20250305142519793.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3dc",
  "name": "externallmg_1741584068736_IMG_20250305142623514.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584068736_IMG_20250305142623514.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3dd",
  "name": "externallmg_1741584068858_IMG_20250305142624164.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584068858_IMG_20250305142624164.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3de",
  "name": "externallmg_1741584068938_IMG_20250305142626091.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584068938_IMG_20250305142626091.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3df",
  "name": "externallmg_1741584069089_IMG_20250305142632445.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069089_IMG_20250305142632445.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e0",
  "name": "externallmg_1741584069163_IMG_20250305143442435.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069163_IMG_20250305143442435.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e1",
  "name": "externallmg_1741584069331_IMG_20250305143443908.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069331_IMG_20250305143443908.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e2",
  "name": "externallmg_1741584069345_IMG_20250305143444705.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069345_IMG_20250305143444705.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e3",
  "name": "externallmg_1741584069462_IMG_20250305143500287.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069462_IMG_20250305143500287.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e4",
  "name": "externallmg_1741584069557_IMG_20250305143509723.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069557_IMG_20250305143509723.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e5",
  "name": "externallmg_1741584069665_IMG_20250305143518560.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069665_IMG_20250305143518560.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e6",
  "name": "externallmg_1741584069938_IMG_20250305143524770.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584069938_IMG_20250305143524770.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e7",
  "name": "externallmg_1741584070037_IMG_20250305_142527.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_1741584070037_IMG_20250305_142527.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e8",
  "name": "externallmg_r_1741584070426_IMG_20250305_142555.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_r_1741584070426_IMG_20250305_142555.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3e9",
  "name": "externallmg_r_1741584071861_IMG_20250305_142603.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_r_1741584071861_IMG_20250305_142603.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ce76ca8037ced5d242e3ea",
  "name": "externallmg_r_1741584070904_IMG_20250305_142557.jpg",
  "path": "cases/67c55b8ea7747af45e4a2ffb/
externallmg_r_1741584070904_IMG_20250305_142557.jpg",
  "orientation": "landscape"
},
{
```

```

    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ce76ca8037ced5d242e3eb",
    "name": "externalImg_r_1741584071391_IMG_20250305_142559.jpg",
    "path": "cases/67c55b8ea7747af45e4a2ffb/
externalImg_r_1741584071391_IMG_20250305_142559.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-03T07:34:38.112Z",
"updatedAt": "2025-03-10T05:21:14.583Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60f91822f3dd69653a5922e3"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			