

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bad7"
    },
    "firstName": "Antriksh",
    "type": "CREDITOFFICER",
    "_id": "666832902ae3637b0ee9b205",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9076172812",
    "email": "operah@bankofbaroda.com"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Antriksh",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bad7",
  "branchCode": "000040",
  "type": "BRANCH",
  "name": "Opera House Branch",
  "email": "operah@bankofbaroda.co.in",
  "mobileNo": "02223888748",
  "alternateMobileNo": "",
  "address": "Modi Chambers,Near French Bridge,Pandit Paluskar Chowk,Opera
House,Mumbai-400004",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "665ac13f42f4717ae30de3d5",
  "role": "PICKUPPERSON",
  "firstName": "NIDHI",
  "email": "nidhi.kajwe97@gmail.com",
  "lastName": "KAJWE",
  "mobileNo": "8850520881",
  "shortName": "NIDHI",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  }
]
```

```
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.955401558271628",
  "longitude": "72.81491550093274"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81491550093274,
    18.955401558271628
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
```

```
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2025-03-06",
    "remark": ""
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
},
```

```
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "02",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "Second Malabar View tenants CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Marine lines",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Chowpathy",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
```

```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```



```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400007",
  "label": false
},
"suburb": {
  "status": true,
```

```
"name": "Suburb",
"key": "suburb",
"value": "Charni Road West",
"label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
```

```
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```



```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c67987a8da631a7e9002af",
"ownerName": "Mrs. Sunderben J Jhaveri, Mr. Atul J Jhaveri & Mr. Sunil J Jhaveri ",
"ownerPhoneNo": "9820777654",
"appAddress": "Flat No 2 Ground Floor Building No 2 Second Malabar View Tenants
Co op Hsg Soc Ltd Marine Lines Chowpatty Charni Road West Mumbai - 400007",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67c67987a8da631a7e9002af/document_1741060286988_17410602
83205_Previous_Valuation_Report_Sunderben_J_Jhaveri__Atul_J_Jhaveri__Sunil_J_J
haveri.pdf",
    "fileName": "document_1741060286988_1741060283205_Previous_Valuation_Rep
ort_Sunderben_J_Jhaveri__Atul_J_Jhaveri__Sunil_J_Jhaveri.pdf",
    "id": "390216",
    "uploadedBy": "665ac13f42f4717ae30de3d5",
    "createdAt": "Tue Mar 04 2025 03:54:46 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67c67987a8da631a7e9002af/document_1741060355394_1741060351511_Agreement_Sunderben_J_Jhaveri_Atul_Jhaveri__Sunil_Jhaveri.pdf",
  "fileName": "document_1741060355394_1741060351511_Agreement_Sunderben_J_Jhaveri_Atul_Jhaveri__Sunil_Jhaveri.pdf",
  "id": "182709",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Tue Mar 04 2025 03:54:46 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67c67987a8da631a7e9002af/document_1742459373928_1742459373385_Structural_Report_Sunderben_Jhaveri.pdf",
  "fileName": "document_1742459373928_1742459373385_Structural_Report_Sunderben_Jhaveri.pdf",
  "id": "295723",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Thu Mar 20 2025 08:29:36 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014662",
"createdBy": "665ac13f42f4717ae30de3d5",
"caseHistory": [
  {
```

```
"id": "612143",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Tue Mar 04 2025 03:54:47 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mrs. Sunderben J Jhaveri, Mr. Atul J Jhaveri & Mr. Sunil J Jhaveri ",
"phone": "9820777654",
"ownershipShare": "",
"email": "",
"id": "570717"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67c95ada77162bd3bef317a7",
"name": "externalImg_1741249241907_1741249239710_image_0.jpeg",
"path": "cases/67c67987a8da631a7e9002af/externalImg_1741249241907_1741249239710_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67c95ada77162bd3bef317a8",
"name": "externalImg_1741249242391_1741249239710_image_1.jpeg",
"path": "cases/67c67987a8da631a7e9002af/externalImg_1741249242391_1741249239710_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "67c95ac1911180d3bfd3923",
```

```
    "name": "externallmg_1741249214018_1741249210457_image_0.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214018_1741249210457_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd3924",
    "name": "externallmg_1741249214289_1741249210458_image_1.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214289_1741249210458_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd3925",
    "name": "externallmg_1741249214409_1741249210458_image_2.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214409_1741249210458_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd3926",
    "name": "externallmg_1741249214475_1741249210458_image_3.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214475_1741249210458_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd3927",
    "name": "externallmg_1741249214588_1741249210458_image_4.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214588_1741249210458_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd3928",
    "name": "externallmg_1741249214626_1741249210458_image_5.jpeg",
```

```
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214626_1741249210458_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd3929",
    "name": "externallmg_1741249214806_1741249210458_image_6.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214806_1741249210458_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd392a",
    "name": "externallmg_1741249214867_1741249210458_image_7.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249214867_1741249210458_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd392b",
    "name": "externallmg_1741249215010_1741249210458_image_8.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249215010_1741249210458_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd392c",
    "name": "externallmg_1741249215098_1741249210458_image_9.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249215098_1741249210458_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c95ac1911180d3bffd392d",
    "name": "externallmg_1741249215347_1741249210458_image_10.jpeg",
    "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249215347_1741249210458_image_10.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c95ac1911180d3bffd392e",
  "name": "externallmg_1741249215644_1741249210458_image_11.jpeg",
  "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249215644_1741249210458_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c95ac1911180d3bffd392f",
  "name": "externallmg_1741249215856_1741249210458_image_12.jpeg",
  "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249215856_1741249210458_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c95ac1911180d3bffd3930",
  "name": "externallmg_1741249215975_1741249210458_image_13.jpeg",
  "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249215975_1741249210458_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c95ac1911180d3bffd3931",
  "name": "externallmg_1741249216158_1741249210458_image_14.jpeg",
  "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249216158_1741249210458_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c95ac1911180d3bffd3932",
  "name": "externallmg_1741249216225_1741249210458_image_15.jpeg",
  "path": "cases/67c67987a8da631a7e9002af/
externallmg_1741249216225_1741249210458_image_15.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67c95ac1911180d3bffd3933",
      "name": "externalImg_1741249216790_1741249210458_image_16.jpeg",
      "path": "cases/67c67987a8da631a7e9002af/
externalImg_1741249216790_1741249210458_image_16.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67c95ac1911180d3bffd3934",
      "name": "externalImg_1741249216906_1741249210458_image_17.jpeg",
      "path": "cases/67c67987a8da631a7e9002af/
externalImg_1741249216906_1741249210458_image_17.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67c95ac1911180d3bffd3935",
      "name": "externalImg_1741249217008_1741249210458_image_18.jpeg",
      "path": "cases/67c67987a8da631a7e9002af/
externalImg_1741249217008_1741249210458_image_18.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "60f9147bf3dd69653a591e8c",
        "role": "MAKER + RATE VERIFIER + CHEAKER",
        "firstName": "Vinita",
        "lastName": "Surve",
        "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
    }
  ]
}
```

```

    "_id": "67cbee588037ced5d2425065",
    "note": "Area not mention ",
    "taskId": "67c69898a8da631a7e9023b5",
    "createdAt": "2025-03-08T07:14:32.985Z"
  }
],
"createdAt": "2025-03-04T03:54:47.202Z",
"updatedAt": "2025-03-20T08:29:36.246Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2, 2nd Floor, Building No 02, Second Malabar View
tenants CHSL, Marine lines, Chowpathy, Charni Road West, Mumbai, 400007, State -
Maharashtra, India",
"updatedBy": "665ac13f42f4717ae30de3d5",
"addressForMap": "",
"caseReferredBy": "665ac13f42f4717ae30de3d5",
"contactPersonName": "Mrs. Sunderben J Jhaveri, Mr. Atul J Jhaveri & Mr. Sunil J
Jhaveri ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9820777654"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			