

Vastukala Consultants (I) Pvt. Ltd.

Valuation Report of the Immovable Property



Details of the property under consideration:

Name of Owner: Shri. Pandurang Keshav Kompalwar.

Plot No.39, S.No.92/2, MCHNO 3687/39, Samarth Nagar, Loha, Tg.Loha, Dist. Nanded. State - Maharashtra, Country - India.

Longitude Latitude: 18.953632, 77.120031

Valuation Done for:

Axis Bank

Pune Branch

S. No. 251, Gawade Crystal LLP, Pimpri-Chinchwad Link Rd, Near Gawade Petrol Pump, Gawade Nagar, Chinchwad, Pune, Pimpri-Chinchwad, PIN - 411033, Maharashtra, India

Raipur

Jaipur



Nanded: 28, S.G.G.S Stadium Complex, Nanded - 431 602, (M.S), INDIA Email: nanded@vastukala.co.in| Tel: +91 2462 244288 +91 94221 71100

Our Pan India Presence at:

Nanded Mumbai

Thane 💡 Nashik

Ahmedabad Opelhi NCR Rajkot

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India

+91 2247495919

👔 mumbai@vastukala.co.in www.vastukala.co.in



Vavalen Stutkertar Coort Shi Radunt (Sel (1) Port. Ltd. 2 of 14

Vastu/Axis Bank/Nanded Br./03/2025/014711/ 2310883 06/7-80 APSC

Date: 06.03.2025

VALUER'S OPINION REPORT

This is to certify that the property situated on Plot No.39, S.No.92/2, MCHNO 3687/39, Samarth Nagar, Loha, Tq. Loha, Dist. Nanded, is belongs to Shri. Pandurang Keshav Kompalwar.

Boundaries of the property.

North Plot No.40.

6.00 m.Wide Road. South

East Plot No.38.

West Land of Datta Shette.

Considering various parameters recorded, existing economic scenario, and the information that is available with reference to the development of neighborhood and method selected for valuation, we are of the opinion that, the property premises can be assessed are as under:

Guideline Value of the Property Rs. 14,91,554.00 Rs. 25,06,612.00 Fair Market Value of the Property Realizable Value of the Property Rs. 22,55,950.00 Forced/ Distress Sale value of the Property. Rs. 20,05,289.00

The valuation of the property is based on the documents produced by the concern. Legal aspects have not been taken into considerations while preparing this valuation report.

Hence certified

For, Vastukala Consultants (I) Pvt. Ltd.




Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09

IBBI Reg.No. IBBI/RV/07/2019/11744

Encl: Valuation report.



Our Pan India Presence at:

Nanded Thane Mumbai

Ahmedabad Opelhi NCR Nashik Raikot Aurangabad Pune

Raipur Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India



🕯 mumbai@vastukala.co.in www.vastukala.co.in



VALUATION REPORT (IN RESPECT OF RESIDENTIAL LAND AND BUILDING)

| 1. | CBB/CCMC/CCSU | Assignment No | | | - | | | | | |
|-----|---|--|--|---|-------------------------|---|--|--|--|--|
| | | | Proposal No | | | | | | | |
| 2. | Name of Owner & Addr | ess: | Shri. Pandurang Keshav Kompalwar. R/o. Plot No.39, S.No.92/2, MCHNO 3687/39, Samarth Nagar, Loha, Tq.Loha, Dist. Nanded. State – Maharashtra, Country - India. Mob. No. # 9527799233 (Pandurang Keshav Kompalwar) Mob. No. # 9096107124 (Ganraj Kompalwar) | | | | | | | |
| | Name of Borrower & Ac | dress | Shri. Pandurang Keshav Kompalwar. R/o. Plot No.39, S.No.92/2, MCHNO 3687/39, Samarth Nagar, Loha, Tq.Loha, Dist. Nanded. State – Maharashtra, Country - India. Mob. No. # 9527799233 (Pandurang Keshav Kompalwar) Mob. No. # 9096107124 (Ganraj Kompalwar) | | | | | | | |
| 3. | Name of the Bank Offic | ial Present | No. | | | | | | | |
| | Name of the Represent | ative & Mobile No. | Owne | er's Represe | ntati | ive, Shri. Pandurang Keshav Kompalwar. | | | | |
| | ///- | | Mob. No. # 9527799233 | | | | | | | |
| 4. | | Details | of the | Property Be | eing | Valued | | | | |
| 4.1 | Description of the Prope | erty | Grou | nd Storeyed | d Re | esidential Building. | | | | |
| 4.2 | Location of Property | | Plot No.39, S.No.92/2, MCHNO 3687/39, Samarth Nagar, Loha, Tq.Loha, Dist. Nanded. State – Maharashtra, Country - India. | | | | | | | |
| | (Rural / Semi Urban / U | Irban) | Semi Urban | | | | | | | |
| 4.3 | Documents Provided : | | 1 | | | | | | | |
| | 1 Photo Copy of | Sale Deed No. 692/2 | 2025, dated 07.02.2025, Joint Sub Registrar, Loha. | | | | | | | |
| | | 2. ULPIN No. 31852254692 dated 05.02.2025. | | | | | | | | |
| | Tq.Loha, Dist. | Nanded. | ated 2024-2025, issued by Chief officer, Municipal Council Loha, | | | | | | | |
| | 4 Photo Copy of Tq.Loha, Dist. | | ssion F | ssion Plan No. Nil issued by Chief officer, Municipal Council Loha, | | | | | | |
| 4.4 | Plot No / Survey No. / | S.No.92/2 | / | Road | Govt Road towards East. | | | | | |
| | Gut No. / Khasra No: | | | | | | | | | |
| 4.5 | Colony / Nagar / | Samarth Nagar. | Locality | | / | Near Safalya Balaji Devasthan | | | | |
| | Sector | | | Landmark | | | | | | |
| 4.6 | Village/Town/City | Nanded. | District: | | | Nanded | | | | |
| 4.7 | State | Maharashtra | Pin code: 431708 | | | | | | | |
| 4.8 | Distance from Area Offi | ce (Nanded Branch) | | @ 31.9 Km | | | | | | |
| 5. | (A) Diete (Decidential / | Carrage raint / Indust | | e of Propert | | | | | | |
| | (A) Plot: (Residential / | | | Residential. | | | | | | |
| | Level of land with topog | • | | Levelled Nagar Parishad | | | | | | |
| | Whether situated in Mul | · · · · · · · · · · · · · · · · · · · | LIIIII | | Nagar Parishad. | | | | | |
| | • | | 01100 / 1 | Pungalaw / | | s, Ground Storeyed Residential Building | | | | |
| | (B) Residential Proper Row House / Flat) | ty: (independent no | ouse / I | Dungalow / | ırıd | dependent house. | | | | |
| | Civic Amenities like sol | nool hospital marks | et etc | (Available | All available nearby. | | | | | |
| | within the radius of Km. | • • | J., U.U. | , wallable, | | | | | | |
| | (C) Commercial / Indu | , | Shop / Unit | N.A. | | | | | | |



Since 1989



Valuers & Appraisers

Architects & Machiners (1)

Chartered Engineers (1)

Lender's Engineer

MH2010 PVCD

| Accessibility / Boundaries / Others | | in a Mall / Gowo | down) | | | | | | | | |
|--|------|--|------------------|-----------------|------------------|---|----|--|--|--|--|
| Personal Transport) 6.2 Distance from Nanded Railway station 32.00 Kms. 6.3 Does the approach road to the Property / Yes. Building is independent and accessible 6.4 Does the property falls under land locked No. Does the property falls under land locked No. Does the property falls in a community No. dominated area 6.5 Cornered / Intermittent Plot Intermittent. 6.6 Boundaries As Per Site As Per Documents North Plot No.40. Plot No.40. South 6.00 m.Wide Road. East Plot No.38. Plot No.38. Plot No.38. West Land of Datta Shette. 6.7 Class of locality (Posh / Higher Middle Class / Middle Class / Lower Middle Class / Poor) 6.8 Quality of Infrastructure in the vicinity (Excellent / Good / Average / Poor) 6.9 Ownership Status of the Property (Free Hold / Reg. Lease / Govt. Authority) 6.10 Approved usage of property Residential (Industrial / Commercial / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (if any) 6.12 Type of Structure (Load Bearing / RCC / Aluform shuttering) 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N.A. 17.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 6. | | | Acces | ndaries / Others | | | | | | |
| 6.3 Does the approach road to the Property / Yes. Building is independent and accessible 6.4 Does the property falls under land locked area 6.5 Cornered / Intermittent Plot 6.6 Boundaries As Per Site North Plot No.40. South 6.00 m.Wide Road. East Plot No.38. West Land of Datta Shette. 6.7 Class of locality (Posh / Higher Middle Class / Middle Class / Lower Middle Class / Poor) 6.8 Quality of Infrastructure in the vicinity (Excellent / Good / Average / Poor) 6.9 Ownership Status of the Property Residential (Industrial / Commercial / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (if any) 6.12 Type of Structure (Load Bearing / RCC / Aluform shuttering) 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) 7. If the property is an accessible No. Will it be able to accommodate a fire extinguisher Will it be able to accommodate a fire extinguisher Will it be able to accommodate a fire extinguisher Will it be able to accommodate a fire extinguisher Will it be able to accommodate a fire extinguisher No. Does the property falls in a community dominated area No. Does the property falls in a community dominated area No. Does the property falls in a community dominated area No. Does the property falls in a community dominated area No. Does the property falls in a community dominated area No. Does the property falls in a community dominated area No. As Per Documents No. Bylot No.0. South 6.00 m.Wide Road. 6.00 m.Wide Road. 6.00 m.Wide Road. Biot No.0. Good Average / Poor) 6.7 Class of locality (Posh / Higher Middle Class / | 6.1 | • | . , | /letro / Local | Train / Bus / | Local Transport, Bus Stand. | | | | | |
| Building is independent and accessible extinguisher 6.4 Does the property falls under land locked area 6.5 Cornered / Intermittent Plot Intermittent. 6.6 Boundaries As Per Site As Per Documents North Plot No.40. Plot No.40. South 6.00 m.Wide Road. 6.00 m.Wide Road. East Plot No.38. Plot No.38. West Land of Datta Shette. Land of Datta Shette. 6.7 Class of locality (Posh / Higher Middle Class / Middle Class / Lower Middle Class / Poor) 6.8 Quality of Infrastructure in the vicinity (Excellent / Good / Average / Poor) 6.9 Ownership Status of the Property (Free Hold / Reg. Freehold Lease / Govt. Authority) 6.10 Approved usage of property (Industrial / Commercial / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (If any) Residential / Mix) 6.12 Type of Structure (Load Bearing / RCC / Aluform shuttering) 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) Owner Occupied 7. If the property is on rent: 7.1 Name of tenant / lease: N.A., Number of years in tenancy: N.A. | 6.2 | Distance from N | Nanded Railway | station 32.0 | 0 Kms. | Bus stop/ Taxi/ Auto Stand 1.5 kms | S | | | | |
| area dominated area 6.5 Cornered / Intermittent Plot Intermittent. 6.6 Boundaries As Per Site As Per Documents North Plot No.40. Plot No.40. South 6.00 m.Wide Road. 6.00 m.Wide Road. East Plot No.38. Plot No.38. West Land of Datta Shette. Land of Datta Shette. 6.7 Class of locality (Posh / Higher Middle Class / Middle Class / Lower Middle Class / Poor) 6.8 Quality of Infrastructure in the vicinity (Excellent / Good / Average / Poor) 6.9 Ownership Status of the Property (Free Hold / Reg. Lease / Govt. Authority) 6.10 Approved usage of property (Industrial / Commercial / Residential / (Industrial / Commercial / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (if any) Residential 6.12 Type of Structure (Load Bearing / RCC / Aluform shuttering) 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) Owner Occupied 7. If the property is on rent: 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 6.3 | | | | Yes. | Will it be able to accommodate a fire No. | | | | | |
| North | 6.4 | 1 | erty falls under | land locked | No. | 1 | | | | | |
| North Plot No.40. Plot No.40. South 6.00 m.Wide Road. 6.00 m.Wide Road. 6.00 m.Wide Road. East Plot No.38. Plot No.39. P | 6.5 | Cornered / Inter | rmittent Plot | | | Intermittent. | | | | | |
| South 6.00 m.Wide Road. 6.00 m.Wide Road. East | 6.6 | Boundaries | | As Per Site | | As Per Documents | 5 | | | | |
| East | | North | | Plot No.40. | | Plot No.40. | | | | | |
| West | | South | 6.00 | m.Wide Roa | d. | | | | | | |
| 6.7 Class of locality (Posh / Higher Middle Class / Middle Class / Lower Middle Class / Poor) 6.8 Quality of Infrastructure in the vicinity (Excellent / Good / Average / Poor) 6.9 Ownership Status of the Property (Free Hold / Reg. Lease / Govt. Authority) 6.10 Approved usage of property (Industrial / Commercial / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (if any) Residential / Mix) 6.12 Type of Structure (Load Bearing / RCC / Aluform shuttering) 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) Owner Occupied 7. If the property is on rent: 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | | East | | Plot No.38. | | | | | | | |
| Class / Lower Middle Class / Poor) 6.8 Quality of Infrastructure in the vicinity (Excellent / Good / Average / Poor) 6.9 Ownership Status of the Property (Free Hold / Reg. Lease / Govt. Authority) 6.10 Approved usage of property (Industrial / Commercial / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (if any) Residential / Mix) 6.12 Type of Structure (Load Bearing / RCC / Aluform RCC Framed Structure shuttering) 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) Owner Occupied 7. If the property is on rent: 7.1 Name of tenant / lease: N.A., Number of years in tenancy: N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | | | | | | | Э. | | | | |
| G.8 Quality of Infrastructure in the vicinity (Excellent / Good / Average / Poor) | 6.7 | | , , | | ass / Middle | Middle Class | | | | | |
| 6.9 Ownership Status of the Property (Free Hold / Reg. Lease / Govt. Authority) 6.10 Approved usage of property (Industrial / Commercial / Residential / Residential / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (if any) 6.12 Type of Structure (Load Bearing / RCC / Aluform shuttering) 6.13 Number of floors | 6.8 | -/- | | vicinity (Excel | lent / Good / | Good | | | | | |
| 6.10 Approved usage of property (Industrial / Commercial / Residential / Mix) 6.11 Restrictive covenants in regards to Land Use, (if any) 6.12 Type of Structure (Load Bearing / RCC / Aluform shuttering) 6.13 Number of floors | 6.9 | Ownership Sta | tus of the Prop | erty (Free H | Freehold | | | | | | |
| 6.12 Type of Structure (Load Bearing / RCC / Aluform RCC Framed Structure shuttering) 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) Owner Occupied 7. If the property is on rent: 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 6.10 | (Industrial | / Commercia | . , | ential | (Industrial / Commercial / | | | | | |
| shuttering) 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) Owner Occupied 7. If the property is on rent: 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 6.11 | Restrictive cove | enants in regard | s to Land Use | Residential | | | | | | |
| 6.13 Number of floors As per Actual Ground Floor. 6.14 Occupancy Details (Self-Occupied / Rented / Vacant) Owner Occupied 7. If the property is on rent: 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 6.12 | | ture (Load Be | aring / RCC | C / Aluform | | | | | | |
| 7. If the property is on rent: 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 6.13 | Number of floor | rs . | As per Actua | al | Ground Floor. | | | | | |
| 7. If the property is on rent: 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 6.14 | Occupancy Det | ails (Self-Occur | oied / Rented | / Vacant) | Owner Occupied | | | | | |
| 7.1 Name of tenant / lease : N.A., Number of years in tenancy : N. A. 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 7. | | | | | | | | | | |
| 7.2 Was there any resistance for valuation: No If yes, from the current occupants: N.A. | 7.1 | | | | Number of | years in tenancy : N. A. | | | | | |
| | | | | aluation: No | | , | | | | | |
| | 7.3 | Does property h | | Yes. | Developme | Development of surrounding area Under | | | | | |
| amenities Underdeveloped / Developing / Developed Developed. 8. If the property is Leasehold | Q | amenities Underdeveloped / Developing / Developed Developed. | | | | | | | | | |
| 8.1 Name of Lesser: N.A. Nature of Lease: N.A. | | | | | | | | | | | |
| | | | | | cupante: N Δ | | | | | | |
| | | | | • | | · | | | | | |
| 8.3 Does property have basic amenities No. Development of surrounding area Underdeveloped Under Developed. Developing / Developed Dev | 0.3 | | | • | | . | | | | | |
| 9. Approval Details | 9. | | | | | | | | | | |
| 9.1 RERA Registration Number Not Applicable | 9.1 | RERA Registra | tion Number | | Not Appli | • • | | | | | |
| 9.2 Layout Approval Number: Not Available. | 9.2 | | | | | | | | | | |
| Date of Approval N.A. | | | | | N.A. | | | | | | |
| Expiry Date N.A. | | | | | | N.A. | | | | | |
| 9.3 Building Plan Approval Number: Not Available. | 9.3 | Building Plan Approval Number: | | | Not Availa | | | | | | |
| Date of Approval N.A. | | | | | | l. | | | | | |



Since 1989



| | Expiry Da | | | | N.A. | | | | | | | | |
|-------|---|-----------|-----------|----------------|---------------------------------|--------------------------|---|--|------------|--------------|-----|-----------------|--|
| 10. | Plot Area Details. | | | | | | | | | | | | |
| 10.01 | Plot Area | l | | | | | Area in Sqm. | | | | | | |
| 10.02 | Plot Area | As per S | ale Deed | t | | | | 118.03 | | | | | |
| 10.03 | Plot Area As per Nagar Parishad Sanctioned Plan | | | | | | | | | 118 | .03 | | |
| 10.04 | Demarcation at Site | | | | | | | | | Ye | S. | | |
| 10.05 | Plot Area | Conside | red for V | aluatio | n | | | | | 118 | .03 | | |
| 10.06 | Construction Area Details | | | | | | | | | | | | |
| | <u> </u> | | | | | uilt up A | p Area in Sqm. Sanctioned Plan Built up Area in Sqr | | | | | | |
| | Ground Floor | | | | 75.65 | | - | | 58.50 | | | | |
| | 2. First Floor | | | | - | | | | 58.50 | | | | |
| | Total | | | | 75.65 | | | | 117.00 |) | | | |
| 10.07 | Only | Ground I | Floor Sar | nctione | ed Built up A | Area Cons | sidered | for Val | uation: 58 | 8.50 Sgm. | | | |
| 10.08 | | | reak up | | | | | | | | ent | Usage | |
| | Floo | | | | up Area | Sanct | ioned | Plan B | uilt up | | | | |
| | | | | in Sqn | - | | | in Sqm | - | , , | | Residential) | |
| | Ground F | loor | /- | 75.65 | | - 4 | _58 | 3.50 | | Residential | | | |
| | First Floor | r | | Nil | | | 58 | 3.50 | | | | | |
| | Total 75.65 | | | | | | 117.00 | | | | | | |
| 10.9 | Amenities Details (if any): | | | | | | | Bore well etc. | | | | | |
| 10.10 | Floor Space Index permissible. | | | | | | | Basic FSI 1.10 | | | | | |
| | | | | | | | | Premium FSI - | | | | | |
| | | | | | | | TDR - | | | | | | |
| | | | | | | | | llary FS | | 51.1 | 4 | - | |
| | | | | | | | | Maximum building potential on Plot including in-situ FSI | | | | | |
| 10.11 | FSI Utilized | | | | | | 1.10 | | | | | | |
| 10.12 | Whether the construction is as per approved | | | | | | • No. | | | | | | |
| | building plan and / or local building bye laws: | | | | | | Construction Permission ,issued by Chief officer, Municipal Council Loha, Tq.Loha, Dist. Nanded. | | | | | | |
| | | | | | | | | | | | | | |
| 10.13 | Details of Extra Construction | | | | | | Floo | | | Extra Bui | | | |
| | Botalio of Extra Construction | | | | | | Ground Floor 17.15 | | | | | | |
| 10.14 | Percentage of Extra Construction | | | | | | 77.32 % | | | | | | |
| 10.15 | Whether the extra construction is Compoundable OR | | | | | | | Compoundable. | | | | | |
| | Non-Compoundable? | | | | | | | | | | | | |
| 10.16 | Quality of construction | | | | | | | Good. | | | | | |
| 10.17 | Maintenance of the Property | | | | | | Well maintained. | | | | | | |
| 10.18 | Condition of Building | | | | | | Good. | | | | | | |
| 10.19 | Current Life of the 7 year. | | | | Project | ojected Future 53 Years. | | | | | | | |
| | structure | | | • | er Owners | Life of | | | | | | | |
| | | | | , . | mation) | | | | | | | | |
| 10.20 | , | | ils not | Municip | pal Taxes Details not available | | | | | | | | |
| | | | able | Paid upto (for | | | | | | | | | |
| | | | | | | Building | g) | | | | | | |
| 11. | Details of Valuation: | | | | | | | | | | | | |
| | S. Part | iculars o | f Plin | ith / | Age of | Estima | ited | Repla | cement | Depreciation | ı | Net Value after | |



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001: 2015 Certified Company

| | L | ltem | Built up Area In Sq. M. | Building Replacement Rate Of Construction | | cost 10.50 | | 6 | Depreciation | | | |
|-----|----------------------------|------------------------------|-------------------------------|---|------------------------|-------------|------------------|--------------|--------------|--------------|--|--|
| | 1 (| 1 Ground Floor 58.50 7 19,60 | | 2.00 | 11,46,717.00 -1,20,405 | |)5.00 | 10,26,312.00 | | | | |
| | | | | | Total | | 10,26,312.00 | | | | | |
| 12. | Details of Amenities | | | | | | | | | | | |
| | 1 | Borewell. | | | | | 1,00,000.00 | | | | | |
| | 2 | Compound | ate. | | | | | | 2,00,000.00 | | | |
| | | | | | | | | To | tal | 3,00,000.00 | | |
| 13. | Government Guideline value | | | | | | | | | | | |
| | Particulars | | | Area in Sq | լ. М. | Rate in Rs. | | | | Value in Rs. | | |
| 1 | Land | | | 118.03 | | | 1400.00 | | | 1,65,242.00 | | |
| 2 | Construction | | | | | | | | | 10,26,312.00 | | |
| 3 | Amenities | | DE 4 1) | | -7 | (TM) | | | 3,00,000.00 | | | |
| | | | | TOTAL | | | | | | 14,91,554.00 | | |
| 14. | Market Value of Land | | | | | | | | | | | |
| | Particulars | | Area in Sq. M. | | Rate in Rs. | | | | Value in Rs. | | | |
| | Land | | 118.03 10,000.00 | | | | 11,80,300.00 | | | | | |
| 15. | Value of the Property | | | | | | | | | | | |
| | | | | Land | b | Bui | lding | Amenities | | Total | | |
| | Government Guideline value | | 1,65,242.00 1 | | 10,26 | ,312.00 | 2.00 3,00,000.00 | | 14,91,554.00 | | | |
| | Marke | Market Value | | 11,80,300.00 10,26 | | 3,00,000.00 | | 11/2 | 25,06,612.00 | | | |
| | Distre | Distressed/Forced Sale Value | | | | | | | | 20,05,289.00 | | |
| | Realiz | Realizable Value | | | | | | | | 22,55,950.00 | | |
| | Insura | Insurable Value | | | | | 8,21,049.00 | | | | | |
| | | Remarks | | | | | | | | | | |
| | TI A | | | | | | | | | | | |

- The Actual Ground Floor Built-up area is 75.65 Sqm (Refer Annexure-1)
- The Sanctioned Ground Floor Built-up Area is 58.50 Sqm (Refer Annexure-2)
- The built-up area considered in sale deed is 118.03 Sqm.(Refer Page No 34/36 in Sale Deed No.692/2025)
- There is deviation in actual Ground floor Built-up area, Sanctioned Built-up area and Built-up in Sale deed No.692/2025.
- No Side, Front and Back Margins as per Sanctioned plan.
- Hence to assess the Fair Market Value by Land and Building method the land area as per sale deed and the plinth area as per Sanctioned Plan is considered.
- There are cracks in compound wall and floor settlement in one bed room.
- Proper maintenance is required.





Undertaking:

- 1. I have / our / representative Md. Shareq Salim Md. Jilani Pasha (Technical Assistant) has inspected the subject property on 04.03.2025 along with Owner's Representative Shri.Pandurang Keshav Kompalwar identified the same based on the documents provided.
- 2. I/We have no direct or indirect interest in the property being valued.
- 3. The information furnished above is true and correct to my/our knowledge
- 4. I/ we have not been dismissed or removed from govt. Service or convicted of an offence connected with any proceedings of income tax act, wealth tax act or gift tax act or have been blacklisted by any bank/ financial institution/ govt. Department/ public sector enterprise/ body corporate etc.
- 5. This valuation is prepared without any prejudice or bias to any person or institution.
- 6. The value of land is taken into account by making due enquires in the locality and ascertaining the sales value of the properties in the locality.
- 7. Any additions/alterations made to the property after the date of valuations shall not fall under the scope of this report.

For, Vastukala Consultants (I) Pvt. Ltd.

Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 IBBI Reg. No. IBBI/RV/07/2019/11744

Date: 06.03.2025

| Attachments | | | | | | | | |
|---|---|---------------|--|--|--|--|--|--|
| Photographs of the Property from inside & outside | 4 | Attached | | | | | | |
| Location sketch for the property: | : | Attached. | | | | | | |
| Geo Tagging | : | Attached. | | | | | | |
| Topography | : | Leveled Land. | | | | | | |
| Government Value Document | : | Attached. | | | | | | |





Actual Site Photographs




















Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Actual Construction Plan Refer Annexure-1




EXISTING GROUND FLOOR PLAN GROUND FLOOR B/UP AREA 75.65 SQ.M






Sanctioned Plan Refer Annexure-2







Page No 34/36 of Sale Deed



Home Print








Since 1989





Route Map of the Property





Longitude Latitude: 18.953632, 77.120031


Note:

- Red Pointer shows Approx. Property Location.
- Blue line shows Route from @ 2.1 Km.



Valuers & Appraisers
Architects &
Architects

Ready Reckoner Rate







ASSUMPTIONS, CAVEATS, LIMITATION AND DISCLAIMERS

- 1. We assume no responsibility for matters of legal nature affecting the property appraised or the title thereto, nor do we render our opinion as to the title, which is assumed to be good and marketable.
- 2. The property is valued as though under responsible ownership.
- 3. It is assumed that the property is free of liens and encumbrances.
- 4. It is assumed that there are no hidden or unapparent conditions of the subsoil or structure that would render it more or less valuable. No responsibility is assumed for such conditions or for engineering that might be required to discover such factors.
- 5. The rates for valuation of the property are in accordance with the Govt. approved rates and prevailing market rates

For, Vastukala Consultants (I) Pvt. Ltd.

Sharadkumar B. Chalikwar

B.E. (Civil), M.E. (Civil), M.Sc. (Real Estate Valuation), M.Sc. (P&M Valuation), FIE (I), FIV, FIWRS Chairman & Managing Director Govt. Reg. Valuer
Chartered Engineer (India)
Reg. No. (N) CCIT/1-14/52/2008-09
IBBI Reg.No. IBBI/RV/07/2019/11744

Date: 06.03.2025 Place: Nanded.



