

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6401aa2a0e28255fb44e5222"
    },
    "firstName": "Minakshi\t",
    "type": "CREDITOFFICER",
    "_id": "6524deba703d7c40db979df7",
    "lastName": "Ajila\t",
    "mobileNo": "",
    "workMobileNo": "9930375648",
    "email": "1bmmsro0630@centrabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "29500000",
    "discussWithPerson": "Minakshi\t",
    "expectedFees": 14750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6401aa2a0e28255fb44e5222",
  "name": "Kandivali East Branch",
  "branchCode": "",
  "mobileNo": "02228546591",
  "alternateMobileNo": "",
  "email": "bmmsro0630@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground Floor, G-Bungalow, Crystal Lane, Thakur Complex, Kandivali
east, Mumbai - 400 101 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "67776d60a5477d50e7dbc213",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "AJAY",
    "email": "ajayrewale503@gmail.com",
    "lastName": "REWALE",
    "mobileNo": "9766640171",
    "designation": "",
    "shortName": "AJAY",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "663da98cfcea71232186f142",
    "role": "ACCOUNTANT",
    "firstName": "SONAL ",
    "email": "sonal.ambekar19@gmail.com",
    "lastName": " SHIVGAN",
```

```
"mobileNo": "9773395869",
"designation": "",
"shortName": "SO",
"workWithDocumentMaker": "",
"profilePhoto": "users/663da98cfcea71232186f142/
profilePhoto_1715317132035_Sonal_Ambekar.jpg"
},
"checker": {
  "_id": "64dc7184ccaf1e7b7f637f47",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg",
  "firstName": "Binumon",
  "lastName": "Moozhickal",
  "shortName": "BS",
  "email": "binu@vastukala.org",
  "designation": "Back Office Team Leader",
  "mobileNo": "9930252906",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.20858623947986",
  "longitude": "72.87098504587273"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87098504587273,
    19.20858623947986
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-07",
      "remark": "CA Gagrani contact person mob no hey "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-06",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-07",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-07",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-07",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-07",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Poisar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "24",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai Suburban",
    "label": true
  }
}
```

```
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Challenger II",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
```



```
"key": "street1",
"value": "Thakur Village",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Challenger Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
```

```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "795/5, 792//10 to 14",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2406",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "R/South",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```

```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 101",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
```

```
"label": "Vitrified Tile Flooring"
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
  "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
},
"windows": {
  "value": "Alluminum_sliding_windows_with_M._S._Grills",
  "label": "Alluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Tower No. 1 & Road",
    "west": "Open Plot ",
    "south": "Samta Vidyamandir ",
    "east": "N.S. Phadke Road "
```

```
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Lift & Common Passage",
    "south": "Flat No. 2405",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it is assumed that
the construction is as per Sanctioned Plan",
"approvePlanVerified": "N.A. ",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
```

```
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "31.499999999999996",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "26618",
  "depreciatedBuildingRate": "1918"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "182410",
  "landRate": "96900",
  "igrImage": "cases/67c9645a911180d3bffd465d/igr_1742464617987_Image.png",
  "squareMeterGuideLineRate": "209772.00",
  "squareFeetGuideLineRate": "19488.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "79",
  "rate": "17286.00",
  "squareFeetGuideLineRate": "17286.00",
  "squareMeterGuideLineRate": "186069.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "Rs. 70,000/- Present Rental Income per Month",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
```

```
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "Information not available",
"tenantName": "Mr. Mr. Amit Goyal <br/> Since 6 Years",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "along with Cover Parking Space No. 2E",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2004",
    "fullDate": "1/1/2004"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
}
```



```
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
"noOfBasement": "",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "27",
"flatFloorNo": "24",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "1325.00",
  "areaType": "Saleable",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67c9645a911180d3bffd465d/
routeMap_1742537010208_Image.png",
```

```
"routeLat": "19.20846",
"routeLng": "72.871455",
"stationName": "Poisar",
"routeDistance": "1.4 Km",
"routeStation": {
  "value": "Metro_Station",
  "label": "Metro Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finalLatLng": false
},
"locationMapImg": [
  {
    "id": "ci3qh",
    "name": "ci3qh",
    "image": "cases/67c9645a911180d3bffd465d/
routeMap_1742536968632_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
```

```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "1",
"othersRate": "1200000",
"totalothersRate": "1200000",
"finaltotal": "36468850.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "35268850.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "datetime": "2025-03-21T06:57:29.618Z",
  "date": "Fri Mar 21 2025 06:57:29 GMT+0000 (Coordinated Universal Time)",
  "number": "2311169",
  "dayCount": "9",
  "monthCount": "366",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "22903950.00",
  "selectedBuildUpValue": "1325.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67ca92847e0bb1d5cc30cd0c",
      "name": "externallmg_1741329024911_1741329011173_image_15.jpeg",
      "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329024911_1741329011173_image_15.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67ca92847e0bb1d5cc30cd04",
      "name": "externallmg_1741329019881_1741329011172_image_7.jpeg",
      "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329019881_1741329011172_image_7.jpeg",
      "orientation": "portrait"
    }
  ],
  {

```

```
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd08",
    "name": "externallmg_1741329021960_1741329011172_image_11.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329021960_1741329011172_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd07",
    "name": "externallmg_1741329021403_1741329011172_image_10.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329021403_1741329011172_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd05",
    "name": "externallmg_1741329020631_1741329011172_image_8.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329020631_1741329011172_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd01",
    "name": "externallmg_1741329017796_1741329011172_image_4.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329017796_1741329011172_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb5",
    "name": "externallmg_1741328989878_1741328969568_image_16.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328989878_1741328969568_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb7",
    "name": "externallmg_1741328990433_1741328969568_image_18.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328990433_1741328969568_image_18.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "status": false,
      "_id": "67ca925f7e0bb1d5cc30ccb6",
      "name": "externallmg_1741328990037_1741328969568_image_17.jpeg",
      "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328990037_1741328969568_image_17.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67ca92847e0bb1d5cc30cd0b",
      "name": "externallmg_1741329023921_1741329011173_image_14.jpeg",
      "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329023921_1741329011173_image_14.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "36000.00",
    "max": "39954.00"
  },
  "builtUpRateRange": {
    "min": "30000.00",
    "max": "33295.00"
  },
  "saleableRateRange": {
    "min": "25000.00",
    "max": "27746.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```



```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
  "presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1325.00",
"empanelmentNo": [
  "SMRO /CREDIT/2017-18/1311"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c9645a911180d3bffd465d",
"ownerName": "Mr. Satyanarayan Gagrani & Mrs. Savitri Gagrani",
"ownerPhoneNo": "9967065195",
"appAddress": "Flat no 2406 24 th floor Bldg Challenger 2 CHS Ltd Thakur village
Kandivali East Mumbai 400101",
"remark": "CA Gagrani contact person mob no hey ",
"documents": [
  {
    "documentType": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
```

```
"documentDate": "21/02/2025",
"from": {
  "value": "Transferor",
  "label": "Transferor"
},
"Transferor": "Mrs. Veena Madanlal Sharma",
"to": {
  "value": "Transferee",
  "label": "Transferee"
},
"Transferee": "Mr. Satyanarayan Gagrani & Mrs. Savitri Gagrani",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "2486/2025"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1742535457201_Agreement_Gagrani.pdf",
"path": "cases/67c9645a911180d3bffd465d/
document_1742535457201_Agreement_Gagrani.pdf",
"id": "737816",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Fri Mar 21 2025 05:37:40 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "07/03/1995",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
}
```

```
    "Document_No": "CHE / 9408 / BP (WS) / AR"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "824904",
  "path": "cases/67c9645a911180d3bffd465d/
document_1742535761822_Commencement.pdf",
  "fileName": "document_1742535761822_Commencement.pdf"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "01/12/2004",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "CHE / 9408 / BP (WS) / AR"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1742535818873_OC.pdf",
  "path": "cases/67c9645a911180d3bffd465d/document_1742535818873_OC.pdf",
  "id": "585066",
  "uploadedBy": "663da98cfcea71232186f142",
  "createdAt": "Fri Mar 21 2025 05:43:39 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Society Registration Certificate",
    "value": "60ae1257aa6d152c1801b335"
  },
  "attachConfig": {
    "fromPage": 0,
```

```
"toPage": 0
},
"attachInReport": false,
"inputs": {
  "documentDate": "21/10/2003",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "MUM / WR / HSG / TC / 12260 / 2003-2004"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1742535902616_Society_Registration_certificate.pdf",
"path": "cases/67c9645a911180d3bffd465d/
document_1742535902616_Society_Registration_certificate.pdf",
"id": "427523",
"uploadedBy": "663da98cfcea71232186f142",
"createdAt": "Fri Mar 21 2025 05:45:02 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Deed Of Rectification",
    "value": "60ae1274aa6d152c1801b3bc"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "19/03/2025",
    "remark": "for area confirmation"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "781157",
  "path": "cases/67c9645a911180d3bffd465d/
document_1742540639964_Rectification_Deed.pdf",
  "fileName": "document_1742540639964_Rectification_Deed.pdf"
}
],
"caseNumber": "014723",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
```

```
"id": "209122",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Thu Mar 06 2025 09:01:14 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "Mr. Satyanarayan Gagrani & Mrs. Savitri Gagrani",
"phone": "9967065195",
"ownershipShare": "",
"email": "",
"id": "907544"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "243550",
"name": "Passage",
"length": "3.50",
"length1": "3",
"length2": "6",
"width": "15.42",
"width1": "15",
"width2": "5",
"totalArea": "53.96",
"images": [],
"extraAreas": [],
"finalArea": "53.96"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
},
{id": "1",
"name": "Cupboard",
"length": "1.08",
"length1": "1",
"length2": "1",
```

```
"width": "4.08",
"width1": "4",
"width2": "1",
"totalArea": "4.42",
"images": [],
"extraAreas": [],
"finalArea": "4.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "14.25",
  "width1": "14",
  "width2": "3",
  "totalArea": "137.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "137.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Living Room",
  "length": "15.58",
  "length1": "15",
  "length2": "7",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "149.34",
  "images": [],
  "extraAreas": [],
  "finalArea": "149.34"
},
{
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Dining",
  "length": "14.58",
  "length1": "14",
  "length2": "7",
  "width": "8.67",
  "width1": "8",
  "width2": "8",
  "totalArea": "126.39",
  "images": [],
  "extraAreas": [],
  "finalArea": "126.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "12.58",
  "length1": "12",
  "length2": "7",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "91.23",
  "images": [],
  "extraAreas": [],
  "finalArea": "91.23"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "3.00",
  "width1": "3",
```

```
"width2": "00",
"totalArea": "13.75",
"images": [],
"extraAreas": [],
"finalArea": "13.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
  "width": "13.58",
  "width1": "13",
  "width2": "7",
  "totalArea": "146.02",
  "images": [],
  "extraAreas": [],
  "finalArea": "146.02"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "7.58",
  "length1": "7",
  "length2": "7",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "39.18",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.18"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "9",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "117.96",
  "images": [],
  "extraAreas": [],
  "finalArea": "117.96"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "7.17",
  "length1": "7",
  "length2": "2",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "29.26",
  "images": [],
  "extraAreas": [],
  "finalArea": "29.26"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "30.00",
```

```
"images": [],
"extraAreas": [],
"finalArea": "30.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeofDocument": {
"label": "Deed Of Rectification",
"value": "60ae1274aa6d152c1801b3bc"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "488615",
"selectAreaTypeDocument": "Saleable",
"totalAreaDocument": "1325",
"squareMeterArea": "123.10",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltpPercentage": "",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "972.23",
"squareMeterArea": "90.32",
"expectedRate": "35999.71",
"percentage": ""
},
"builtUpArea": {
"area": "1166.67",
"squareMeterArea": "108.39",
"expectedRate": "29999.91",
"percentage": "20"
},
"saleableArea": {
"area": "1400.00",
```

```
"squareMeterArea": "130.06",
"expectedRate": "25000.00",
"percentage": "20"
},
"printlnReport": true,
"_id": "67dbe6b02a6e19cd7a538514",
"property": "Residential Flat",
"area": "1400",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Saleable",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "35000000",
"expectedRate": "25000",
"builtUpExpectedRate": "29999.91",
"image": "cases/67c9645a911180d3bffd465d/
indicator_1742464171544_Image.png",
"squareMeter": "130.06",
"id": "663872"
},
{
"carpetArea": {
"area": "590.28",
"squareMeterArea": "54.84",
"expectedRate": "39811.61",
"percentage": ""
},
"builtUpArea": {
"area": "708.33",
"squareMeterArea": "65.81",
"expectedRate": "33176.63",
"percentage": "20"
},
"saleableArea": {
"area": "850.00",
"squareMeterArea": "78.97",
"expectedRate": "27647.06",
"percentage": "20"
},
"printlnReport": true,
"_id": "67dbe6b02a6e19cd7a538515",
"property": "Residential Flat",
"area": "850",
"builtUpPercentage": "20",
```

```
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Saleable",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "23500000",
"expectedRate": "27647.058823529413",
"builtUpExpectedRate": "33176.63",
"image": "cases/67c9645a911180d3bffd465d/
indicator_1742464408366_Image.png",
"squareMeter": "78.97",
"id": "586485"
},
{
  "carpetArea": {
    "area": "1010.38",
    "squareMeterArea": "93.87",
    "expectedRate": "36748.55",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1212.45",
    "squareMeterArea": "112.64",
    "expectedRate": "30623.94",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "1454.94",
    "squareMeterArea": "135.17",
    "expectedRate": "25519.95",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67dbe6b02a6e19cd7a538516",
  "property": "Residential Flat",
  "area": "1212.45",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "37130000.00",
  "expectedRate": "36748.55",
  "builtUpExpectedRate": "37130000.00",
  "image": "cases/67c9645a911180d3bffd465d/
indicator_1742464485974_Image.png",
```

```
"squareMeter": "112.64",
"id": "194493"
},
{
  "carpetArea": {
    "area": "666.67",
    "squareMeterArea": "61.94",
    "expectedRate": "39953.80",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "800.00",
    "squareMeterArea": "74.32",
    "expectedRate": "33295.00",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "960.00",
    "squareMeterArea": "89.19",
    "expectedRate": "27745.83",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67dbe6b02a6e19cd7a538517",
  "property": "Residential Flat",
  "area": "960",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Saleable",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "26636000",
  "expectedRate": "27745.833333333332",
  "builtUpExpectedRate": "33295.00",
  "image": "cases/67c9645a911180d3bffd465d/
indicator_1742464565237_Image.png",
  "squareMeter": "89.19",
  "id": "868476"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30ccfd",
```

```
    "name": "externallmg_1741329014783_1741329011172_image_0.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329014783_1741329011172_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30ccfe",
    "name": "externallmg_1741329016052_1741329011172_image_1.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329016052_1741329011172_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30ccff",
    "name": "externallmg_1741329016745_1741329011172_image_2.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329016745_1741329011172_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd00",
    "name": "externallmg_1741329017063_1741329011172_image_3.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329017063_1741329011172_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd01",
    "name": "externallmg_1741329017796_1741329011172_image_4.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329017796_1741329011172_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd02",
    "name": "externallmg_1741329018553_1741329011172_image_5.jpeg",
```



```
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329018553_1741329011172_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd03",
    "name": "externallmg_1741329019313_1741329011172_image_6.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329019313_1741329011172_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd04",
    "name": "externallmg_1741329019881_1741329011172_image_7.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329019881_1741329011172_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd05",
    "name": "externallmg_1741329020631_1741329011172_image_8.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329020631_1741329011172_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd06",
    "name": "externallmg_1741329021024_1741329011172_image_9.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329021024_1741329011172_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ca92847e0bb1d5cc30cd07",
    "name": "externallmg_1741329021403_1741329011172_image_10.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329021403_1741329011172_image_10.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd08",
  "name": "externallmg_1741329021960_1741329011172_image_11.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329021960_1741329011172_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd09",
  "name": "externallmg_1741329022748_1741329011173_image_12.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329022748_1741329011173_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd0a",
  "name": "externallmg_1741329023541_1741329011173_image_13.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329023541_1741329011173_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd0b",
  "name": "externallmg_1741329023921_1741329011173_image_14.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329023921_1741329011173_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd0c",
  "name": "externallmg_1741329024911_1741329011173_image_15.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329024911_1741329011173_image_15.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd0d",
  "name": "externallmg_1741329025831_1741329011173_image_16.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329025831_1741329011173_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd0e",
  "name": "externallmg_1741329026794_1741329011173_image_17.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329026794_1741329011173_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ca92847e0bb1d5cc30cd0f",
  "name": "externallmg_1741329027246_1741329011173_image_18.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741329027246_1741329011173_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ca925f7e0bb1d5cc30cca5",
  "name": "externallmg_1741328972185_1741328969568_image_0.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328972185_1741328969568_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ca925f7e0bb1d5cc30cca6",
  "name": "externallmg_1741328975163_1741328969568_image_1.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328975163_1741328969568_image_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ca925f7e0bb1d5cc30cca7",
  "name": "externallmg_1741328976518_1741328969568_image_2.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328976518_1741328969568_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ca925f7e0bb1d5cc30cca8",
  "name": "externallmg_1741328976895_1741328969568_image_3.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328976895_1741328969568_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ca925f7e0bb1d5cc30cca9",
  "name": "externallmg_1741328978297_1741328969568_image_4.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328978297_1741328969568_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ca925f7e0bb1d5cc30ccaa",
  "name": "externallmg_1741328980068_1741328969568_image_5.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328980068_1741328969568_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67ca925f7e0bb1d5cc30ccab",
  "name": "externallmg_1741328982348_1741328969568_image_6.jpeg",
  "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328982348_1741328969568_image_6.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccac",
    "name": "externallmg_1741328983558_1741328969568_image_7.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328983558_1741328969568_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccad",
    "name": "externallmg_1741328984645_1741328969568_image_8.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328984645_1741328969568_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccae",
    "name": "externallmg_1741328985405_1741328969568_image_9.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328985405_1741328969568_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccaf",
    "name": "externallmg_1741328986389_1741328969568_image_10.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328986389_1741328969568_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb0",
    "name": "externallmg_1741328987161_1741328969568_image_11.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328987161_1741328969568_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb1",
    "name": "externallmg_1741328987431_1741328969568_image_12.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328987431_1741328969568_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb2",
    "name": "externallmg_1741328987913_1741328969568_image_13.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328987913_1741328969568_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb3",
    "name": "externallmg_1741328988601_1741328969568_image_14.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328988601_1741328969568_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb4",
    "name": "externallmg_1741328989452_1741328969568_image_15.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328989452_1741328969568_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb5",
    "name": "externallmg_1741328989878_1741328969568_image_16.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externallmg_1741328989878_1741328969568_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "67ca925f7e0bb1d5cc30ccb6",
    "name": "externalimg_1741328990037_1741328969568_image_17.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externalimg_1741328990037_1741328969568_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67ca925f7e0bb1d5cc30ccb7",
    "name": "externalimg_1741328990433_1741328969568_image_18.jpeg",
    "path": "cases/67c9645a911180d3bffd465d/
externalimg_1741328990433_1741328969568_image_18.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "29938-2025-JEMANT JAIN-DINDOSHI GOREGAON BRANCH-
FLAT.pdf",
    "filename": "1742463442356_299382025JEMANT_JAINDINDOSHI_GOREGAON_
BRANCHFLAT.pdf",
    "path": "cases/67c9645a911180d3bffd465d/processingDocuments/1742463442356
_299382025JEMANT_JAINDINDOSHI_GOREGAON_BRANCHFLAT.pdf",
    "size": "977624",
    "createdAt": "Thu Mar 20 2025 09:37:22 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "ACE Scanner_2025_03_19 (1).pdf",
    "filename": "1742464026474_ACE_Scanner_2025_03_19_1.pdf",
    "path": "cases/67c9645a911180d3bffd465d/
processingDocuments/1742464026474_ACE_Scanner_2025_03_19_1.pdf",
    "size": "50869884",
    "createdAt": "Thu Mar 20 2025 09:47:09 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "Satyanarayan Gagrani And Mrs. Savitri Gagrani - Flat No. 2406 -
Central Bank of India ( Kandivali East Branch ).xlsx",
    "filename": "1742464672405_Satyanarayan_Gagrani_And_Mrs_Savitri_Gagrani___
Flat_No_2406___Central_Bank_of_India__Kandivali_East_Branch_.xlsx",
    "path": "cases/67c9645a911180d3bffd465d/processingDocuments/1742464672405
_Satyanarayan_Gagrani_And_Mrs_Savitri_Gagrani___Flat_No_2406___Central_Bank_
of_India__Kandivali_East_Branch_.xlsx",
```

```
"size": "2852980",
"createdAt": "Thu Mar 20 2025 09:57:52 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "67cbd1ca021414d63cdede4e",
"note": "Required approved plan area deviation between measured and agreement
carpet area ",
"taskId": "67c99ffb8037ced5d24108c0",
"createdAt": "2025-03-08T05:12:42.831Z"
}
],
"createdAt": "2025-03-06T09:01:14.321Z",
"updatedAt": "2025-03-21T07:22:36.380Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 2406, 24th Floor, Challenger II, Challenger Co-Op.
Hsg. Soc. Ltd., Thakur Village, Village - Poisar, Municipality Ward No. R/South,
Kandivali (East), Taluka - Borivali, District - Mumbai Suburban, Mumbai, 400 101, State
- Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Amit Goyal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```



```
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"rerald": "",
"siteVisitContactNo": "9967065195",
"buildingServicesRate": "2800",
"finalAreaType": "Saleable Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Saleable Area in Sq. Ft. = 1325.00",
"flatRate": "27500",
"landOtherRate": "24700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Passage + Cupboard
+ Dining + 3 Toilet",
"carpetTotal": "939.26",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1033.19",
"finalCarpetArea": "939.26",
"finalSalableArea": "1136.50",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": ""
```

```

    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Mar 21 2025 05:58:07 GMT+0000 (Coordinated Universal Time)",
"siteVisitDate": "2025-03-07"
}

```

Name	Length	Width	Total
Composition :			
Passage	3'6"	15'5"	53.96
Cupboard	1'1"	4'1"	4.42
Bedroom	9'8"	14'3"	137.75
Living Room	15'7"	9'7"	149.34
Dining	14'7"	8'8"	126.39
Kitchen	12'7"	7'3"	91.23
Passage	4'7"	3'00"	13.75
Bedroom	10'9"	13'7"	146.02
Toilet	7'7"	5'2"	39.18
Bedroom	12'5"	9'6"	117.96
Toilet	7'2"	4'1"	29.26
Toilet	4'00"	7'6"	30.00
Other Composition :			