

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Abhijit",
    "type": "CREDITOFFICER",
    "_id": "66581caa2611441081269f7e",
    "lastName": "Adsul",
    "mobileNo": "",
    "workMobileNo": "9833817601",
    "email": "abhijeet.adsul@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Abhijit",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.212640351665062",
  "longitude": "73.12974314967856"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.12974314967856,
    19.212640351665062
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-07",
      "remark": ""
    }
  ]
},
"schedule": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Adivali & Dhokali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Seasons Sahara Nano Building No. A & B",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Behind 50-50 Dhaba, Opp. Essar Petrol Pump , Haji Malang Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "23",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 306",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kalyan (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
```

```
"label": "Proposed R.C.C. Slab"
},
"flooring": {
  "value": "Proposed_Vitrified_tiles_flooring",
  "label": "Proposed Vitrified tiles flooring"
},
"doors": {
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
  "label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
  "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
},
"finishing": {
  "value": "Proposed_Cement_Plastering",
  "label": "Proposed Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  }
},
```

```

"asPerActualAgreement": {
  "north": "Open Plot",
  "west": "Ganesh mahale Apartment",
  "south": " Haji Malang Road",
  "east": "Shree Krishna Apartment"
},
"asPerDocumentAgreement": {
  "north": "Property of Tukaram Kaluram Bhane",
  "west": " Property of Baliram Chandrakant Bhane",
  "south": " Property of Datta Arjun Gavali",
  "east": " Property of Ramachandra Babu Bhane"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building is under construction ",
    "east": "Building is under construction ",
    "south": "Building is under construction ",
    "west": "Building is under construction "
  },
  "asPerDocument": {
    "north": "Marginal Space ",
    "east": "Marginal Space ",
    "south": "Flat No. 607",
    "west": "Lobby "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per site inspection, RCC plinth work was in progress. As per Approved Building Plan, the composition of Flat will be 1 Bedroom + Living Room + Kitchen + Passage + W.C + Bath. (i.e. 1BHK)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No.KDMC / TPD / BP /

```

27 Village / 2024 - 25 / 09 Dated 12.07.2024 issued by Kalyan Dombivli Municipal Corporation.",

```
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Building is under construction ",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "10000.00",
  "depreciatedBuildingRate": "2800"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "32400",
  "landRate": "4100",
  "igrImage": "cases/67c98e598037ced5d240f0d6/igr_1741421041446_Image.png",
  "squareMeterGuideLineRate": "34020.00",
  "squareFeetGuideLineRate": "3161.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "32400.00",
  "squareMeterGuideLineRate": "34020.00",
  "squareFeetGuideLineRate": "3161.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per KDMC norms ",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
```

```
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "6",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "7"
},
```



```
"finalPlinthArea": {
  "area": "425.70",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67c98e598037ced5d240f0d6/
routeMap_1741684639598_Image.png",
    "routeLat": "19.212306",
    "routeLng": "73.129611",
    "stationName": "Kalyan",
    "routeDistance": "6.00 KM. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "q8lxpm",
      "name": "q8lxpm",
      "image": "cases/67c98e598037ced5d240f0d6/
routeMap_1741684525230_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
}
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3870000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "3870000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "InProgress",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "5.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1345638.00",
  "selectedBuildUpValue": "425.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67cacb2b7e0bb1d5cc311c9a",
      "name": "externalImg_1741343524424_1741343516118_image_2.jpeg",
      "path": "cases/67c98e598037ced5d240f0d6/
externalImg_1741343524424_1741343516118_image_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67cacb2b7e0bb1d5cc311c98",
      "name": "externalImg_1741343519089_1741343516118_image_0.jpeg",
      "path": "cases/67c98e598037ced5d240f0d6/
externalImg_1741343519089_1741343516118_image_0.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67cacb2b7e0bb1d5cc311c9d",
    "name": "externallmg_1741343529081_1741343516118_image_5.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343529081_1741343516118_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67cacb2b7e0bb1d5cc311c9b",
    "name": "externallmg_1741343524909_1741343516118_image_3.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343524909_1741343516118_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67cac5ab8037ced5d2419f0b",
    "name": "externallmg_1741342103785_1741341984125_image_3.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741342103785_1741341984125_image_3.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8718.00",
    "max": "12427.00"
  },
  "builtUpRateRange": {
    "min": "7926.00",
    "max": "11297.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
```



```
"totalValue": 0,
"additionTotalValue": 0,
"lessTotalValue": 0,
"presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "387.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c98e598037ced5d240f0d6",
"ownerName": "Mr. Vikas Ashruba Darade & Mrs. Swati Vikas Darade ",
"ownerPhoneNo": "8422974650",
"appAddress": "Flat no. 601, 6th Floor, Building no. A, Season Sahara Nano A & B
Building, Adivali Dhokali, Kalyan ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    }
  }
]
```

```
},
"attachConfig": {
  "fromPage": 0,
  "toPage": 0
},
"attachInReport": false,
"inputs": {
  "documentDate": "17/01/2025",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "M/s. Samarth Sai Builders & Developers ",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Vikas Ashruba Darade & Mrs. Swati Vikas Darade ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "844 / 2025"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1741682644280_Vikas_darade.pdf",
"path": "cases/67c98e598037ced5d240f0d6/
document_1741682644280_Vikas_darade.pdf",
"id": "780980",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Mar 11 2025 08:44:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Approved Building Plan",
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "12/07/2024",
    "nameOfApprovingAuthority": {
```

```
    "value": "Kalyan_Dombivli_Municipal_Corporation",
    "label": "Kalyan Dombivli Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "KDMC / TPD / BP / 27 Villages / 2024 - 25 / 09"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1741682766921_1741421568584_Approved_plan.pdf",
"path": "cases/67c98e598037ced5d240f0d6/
document_1741682766921_1741421568584_Approved_plan.pdf",
"id": "842952",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Mar 11 2025 08:46:07 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "12/07/2024",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KDMC / TPD / BP / 27 Villages / 2024 - 25 / 09"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1741682840241_1741421576837_CC.pdf",
  "path": "cases/67c98e598037ced5d240f0d6/
document_1741682840241_1741421576837_CC.pdf",
  "id": "574277",
```

```
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Mar 11 2025 08:47:20 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "RERA Certificate",
    "value": "60ae129faa6d152c1801b47d"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "25/10/2024",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700077747"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1741682893213_1741421580320_Rera_Certificate.pdf",
"path": "cases/67c98e598037ced5d240f0d6/
document_1741682893213_1741421580320_Rera_Certificate.pdf",
"id": "351966",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Mar 11 2025 08:48:13 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014731",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "252171",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 06 2025 12:00:25 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
```

```
{
  "name": "Mr. Vikas Ashruba Darade & Mrs. Swati Vikas Darade ",
  "phone": "8422974650",
  "ownershipShare": "",
  "email": "",
  "id": "162094"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "589104",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "387",
    "squareMeterArea": "35.95",
    "docFinalBuiltUp": "425.7",
    "docFinalBuiltUpSquareMeter": "39.545",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "338.00",
      "squareMeterArea": "31.40",
      "expectedRate": "12426.04",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "371.80",
```

```
"squareMeterArea": "34.54",
"expectedRate": "11296.40",
"percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67cbfa288037ced5d242643a",
"property": "Residential Flat",
"area": "338",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "4200000",
"expectedRate": "12426.04",
"builtUpExpectedRate": "11296.40",
"image": "cases/67c98e598037ced5d240f0d6/
indicator_1741420365310_Image.png",
"squareMeter": "31.40",
"id": "825624"
},
{
  "carpetArea": {
    "area": "338.00",
    "squareMeterArea": "31.40",
    "expectedRate": "11094.67",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "371.80",
    "squareMeterArea": "34.54",
    "expectedRate": "10086.07",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```

```
},
"printlnReport": true,
"_id": "67cbfa288037ced5d242643b",
"property": "Residential Flat ",
"area": "338",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "3750000",
"expectedRate": "11094.67",
"builtUpExpectedRate": "10086.07",
"image": "cases/67c98e598037ced5d240f0d6/
indicator_1741420408944_Image.png",
"squareMeter": "31.40",
"id": "166554"
},
{
  "carpetArea": {
    "area": "640.00",
    "squareMeterArea": "59.46",
    "expectedRate": "8717.87",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "704.00",
    "squareMeterArea": "65.40",
    "expectedRate": "7925.34",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67cbfa288037ced5d242643c",
  "property": "Residential Flat ",
  "area": "640",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
```

```
"floor": "",
"source": "Index_no.2",
"expectedPrice": "5579438",
"expectedRate": "8717.87",
"builtUpExpectedRate": "7925.34",
"image": "cases/67c98e598037ced5d240f0d6/
indicator_1741420461265_Image.png",
"squareMeter": "59.46",
"id": "973006"
},
{
"carpetArea": {
"area": "462.00",
"squareMeterArea": "42.92",
"expectedRate": "9632.03",
"percentage": ""
},
"builtUpArea": {
"area": "508.20",
"squareMeterArea": "47.21",
"expectedRate": "8756.40",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67cbfa288037ced5d242643d",
"property": " Residential Flat",
"area": "462",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4450000",
"expectedRate": "9632.03",
"builtUpExpectedRate": "8756.40",
"image": "cases/67c98e598037ced5d240f0d6/
indicator_1741420496359_Image.png",
"squareMeter": "42.92",
"id": "400193"
```



```
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cacb2b7e0bb1d5cc311c98",
    "name": "externallmg_1741343519089_1741343516118_image_0.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343519089_1741343516118_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cacb2b7e0bb1d5cc311c99",
    "name": "externallmg_1741343521329_1741343516118_image_1.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343521329_1741343516118_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cacb2b7e0bb1d5cc311c9a",
    "name": "externallmg_1741343524424_1741343516118_image_2.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343524424_1741343516118_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cacb2b7e0bb1d5cc311c9b",
    "name": "externallmg_1741343524909_1741343516118_image_3.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343524909_1741343516118_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cacb2b7e0bb1d5cc311c9c",
    "name": "externallmg_1741343528253_1741343516118_image_4.jpeg",
    "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343528253_1741343516118_image_4.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cacb2b7e0bb1d5cc311c9d",
  "name": "externallmg_1741343529081_1741343516118_image_5.jpeg",
  "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741343529081_1741343516118_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cac5ab8037ced5d2419f08",
  "name": "externallmg_1741342023887_1741341984124_image_0.jpeg",
  "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741342023887_1741341984124_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cac5ab8037ced5d2419f09",
  "name": "externallmg_1741342050321_1741341984125_image_1.jpeg",
  "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741342050321_1741341984125_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cac5ab8037ced5d2419f0a",
  "name": "externallmg_1741342084003_1741341984125_image_2.jpeg",
  "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741342084003_1741341984125_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67cac5ab8037ced5d2419f0b",
  "name": "externallmg_1741342103785_1741341984125_image_3.jpeg",
  "path": "cases/67c98e598037ced5d240f0d6/
externallmg_1741342103785_1741341984125_image_3.jpeg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67cacb2a7e0bb1d5cc311c7d",
      "name": "externalImg_1741343500790_1741343488149_image_0.jpeg",
      "path": "cases/67c98e598037ced5d240f0d6/
externalImg_1741343500790_1741343488149_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "1716632370231_Calculation_Sheet_NEW.xlsx",
      "filename": "1741421425590_1716632370231_Calculation_Sheet_NEW.xlsx",
      "path": "cases/67c98e598037ced5d240f0d6/processingDocuments/1741421425590_
1716632370231_Calculation_Sheet_NEW.xlsx",
      "size": "2627726",
      "createdAt": "Sat Mar 08 2025 08:13:01 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "64cde526dc9f3034f3fefa49"
    },
    {
      "originalname": "Ankush More - Final Report.pdf",
      "filename": "1741421476458_Ankush_More__Final_Report.pdf",
      "path": "cases/67c98e598037ced5d240f0d6/
processingDocuments/1741421476458_Ankush_More__Final_Report.pdf",
      "size": "20615315",
      "createdAt": "Sat Mar 08 2025 08:13:01 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "64cde526dc9f3034f3fefa49"
    },
    {
      "originalname": "Approved plan.pdf",
      "filename": "1741421568584_Approved_plan.pdf",
      "path": "cases/67c98e598037ced5d240f0d6/
processingDocuments/1741421568584_Approved_plan.pdf",
      "size": "2494214",
      "createdAt": "Sat Mar 08 2025 08:13:01 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "64cde526dc9f3034f3fefa49"
    },
    {
      "originalname": "CC.pdf",
      "filename": "1741421576837_CC.pdf",
      "path": "cases/67c98e598037ced5d240f0d6/
processingDocuments/1741421576837_CC.pdf",
      "size": "1810764",
```

```
"createdAt": "Sat Mar 08 2025 08:13:01 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "Rera Certificate.pdf",
  "filename": "1741421580320_Rera_Certificate.pdf",
  "path": "cases/67c98e598037ced5d240f0d6/
processingDocuments/1741421580320_Rera_Certificate.pdf",
  "size": "708473",
  "createdAt": "Sat Mar 08 2025 08:13:01 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67cbeeb2021414d63cdf066b",
    "note": "Value given for confirmation",
    "taskId": "67c99d4a8037ced5d241052c",
    "createdAt": "2025-03-08T07:07:30.676Z"
  }
],
"createdAt": "2025-03-06T12:00:25.724Z",
"updatedAt": "2025-03-11T09:18:21.150Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 601, 6th Floor, Wing - A, Seasons Sahara Nano
Building No. A & B, Behind 50-50 Dhaba, Opp. Essar Petrol Pump , Haji Malang Road,
Village - Adivali & Dhokali, Kalyan (East), Taluka - Ambarnath, District - Thane, PIN -
421 306, State - Maharashtra, Country - India",
"updatedBy": "62fe044a48a26047e6552796",
```

```
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Pawan Pawar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Builder Person ",
"rerald": "",
"siteVisitContactNo": "9323682081",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 387.00",
"flatRate": "10000",
"landOtherRate": "7200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 289.00\nBalcony Area in Sq. Ft. = 98.00",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
}
```

```
"leaseDetails": {  
  "lessorName": "",  
  "lesseeName": "",  
  "leasePremium": "",  
  "leaseRent": "",  
  "leasePeriod": 0,  
  "leaseFrom": "",  
  "leaseTo": "",  
  "remainingLeasePeriod": 0,  
  "leaseDate": ""  
}  
}  
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			