

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "647ed1960ab64c23c9fcf71d",
```

```
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
```

```
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.995245",
  "longitude": "73.752763"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "101, Final Plot No. 489 (P), T.P.S No. II",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sneh Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dr BS Moonje Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Mahatma Nagar Ground, Parijat Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "728/ 1 to 10, 13 B to 25/ A/ 173",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "4",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "PIN Code - 422007",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
```

```
"label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Nashik_Municipal_Corporation_",
  "label": "Nashik Municipal Corporation "
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Plot No. 100",
  "west": "Plot No. 107",
  "south": "Plot No. 102",
  "east": "Colony Road"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 100",
  "west": "Plot No. 107",
  "south": "Plot No. 102",
  "east": "Colony Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Side Marginal Space & Terrace",
    "east": "Apt. Unit No. 3 & Staircase",
    "south": "Side Marginal Space",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Side Marginal Space & Terrace",
    "east": "Apt. Unit No. 3 & Staircase",
    "south": "Side Marginal Space",
    "west": "Marginal Space"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  }
},
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Accompanying
Commencement Certificate No. 1714/ 5741 dated.21-1-1999 issued by Executive
Engineer Town Planning Nashik Municipal Corporation, Nashik",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "33",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "6640",
  "depreciatedBuildingRate": "1340"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "63200",
  "landRate": "51500",
  "igrImage": "cases/67cad6b18037ced5d241b715/igr_1741347618275_Image.png",
  "squareMeterGuideLineRate": "60040.00",
  "squareFeetGuideLineRate": "5578.00"
},
"igrFinalRate": {
  "floorRatePercentage": "95",
  "depreciationPercentage": "78",
  "rate": "5403.00",
  "squareFeetGuideLineRate": "5403.00",
  "squareMeterGuideLineRate": "58161.00"
```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details Not Provided",
  "taxPaidHolderName": "Details Not Provided",
  "taxAmount": "Details Not Provided",
  "electricityServiceConnectionNo": "Details Not Provided",
  "meterCardHolderName": "Details Not Provided",
  "undividedAreaOfLandAsPerSaleDeed": "NA",
  "floorSpaceIndex": "As Per NMC Norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Excellent",
    "label": "Excellent"
  },
  "anyFavouringForExtraPotentialValue": "Located in developing area",
  "negativeFactorsOfAffectMarketValue": "NA"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
},
```

```
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered Car Parking ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
```



```
"totalLifeBuilding": "60",
"estimatedAge": "38",
"ageOfBuilding": "22",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "1",
"noOfLifts": "-",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "1225.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Notarized Agreement for Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67cad6b18037ced5d241b715/
routeMap_1741349036841_Image.png",
    "routeLat": "19.995245",
    "routeLng": "73.752763",
    "stationName": "Nashik Road",
    "routeDistance": "12.6",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "ohuqt",
    "name": "ohuqt",
    "image": "cases/67cad6b18037ced5d241b715/
routeMap_1741348992673_Image.png"
```

```
}
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8134000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "8134000.00",
  "purchaseValueDocument": {
    "documentType": {
      "label": "Notarized Agreement for Sale",
      "value": "60ae12adaa6d152c1801b4bf"
```

```
},
"attachConfig": {
  "fromPage": 0,
  "toPage": 0
},
"attachInReport": true,
"isHardCopy": false,
"displayStatus": true,
"id": "385141",
"path": "cases/67cad6b18037ced5d241b715/
document_1741346312453_Notary_Agreement.pdf",
"fileName": "document_1741346312453_Notary_Agreement.pdf",
"documentDate": "03/03/2025",
"amount": "6700000",
"from": {
  "value": "Seller",
  "label": "Seller"
},
"to": {
  "value": "buyer",
  "label": "buyer"
},
"buyer": "Shri. Eknath Uttamrao Kulkarni & Sau. Sandhya Eknath Kulkarni\t"
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6618675.00",
  "selectedBuildUpValue": "1225.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67cad7038037ced5d241b832",
      "name":
"externallmg_1741346559880_WhatsApp_Image_20250306_at_11518_PM_1.jpeg",
      "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346559880_WhatsApp_Image_20250306_at_11518_PM_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "67cad7038037ced5d241b835",
      "name": "Living Room",
      "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560628_WhatsApp_Image_20250306_at_11519_PM_1.jpeg",
      "orientation": "landscape"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "67cad7038037ced5d241b83b",
  "name": "Living Room",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346561664_WhatsApp_Image_20250306_at_11521_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "67cad7038037ced5d241b841",
  "name": "Living Room",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346562894_WhatsApp_Image_20250306_at_11525_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "67cad7038037ced5d241b837",
  "name": "Living Room",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560863_WhatsApp_Image_20250306_at_11520_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "67cad7038037ced5d241b839",
  "name": "Living Room",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346561275_WhatsApp_Image_20250306_at_11520_PM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "67cad7038037ced5d241b83a",
  "name": "Living Room",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346561372_WhatsApp_Image_20250306_at_11521_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "67cad7038037ced5d241b838",
  "name": "Living Room",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560981_WhatsApp_Image_20250306_at_11520_PM_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67cad7038037ced5d241b834",
    "name": "Living Room",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560314_WhatsApp_Image_20250306_at_11518_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67cad7038037ced5d241b830",
    "name": "Living Room",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346559365_WhatsApp_Image_20250306_at_11517_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67cad7038037ced5d241b831",
    "name": "Living Room",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346559624_WhatsApp_Image_20250306_at_11517_PM.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7220.00",
    "max": "9416.00"
  },
  "builtUpRateRange": {
    "min": "6017.00",
    "max": "7847.00"
  },
  "saleableRateRange": {
    "min": "5014.00",
    "max": "6539.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
```

```
"presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1225.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67cad6b18037ced5d241b715",
"ownerName": "Smt. Anuradha Nandkumar Gokhale",
"ownerPhoneNo": "9921604675",
"fullAddress": "Residential Flat No. 4, 1st Floor, Sneh Apartment, Near Mahatma
Nagar Ground, Parijat Nagar, Plot No. 101, Final Plot No. 489 (P), T.P.S No. II, Dr BS
Moonje Marg, Taluka - Nashik, District - Nashik, Nashik, PIN Code - 422007, State -
Maharashtra, Country - India",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Notarized Agreement for Sale",
      "value": "60ae12adaa6d152c1801b4bf"
    }
  },

```

```
"attachConfig": {
  "fromPage": 0,
  "toPage": 0
},
"attachInReport": true,
"inputs": {
  "documentDate": "03/03/2025",
  "amount": "6700000",
  "from": {
    "value": "Seller",
    "label": "Seller"
  },
  "Seller": "Smt. Anuradha Nadkumar Gokhale",
  "to": {
    "value": "buyer",
    "label": "buyer"
  },
  "buyer": "Shri. Eknath Uttamrao Kulkarni & Sau. Sandhya Eknath Kulkarni\t"
},
"isHardCopy": false,
"displayStatus": true,
"id": "385141",
"path": "cases/67cad6b18037ced5d241b715/
document_1741346312453_Notary_Agreement.pdf",
"fileName": "document_1741346312453_Notary_Agreement.pdf"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "21/01/1999",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "LND/ BP/ 1714/ 5741"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1741346360624_Commencement_Letter.pdf",
  "path": "cases/67cad6b18037ced5d241b715/
document_1741346360624_Commencement_Letter.pdf",
  "id": "564136",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Fri Mar 07 2025 11:21:20 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Approved Building Plan",
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "21/01/1999",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "1714/ 5741 "
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1741346403831_Commencement_Letter.pdf",
  "path": "cases/67cad6b18037ced5d241b715/
document_1741346403831_Commencement_Letter.pdf",
  "id": "781081",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Fri Mar 07 2025 11:21:20 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  }
}
```

```
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "10/04/2003",
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    },
    "No": "Javak No. NNRV/ Nashik/ 002814"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1741346464307_Complition_Certificate.pdf",
  "path": "cases/67cad6b18037ced5d241b715/
document_1741346464307_Complition_Certificate.pdf",
  "id": "329144",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Fri Mar 07 2025 11:21:20 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014757",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "241368",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 07 2025 11:21:21 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Smt. Anuradha Nandkumar Gokhale",
    "phone": "9921604675",
```

```
"ownershipShare": "",
"email": "",
"id": "587870"
},
],
"proposePurchasers": [
{
"name": "Shri. Eknath Uttamrao Kulkarni & Sau. Sandhya Eknath Kulkarni",
"phone": "",
"email": "",
"ownershipShare": "",
"panNo": "",
"aadharNo": ""
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "670134",
"name": "Living Room",
"length": "14.08",
"length1": "14",
"length2": "1",
"width": "11.33",
"width1": "11",
"width2": "4",
"totalArea": "159.61",
"images": [],
"extraAreas": [],
"finalArea": "159.61"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "8.67",
"length1": "8",
"length2": "8",
"width": "8.67",
```

```
"width1": "8",
"width2": "8",
"totalArea": "75.11",
"images": [],
"extraAreas": [],
"finalArea": "75.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "101.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "101.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "101.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "101.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
```



```
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "11.25",
  "width1": "11",
  "width2": "3",
  "totalArea": "126.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "126.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "8.33",
  "length1": "8",
  "length2": "4",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "44.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "44.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "8.33",
  "length1": "8",
  "length2": "4",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
```

```
"totalArea": "44.44",
"images": [],
"extraAreas": [],
"finalArea": "44.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "WC",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "39.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Balcony",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "81.36",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },

```

```
"id": "9",
"name": "Passage",
"length": "9.67",
"length1": "9",
"length2": "8",
"width": "5.33",
"width1": "5",
"width2": "4",
"totalArea": "51.56",
"images": [],
"extraAreas": [],
"finalArea": "51.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Balcony",
  "length": "8.33",
  "length1": "8",
  "length2": "4",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "44.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "44.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "8.33",
  "length1": "8",
  "length2": "4",
  "width": "8.67",
  "width1": "8",
  "width2": "8",
  "totalArea": "72.22",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "72.22"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeofDocument": {
"label": "Notarized Agreement for Sale",
"value": "60ae12adaa6d152c1801b4bf"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "113.81",
"totalAreaDocument": "1225",
"docBuiltpPercentage": "",
"docFinalBUILTUp": "0.00",
"docFinalBUILTUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "441277"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "1541.67",
"squareMeterArea": "143.23",
"expectedRate": "8497.28",
"percentage": ""
},
"builtUpArea": {
"area": "1850.00",
"squareMeterArea": "171.87",
"expectedRate": "7081.08",
"percentage": "20"
},
"saleableArea": {
"area": "2220.00",
"squareMeterArea": "206.24",
```

```
    "expectedRate": "5900.90",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67cadb33021414d63cde93cd",
  "property": "Flat",
  "area": "1850",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "13100000",
  "expectedRate": "8497.28",
  "builtUpExpectedRate": "13100000",
  "image": "cases/67cad6b18037ced5d241b715/
indicator_1741347346332_Image.png",
  "squareMeter": "171.87",
  "id": "388552"
},
{
  "carpetArea": {
    "area": "1540.00",
    "squareMeterArea": "143.07",
    "expectedRate": "9415.58",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1848.00",
    "squareMeterArea": "171.68",
    "expectedRate": "7846.32",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "2217.60",
    "squareMeterArea": "206.02",
    "expectedRate": "6538.60",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "67cadb33021414d63cde93ce",
  "property": "Flat",
  "area": "1540",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "14500000",
"expectedRate": "9415.58",
"builtUpExpectedRate": "7846.32",
"image": "cases/67cad6b18037ced5d241b715/
indicator_1741347443241_Image.png",
"squareMeter": "143.07",
"id": "656214"
},
{
"carpetArea": {
"area": "2008.33",
"squareMeterArea": "186.58",
"expectedRate": "7219.93",
"percentage": ""
},
"builtUpArea": {
"area": "2410.00",
"squareMeterArea": "223.90",
"expectedRate": "6016.60",
"percentage": "20"
},
"saleableArea": {
"area": "2892.00",
"squareMeterArea": "268.68",
"expectedRate": "5013.83",
"percentage": "20"
},
"printInReport": true,
"_id": "67cadb33021414d63cde93cf",
"property": "Flat",
"area": "2410",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "14500000",
"expectedRate": "7219.93",
"builtUpExpectedRate": "14500000",
"image": "cases/67cad6b18037ced5d241b715/
indicator_1741347564420_Image.png",
```

```
    "squareMeter": "223.90",
    "id": "799994"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b830",
    "name":
"externallmg_1741346559365_WhatsApp_Image_20250306_at_11517_PM_1.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346559365_WhatsApp_Image_20250306_at_11517_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b831",
    "name":
"externallmg_1741346559624_WhatsApp_Image_20250306_at_11517_PM.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346559624_WhatsApp_Image_20250306_at_11517_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b832",
    "name":
"externallmg_1741346559880_WhatsApp_Image_20250306_at_11518_PM_1.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346559880_WhatsApp_Image_20250306_at_11518_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b833",
    "name":
"externallmg_1741346560136_WhatsApp_Image_20250306_at_11518_PM_2.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560136_WhatsApp_Image_20250306_at_11518_PM_2.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b834",
    "name":
"externallmg_1741346560314_WhatsApp_Image_20250306_at_11518_PM.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560314_WhatsApp_Image_20250306_at_11518_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b835",
    "name":
"externallmg_1741346560628_WhatsApp_Image_20250306_at_11519_PM_1.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560628_WhatsApp_Image_20250306_at_11519_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b836",
    "name":
"externallmg_1741346560745_WhatsApp_Image_20250306_at_11519_PM.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560745_WhatsApp_Image_20250306_at_11519_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b837",
    "name":
"externallmg_1741346560863_WhatsApp_Image_20250306_at_11520_PM_1.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560863_WhatsApp_Image_20250306_at_11520_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cad7038037ced5d241b838",
    "name":
"externallmg_1741346560981_WhatsApp_Image_20250306_at_11520_PM_2.jpeg",
    "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346560981_WhatsApp_Image_20250306_at_11520_PM_2.jpeg",
```



```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b839",
  "name":
  "externallmg_1741346561275_WhatsApp_Image_20250306_at_11520_PM.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346561275_WhatsApp_Image_20250306_at_11520_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b83a",
  "name":
  "externallmg_1741346561372_WhatsApp_Image_20250306_at_11521_PM_1.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346561372_WhatsApp_Image_20250306_at_11521_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b83b",
  "name":
  "externallmg_1741346561664_WhatsApp_Image_20250306_at_11521_PM.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346561664_WhatsApp_Image_20250306_at_11521_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b83c",
  "name":
  "externallmg_1741346561877_WhatsApp_Image_20250306_at_11523_PM_1.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346561877_WhatsApp_Image_20250306_at_11523_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b83d",
```

```
"name":
"externallmg_1741346562054_WhatsApp_Image_20250306_at_11523_PM_2.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346562054_WhatsApp_Image_20250306_at_11523_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b83e",
  "name":
"externallmg_1741346562268_WhatsApp_Image_20250306_at_11523_PM.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346562268_WhatsApp_Image_20250306_at_11523_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b83f",
  "name":
"externallmg_1741346562445_WhatsApp_Image_20250306_at_11524_PM.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346562445_WhatsApp_Image_20250306_at_11524_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b840",
  "name":
"externallmg_1741346562621_WhatsApp_Image_20250306_at_11525_PM_1.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346562621_WhatsApp_Image_20250306_at_11525_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b841",
  "name":
"externallmg_1741346562894_WhatsApp_Image_20250306_at_11525_PM.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346562894_WhatsApp_Image_20250306_at_11525_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cad7038037ced5d241b842",
  "name":
"externallmg_1741346563113_WhatsApp_Image_20250306_at_11526_PM.jpeg",
  "path": "cases/67cad6b18037ced5d241b715/
externallmg_1741346563113_WhatsApp_Image_20250306_at_11526_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Eknath Kulkarni CAI.xlsx",
  "filename": "1741347657047_Eknath_Kulkarni_CAI.xlsx",
  "path": "cases/67cad6b18037ced5d241b715/
processingDocuments/1741347657047_Eknath_Kulkarni_CAI.xlsx",
  "size": "877732",
  "createdAt": "Fri Mar 07 2025 11:40:58 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "647ed1960ab64c23c9fcf71d"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-07T11:21:21.249Z",
"updatedAt": "2025-03-07T12:04:59.916Z",
"__v": 0,
"updatedBy": "647ed1960ab64c23c9fcf71d",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Smt. Anuradha Nandkumar Gokhale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Shri. Eknath Uttamrao Kulkarni & Sau. Sandhya Eknath
Kulkarni",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Purchaser",
"rerald": "",
"siteVisitContactNo": "9921604675",
"buildingServicesRate": "2000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Notarized Agreement for Sale",
```

```
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1225.00",
"flatRate": "7300",
"landOtherRate": "5300",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Toilet + Bathroom +
WC + 2 Balcony + 2 Passage",
"carpetTotal": "942.19",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1036.41",
"finalCarpetArea": "942.19",
"finalSalableArea": "1140.05",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	14'1"	11'4"	159.61
Kitchen	8'8"	8'8"	75.11
Bedroom	10'1"	10'1"	101.67
Bedroom	10'1"	10'1"	101.67
Bedroom	11'3"	11'3"	126.56
Toilet	8'4"	5'4"	44.44
Bathroom	8'4"	5'4"	44.44
WC	7'4"	5'4"	39.11
Balcony	8'5"	9'8"	81.36
Passage	9'8"	5'4"	51.56
Balcony	8'4"	5'4"	44.44
Passage	8'4"	8'8"	72.22
Other Composition :			