

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba7a"
    },
    "firstName": "Afrin",
    "type": "CREDITOFFICER",
    "_id": "65322d2e619c14402da74768",
    "lastName": "Shaikh",
    "mobileNo": "",
    "workMobileNo": "9819111447",
    "email": "1ubin0539287@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Afrin",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba7a",
  "branchCode": "000023",
  "type": "BRANCH",
  "name": "Bhayander (West) Branch",
  "email": "cbsbhayander@unionbankofindia.com",
  "mobileNo": "02228192334",
  "alternateMobileNo": "9137539280",
  "address": "Zainab Manzil, Ground Floor, Station Road Bhayander
(W)Thane-401101",
  "ledgerName": "",
  "fax": "02228190228",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "ck06806@gmail.com",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
```

```
"latitude": "19.944121107565422",
"longitude": "72.86635604855658"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86635604855658,
    19.944121107565422
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Manipur",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ganjad Gram panchayat",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
```

```
"name": "Project Name",
"key": "projectName",
"value": "House No. 1483",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dahanu",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
}
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```



```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67cedafe7e0bb1d5cc32c0ee",
"ownerName": "SURESHKUMAR CHHAGGANLAL JAIN PURPOSED PURCHASE
PUNIT LALIT MEHTA",
"ownerPhoneNo": "9004481604",
"appAddress": "Industrial shed bearing Ganjad Gram panchayat hosue no 1483
Ground floor Ganjad grampanchayt village manipur dahanu palghar \n",
"remark": "Urgent visit \n\nPunit mehta proposed purchaser 9004481604\n",
"documents": [
  {
    "documentType": {
      "label": "Power Of Attorney",
      "value": "60ae1248aa6d152c1801b2ed"
    }
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
document_1741609379138_1741609378047_dahanu_rashi_2.pdf",
```

```
"fileName": "document_1741609379138_1741609378047_dahanu_rashi_2.pdf",
"id": "121844",
"uploadedBy": "659ccce98f39506e83489828",
"createdAt": "Mon Mar 10 2025 12:28:45 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Draft Agreement",
    "value": "60ae124aaa6d152c1801b2f8"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
document_1741609524167_1741609523377_Adobe_Scan_7_Mar_2025.pdf",
  "fileName":
"document_1741609524167_1741609523377_Adobe_Scan_7_Mar_2025.pdf",
  "id": "179804",
  "uploadedBy": "659ccce98f39506e83489828",
  "createdAt": "Mon Mar 10 2025 12:28:45 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Deed of Conveyance",
    "value": "60ae1253aa6d152c1801b321"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
document_1741609545522_1741609544938_dahanu_rashi_1.pdf",
  "fileName": "document_1741609545522_1741609544938_dahanu_rashi_1.pdf",
  "id": "140614",
  "uploadedBy": "659ccce98f39506e83489828",
  "createdAt": "Mon Mar 10 2025 12:28:45 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014820",
```

```
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "329290",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Mar 10 2025 12:28:46 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "SURESHKUMAR CHHAGGANLAL JAIN PURPOSED PURCHASE
PUNIT LALIT MEHTA",
    "phone": "9004481604",
    "ownershipShare": "",
    "email": "",
    "id": "405360"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d2448945",
    "name": "externalImg_1741747990972_1741747988672_image_0.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalImg_1741747990972_1741747988672_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d2448946",
    "name": "externalImg_1741747991145_1741747988672_image_1.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalImg_1741747991145_1741747988672_image_1.jpeg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d2448947",
  "name": "externallmg_1741747992245_1741747988672_image_2.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741747992245_1741747988672_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d2448948",
  "name": "externallmg_1741747993780_1741747988672_image_3.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741747993780_1741747988672_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d2448949",
  "name": "externallmg_1741747995513_1741747988672_image_4.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741747995513_1741747988672_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d244894a",
  "name": "externallmg_1741747998364_1741747988672_image_5.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741747998364_1741747988672_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d244894b",
  "name": "externallmg_1741747999664_1741747988672_image_6.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741747999664_1741747988672_image_6.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d244894c",
    "name": "externallmg_1741747999886_1741747988672_image_7.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741747999886_1741747988672_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d244894d",
    "name": "externallmg_1741748000356_1741747988672_image_8.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748000356_1741747988672_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d244894e",
    "name": "externallmg_1741748000920_1741747988672_image_9.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748000920_1741747988672_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d244894f",
    "name": "externallmg_1741748001466_1741747988672_image_10.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748001466_1741747988672_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d2448950",
    "name": "externallmg_1741748002297_1741747988672_image_11.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748002297_1741747988672_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "67d0f7298037ced5d2448951",
  "name": "externallmg_1741748003397_1741747988672_image_12.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748003397_1741747988672_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d2448952",
  "name": "externallmg_1741748004396_1741747988672_image_13.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748004396_1741747988672_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d2448953",
  "name": "externallmg_1741748005080_1741747988672_image_14.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748005080_1741747988672_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d2448954",
  "name": "externallmg_1741748005990_1741747988672_image_15.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748005990_1741747988672_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d0f7298037ced5d2448955",
  "name": "externallmg_1741748006745_1741747988672_image_16.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748006745_1741747988672_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "67d0f7298037ced5d2448956",
    "name": "externalimg_1741748007548_1741747988672_image_17.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalimg_1741748007548_1741747988672_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d2448957",
    "name": "externalimg_1741748008142_1741747988672_image_18.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalimg_1741748008142_1741747988672_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d0f7298037ced5d2448958",
    "name": "externalimg_1741748008637_1741747988672_image_19.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalimg_1741748008637_1741747988672_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1af",
    "name": "externalimg_1741748080444_1741748075605_image_0.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalimg_1741748080444_1741748075605_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1b0",
    "name": "externalimg_1741748081922_1741748075605_image_1.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalimg_1741748081922_1741748075605_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1b1",
```

```
    "name": "externallmg_1741748083125_1741748075605_image_2.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748083125_1741748075605_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1b2",
    "name": "externallmg_1741748083964_1741748075605_image_3.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748083964_1741748075605_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1b3",
    "name": "externallmg_1741748085497_1741748075605_image_4.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748085497_1741748075605_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1b4",
    "name": "externallmg_1741748087165_1741748075605_image_5.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748087165_1741748075605_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1b5",
    "name": "externallmg_1741748088237_1741748075605_image_6.jpeg",
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748088237_1741748075605_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d0f78c021414d63ce0e1b6",
    "name": "externallmg_1741748089246_1741748075605_image_7.jpeg",
```



```
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/  
externallmg_1741748089246_1741748075605_image_7.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67d0f78c021414d63ce0e1b7",  
    "name": "externallmg_1741748090011_1741748075605_image_8.jpeg",  
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/  
externallmg_1741748090011_1741748075605_image_8.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67d0f78c021414d63ce0e1b8",  
    "name": "externallmg_1741748091164_1741748075605_image_9.jpeg",  
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/  
externallmg_1741748091164_1741748075605_image_9.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67d0f78c021414d63ce0e1b9",  
    "name": "externallmg_1741748092119_1741748075606_image_10.jpeg",  
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/  
externallmg_1741748092119_1741748075606_image_10.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67d0f78c021414d63ce0e1ba",  
    "name": "externallmg_1741748093845_1741748075606_image_11.jpeg",  
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/  
externallmg_1741748093845_1741748075606_image_11.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67d0f78c021414d63ce0e1bb",  
    "name": "externallmg_1741748094887_1741748075606_image_12.jpeg",  
    "path": "cases/67cedafe7e0bb1d5cc32c0ee/  
externallmg_1741748094887_1741748075606_image_12.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d0f78c021414d63ce0e1bc",
  "name": "externallmg_1741748096802_1741748075606_image_13.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748096802_1741748075606_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d0f78c021414d63ce0e1bd",
  "name": "externallmg_1741748098783_1741748075606_image_14.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748098783_1741748075606_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d0f78c021414d63ce0e1be",
  "name": "externallmg_1741748100397_1741748075606_image_15.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748100397_1741748075606_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d0f78c021414d63ce0e1bf",
  "name": "externallmg_1741748102236_1741748075606_image_16.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748102236_1741748075606_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d0f78c021414d63ce0e1c0",
  "name": "externallmg_1741748105048_1741748075606_image_17.jpeg",
  "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externallmg_1741748105048_1741748075606_image_17.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d0f78c021414d63ce0e1c1",
      "name": "externalImg_1741748106078_1741748075606_image_18.jpeg",
      "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalImg_1741748106078_1741748075606_image_18.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d0f78c021414d63ce0e1c2",
      "name": "externalImg_1741748107057_1741748075606_image_19.jpeg",
      "path": "cases/67cedafe7e0bb1d5cc32c0ee/
externalImg_1741748107057_1741748075606_image_19.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2025-03-10T12:28:46.206Z",
  "updatedAt": "2025-03-12T02:55:08.706Z",
  "__v": 0,
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "fullAddress": "Residential Land and Building No. Ground Floor, Ganjad Gram
panchayat, House No. 1483, Village - Manipur, Dahanu, District - Palghar",
  "updatedBy": "62550ed0aba01e0af98f2f75",
  "addressForMap": "",
  "caseReferredBy": "659ccce98f39506e83489828",
  "contactPersonName": "SURESHKUMAR CHHAGGANLAL JAIN PURPOSED
PURCHASE PUNIT LALIT MEHTA",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
```

"rerald": "",
"siteVisitContactNo": "9004481604"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
