

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cb"
    },
    "firstName": "Mukesh",
    "type": "CREDITOFFICER",
    "_id": "668bb759e61b5802e8d945d3",
    "email": "amt5so.09276@sbi.co.in",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7208509979"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454648",
    "discussWithPerson": "Mukesh",
    "expectedFees": 3227.324,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cb",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Diamond Branch (BKC)",
  "email": "sbi.09276@sbi.co.in",
  "mobileNo": "022-2675 2300",
  "alternateMobileNo": "",
  "address": "D/3, West Core, Bharat Dimond Bourse, Bandra-Kurla Complex, Bandra
(East), Mumbai - 400 051, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - BHARAT DIAMOND BRANCH",
  "fax": "022-2675 2381",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6006d4ce5080a310ac1fdfc2",
  "role": "ADMIN",
  "firstName": "Jagdish ",
  "email": "jagdish.bhatt@vastukala.org",
  "lastName": "Bhatt",
  "mobileNo": "8425864014",
  "designation": "",
  "shortName": "JB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6006d4ce5080a310ac1fdfc2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
```

```
"lastName": "Patil",
"mobileNo": "8830049996",
"designation": "Valuation Engineer",
"shortName": "SSP",
"workWithDocumentMaker": "60f91822f3dd69653a5922e3",
"profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1739013850922_20240602_151410.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "21.292720749302468",
  "longitude": "72.87514567084708"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87514567084708,
```

```
21.292720749302468
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Surat",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near kapodra police station",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "kalakunj road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "16",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "2",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "395006",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
```

```
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67cee1328037ced5d243b5a8",
"ownerName": "G.G.exports ",
"ownerPhoneNo": "8451896095",
"appAddress": "Survey no - 16, Hissa no - 2, TPS no - 16 (kapodra), Near kapodra
police station, kalakunj road, kapodra, Surat - 395006",
"remark": "Wednesday report required \nurgent basis ",
"documents": [],
"caseNumber": "014825",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "253938",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Mar 10 2025 12:55:14 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "G.G.exports ",
    "phone": "8451896095",
    "ownershipShare": "",
    "email": "",
    "id": "965790"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e4c",
    "name": "externalImg_1741852934930_IMG20250312WA0074.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852934930_IMG20250312WA0074.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e4d",
    "name": "externalImg_1741852935000_IMG20250312WA0075.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852935000_IMG20250312WA0075.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e4e",
    "name": "externalImg_1741852935009_IMG20250312WA0076.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852935009_IMG20250312WA0076.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e4f",
    "name": "externalImg_1741852935121_IMG20250312WA0077.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852935121_IMG20250312WA0077.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "67d29108ca9127630f5e4e50",
    "name": "externallmg_1741852935139_IMG20250312WA0078.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935139_IMG20250312WA0078.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e51",
    "name": "externallmg_1741852935279_IMG20250312WA0079.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935279_IMG20250312WA0079.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e52",
    "name": "externallmg_1741852935301_IMG20250312WA0080.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935301_IMG20250312WA0080.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e53",
    "name": "externallmg_1741852935437_IMG20250312WA0081.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935437_IMG20250312WA0081.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e54",
    "name": "externallmg_1741852935448_IMG20250312WA0082.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935448_IMG20250312WA0082.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e55",
```

```
    "name": "externallmg_1741852935616_IMG20250312WA0083.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935616_IMG20250312WA0083.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e56",
    "name": "externallmg_1741852935624_IMG20250312WA0084.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935624_IMG20250312WA0084.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e57",
    "name": "externallmg_1741852935702_IMG20250312WA0085.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935702_IMG20250312WA0085.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e58",
    "name": "externallmg_1741852935718_IMG20250312WA0086.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935718_IMG20250312WA0086.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29108ca9127630f5e4e59",
    "name": "externallmg_1741852935874_IMG20250312WA0087.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852935874_IMG20250312WA0087.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29118ca9127630f5e4e91",
    "name": "externallmg_1741852951329_IMG20250312WA0088.jpg",
```

```
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951329_IMG20250312WA0088.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29118ca9127630f5e4e92",
    "name": "externallmg_1741852951365_IMG20250312WA0089.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951365_IMG20250312WA0089.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29118ca9127630f5e4e93",
    "name": "externallmg_1741852951511_IMG20250312WA0090.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951511_IMG20250312WA0090.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29118ca9127630f5e4e94",
    "name": "externallmg_1741852951527_IMG20250312WA0091.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951527_IMG20250312WA0091.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29118ca9127630f5e4e95",
    "name": "externallmg_1741852951722_IMG20250312WA0092.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951722_IMG20250312WA0092.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d29118ca9127630f5e4e96",
    "name": "externallmg_1741852951757_IMG20250312WA0093.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951757_IMG20250312WA0093.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e97",
  "name": "externallmg_1741852951890_IMG20250312WA0094.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951890_IMG20250312WA0094.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e98",
  "name": "externallmg_1741852951906_IMG20250312WA0095.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852951906_IMG20250312WA0095.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e99",
  "name": "externallmg_1741852952073_IMG20250312WA0096.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852952073_IMG20250312WA0096.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e9a",
  "name": "externallmg_1741852952159_IMG20250312WA0097.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852952159_IMG20250312WA0097.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e9b",
  "name": "externallmg_1741852952171_IMG20250312WA0098.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852952171_IMG20250312WA0098.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e9c",
  "name": "externallmg_1741852952309_IMG20250312WA0099.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852952309_IMG20250312WA0099.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e9d",
  "name": "externallmg_1741852952372_IMG20250312WA0100.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852952372_IMG20250312WA0100.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d29118ca9127630f5e4e9e",
  "name": "externallmg_1741852952402_IMG20250312WA0101.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852952402_IMG20250312WA0101.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f01",
  "name": "externallmg_1741852971742_IMG20250312WA0102.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852971742_IMG20250312WA0102.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f02",
  "name": "externallmg_1741852971762_IMG20250312WA0103.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852971762_IMG20250312WA0103.jpg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f03",
  "name": "externallmg_1741852971786_IMG20250312WA0104.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852971786_IMG20250312WA0104.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f04",
  "name": "externallmg_1741852971950_IMG20250312WA0105.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852971950_IMG20250312WA0105.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f05",
  "name": "externallmg_1741852972006_IMG20250312WA0106.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972006_IMG20250312WA0106.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f06",
  "name": "externallmg_1741852972154_IMG20250312WA0107.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972154_IMG20250312WA0107.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f07",
  "name": "externallmg_1741852972165_IMG20250312WA0108.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972165_IMG20250312WA0108.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2912dca9127630f5e4f08",
    "name": "externallmg_1741852972286_IMG20250312WA0109.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972286_IMG20250312WA0109.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2912dca9127630f5e4f09",
    "name": "externallmg_1741852972297_IMG20250312WA0110.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972297_IMG20250312WA0110.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2912dca9127630f5e4f0a",
    "name": "externallmg_1741852972418_IMG20250312WA0111.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972418_IMG20250312WA0111.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2912dca9127630f5e4f0b",
    "name": "externallmg_1741852972428_IMG20250312WA0112.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972428_IMG20250312WA0112.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2912dca9127630f5e4f0c",
    "name": "externallmg_1741852972555_IMG20250312WA0113.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852972555_IMG20250312WA0113.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67d2912dca9127630f5e4f0d",
  "name": "externalimg_1741852972582_IMG20250312WA0114.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externalimg_1741852972582_IMG20250312WA0114.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2912dca9127630f5e4f0e",
  "name": "externalimg_1741852972698_IMG20250312WA0115.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externalimg_1741852972698_IMG20250312WA0115.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2913cca9127630f5e4f7b",
  "name": "externalimg_1741852987261_IMG20250312WA0116.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externalimg_1741852987261_IMG20250312WA0116.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2913cca9127630f5e4f7c",
  "name": "externalimg_1741852987313_IMG20250312WA0117.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externalimg_1741852987313_IMG20250312WA0117.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2913cca9127630f5e4f7d",
  "name": "externalimg_1741852987342_IMG20250312WA0118.jpg",
  "path": "cases/67cee1328037ced5d243b5a8/
externalimg_1741852987342_IMG20250312WA0118.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67d2913cca9127630f5e4f7e",
    "name": "externallmg_1741852987491_IMG20250312WA0119.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852987491_IMG20250312WA0119.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f7f",
    "name": "externallmg_1741852987506_IMG20250312WA0120.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852987506_IMG20250312WA0120.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f80",
    "name": "externallmg_1741852987662_IMG20250312WA0121.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852987662_IMG20250312WA0121.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f81",
    "name": "externallmg_1741852987675_IMG20250312WA0122.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852987675_IMG20250312WA0122.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f82",
    "name": "externallmg_1741852987818_IMG20250312WA0123.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852987818_IMG20250312WA0123.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f83",
```

```
    "name": "externalImg_1741852987830_IMG20250312WA0124.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852987830_IMG20250312WA0124.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f84",
    "name": "externalImg_1741852987967_IMG20250312WA0125.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852987967_IMG20250312WA0125.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f85",
    "name": "externalImg_1741852987982_IMG20250312WA0126.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852987982_IMG20250312WA0126.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f86",
    "name": "externalImg_1741852988123_IMG20250312WA0127.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852988123_IMG20250312WA0127.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f87",
    "name": "externalImg_1741852988169_IMG20250312WA0128.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externalImg_1741852988169_IMG20250312WA0128.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f88",
    "name": "externalImg_1741852988292_IMG20250312WA0129.jpg",
```

```
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852988292_IMG20250312WA0129.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f89",
    "name": "externallmg_1741852988357_IMG20250312WA0130.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852988357_IMG20250312WA0130.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f8a",
    "name": "externallmg_1741852988439_IMG20250312WA0131.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852988439_IMG20250312WA0131.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f8b",
    "name": "externallmg_1741852988554_IMG20250312WA0132.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852988554_IMG20250312WA0132.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f8c",
    "name": "externallmg_1741852988564_IMG20250312WA0133.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852988564_IMG20250312WA0133.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2913cca9127630f5e4f8d",
    "name": "externallmg_1741852988677_IMG20250312WA0134.jpg",
    "path": "cases/67cee1328037ced5d243b5a8/
externallmg_1741852988677_IMG20250312WA0134.jpg",
```

```
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "KAPODRA -GG -COR (1).pdf",
    "filename": "1741775419753_KAPODRA_GG_COR_1.pdf",
    "path": "cases/67cee1328037ced5d243b5a8/
processingDocuments/1741775419753_KAPODRA_GG_COR_1.pdf",
    "size": "4168927",
    "createdAt": "Wed Mar 12 2025 10:30:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "MAP - 2.pdf",
    "filename": "1741775420084_MAP__2.pdf",
    "path": "cases/67cee1328037ced5d243b5a8/
processingDocuments/1741775420084_MAP__2.pdf",
    "size": "507281",
    "createdAt": "Wed Mar 12 2025 10:30:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "MAP - 1 (2).pdf",
    "filename": "1741775421247_MAP__1_2.pdf",
    "path": "cases/67cee1328037ced5d243b5a8/
processingDocuments/1741775421247_MAP__1_2.pdf",
    "size": "422525",
    "createdAt": "Wed Mar 12 2025 10:30:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "MAP - 4.pdf",
    "filename": "1741775421306_MAP__4.pdf",
    "path": "cases/67cee1328037ced5d243b5a8/
processingDocuments/1741775421306_MAP__4.pdf",
    "size": "444245",
    "createdAt": "Wed Mar 12 2025 10:30:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "MAP - 3.pdf",
    "filename": "1741775421353_MAP__3.pdf",
    "path": "cases/67cee1328037ced5d243b5a8/
processingDocuments/1741775421353_MAP__3.pdf",
```

```
"size": "306913",
"createdAt": "Wed Mar 12 2025 10:30:21 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
"originalname": "MAP - 5 (1).pdf",
"filename": "1741775421359_MAP__5_1.pdf",
"path": "cases/67cee1328037ced5d243b5a8/
processingDocuments/1741775421359_MAP__5_1.pdf",
"size": "460113",
"createdAt": "Wed Mar 12 2025 10:30:21 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
"originalname": "GG Exports - 12.03.2025.xlsx",
"filename": "1741848443364_GG_Exports__12032025.xlsx",
"path": "cases/67cee1328037ced5d243b5a8/
processingDocuments/1741848443364_GG_Exports__12032025.xlsx",
"size": "614859",
"createdAt": "Thu Mar 13 2025 06:47:23 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "67d18c87da474c62c8e47fdb",
"note": "Value given for confirmation",
"taskId": "67cfda3c7e0bb1d5cc33025e",
"createdAt": "2025-03-12T13:30:47.591Z"
}
],
"createdAt": "2025-03-10T12:55:14.172Z",
"updatedAt": "2025-03-13T08:03:08.973Z",
```



```

    "__v": 0,
    "assignmentType": {
      "value": "Retail",
      "label": "Retail"
    },
    "fullAddress": "Residential Land and Building No. Basement Floor, New/Current
Survey No. 16, Hissa No. 2, Near kapodra police station, kalakunj road, District - Surat,
395006, State - Maharashtra, India",
    "updatedBy": "65dee3f79a876858ab30487f",
    "addressForMap": "",
    "caseReferredBy": "62723addafd7d55eddeddfe4",
    "contactPersonName": "G.G.exports ",
    "email": "",
    "isExternal": "false",
    "isUrgent": "false",
    "ownershipShare": "",
    "proposePurchaserName": "",
    "purchaseValueAsPerDocument": "",
    "relationWithOwner": "self",
    "rerald": "",
    "siteVisitContactNo": "8451896095"
  }

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			