

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b265fb191f7b344b008c29"
    },
    "firstName": "Akash",
    "type": "CREDITOFFICER",
    "_id": "64c1fde69d3a3e4ed9d2c03f",
    "lastName": "Patil",
    "mobileNo": "",
    "workMobileNo": "9870704907",
    "email": "akash.patil64@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9481315",
    "discussWithPerson": "Akash",
    "expectedFees": 4740.6575,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b265fb191f7b344b008c29",
  "name": "SME MIDC ANDHERI (EAST)",
  "branchCode": "",
  "mobileNo": "022-28329368",
  "alternateMobileNo": "",
  "email": "sbi.17879@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Plot No. B-1, MIDC Industrial Area, Central Road, Andheri (East),
Mumbai. "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.160085776892732",
```

```
"longitude": "72.84744176602356"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84744176602356,
    19.160085776892732
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "12/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Pahadi Goregaon",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "jawahar Nagar CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "jawahar Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```

```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```



```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "61",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400082",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
```



```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d11bd1021414d63ce10495",
"ownerName": "Mr. Mitesh R Shah And Mrs. Dhavani M Shah",
"ownerPhoneNo": "9320249895",
"appAddress": "flat no 61, 6th floor, Prem krupa co operative housing society Ltd, 123,
Jawahar Nagar, Goregaon West, Mumbai-400062, ",
"remark": "contact person - kaushik somani \n",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
```

```
"isHardCopy": false,
"displayStatus": false,
"path": "cases/67d11bd1021414d63ce10495/
document_1741757607849_1741757604390_61_Mitesh.pdf",
"fileName": "document_1741757607849_1741757604390_61_Mitesh.pdf",
"id": "644232",
"uploadedBy": "62723addafd7d55eddeddfe4",
"createdAt": "Wed Mar 12 2025 05:37:24 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67d11bd1021414d63ce10495/
document_1741757735487_1741757730339_mitesh_OC.pdf",
"fileName": "document_1741757735487_1741757730339_mitesh_OC.pdf",
"id": "370523",
"uploadedBy": "62723addafd7d55eddeddfe4",
"createdAt": "Wed Mar 12 2025 05:37:24 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67d11bd1021414d63ce10495/
document_1741757820904_1741757817640_Mitesh_electricity.pdf",
"fileName": "document_1741757820904_1741757817640_Mitesh_electricity.pdf",
"id": "339934",
"uploadedBy": "62723addafd7d55eddeddfe4",
"createdAt": "Wed Mar 12 2025 05:37:24 GMT+0000 (Coordinated Universal Time)"
}
```

```
    },
    {
      "documentType": {
        "label": "Any Other Document",
        "value": "60ae124aaa6d152c1801b2f7"
      },
      "attachConfig": {
        "fromPage": 0,
        "toPage": 0
      },
      "attachInReport": false,
      "isHardCopy": false,
      "displayStatus": false,
      "path": "cases/67d11bd1021414d63ce10495/
document_1741757839726_1741757835763_Mitesh_maintenance.pdf",
      "fileName":
"document_1741757839726_1741757835763_Mitesh_maintenance.pdf",
      "id": "138167",
      "uploadedBy": "62723addafd7d55eddeddfe4",
      "createdAt": "Wed Mar 12 2025 05:37:24 GMT+0000 (Coordinated Universal Time)"
    }
  ],
  "caseNumber": "014864",
  "createdBy": "62723addafd7d55eddeddfe4",
  "caseHistory": [
    {
      "id": "170065",
      "title": "Create Lead",
      "description": "Create Lead",
      "datetime": "Wed Mar 12 2025 05:29:53 GMT+0000 (Coordinated Universal Time)"
    }
  ],
  "owners": [
    {
      "name": "Mr. Mitesh R Shah And Mrs. Dhavani M Shah",
      "phone": "9320249895",
      "ownershipShare": "",
      "email": "",
      "id": "406467"
    }
  ],
  "proposePurchasers": [],
  "siteInspection": [],
  "composition": [],
  "otherComposition": [],
  "externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d1ca26ca9127630f5dfa59",
    "name": "externalImg_1741802007682_1741802003130_image_0.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalImg_1741802007682_1741802003130_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d1ca26ca9127630f5dfa5a",
    "name": "externalImg_1741802009476_1741802003131_image_1.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalImg_1741802009476_1741802003131_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d1ca26ca9127630f5dfa5b",
    "name": "externalImg_1741802012675_1741802003132_image_2.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalImg_1741802012675_1741802003132_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d1ca26ca9127630f5dfa5c",
    "name": "externalImg_1741802013367_1741802003132_image_3.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalImg_1741802013367_1741802003132_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d1ca26ca9127630f5dfa5d",
    "name": "externalImg_1741802015151_1741802003132_image_4.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalImg_1741802015151_1741802003132_image_4.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa5e",
  "name": "externallmg_1741802015734_1741802003132_image_5.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802015734_1741802003132_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa5f",
  "name": "externallmg_1741802016038_1741802003132_image_6.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802016038_1741802003132_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa60",
  "name": "externallmg_1741802018882_1741802003132_image_7.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802018882_1741802003132_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa61",
  "name": "externallmg_1741802019766_1741802003132_image_8.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802019766_1741802003132_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa62",
  "name": "externallmg_1741802019845_1741802003132_image_9.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802019845_1741802003132_image_9.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67d1ca26ca9127630f5dfa63",
      "name": "externallmg_1741802019875_1741802003132_image_10.jpeg",
      "path": "cases/67d11bd1021414d63ce10495/externallmg_1741802019875_1741802003132_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67d1ca26ca9127630f5dfa64",
      "name": "externallmg_1741802020138_1741802003132_image_11.jpeg",
      "path": "cases/67d11bd1021414d63ce10495/externallmg_1741802020138_1741802003132_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67d1ca26ca9127630f5dfa65",
      "name": "externallmg_1741802020314_1741802003132_image_12.jpeg",
      "path": "cases/67d11bd1021414d63ce10495/externallmg_1741802020314_1741802003132_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67d1ca26ca9127630f5dfa66",
      "name": "externallmg_1741802020523_1741802003132_image_13.jpeg",
      "path": "cases/67d11bd1021414d63ce10495/externallmg_1741802020523_1741802003132_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67d1ca26ca9127630f5dfa67",
      "name": "externallmg_1741802020683_1741802003132_image_14.jpeg",
      "path": "cases/67d11bd1021414d63ce10495/externallmg_1741802020683_1741802003132_image_14.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa68",
  "name": "externallmg_1741802020919_1741802003132_image_15.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802020919_1741802003132_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa69",
  "name": "externallmg_1741802021165_1741802003132_image_16.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802021165_1741802003132_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa6a",
  "name": "externallmg_1741802021343_1741802003132_image_17.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802021343_1741802003132_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa6b",
  "name": "externallmg_1741802021503_1741802003132_image_18.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802021503_1741802003132_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d1ca26ca9127630f5dfa6c",
  "name": "externallmg_1741802021715_1741802003132_image_19.jpeg",
  "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802021715_1741802003132_image_19.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfa9f",
    "name": "externallmg_1741802039955_1741802034413_image_0.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802039955_1741802034413_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa0",
    "name": "externallmg_1741802041596_1741802034416_image_1.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802041596_1741802034416_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa1",
    "name": "externallmg_1741802041763_1741802034416_image_2.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802041763_1741802034416_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa2",
    "name": "externallmg_1741802041965_1741802034416_image_3.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802041965_1741802034416_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa3",
    "name": "externallmg_1741802042098_1741802034416_image_4.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externallmg_1741802042098_1741802034416_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa4",
    "name": "externalimg_1741802042356_1741802034416_image_5.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalimg_1741802042356_1741802034416_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa5",
    "name": "externalimg_1741802042614_1741802034416_image_6.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalimg_1741802042614_1741802034416_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa6",
    "name": "externalimg_1741802042769_1741802034416_image_7.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalimg_1741802042769_1741802034416_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa7",
    "name": "externalimg_1741802042903_1741802034416_image_8.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalimg_1741802042903_1741802034416_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d1ca3bca9127630f5dfaa8",
    "name": "externalimg_1741802043095_1741802034416_image_9.jpeg",
    "path": "cases/67d11bd1021414d63ce10495/
externalimg_1741802043095_1741802034416_image_9.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
```

```

"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-12T05:29:53.460Z",
"updatedAt": "2025-03-12T17:54:03.844Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62691c48afd7d55eddecfda3",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 61, 6th Floor, jawahar Nagar CHSL, jawahar
Nagar, Village - Pahadi Goregaon, Mumbai, 400082",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mr. Mitesh R Shah And Mrs. Dhavani M Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9320249895"

```

}	Name	Length	Width	Total
Composition :				
Other				
Composition :				