

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Avinash",
    "type": "CREDITOFFICER",
    "_id": "675287fccfae933db22a82ff",
    "email": "avinash.bhosle.ssl@gmail.com",
    "lastName": "Bhosle",
    "mobileNo": "",
    "workMobileNo": "9167389229"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Avinash",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.114160367572754",
  "longitude": "72.93349094688892"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.93349094688892,
19.114160367572754
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-13",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-12",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-13",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-12",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Hariyali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "14",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "37",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Prasad Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tagore Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```



```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "113(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```

```
"status": true,
"name": "CTS No.",
"key": "CTSNo",
"value": "349(Part) 01 to 07",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1404",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 083",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vikhroli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
```

```
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement Plastering + POP Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Ashok N Pangare Marg",
    "west": "Building No. 8",
    "south": "Internal Road ",
    "east": "Ramakant Deshmukh Marg"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
```

```
"asPerActual": {
  "north": "Marginal Space ",
  "east": "Marginal Space ",
  "south": "Passage ",
  "west": "Marginal Space "
},
"asPerDocument": {
  "north": "Details not available ",
  "east": "Details not available ",
  "south": "Details not available ",
  "west": "Details not available "
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received, we assumed that
the construction is as per Sanction Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": ""
```

```
"salvageValue": "",
"buildingServicesDepreciatedRate": "0",
"depreciatedCostOfConstruction": "23000.00",
"depreciatedBuildingRate": "3000"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "135960",
  "landRate": "58490",
  "igrImage": "cases/67d135037e0bb1d5cc33c0cb/igr_1741861578048_Image.png",
  "squareMeterGuideLineRate": "149556.00",
  "squareFeetGuideLineRate": "13894.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "95",
  "rate": "13471.00",
  "squareFeetGuideLineRate": "13471.00",
  "squareMeterGuideLineRate": "145003.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "30,000/- (Expected rental income per month)",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Bill No. 100072062632",
  "meterCardHolderName": "Mrs. Minal Nandkumar Patil & Miss. Sonam Nandkumar Patil\n",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
```

```
"marketabilityList": {
  "value": "Good",
  "label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area ",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open / Covered Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2022",
    "fullDate": "1/1/2022"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  }
}
```

```
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
```



```
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "57",
"ageOfBuilding": "3",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "14",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
"area": "579.70",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/67d135037e0bb1d5cc33c0cb/
routeMap_1741867912379_Image.png",
"routeLat": "19.114167",
"routeLng": "72.933500",
"stationName": "Vikhroli",
"routeDistance": "1.00 Km. ",
"routeStation": {
```

```
    "value": "Railway_Station",
    "label": "Railway Station"
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "qtslh",
    "name": "qtslh",
    "image": "cases/67d135037e0bb1d5cc33c0cb/
routeMap_1741867778665_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
```

```
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "12121000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "12121000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "7809139.00",
  "selectedBuildUpValue": "579.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67d24b17da474c62c8e48a86",
      "name": "externallmg_1741835028544_1741835024429_image_3.jpeg",
      "path": "cases/67d135037e0bb1d5cc33c0cb/externallmg_1741835028544_1741835024429_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67d24b17da474c62c8e48a85",
      "name": "externallmg_1741835028263_1741835024429_image_2.jpeg",
      "path": "cases/67d135037e0bb1d5cc33c0cb/externallmg_1741835028263_1741835024429_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67d24b17da474c62c8e48a88",
      "name": "externallmg_1741835029005_1741835024429_image_5.jpeg",
      "path": "cases/67d135037e0bb1d5cc33c0cb/externallmg_1741835029005_1741835024429_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67d24b65da474c62c8e48aca",
      "name": "externallmg_1741835104234_1741835066912_image_0.jpeg",
```

```
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835104234_1741835066912_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67d24b65da474c62c8e48ad2",
    "name": "externallmg_1741835106589_1741835066912_image_8.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106589_1741835066912_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d24b65da474c62c8e48ad3",
    "name": "externallmg_1741835106811_1741835066912_image_9.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106811_1741835066912_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d24b65da474c62c8e48ad1",
    "name": "externallmg_1741835106542_1741835066912_image_7.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106542_1741835066912_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d24b65da474c62c8e48ad0",
    "name": "externallmg_1741835106173_1741835066912_image_6.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106173_1741835066912_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d24b65da474c62c8e48ad7",
    "name": "externallmg_1741835107709_1741835066912_image_13.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835107709_1741835066912_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "67d24b65da474c62c8e48ada",
    "name": "externallmg_1741835108327_1741835066912_image_16.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835108327_1741835066912_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d24b65da474c62c8e48ad8",
    "name": "externallmg_1741835107938_1741835066912_image_14.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835107938_1741835066912_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d24b65da474c62c8e48adb",
    "name": "externallmg_1741835108537_1741835066912_image_17.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835108537_1741835066912_image_17.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "19551.00",
    "max": "24668.00"
  },
  "builtUpRateRange": {
    "min": "17773.00",
    "max": "22426.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
  "presentMarketValue": 0
}
```

```
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "527.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d135037e0bb1d5cc33c0cb",
"ownerName": "Mrs. Minal Nandkumar Patil & Miss. Sonam Nandkumar Patil",
"ownerPhoneNo": "9892351293",
"appAddress": "Flat no. 1404, 14th Floor, Tagore Nagar Sai Prasad CHS, Building no.
37, Vikroli East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    }
  },
  "attachConfig": {
```

```
"fromPage": 0,
"toPage": 0
},
"attachInReport": false,
"inputs": {
  "documentDate": "24/01/2022",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Adityaraj Builders ",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mrs. Minal Nandkumar Patil & Miss. Sonam Nandkumar Patil",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "1358 / 2022"
},
"isHardCopy": false,
"displayStatus": true,
"id": "555891",
"path": "cases/67d135037e0bb1d5cc33c0cb/
document_1741763863520_1741763859691_AGREEMENT.pdf",
"fileName": "document_1741763863520_1741763859691_AGREEMENT.pdf"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "17/10/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "MH / EE / (B.P) / GM / MHADA - 8 / 096 / 2022"
},
"isHardCopy": false,
"displayStatus": false,
"id": "319613",
"path": "cases/67d135037e0bb1d5cc33c0cb/
document_1741763915849_1227025.pdf",
"fileName": "document_1741763915849_1227025.pdf"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "14/03/2019",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "MH / EE / (B.P) / GM / MHADA - 8 / 096 / 2019"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1741865229789_259063.pdf",
"path": "cases/67d135037e0bb1d5cc33c0cb/
document_1741865229789_259063.pdf",
"id": "877413",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Mar 13 2025 11:27:10 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "RERA Certificate",
```

```
"value": "60ae129faa6d152c1801b47d"
},
"attachConfig": {
  "fromPage": 0,
  "toPage": 0
},
"attachInReport": false,
"inputs": {
  "documentDate": "10/08/2021",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  }
},
"No": "P51800004104"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1741865376546_219469.pdf",
"path": "cases/67d135037e0bb1d5cc33c0cb/
document_1741865376546_219469.pdf",
"id": "446932",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Mar 13 2025 11:29:36 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Electricity Bill",
    "value": "6077c791395bc80714864a30"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "100072062632 dated 17.02.2025 in the name of Mrs. Minal Nandkumar Patil & Miss. Sonam Nandkumar Patil issued by Adani Electricity "
},
```

```
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741865465008_Light_Bill.pdf",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
document_1741865465008_Light_Bill.pdf",
    "id": "365030",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Thu Mar 13 2025 11:31:05 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014874",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "781511",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 12 2025 07:17:23 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Minal Nandkumar Patil & Miss. Sonam Nandkumar Patil",
    "phone": "9892351293",
    "ownershipShare": "",
    "email": "",
    "id": "553399"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "710524",
    "name": "Living Room",
    "length": "13.75",
    "length1": "13",
    "length2": "9",
    "width": "9.42",
    "width1": "9",
    "width2": "5",
    "totalArea": "129.48",
```

```
"images": [],
"extraAreas": [],
"finalArea": "129.48"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "5.75",
  "length1": "5",
  "length2": "9",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "42.65",
  "images": [],
  "extraAreas": [],
  "finalArea": "42.65"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
```



```
"name": "Kitchen",
"length": "6.75",
"length1": "6",
"length2": "9",
"width": "9.42",
"width1": "9",
"width2": "5",
"totalArea": "63.56",
"images": [],
"extraAreas": [],
"finalArea": "63.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "13.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "28.00",
  "length1": "28",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "26.00",
  "length1": "26",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "26.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "107.00",
  "length1": "107",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "107.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "107.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    }
  }
]
```

```
},
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "575518",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "527",
"squareMeterArea": "48.96",
"docFinalBuiltUp": "579.7",
"docFinalBuiltUpSquareMeter": "53.856",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "500.00",
      "squareMeterArea": "46.45",
      "expectedRate": "22000.00",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "550.00",
      "squareMeterArea": "51.10",
      "expectedRate": "20000.00",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printInReport": true,
  "_id": "67d2d09bdb5e3bc763996c9b",
  "property": "Tagore Nagar Sai Prasad, Vikhroli East",
  "area": "500",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
```

```
"floor": "1",
"source": "https://www.99acres.com/",
"expectedPrice": "11000000",
"expectedRate": "22000.00",
"builtUpExpectedRate": "20000.00",
"image": "cases/67d135037e0bb1d5cc33c0cb/
indicator_1741869211066_Image.png",
"squareMeter": "46.45",
"id": "402353"
},
{
"carpetArea": {
"area": "527.00",
"squareMeterArea": "48.96",
"expectedRate": "24667.93",
"percentage": ""
},
"builtUpArea": {
"area": "579.70",
"squareMeterArea": "53.86",
"expectedRate": "22425.39",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "67d2b318ca9127630f5e7ba6",
"property": "Tagore Nagar Sai Prasad, Vikhroli East",
"area": "527",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "22",
"source": "https://www.99acres.com/",
"expectedPrice": "13000000",
"expectedRate": "24667.93",
"builtUpExpectedRate": "22425.39",
"image": "cases/67d135037e0bb1d5cc33c0cb/
indicator_1741861143003_Image.png",
"squareMeter": "48.96",
"id": "330340"
```

```
},
{
  "carpetArea": {
    "area": "507.00",
    "squareMeterArea": "47.10",
    "expectedRate": "21175.54",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "557.70",
    "squareMeterArea": "51.81",
    "expectedRate": "19250.49",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67d2b318ca9127630f5e7ba7",
  "property": "Tagore Nagar, Vikhroli East",
  "area": "507",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "7",
  "source": "https://www.99acres.com/",
  "expectedPrice": "10736000",
  "expectedRate": "21175.54",
  "builtUpExpectedRate": "19250.49",
  "image": "cases/67d135037e0bb1d5cc33c0cb/
indicator_1741861246602_Image.png",
  "squareMeter": "47.10",
  "id": "752184"
},
{
  "carpetArea": {
    "area": "409.00",
    "squareMeterArea": "38.00",
    "expectedRate": "19550.21",
    "percentage": ""
  },
  "builtUpArea": {
```

```
    "area": "449.90",
    "squareMeterArea": "41.80",
    "expectedRate": "17772.92",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67d2b318ca9127630f5e7ba8",
  "property": "Tagore Nagar, Vikhroli East",
  "area": "409",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "21",
  "source": "Index_no.2",
  "expectedPrice": "7996036",
  "expectedRate": "19550.21",
  "builtUpExpectedRate": "17772.92",
  "image": "cases/67d135037e0bb1d5cc33c0cb/
indicator_1741861333087_Image.png",
  "squareMeter": "38.00",
  "id": "115630"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b17da474c62c8e48a83",
    "name": "externalimg_1741835027854_1741835024429_image_0.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externalimg_1741835027854_1741835024429_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b17da474c62c8e48a84",
    "name": "externalimg_1741835028043_1741835024429_image_1.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externalimg_1741835028043_1741835024429_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a85",
  "name": "externallmg_1741835028263_1741835024429_image_2.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835028263_1741835024429_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a86",
  "name": "externallmg_1741835028544_1741835024429_image_3.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835028544_1741835024429_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a87",
  "name": "externallmg_1741835028849_1741835024429_image_4.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835028849_1741835024429_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a88",
  "name": "externallmg_1741835029005_1741835024429_image_5.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835029005_1741835024429_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a89",
  "name": "externallmg_1741835029399_1741835024429_image_6.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835029399_1741835024429_image_6.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a8a",
  "name": "externallmg_1741835029808_1741835024429_image_7.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835029808_1741835024429_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a8b",
  "name": "externallmg_1741835030480_1741835024429_image_8.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835030480_1741835024429_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b17da474c62c8e48a8c",
  "name": "externallmg_1741835030981_1741835024429_image_9.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835030981_1741835024429_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b65da474c62c8e48aca",
  "name": "externallmg_1741835104234_1741835066912_image_0.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835104234_1741835066912_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b65da474c62c8e48acb",
  "name": "externallmg_1741835104827_1741835066912_image_1.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835104827_1741835066912_image_1.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b65da474c62c8e48acc",
  "name": "externallmg_1741835105066_1741835066912_image_2.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835105066_1741835066912_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b65da474c62c8e48acd",
  "name": "externallmg_1741835105275_1741835066912_image_3.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835105275_1741835066912_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b65da474c62c8e48ace",
  "name": "externallmg_1741835105517_1741835066912_image_4.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835105517_1741835066912_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b65da474c62c8e48acf",
  "name": "externallmg_1741835105950_1741835066912_image_5.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835105950_1741835066912_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d24b65da474c62c8e48ad0",
  "name": "externallmg_1741835106173_1741835066912_image_6.jpeg",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106173_1741835066912_image_6.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad1",
    "name": "externallmg_1741835106542_1741835066912_image_7.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106542_1741835066912_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad2",
    "name": "externallmg_1741835106589_1741835066912_image_8.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106589_1741835066912_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad3",
    "name": "externallmg_1741835106811_1741835066912_image_9.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835106811_1741835066912_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad4",
    "name": "externallmg_1741835107045_1741835066912_image_10.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835107045_1741835066912_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad5",
    "name": "externallmg_1741835107271_1741835066912_image_11.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835107271_1741835066912_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67d24b65da474c62c8e48ad6",
    "name": "externallmg_1741835107482_1741835066912_image_12.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835107482_1741835066912_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad7",
    "name": "externallmg_1741835107709_1741835066912_image_13.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835107709_1741835066912_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad8",
    "name": "externallmg_1741835107938_1741835066912_image_14.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835107938_1741835066912_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ad9",
    "name": "externallmg_1741835108119_1741835066912_image_15.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835108119_1741835066912_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48ada",
    "name": "externallmg_1741835108327_1741835066912_image_16.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externallmg_1741835108327_1741835066912_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "67d24b65da474c62c8e48adb",
    "name": "externalimg_1741835108537_1741835066912_image_17.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externalimg_1741835108537_1741835066912_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d24b65da474c62c8e48adc",
    "name": "externalimg_1741835108850_1741835066912_image_18.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externalimg_1741835108850_1741835066912_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d24afdf5937a62ce491596",
    "name": "externalimg_1741835004542_1741834998944_image_0.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externalimg_1741835004542_1741834998944_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d24afdf5937a62ce491597",
    "name": "externalimg_1741835004585_1741834998944_image_1.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externalimg_1741835004585_1741834998944_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d24afdf5937a62ce491598",
    "name": "externalimg_1741835004739_1741834998944_image_2.jpeg",
    "path": "cases/67d135037e0bb1d5cc33c0cb/
externalimg_1741835004739_1741834998944_image_2.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
```

```
"originalname":
"1739858091972_1719386343043_1717159298325_Calculation_1.xlsx",
  "filename": "1741861601691_1739858091972_1719386343043_1717159298325_C
alculation_1.xlsx",
  "path": "cases/67d135037e0bb1d5cc33c0cb/processingDocuments/1741861601691
_1739858091972_1719386343043_1717159298325_Calculation_1.xlsx",
  "size": "680628",
  "createdAt": "Thu Mar 13 2025 10:26:41 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "igr_20948.pdf",
  "filename": "1741861601712_igr_20948.pdf",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
processingDocuments/1741861601712_igr_20948.pdf",
  "size": "127462",
  "createdAt": "Thu Mar 13 2025 10:26:41 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "igr_23580.pdf",
  "filename": "1741861601774_igr_23580.pdf",
  "path": "cases/67d135037e0bb1d5cc33c0cb/
processingDocuments/1741861601774_igr_23580.pdf",
  "size": "125982",
  "createdAt": "Thu Mar 13 2025 10:26:41 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-12T07:17:23.113Z",
"updatedAt": "2025-03-13T12:33:41.158Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f915d3f3dd69653a592199",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1404, 14th Floor, Building No 37, Sai Prasad Co-
Op. Hsg. Soc. Ltd., Tagore Nagar, Village - Hariyali, Vikhroli (East), Taluka - Kurla,
District - Mumbai Suburban , PIN - 400 083, State - Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
```

```
"contactPersonName": "Mrs. Minal Nandkumar Patil \n",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"rerald": "",
"siteVisitContactNo": "9892351293",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 527.00",
"flatRate": "23000",
"landOtherRate": "20000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "510.31",
"extendOfSiteRemark": "\nAll the above areas are within 3% of the Agreement for Sale Area. The above calculations and detailed measurements taken by us prove that the Agreement for Sale area is not exorbitantly inflated. Hence, valuation is prepared based on the Agreement for Sale area.",
"finalBuiltupArea": "561.34",
"finalCarpetArea": "510.31",
"finalSalableArea": "617.48",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + Passage + 2 Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
```

```

"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Thu Mar 13 2025 11:14:25 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-03-12"
}

```

Name	Length	Width	Total
Composition :			
Living Room	13'9"	9'5"	129.48
Dining	5'9"	7'5"	42.65
Bedroom	10'00"	10'00"	100.00
Kitchen	6'9"	9'5"	63.56
Passage	4'5"	3'1"	13.62
Toilet	28'00"	1'00"	28.00
Toilet	26'00"	1'00"	26.00
Bedroom	107'00"	1'00"	107.00
Other Composition :			