

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b895"
    },
    "firstName": "ASMITA ",
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b2f",
    "email": "asmita.doshi@cosmosbank.in",
    "mobileNo": "",
    "workMobileNo": "9922662811",
    "lastName": " DOSHI"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3500000",
    "discussWithPerson": "ASMITA ",
    "expectedFees": 1750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b895",
  "branchCode": "000001",
  "type": "BRANCH",
  "name": "Bhayander (West) Branch",
  "email": "bhayander@cosmosbank.in",
  "mobileNo": "022-28041167",
  "alternateMobileNo": "022-28041168",
  "address": "Shop No. 3, 4, 5, Rishab Apartment, S. No. - 5A, Hissa No. 1Part, Patel
Nagar No.1, Station Road, Bhayander (West), Thane - 401 101, State -Maharashtra,
Country - India",
  "ledgerName": "COSMOS BANK - Bhayander",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.300090528952854",
  "longitude": "72.84907800316698"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84907800316698,
    19.300090528952854
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "6/03/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
```

```
    "dateTime": "2025-03-07",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bhayandar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
}
```

```
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2A",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhayandar (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "Shiv Kripa ",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1 ",
  "key": "street1",
  "value": "150 Feet Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Opp. Padmavati Nagar",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
```



```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "263/1, 251/2",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```

```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 101",
  "label": false
},
"suburb": {
  "status": false,
```

```

    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
},

```

```
"townplanApprovedByList": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "150 Feet Road",
  "west": "Raghuleela Building",
  "south": "Ramdev Vaayu Building",
  "east": "Roop Rajat Plaza CHSL"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  },
  "auto": {
```

```
    "title": "Auto",
    "status": true
  },
  "privateCars": {
    "title": "Private Cars",
    "status": true
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved Building Plan were not provided and not
verified.",
"approvePlanVerified": "No",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"classOfSanitary": {
  "value": "superior_white",
  "label": "Superior White"
},
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
```

```
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per MBMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered / Open Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2007",
    "fullDate": "1/1/2007"
  },
}
```

```
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
```

```
"label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "42",
"ageOfBuilding": "18",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "796.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
```



```
    "routeMapImg": "cases/67c936ae629772d404c296fc/
routeMap_1741412549466_Image.png",
    "routeLat": "19.294157",
    "routeLng": "72.846591",
    "stationName": "Bhayandar",
    "routeDistance": "3 km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "5a0kbn",
      "name": "5a0kbn",
      "image": "cases/67c936ae629772d404c296fc/
routeMap_1741412427998_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    }
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "796.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67caed4d7e0bb1d5cc3158b8",
      "name": "externalImg_1741352268809_IMG20250307WA0163.jpg",
      "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352268809_IMG20250307WA0163.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
```

```
{
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158c3",
  "name": "externalImg_1741352268986_IMG20250307WA0152.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352268986_IMG20250307WA0152.jpg",
  "orientation": "landscape"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c1",
    "name": "externalImg_1741352268958_IMG20250307WA0153.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352268958_IMG20250307WA0153.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158ba",
    "name": "externalImg_1741352268830_IMG20250307WA0161.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352268830_IMG20250307WA0161.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c6",
    "name": "Living Room",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352269044_IMG20250307WA0147.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c9",
    "name": "Living Room",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352269138_IMG20250307WA0145.jpg",
    "orientation": "portrait"
  },
]
```

```
{
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315908",
  "name": "Living Room",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352285554_IMG20250307WA0146.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67caed5d7e0bb1d5cc31590b",
  "name": "Living Room",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352285592_IMG20250307WA0141.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315911",
  "name": "Living Room",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352285717_IMG20250307WA0135.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315913",
  "name": "Living Room",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352285773_IMG20250307WA0134.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315915",
  "name": "Living Room",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352285782_IMG20250307WA0132.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158c4",
  "name": "Living Room",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352269037_IMG20250307WA0150.jpg",
```

```
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```



```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "664.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
```

```
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c936ae629772d404c296fc",
"ownerName": "Shri. Nandkishore Ramniranjan Singhania",
"ownerPhoneNo": "9699333331",
"appAddress": "FLAT NO 203 A WING BLDG NO 2A SHIVKRIPA BHAYNDER
VILLAGE BHAYNDER WEST THANE ",
"remark": "Radhesh singhania 9699333331\nOC not available",
"documents": [
{
  "documentType": {
    "label": "Agreement for sale",
    "value": "60af48bf2ffdf65bcd6585fa"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "31/12/2009",
    "from": {
      "value": "Builder",
      "label": "Builder"
    },
    "Builder": "M/s. Shiv Kripa Construction, a Partnership Firm",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Shri. Nandkishore Ramniranjan Singhania & Mahadevi Nandkishore
Singhania",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": " 1706/2010 dated 20/02/2010"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "598765",
  "path": "cases/67c936ae629772d404c296fc/document_1741239961481_174123996
1051_Nankishore_singhania_agreement_1.pdf",
  "fileName": "document_1741239961481_1741239961051_Nankishore_singhania_a
```

```
greement_1.pdf"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "17/03/2007",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " M.B./MNP/NR/4178/06-07"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "183407",
  "path": "cases/67c936ae629772d404c296fc/document_1741415457834_CC.pdf",
  "fileName": "document_1741415457834_CC.pdf"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "31/12/2007",
    "remark": "(Agreement for Additional Amenities)",
    "from": {
      "value": "Developers",
      "label": "Developers"
    }
  }
}
```

```
    },
    "Developers": "M/s. Shiv Kripa Construction, a Partnership Firm",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Shri. Nandkishore Ramniranjan Singhania & Mahadevi Nandkishore Singhania",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": " 1706/2010 dated 20/02/2010"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "986531",
  "path": "cases/67c936ae629772d404c296fc/document_1741415883517_Agreement_for_Additional_Amenities.pdf",
  "fileName": "document_1741415883517_Agreement_for_Additional_Amenities.pdf"
}
],
"caseNumber": "014713",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "376679",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 06 2025 05:46:22 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri. Nandkishore Ramniranjan Singhania",
    "phone": "9699333331",
    "ownershipShare": "",
    "email": "",
    "id": "852417"
  },
  {
    "name": "Mahadevi Nandkishore Singhania",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "panNo": ""
  }
]
```

```
"aadharNo": "",
"id": "658517"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "698356",
  "name": "Living Room",
  "length": "18.00",
  "length1": "18",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "180.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "180.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "23.49",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.49"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "29.29",
  "images": [],
  "extraAreas": [],
  "finalArea": "29.29"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Kitchen",
  "length": "",
  "length1": "10",
  "length2": "1",
  "width": "",
  "width1": "8",
  "width2": "1",
  "totalArea": "81.51",
  "images": [],
  "finalArea": "81.51",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
```

```
"totalArea": "20.00",
"images": [],
"extraAreas": [],
"finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "WC",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "15.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "14.08",
  "length1": "14",
  "length2": "1",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "137.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "137.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Kitchen",
  "length": "10.00",
  "length1": "10",
  "length2": "10",
  "width": "10.00",
  "width1": "10",
  "width2": "10",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Living Room",
  "length": "15.00",
  "length1": "15",
  "length2": "15",
  "width": "15.00",
  "width1": "15",
  "width2": "15",
  "totalArea": "225.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "225.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "5",
  "width": "5.00",
  "width1": "5",
  "width2": "5",
  "totalArea": "25.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Hallway",
  "length": "3.00",
  "length1": "3",
  "length2": "3",
  "width": "3.00",
  "width1": "3",
  "width2": "3",
  "totalArea": "9.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "9.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Closet",
  "length": "2.00",
  "length1": "2",
  "length2": "2",
  "width": "2.00",
  "width1": "2",
  "width2": "2",
  "totalArea": "4.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "4.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Porch",
  "length": "10.00",
  "length1": "10",
  "length2": "10",
  "width": "10.00",
  "width1": "10",
  "width2": "10",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Garage",
  "length": "20.00",
  "length1": "20",
  "length2": "20",
  "width": "20.00",
  "width1": "20",
  "width2": "20",
  "totalArea": "400.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "400.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "14",
  "name": "Front Yard",
  "length": "10.00",
  "length1": "10",
  "length2": "10",
  "width": "10.00",
  "width1": "10",
  "width2": "10",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "15",
  "name": "Back Yard",
  "length": "10.00",
  "length1": "10",
  "length2": "10",
  "width": "10.00",
  "width1": "10",
  "width2": "10",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "16",
  "name": "Total Area",
  "length": "0.00",
  "length1": "0",
  "length2": "0",
  "width": "0.00",
  "width1": "0",
  "width2": "0",
  "totalArea": "1000.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "1000.00"
}
```

```
"id": "7",
"name": "Toilet",
"length": "7.33",
"length1": "7",
"length2": "4",
"width": "4.17",
"width1": "4",
"width2": "2",
"totalArea": "30.56",
"images": [],
"extraAreas": [],
"finalArea": "30.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "10.92",
  "length1": "10",
  "length2": "11",
  "width": "10.17",
  "width1": "10",
  "width2": "2",
  "totalArea": "110.99",
  "images": [],
  "extraAreas": [],
  "finalArea": "110.99"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flowerbed",
      "value": "Flowerbed"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```



```
"id": "1",
"length": "10.75",
"length1": "10",
"length2": "9",
"width": "7.00",
"width1": "7",
"width2": "0",
"totalArea": "75.25",
"images": [],
"extraAreas": [],
"finalArea": "75.25",
"percentageBeforeTotal": "75.25",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement for sale",
    "value": "60af48bf2ffdf65bcd6585fa"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "545650",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "664",
  "squareMeterArea": "61.69",
  "docFinalBuiltUp": "796.8",
  "docFinalBuiltUpSquareMeter": "74.02799999999999",
  "docBultupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158b6",
  "name": "externalImg_1741352268753_IMG20250307WA0165.jpg",
```

```
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268753_IMG20250307WA0165.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158b7",
    "name": "externallmg_1741352268781_IMG20250307WA0164.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268781_IMG20250307WA0164.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158b8",
    "name": "externallmg_1741352268809_IMG20250307WA0163.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268809_IMG20250307WA0163.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158b9",
    "name": "externallmg_1741352268818_IMG20250307WA0162.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268818_IMG20250307WA0162.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158ba",
    "name": "externallmg_1741352268830_IMG20250307WA0161.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268830_IMG20250307WA0161.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158bb",
    "name": "externallmg_1741352268840_IMG20250307WA0160.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268840_IMG20250307WA0160.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158bc",
  "name": "externallmg_1741352268861_IMG20250307WA0159.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268861_IMG20250307WA0159.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158bd",
  "name": "externallmg_1741352268885_IMG20250307WA0158.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268885_IMG20250307WA0158.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158be",
  "name": "externallmg_1741352268915_IMG20250307WA0155.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268915_IMG20250307WA0155.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158bf",
  "name": "externallmg_1741352268928_IMG20250307WA0157.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268928_IMG20250307WA0157.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158c0",
  "name": "externallmg_1741352268940_IMG20250307WA0156.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268940_IMG20250307WA0156.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c1",
    "name": "externallmg_1741352268958_IMG20250307WA0153.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268958_IMG20250307WA0153.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c2",
    "name": "externallmg_1741352268973_IMG20250307WA0154.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268973_IMG20250307WA0154.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c3",
    "name": "externallmg_1741352268986_IMG20250307WA0152.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352268986_IMG20250307WA0152.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c4",
    "name": "externallmg_1741352269037_IMG20250307WA0150.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352269037_IMG20250307WA0150.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed4d7e0bb1d5cc3158c5",
    "name": "externallmg_1741352269040_IMG20250307WA0149.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352269040_IMG20250307WA0149.jpg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158c6",
  "name": "externallmg_1741352269044_IMG20250307WA0147.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352269044_IMG20250307WA0147.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158c7",
  "name": "externallmg_1741352269089_IMG20250307WA0148.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352269089_IMG20250307WA0148.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158c8",
  "name": "externallmg_1741352269113_IMG20250307WA0151.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352269113_IMG20250307WA0151.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed4d7e0bb1d5cc3158c9",
  "name": "externallmg_1741352269138_IMG20250307WA0145.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352269138_IMG20250307WA0145.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315908",
  "name": "externallmg_1741352285554_IMG20250307WA0146.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externallmg_1741352285554_IMG20250307WA0146.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc315909",
    "name": "externalImg_1741352285563_IMG20250307WA0143.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285563_IMG20250307WA0143.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc31590a",
    "name": "externalImg_1741352285590_IMG20250307WA0144.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285590_IMG20250307WA0144.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc31590b",
    "name": "externalImg_1741352285592_IMG20250307WA0141.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285592_IMG20250307WA0141.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc31590c",
    "name": "externalImg_1741352285622_IMG20250307WA0140.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285622_IMG20250307WA0140.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc31590d",
    "name": "externalImg_1741352285648_IMG20250307WA0142.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285648_IMG20250307WA0142.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67caed5d7e0bb1d5cc31590e",
  "name": "externalimg_1741352285651_IMG20250307WA0138.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externalimg_1741352285651_IMG20250307WA0138.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed5d7e0bb1d5cc31590f",
  "name": "externalimg_1741352285674_IMG20250307WA0139.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externalimg_1741352285674_IMG20250307WA0139.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315910",
  "name": "externalimg_1741352285684_IMG20250307WA0137.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externalimg_1741352285684_IMG20250307WA0137.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315911",
  "name": "externalimg_1741352285717_IMG20250307WA0135.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externalimg_1741352285717_IMG20250307WA0135.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67caed5d7e0bb1d5cc315912",
  "name": "externalimg_1741352285754_IMG20250307WA0136.jpg",
  "path": "cases/67c936ae629772d404c296fc/
externalimg_1741352285754_IMG20250307WA0136.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67caed5d7e0bb1d5cc315913",
    "name": "externalImg_1741352285773_IMG20250307WA0134.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285773_IMG20250307WA0134.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc315914",
    "name": "externalImg_1741352285779_IMG20250307WA0133.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285779_IMG20250307WA0133.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc315915",
    "name": "externalImg_1741352285782_IMG20250307WA0132.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285782_IMG20250307WA0132.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5d7e0bb1d5cc315916",
    "name": "externalImg_1741352285793_IMG20250307WA0131.jpg",
    "path": "cases/67c936ae629772d404c296fc/
externalImg_1741352285793_IMG20250307WA0131.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67caed5e7e0bb1d5cc315917",
    "name": "externalImg_1741352285822_WhatsApp_Image_20250307_at_172955_9
9a06a20.jpg",
    "path": "cases/67c936ae629772d404c296fc/externalImg_1741352285822_WhatsAp
p_Image_20250307_at_172955_99a06a20.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
```



```
{
  "originalname": "Agreement for Additional Amenities.pdf",
  "filename": "1741416995896_Agreement_for_Additional_Amenities.pdf",
  "path": "cases/67c936ae629772d404c296fc/
processingDocuments/1741416995896_Agreement_for_Additional_Amenities.pdf",
  "size": "1406665",
  "createdAt": "Sat Mar 08 2025 06:56:37 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "CC.pdf",
  "filename": "1741416995982_CC.pdf",
  "path": "cases/67c936ae629772d404c296fc/
processingDocuments/1741416995982_CC.pdf",
  "size": "1297057",
  "createdAt": "Sat Mar 08 2025 06:56:37 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Dimension.jpg",
  "filename": "1741416996062_Dimension.jpg",
  "path": "cases/67c936ae629772d404c296fc/
processingDocuments/1741416996062_Dimension.jpg",
  "size": "87867",
  "createdAt": "Sat Mar 08 2025 06:56:37 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Googel Location.jpg",
  "filename": "1741416996162_Googel_Location.jpg",
  "path": "cases/67c936ae629772d404c296fc/
processingDocuments/1741416996162_Googel_Location.jpg",
  "size": "61368",
  "createdAt": "Sat Mar 08 2025 06:56:37 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Deed - 2010.pdf",
  "filename": "1741416996167_Sale_Deed__2010.pdf",
  "path": "cases/67c936ae629772d404c296fc/
processingDocuments/1741416996167_Sale_Deed__2010.pdf",
  "size": "10718253",
  "createdAt": "Sat Mar 08 2025 06:56:37 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
```

```
    "originalname": "Site Detail.jpg",
    "filename": "1741416996501_Site_Detail.jpg",
    "path": "cases/67c936ae629772d404c296fc/
processingDocuments/1741416996501_Site_Detail.jpg",
    "size": "174559",
    "createdAt": "Sat Mar 08 2025 06:56:37 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sketch.jpg",
    "filename": "1741416997126_Sketch.jpg",
    "path": "cases/67c936ae629772d404c296fc/
processingDocuments/1741416997126_Sketch.jpg",
    "size": "78673",
    "createdAt": "Sat Mar 08 2025 06:56:37 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-06T05:46:22.382Z",
"updatedAt": "2025-03-10T05:38:57.000Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 203, 2nd Floor, Building No 2A, Wing - A, Shiv
Kripa , 150 Feet Road, Opp. Padmavati Nagar, Village - Bhayandar, Taluka - Thane,
District - Thane, Bhayandar (West), PIN - 401 101, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Yuvraj Singhania",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owners Son",
"reald": "",
"siteVisitContactNo": "8356922659",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + Passage +
Bathroom + WC + Toilet",
```

"carpetTotal": "628.46",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "75.25",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "75.83",
 "otherCompositionSaleableTotal": "0.00",
 "builtupPercentage": "20",
 "finalBuiltupArea": "845.15",
 "finalCarpetArea": "704.29",
 "finalSalableArea": "845.15",
 "salablePercentage": "0",
 "toBeAdded": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement for sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 664.00",
 "reportGeneratedDate": "Sat Mar 08 2025 05:28:49 GMT+0000 (Coordinated
 Universal Time)",
 "siteVisitDate": "2025-03-07"

Name	Length	Width	Total
Composition :			
Living Room	18'00"	10'00"	180.00
Dining	7'5"	3'2"	23.49
Passage	9'6"	3'1"	29.29
Kitchen	10'1"	8'1"	81.51
Bathroom	5'00"	4'00"	20.00
WC	4'10"	3'2"	15.31
Bedroom	14'1"	9'9"	137.31
Toilet	7'4"	4'2"	30.56
Bedroom	10'11"	10'2"	110.99
Other Composition :			
Flowerbed	10'9"	7'0"	75.25